

12/02/2017

ASS. REC. BY:

REF CS/MSG17019800/T2t6e2

Special Instructions:

1002101
Mennen Taufikh

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSG

Date/Time:

16/10/17 @ 10:57am

Estimated Cost:

Bill to

OD / TP / WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No:

SLE1871C

Insured:

SGM 426SA

at Workshop m/s

Ding Auto

Fel:

6421208

of Blk 10, # 01-20, Sin Ming Ind Est. Sec C, 575645

Policy No:

A80385532 QMX

Claim No:

532961

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

13/10/2017

CA / REV / REP. / REV 24 HRS

up'

249 Jalan Boon Lay

R.O.D. Endorsement

Date/Time:

16/10/17 @ 11:09am

Person Contacted:

Alex

Vehicle

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLE1871C - X

SGM 426SA - NJA / INC10000548 / 1 - D.O.A: 10/21/2010

17/10/17 @

5.26pm verified to Catherine Thia via Mennen.

Sir: *Tanji*

REF: *MS/G*

ASSIGNMENT

From: Date: *16-10-2017*

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLS 79110*

at Workshop m/s

of *45 Long Kue Road*

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: *After lunch*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: *SLE 1871C*

Yr Regn: *2016 July*

Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Toyota A/Hs* *1598*

Colour: *Blue* A/C: Insured / Std / NI / NA

Sp.Reading: *104 121* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *MROS3REH104 554350*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/55R16*

R: *2*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. *Ding* D.O.I. *16/10/17*

Survey held at

Des. of Damages: Frt / *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/5/2000, 5dys (Red: 6220.85, 750/0)

RECEIVED

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

_____ S + RS. _____ SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) *TP 2000*

200

10

210

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile**MSIG INSURANCE (SINGAPORE) PTE LTD**

Ref : CS/MSG17019800/T11b

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-10-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGM 4265A	Veh. Inspected	SLE 1871C
Policy No.	A80385532QMX	Coverage (\$)	0.00
Claim No.	532961	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	16/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/10/2017	Inspection Date	16/10/2017
Survey held at	249 JALAN BOON LAY		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Oct 2017 Sendback Est	16 Oct 2017 08:42 S\$8,220.85	16 Oct 2017 10:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NEO BEE LAY, ID: S7530813B		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLE1871C	Date of Loss:	13/10/2017 07:00 - :59
Claim Type:	TP / 532961	Policy/Cover Note No.:	A80385532QMX (Comprehensive) Coverage: 17/10/2016 - 16/10/2017
Vehicle Reg. No. (Insured):	SGM4265A	Policy No. (Claimant):	
	Excess:		
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/10/2017]		
Driver/Custodian (Insured):	LOW SEOW HUI (), NRIC: S7324280J, Tel: +6598504735		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS ☐

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 17 Oct 2017

Preliminary Advice

Insured Vehicle No	: SGM4265A	Accident Date	: 13/10/2017
TP Vehicle No	: SLE1871C	Assignment Date	: 16/10/2017
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 5.00
Date of Inspection	: 16/10/2017		
Inspection At	: DING AUTO PTE LTD (HQ) BLK 10, #01-20, SIN MING INDUSTRIAL ESTATE SECTOR C SINGAPORE 575645		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,220.85
Revised Amount	:S\$	2,284.00
Check Items (Estimated)	:S\$	322.00
Total	:S\$	2,606.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/10/2017 16:49
Date Of Accident	13/10/2017 07:35
Exact Location Of Accident	UBI AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE1871C
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999995174
Cover Note Number	
Driver	
Name of Driver	ONG CHAI HOCK
NRIC No	S1328900Z
Date Of Birth	17/02/1958
Occupation	OUTDOOR
Date Of Driving Pass	19/10/1977
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGM4265A
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LOW SEOW HUI
NRIC/Passport Number S7324280J
Contact Number 98504735

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Attach Sketch Plan

Sketch Plan #2 Pg. 1


Describe Circumstances of the Accident


On 13/10/17 at 7.35am I was traveling at Ubi Ave 2
wait for traffic light to turn green. A few second
later, I feel an impact a m/vehicle SGM4265A hit
into my rear portion of my vehicle. No one was injured


Declaration


We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Personnel





A = SLE 1871C
 B = SGM 4265A
 Low Seow Hui
 573242805

Ding Auto Pte Ltd (Co.Reg.No.201311788Z)

Blk 10, #01-20, Sin Ming Industrial Estate Sector C

Singapore 575645

Tel: 64521208 Fax: 64520614 Email: anna.chua@dingauto.sg; admin@dingauto.sg; ding@dingauto.sg

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

LOW SEOW HUI

Singapore

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY
 Policy No.:
 Vehicle Reg. No.: SLE1871C
 Party At Fault: UNKNOWN
 Driver (TP): ONG CHAI HOCK

Ref. No:
 Date of Loss: 13/10/2017
 Driveable?

Make/Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC
 CVT (A)
 Vehicle Colour: GREY
 Engine No: 1ZRX585840
 Odometer: 0 KM

Vehicle Reg. Date: 14/07/2016

Chassis No: MR053REH104554350

Faint Type:
 Total Loss? NO
 Est. Duration of Repair (day): 10

Description of Accident/Loss: PLEASE REFER TO GIA REPORT

Remarks: VEHICLE LYING AT 249 JALAN BOON LAY

Present Location: DING AUTO PTE LTD (HQ)

COST OF CLAIMS

Parts
 Miscellaneous Items
 Labour
 Paintwork Labour
 Towing

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Gross Total (S\$) 8,220.85
 + GST 7.00% (S\$) 575.46
 Nett Amount (S\$) 8,796.31

Taufik 97495749.
 - WP
 Resurvey before paint
 taufik e khantaw m
 sir @ khantaw m.
 16/10/17 @ 1510
 5 days.

[Signature]
 19/10/17

This claim is handled by: XIAO TING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

P DETAILS

BPM000

Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Oct 2017)

 No. 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SLE1871C/16/10/2017 08:42

 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the
 END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	0.00	0.00	de 200.00 F
2	1		*REAR BUMPER RETIANER SHORT LHS	0.00	0.00	ne 20.00 F
3	1		*REAR BUMPER RETIANER SHORT RHS	0.00	0.00	ne 20.00 F
4	1		*REAR BUMPER RETIANER LONG RHS	0.00	0.00	ne 25.00 F
5	1		*REAR BUMPER RETIANER LONG LHS	0.00	0.00	ne 25.00 F
6	1		*REAR BUMPER CLIP	0.00	0.00	ne 35.00 F
7	1		*REAR BUMPER SIDE REFLECTOR LHS	0.00	0.00	an x 36.00 F
8	1		*REAR BUMPER SIDE REFLECTOR RHS	0.00	0.00	an x 36.00 F
9	1		*REVERSE SENSOR	0.00	0.00	An 160.00 F
10	1		*REAR BOOT	0.00	0.00	Ry 350.00 F
11	1		*REAR BOOT EMBLEM - LOGO	0.00	0.00	ne 25.00 F
12	1		*REAR BOOT EMBLEM - COROLLA	0.00	0.00	ne 25.00 F
13	1		*REAR BOOT EMBLEM - ALTIS	0.00	0.00	ne 25.00 F
14	1		*REAR BOOT NUMBER PLATE LAMP LHS	0.00	0.00	an x 40.00 F
15	1		*REAR BOOT NUMBER PLATE LAMP RHS	0.00	0.00	an x 40.00 F
16	1		*REAR BOOT CHROME	0.00	0.00	an x 150.00 F
17	1		*REAR BOOT LOCK	0.00	0.00	dis 185.00 F
18	1		*REAR BOOT LOCK CATCH	0.00	0.00	an 25.00 F
19	1		*REAR END PANEL	0.00	0.00	Ry 180.00 F
20	1		*REAR END PANEL TOP GARNISH	0.00	0.00	de 125.00 F
21	1		*REAR END PANEL TOP GARNISH CLIP	0.00	0.00	ne 35.00 F
22	1		*SPARE TYRE PANEL	0.00	0.00	x an 180.00 F
23	1		*SPARE TYRE PANEL BOARD	0.00	0.00	x an 145.00 F
24	1		*REAR END WEATERSTRIP	0.00	0.00	an 65.00 F
25	1		*REAR END PANEL BRACKET LHS	0.00	0.00	de 35.00 F
26	1		*REAR END PANEL BRACKET RHS	0.00	0.00	de 35.00 F
27	1		*TAIL LAMP OUTER LHS	0.00	0.00	x 150.00 F
28	1		*TAIL LAMP OUTER RHS	0.00	0.00	x 150.00 F
29	1		*TAIL LAMP INNER RHS	0.00	0.00	x 140.00 F
30	1		*TAIL LAMP INNER LHS	0.00	0.00	x 140.00 F
31	1		*REAR BOOT INNER LINING CLIP	0.00	0.00	x 35.00 F
32	1		*REAR FENDER LHS	0.00	0.00	x 450.00 F
33	1		*REAR FENDER INNER SHIELD LHS CLIP	0.00	0.00	x 35.00 F
34	1		*REAR FENDER INNER SHIELD LHS	0.00	0.00	x 36.00 F
35	1		*REAR FENDER RHS	0.00	0.00	x 450.00 F
36	1		*REAR FENDER RHS INNER SHIELD RHS	0.00	0.00	x 36.00 F
37	1		*REAR FENDER RHS INNER SHIELD RHS CLIP	0.00	0.00	x 35.00 F

* In-house part.

Sub Total (S\$)

990 3,879.00

+ Margin on L,N Items 15.00% (S\$)

581.85

Total Parts (S\$)

1138.50 4,460.85

Estimates on Miscellaneous Items

No new miscellaneous items selected.

Estimates on Labour

Particulars	Lab.Type	Amount
<u>Labour Items</u>		
1 STRAUGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	600. 1,400.00
2 R&R BOOT COMPONENTS	New	40. 80.00
3 R&R WINDSCREEN	New	X 150.00
4 R&R SPARE TYRE BOARD/CARPET/TRIM	New	40. 100.00
5 R&R REAR WINDSCREEN	New	X 150.00
6 R&R REVERSE SENSOR	New	30 100.00
7 SPRAY REAR BUMPER	New	200 250.00
8 SPRAY REAR END PANEL	New	200 250.00
9 SPRAY REAR BOOT	New	200 250.00
10 SPRAY REAR FENDER LHS	New	X 250.00
11 SPRAY REAR FENDER RHS	New	X 250.00
12 SPRAY SPARE TYRE PANEL	New	30. 100.00
13 CHECK WIRING	New	30 80.00
14 RUSH PROOFING	New	40. 100.00
15 SPRAY REAR REVERSE SENSOR	New	
Gross Labour Cost (S\$)		3,760.00

1410

Ding Auto Pte Ltd/SLE1871C/16/10/2017 08:42. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1138.5
 1410

 2548.50
 4582000

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Oct 2017 Sendback Est	16 Oct 2017 08:42 S\$8,220.85	16 Oct 2017 10:57 Edit Adj Rpt	S\$2,000.00 Edit Estimates	S\$2,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	NEO BEE LAY, ID: S7530813B		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLE1871C	Date of Loss:	13/10/2017 07:00 - :59
Claim Type:	TP / 532961	Policy/Cover Note No.:	A80385532QMX (Comprehensive) Coverage: 17/10/2016 - 16/10/2017
Vehicle Reg. No. (Insured):	SGM4265A	Policy No. (Claimant):	
		Excess:	
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/11/2017]		
Driver/Custodian (Insured):	LOW SEOW HUI (), NRIC: S7324280J, Tel: +6598504735		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLE1871C (532961)
[SGM4265A]
TP
LCRF PTE LTD
Oct 13 2017 7:00AM
[NEO BEE LAY]
Ding Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View In Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Ding Auto Pte Ltd (HQ)							Thumbnail	Print	
1	16/10/17 08:42	Repairer Estimates							1 Load HTM		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	16/10/17 09:51	Accident Statement From:SC - Reg. No: SGM4265A, Claimant: NEO BEE LAY							1 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	17/10/17 17:26	Adjuster Immediate Advice							1 Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
2	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
3	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
4	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
5	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
6	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
7	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
8	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
9	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
10	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
11	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
12	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
13	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
14	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
15	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
16	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
17	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
18	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
19	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
20	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
21	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
22	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
23	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
24	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
25	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
26	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
27	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	
28	09/01/18 11:45	General View							1 Load JPG	<input checked="" type="checkbox"/>	

29	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	09/01/18 11:45	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	09/01/18 11:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	09/01/18 11:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	09/01/18 11:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	09/01/18 11:45	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Ding Auto Pte Ltd (HQ)		Thumbnail	Print
1	13/10/17 19:06	GIA REPORT	1	Load PDF	
2	13/10/17 19:06	Drivers NRIC	1	Load TIF	
3	16/10/17 08:43	E-filed GIA report	1	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/10/17 09:51	SLE1871C GIA RPT From:SC - Reg. No: SGM4265A, Claimant: NEO BEE LAY	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <div style="text-align: right;"> ^ v </div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17019800/T1TB2

Date: 15/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A80385532QMX
 Claimant Vehicle No: SLE1871C Insured Vehicle No: SGM4265A
 Date of Loss: 13/10/2017 Nature of Claim: TP Claim No: 532961

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE1871C**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZR585840
 Reg. Date: 13/07/2016 (Man. Year: 2016) Chassis No: MR053REH104554350
 Colour: Blue Odometer: 104121 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,460.85	1,138.50	3,322.35	74.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,410.00	2,350.00	62.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	8,220.85	2,548.50	5,672.35	69.00
Approved Total (Overridden) (\$)		2,000.00		
(\$)	8,220.85	2,000.00	6,220.85	75.67
+ GST 7.00/7.00% (\$)	575.46	140.00	435.46	75.67
Nett Amount (\$)	8,796.31	2,140.00	6,656.31	75.67

INSPECTION

Date of Assignment: 16/10/2017 Present Location: Ding Auto Pte Ltd (HQ)
 Date Inspected: 16/10/2017 Inspected At: Blk 10, #01-20, Sin Ming Industrial Estate
 Sector C
 Singapore 575645
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE1871C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Deformed	200.00 F	*200.00 F
2	1		*REAR BUMPER RETIANER SHORT LHS (WCP)	Necessary	20.00 F	*20.00 F
3	1		*REAR BUMPER RETIANER SHORT RHS (WCP)	Necessary	20.00 F	*20.00 F
4	1		*REAR BUMPER RETIANER LONG RHS (WCP)	Not Necessary	25.00 F	*- F
5	1		*REAR BUMPER RETIANER LONG LHS (WCP)	Not Necessary	25.00 F	*- F
6	1		*REAR BUMPER CLIP (WCP)	Necessary	35.00 F	*35.00 F
7	1		*REAR BUMPER SIDE REFLECTOR LHS (WCP)	Not Necessary	36.00 F	*- F
8	1		*REAR BUMPER SIDE REFLECTOR RHS (WCP)	Not Necessary	36.00 F	*- F
9	1		*REVERSE SENSOR (WCP)	Not Working	160.00 F	*160.00 F
10	1		*REAR BOOT (WCP)	Repair	350.00 F	*- F
11	1		*REAR BOOT EMBLEM - LOGO (WCP)	Necessary	25.00 F	*25.00 F
12	1		*REAR BOOT EMBLEM - COROLLA (WCP)	Necessary	25.00 F	*25.00 F
13	1		*REAR BOOT EMBLEM - ALTIS (WCP)	Necessary	25.00 F	*25.00 F
14	1		*REAR BOOT NUMBER PLATE LAMP LHS (WCP)	Not Necessary	40.00 F	*- F
15	1		*REAR BOOT NUMBER PLATE LAMP RHS (WCP)	Not Necessary	40.00 F	*- F
16	1		*REAR BOOT CHROME (WCP)	Not Necessary	150.00 F	*- F
17	1		*REAR BOOT LOCK (WCP)	Distorted	185.00 F	*185.00 F
18	1		*REAR BOOT LOCK CATCH (WCP)	Not Necessary	25.00 F	*- F
19	1		*REAR END PANEL (WCP)	Repair	180.00 F	*- F
20	1		*REAR END PANEL TOP GARNISH (WCP)	Deformed	125.00 F	*125.00 F
21	1		*REAR END PANEL TOP GARNISH CLIP (WCP)	Necessary	35.00 F	*35.00 F
22	1		*SPARE TYRE PANEL (WCP)	Not Necessary	180.00 F	*- F
23	1		*SPARE TYRE PANEL BOARD (WCP)	Not Necessary	145.00 F	*- F
24	1			Twisted	65.00 F	*65.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR END WEATERSTRIP (WCP)			
25	1		*REAR END PANEL BRACKET LHS (WCP)	Deformed	35.00 F	*35.00 F
26	1		*REAR END PANEL BRACKET RHS (WCP)	Deformed	35.00 F	*35.00 F
27	1		*TAIL LAMP OUTER LHS (WCP)	Not Necessary	150.00 F	*- F
28	1		*TAIL LAMP OUTER RHS (WCP)	Not Necessary	150.00 F	*- F
29	1		*TAIL LAMP INNER RHS (WCP)	Not Necessary	140.00 F	*- F
30	1		*TAIL LAMP INNER LHS (WCP)	Not Necessary	140.00 F	*- F
31	1		*REAR BOOT INNER LINING CLIP (WCP)	Not Necessary	35.00 F	*- F
32	1		*REAR FENDER LHS (WCP)	Not Necessary	450.00 F	*- F
33	1		*REAR FENDER INNER SHIELD LHS CLIP (WCP)	Not Necessary	35.00 F	*- F
34	1		*REAR FENDER INNER SHIELD LHS (WCP)	Not Necessary	36.00 F	*- F
35	1		*REAR FENDER RHS (WCP)	Not Necessary	450.00 F	*- F
36	1		*REAR FENDER RHS INNER SHIELD RHS (WCP)	Not Necessary	36.00 F	*- F
37	1		*REAR FENDER RHS INNER SHIELD RHS CLIP (WCP)	Not Necessary	35.00 F	*- F

F=Franchise part.

Sub Total (S\$)	3,879.00	990.00
+ Margin on L,N Items 15.00/15.00% (S\$)	581.85	148.50
Total Parts (S\$)	4,460.85	1,138.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAUGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	1,400.00	600.00
2	R&R BOOT COMPONENTS	New	80.00	40.00
3	R&R WINDSCREEN	New	150.00	0.00
4	R&R SPARE TYRE BOARD/CARPET/TRIM	New	100.00	40.00
5	R&R REAR WINSCREEN	New	150.00	0.00
6	R&R REVERSE SENSOR	New	100.00	30.00
7	SPRAY REAR BUMPER	New	250.00	200.00
8	SPRAY REAR END PANEL	New	250.00	200.00
9	SPRAY REAR BOOT	New	250.00	200.00
10	SPRAY REAR FENDER LHS	New	250.00	0.00
11	SPRAY REAR FENDER RHS	New	250.00	0.00
12	SPRAY SPARE TYRE PANEL	New	250.00	0.00
13	CHECK WIRING	New	100.00	30.00
14	RUSH PROOFING	New	80.00	30.00
15	SPRAY REAR REVERSE SENSOR	New	100.00	40.00
Gross Labour Cost (\$\$)			3,760.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >