

ASS. REC. BY:

REF: CS/EG17019803/Krbn2

Special Instructions:

Signature:

Kenneth

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EG1

Date/Time: 16/10/17 @ 10:41 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFE 977J

Insured: GBB 8032X

at Workshop m/s

Motor Image

Tel: 90963323

of 19 Lorong 8 Toa Payoh / 319255

Policy No:

Claim No: DSMCV1701640

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11/06/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement

Date/Time: 16/10/17 @ 10:58pm

Person Contacted: Fazli

Vehicle: INLOUT

Date/Time

Action/Instruction (✓) Estimate

SFE 977J - X

GBB 8032X - NS/INC14011787/H19m 3x3 - D.O.A. - 22/6/2014

Confirm \$2478 @ 2 days

Red: \$1880.36, 431

ASS. REC. BY:

REF:

ER1/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.21 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SFE 911JYr Regn: 01, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru ImprezaC.C. 1998Colour: A. Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 13227

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JFIVAGK8514G 017101Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: NII / S/Rim / STD A/Rim orTyre Size: F: 245/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 11/16/17D.O.I. 16/10/17Survey held at ✓Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
17/10	File pass to Customer

RECEIVED 14 AUG 2018

Date/Time, File Pass to?

☐

Preli. Report

1) typist☒

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

250

Report Format: 7PLump Sum / I.B.I: (\$ 2478.00)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EG17019803/Krb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 16-10-2017



Code : EGI

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	GBB 8032X	Veh. Inspected	SFE 977J
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1701640	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	16/10/2017

Vehicle Particulars & Condition

2.

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

Description of Damages

4.

--

General Information

5.

Accident Date	11/06/2017	Inspection Date	16/10/2017
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 16 October, 2017 10:41 AM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB8032X / TP : SFE977J/LKK / DOA : 11.06.2017 (DSMCV1701640)
Attachments: GBB8032X - SAS.pdf; SFE977J - SAS.pdf; SFE977J - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **MOTOR IMAGE ENTERPRISES PTE LTD**

ADDRESS : 19 LORONG 8 TOA PAYOH
SINGAPORE 319255

PERSON TO CONTACT : MOHAMAD FAZLI @ 9090 3323 / 6703 8104

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.

 **BUY NOW**

ERGO

Date: 23.06.2017
 Our Reference: GBB 8032X/SE/pl
 Your Reference: SFE 977J

Sent via Fax

or

Email

fai@bocho@motorimage.net

To: MOTOR IMAGE ENTERPRISES PTE LTDPre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SFE 977J
 Insured's Vehicle: GBB 8032X
 Date Of Accident: 11.06.2017


We acknowledge receipt of your request for PRS on: 23.06.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK AUTO CONSULTANTS PTE LTD.

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
ETA	EnrmTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☒ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☒ Our insured's driver has not reported the accident to us to date.
 Others: _____

Prepared by:		Pei Li	6029 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
 Assignment Time: _____

Remarks:

Workshop use only:Assessor attended workshop on:

Date: _____
 Time: _____
 Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

CV1701640

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0377/2017
DATE : 11-SEP-2017

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : FOO FANG YONG (FU FANGRONG)
ADDRESS : BLK 651 PUNGGOL CENTRAL #11-304
S(820651)
TELEPHONE NO : 9748 0615

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1
VEHICLE NO : SFE977J
MODEL CODE : VAGCKB8
MODEL/YEAR : WRX 4D 2.0 AWD CVT
ENGINE NO : FA20B921582
CHASSIS NO : JF1VAGK85HG017101
MILEAGE : 1 KM
DATE IN : 11/09/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 11/06/2017

Print Date : 14/09/2017
Print Time : 12:44:21

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFE977J

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	22/001	REMOVE/REPLACE FRT RH HEADLAMP ASSY	125.00	✓
2	22/002	CHECK LIGHTINGS AFTER REPAIR	50.00	✓
3	22/003	REPAIR/REPLACE FRT BUMPER, FRT PANEL	1120.00	2800 ✓
4	22/004	REPRAY FRT BUMPER, FRT PANEL	840.00	4200 ✓
TOTAL LABOUR CHARGES			2135.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFE977J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
		NETT	LIST	S/NETT		
1 BUMPER PUNCHING FSDN	57702VA020	540.00	X			
2 BRKT CORNER F RH	57707VA000	32.40	X			
3 BRKT CORNER F LH	57707VA010	32.40	X			
4 BRKT SD F RH	57707VA020	7.20	X			
5 BRKT SD F LH	57707VA030	7.20	X			
6 LAMP ASSY HEAD RLB	84002VA001	2160.00				
SUB TOTAL		2779.20	0.00	0.00		0.00
LESS DISCOUNT (NETT-20 %)		555.84	0.00	0.00		0.00
GRAND TOTAL		2223.36	0.00	0.00		0.00
OVERALL TOTAL		2223.36				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFE977J

TOTAL LABOUR CHARGES	2135.00
TOTAL SPARE PARTS CHARGES	2223.36
GRAND TOTAL	4358.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Not Withheld
I.B.1
Penang After Repair
2 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

Kr

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFE977J

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	REMOVE/REPLACE FRT RH HEADLAMP ASSY	125.00	.00
2 ZZ/002	CHECK LIGHTINGS AFTER REPAIR	50.00	50.00
3 ZZ/003	REPAIR/REPLACE FRT BUMPER, FRT PANEL	1120.00	280.00
4 ZZ/004	REPRAY FRT BUMPER, FRT PANEL	840.00	420.00
TOTAL LABOUR CHARGES		2135.00	750.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFE977J

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 BUMPER PUNCHING FSDN	57702VA020	540.00			X
2 BRKT CORNER F RH	57707VA000	32.40			X
3 BRKT CORNER F LH	57707VA010	32.40			X
4 BRKT SD F RH	57707VA020	7.20			X
5 BRKT SD F LH	57707VA030	7.20			X
6 LAMP ASSY HEAD RLB	84002VA001	2160.00			OK
SUB TOTAL		2160.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		432.00	0.00	0.00	0.00
GRAND TOTAL		1728.00	0.00	0.00	0.00
OVERALL TOTAL		1728.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SFE977J

NETT ITEM 2160.00
LESS 20 % -432.00
NETT AMOUNT 1728.00

LIST ITEM 0.00
LESS 50 % 0.00
LIST AMOUNT 0.00

SPECIAL NETT AMOUNT 0.00

S/LIST ITEM 0.00
LESS 30 % 0.00
S/LIST AMOUNT 0.00

TOTAL LABOUR CHARGES 750.00
TOTAL SPARE PARTS CHARGES 1728.00

TOTAL CHARGES 2478.00
ADD 7 % GST 173.46

GRAND TOTAL 2651.46



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17019803/Krbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 21-08-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 8032X	Veh. Inspected	SFE 977J	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1701640	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	16/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU IMPREZA WRX (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1VAGK85HG017101	Colour	METALLIC BLUE	
Odometer	13227	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	DUNLOP	8 mm	
L/H Front Tyre	245/40 R18	DUNLOP	8 mm	
R/H Rear Tyre	245/40 R18	DUNLOP	8 mm	
L/H Rear Tyre	245/40 R18	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/06/2017	Inspection Date	16/10/2017	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFE 977J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LAMP ASSY HEAD RLB (N)	CUT	2,160.00	2,160.00
1	BUMPER PUNCHING FSDN (N)	TO REPAIR SEE LABOUR	540.00	-
1	BRKT CORNER F RH (N)	SERVICEABLE	32.40	-
1	BRKT CORNER F LH (N)	SERVICEABLE	32.40	-
1	BRKT SD F RH (N)	SERVICEABLE	7.20	-
1	BRKT SD F LH (N)	SERVICEABLE	7.20	-
	LESS 20% DISCOUNT		-555.84	-432.00
			2,223.36	1,728.00
LABOUR				
	REPAIR/REPLACE FRT BUMPER, FRT PANEL INCLUSIVE OF THE REPAIR OF BUMPER PUNCHING FSDN. }		1,120.00	280.00
	REMOVE/REPLACE FRT RH HEADLAMP ASSY. }		125.00	-
	RESPRAY FRT BUMPER, FRT PANEL.		840.00	420.00
	CHECK LIGHTING AFTER REPAIR.		50.00	50.00
			2,135.00	750.00
GRAND TOTAL			4,358.36	2,478.00
RECOMMENDED COST OF REPAIRS				2,478.00

Report Ref No. CS/EG117019803/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.