

22/03/2002

ASS. REC. BY:

REF:

CS/AXA/7019814/Rltb22

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Yume Ang

of

AXA

Date/Time:

16-10-2017 9:41am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKX 9661B

Insured:

at Workshop m/s

Mova Automotile

Tel:

6272 3892

of

Blt 1008 Bukit Merah Lane 3 # 01-04

Policy No:

Claim No:

S7M002W5

Sum Insured:

Excess:

\$ 400.00

Make of Veh:

D.O.A.

11-10-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

19.10.2017 @ after 10am

H.O.D. Endorsement:

Date/Time:

16-10-2017

10:14am

Person Contacted:

Eva

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKX 9661B - x
20/10-	Revert via menmen
	Part by part \$4115/- (Red. 475 : 10%)
	Parts + labour in the
	Supplier invoice attached.

16/10/18.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CS/AXA17019814/R1tb

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 16-10-2017



Code : AXA2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKX 9661B
Policy No.	Coverage (\$)	0.00
Claim No. S7M002W5	Excess (\$)	400.00
Assign From SMART CLAIM (YVONNE ANG)	Assign Date	16/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/10/2017	Inspection Date
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722	

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

57M002W5
CR129697

« Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
General Details				Workshop Details			
Involving	1 2015 TOYOTA HARRIER 2.0 (SKX9661B)			Total Rebate Amount	0		
Date of Loss	11 October 2017			Nett Loss Amount	\$0.00		
Time of Loss	21.45			Assigned Workshop	MOVA AUTOMOTIVE PTE LTD		
Loss Description	REFER TO SKETCH PLAN			Vendor	-- Choose Assessment Vendor --		
Comment				Target Date of Completion	18/10/2017		
				Days of work completion	5		

Enquire Transfer Fee

Vehicle Details

Vehicle No. : SKX9661B
Vehicle Type : P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1 : With Sun Roof
Vehicle Scheme : Normal
Vehicle Make : TOYOTA
Vehicle Model : HARRIER 2.0 PREMIUM AT AIRBAG 2WD
Chassis No. : ZSU600065078
Propellant : Petrol
Engine No. : 3ZRB682340
Engine Capacity : 1986 cc
Maximum Power Output : 111.0 kW (148 bhp)
Maximum Laden Weight : 1885 kg
Unladen Weight : 1610 kg
Year Of Manufacture : 2015
Original Registration Date : 04 Jan 2016
Lifespan Expiry Date : -
COE Category : B - Car above 1600cc or 97kW (130bhp)
Quota Premium : \$60,001.00
COE Expiry Date : 03 Jan 2026
Road Tax Expiry Date : 03 Jan 2019
PARF Eligibility Expiry Date : 03 Jan 2026
Inspection Due Date : 03 Jan 2019
Intended Transfer Date : 25 Apr 2018
CO2 Emission : 133.00 (g/km)
CEV/VES Rebate Utilised Amount : \$5,000.00

CO Emission : -
HC Emission : -
NOx Emission : -
PM Emission : -
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.
Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/10/2017 15:51
Date Of Accident	11/10/2017 21:45
Exact Location Of Accident	JUNCTION OF DUNEARN RD & HILLCREST RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX9661B
Insured/Policyholder	
Name Of Registered Owner	TEO CHIANG KEI ANDREW
NRIC No	S7520130C
Email Address	ANDREW_CK@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98633430
Alternative Phone No	OFFICE-98633430
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARRIER-2.0 PREMIUM SUNROOF (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA084310
Cover Note Number	
Driver	
Name of Driver	TEO CHIANG KEI ANDREW
NRIC No	S7520130C
Date Of Birth	11/07/1975
Occupation	INDOOR
Date Of Driving Pass	30/12/1996
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98633430
Fax Number	
Contact Number	OFFICE-98633430
Email Address	ANDREW_CK@HOTMAIL.COM

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EP8383Z
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident ACCIDENT DATE: 11 Oct 2017 ACCIDENT TIME: 9:45 pm LOCATION: Junction of Dunearn Rd and Hillcrest Rd Turning onto Dunearn Rd from Hillcrest Rd. Hit rear bumper of EP8383Z. Driver is not the car owner. Car EP8383Z is under NTUC insurance. dy Driver tel: 94754883. (Name: Lee) Car owner tel: 96922220 (Name: Elvin)	LICENSE PLATE NUMBER: SKX9661B CONTACT NUMBER: 98633430 EMAIL: andrew_ck@hotmail.com
(This area is for additional details or a diagram. The image shows a large empty space with horizontal lines.)	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION.	
Please state: ☒ Claim Own Policy ☐ Claim Third Party ☐ Claim OD/TP at other workshop ☐ Reporting Only	

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel



<< Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
----------------------------	--------------------------	-------------------	---------------	----------------	---------------	---------

Parts

Add

EDIT	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1			AIR CLEANER INLET				85		85	Reviewing	7 DE
	1			FRONT BUMPER				580		580	Reviewing	DE
	1			FRONT BUMPER BEAM LH				60		60	Reviewing	pt
	1			FRONT BUMPER BEAM SPONGE LH				35		35	Reviewing	7 CPA
	10			FRONT BUMPER CLIPS				2.5		25	Reviewing	ne

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC OUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1			FRONT BUMPER RETAINER LH				55		55	Reviewing	<i>new</i>
	2			FRONT BUMPER SIDE HOLDER				15		30	Reviewing	<i>new</i>
	2			FRONT BUMPER SIDE HOLDER CLIPS				5		10	Reviewing	<i>new</i>
	1			FRONT BUMPER SPONGE				60		60	Reviewing	<i>2X new</i>
	10			FRONT FENDER COWLING CLIPS				2.5		25	Reviewing	<i>new</i>
	1			FRONT FENDER COWLING LH				180		180	Reviewing	<i>cut</i>
	1			FRONT FENDER INNER PANEL LH- REPAIR						0	Reviewing	<i>R</i>
	1			FRONT FENDER LH				360		360	Reviewing	<i>Blue</i>

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC OUNT%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1			FRONT FOG LAMP COVER LH				60		60	Reviewing <i>X sue</i>	<i>sue</i>
	1			FRONT FOG LAMP LH				130		130	Reviewing <i>? car</i>	<i>? car</i>
	1			FRONT GRILLE ASSY				250		250	Reviewing <i>? car</i>	<i>? car</i>
	1			FRONT HEADLAMP ASSY LH				1200		1200	Reviewing <i>sue</i>	<i>sue</i>
	1			FRONT HEADLAMP PANEL LH				95		95	Reviewing <i>SK R</i>	<i>SK R</i>
	10			FRONT PANEL TOP GARNISH CLIPS				2.5		25	Reviewing <i>new</i>	<i>new</i>
	1			RESONATOR				85		85	Reviewing <i>DE ? car</i>	<i>DE ? car</i>

Labour

Add

EDIT	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	REPAIR/REPLACE (LABOUR)	ACTION (LABOUR)	COMMENT	REMOVE
	TO INSPECT FRONT LIGHTING AND WATER LEAKAGE TEST		40			Reviewing		<i>30</i>

EDIT	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	REPAIR/REPLACE (LABOUR)	ACTION (LABOUR)	COMMENT	REMOVE
	TO REPAIR FRONT FENDER INNER PANEL LH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS		600	500		Reviewing		
	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS		600	450		Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS

« Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$4,590.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$3,350.00	\$3,350.00
Labour	\$640.00	\$640.00
Paint	\$600.00	\$600.00

Submit for Review

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resu
Hp 90010068

5 days

P/R

19/10/17 @ 1130

EXCESS: 400

Authorized

Resurvey by paint

SERVICE REQUESTS

MESSAGES

CLAIMS

Attn: Ah Khen

57M002W5

CK129697

 Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2015 TOYOTA HARRIER 2.0 (SKX9661B)

Date of Loss 11 October 2017

Time of Loss 21.45

Loss Description REFER TO SKETCH PLAN

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

MOVA AUTOMOTIVE PTE LTD

Vendor

-- Choose Assessment Vendor -- ▾

Target Date of
Completion *

18/10/2017

Days of work
completion *

5



Service Requests Messages Claims

Attn: Ah Kuen

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add

EDIT	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISCOUNT%	PART PRICE/NET	ACTION (PARTS)	REMOVE
☐	1			AIR CLEANER INLET				85		85	Reviewing	☐
☐	1			FRONT BUMPER				580		580	Reviewing	☒
☐	1			FRONT BUMPER BEAM LH				60		60	Reviewing	☒
☐	1			FRONT BUMPER BEAM SPONGE LH				35		35	Reviewing	☒
☐	10			FRONT BUMPER CLIPS				2.5		25	Reviewing	☒

EDIT	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNTS	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐	1			FRONT BUMPER RETAINER LH				55		55	Reviewing	☐ New
☐	2			FRONT BUMPER SIDE HOLDER				15		30	Reviewing	☐ New
☐	2			FRONT BUMPER SIDE HOLDER CLIPS				5		10	Reviewing	☐ New
☐	1			FRONT BUMPER SPONGE				60		60	Reviewing	☐ New
☐	10			FRONT FENDER COWLING CLIPS				2.5		25	Reviewing	☐ New
☐	1			FRONT FENDER COWLING LH				180		180	Reviewing	☐ cut
☐	1			FRONT FENDER INNER PANEL LH- REPAIR						0	Reviewing	☐ R
☐	1			FRONT FENDER LH				360		360	Reviewing	☐ New

AKA

English (SG) MOVA AUTOMOTIVE PTE LTD

SERVICE REQUESTS MESSAGES CLAIMS

Att: Ah Ewn

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add

EDIT	QUAN TITY	MATERIAL	SIZE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC COUNTX	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐	✓ 1			AIR CLEANER INLET				85		85	Reviewing	☐ ?
☐	✓ 1			FRONT BUMPER				580		580	Reviewing	☐ X-
☐	✓ 1			FRONT BUMPER BEAM LH				60		60	Reviewing	☐ P41
☐	✓ 1			FRONT BUMPER BEAM SPONGE LH				35		35	Reviewing	☐ ?
☐	✓ 10			FRONT BUMPER CLIPS				25		25	Reviewing	☐ na/

Attu: Ah Kren

EDIT	QUAN TTY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUANTITY	PART PRICE(NET)	ACTION (PARTS)	REMOVE
☐	✓ 1			FRONT BUMPER RETAINER LH				55		55	Reviewing	☐ <i>Ne/</i>
☐	✓ 2			FRONT BUMPER SIDE HOLDER				15		30	Reviewing	☐ <i>Ne/</i>
☐	✓ 2			FRONT BUMPER SIDE HOLDER CLIPS				5		10	Reviewing	☐ <i>Ne/</i>
☐	✓ 1			FRONT BUMPER SPONGE				60		60	Reviewing	☐ <i>Ne/</i>
☐	✓ 10			FRONT FENDER COWLING CLIPS				25		25	Reviewing	☐ <i>Ne/</i>
☐	✓ 1			FRONT FENDER COWLING LH				180		180	Reviewing	☐ <i>cut/</i>
☐	✓ 1			FRONT FENDER INNER PANEL LH- REPAIR					0		Reviewing	☐ <i>R</i>
☐	✓ 1			FRONT FENDERLH				360		360	Reviewing	☐ <i>Ne/</i>

Attn: Ak Khan

EDIT	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DISC QUANTITY	PART PRICE (NET)	ACTION (PARTS)	REMOVE
☐	1			FRONT FOG LAMP LH				60		60	Reviewing	☐ See
☐	1			FRONT FOG LAMP LH				130		130	Reviewing	☐ ?
☐	1			FRONT GRILLE ASSY				250		250	Reviewing	☐ ?
☐	1			FRONT HEADLAMP ASSY LH				1200		1200	Reviewing	☐ See
☐	1			FRONT HEADLAMP PANEL LH				95		95	Reviewing	☐ OK
☐	10			FRONT PANEL TOP GARNISH CLIPS				2.5		25	Reviewing	☐ no
☐	1			RESONATOR				85		85	Reviewing	☐ ?
☐	1			TO INSPECT FRONT LIGHTING AND WATER LEAKAGE TEST				40		36	Reviewing	☐ 36

Add

Attn: An Ewen

EDIT	PART NAME	LABOUR PER	LABOUR REPAIR	PAINT	REPAIR/REPLACE (LABOUR)	ACTION (LABOUR)	COMMENT	REMOVE
☐	TO REPAIR FRONT FENDER INNER PANEL LH. TO REMOVE AND REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS		600	500		Reviewing		
☐	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS		600	450		Reviewing		

Attn: Ah Khan

SERVICE REQUESTS

MESSAGES

CLAIMS

Assessment Details

General & Workshop Details			
Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour
Miscellaneous	Summary		
Claim Amount	ESTIMATE	REVISED AMOUNT	
\$4,590.00			
Spare Parts	\$3,350.00	\$3,350.00	
Labour	\$640.00	\$640.00	
Paint	\$600.00	\$600.00	

Submit for Review

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Parts : \$3135.00
 Labour : \$980.00
 Total : \$4115.00 *

2454
 HP 90010068
 S clasp
 P/P
 19/10/17 @ 1130
 excess : 400
 Authorised
 Resurvey by paint



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: MOVA AUTOMOTIVE PTE LTD

BLK 1008 #01-04

BUKIT MERAH LANE 3

SINGAPORE 159722

SKX9661B

JIA YU

NO: DLI9194796

PAGE: 1

DATE: 19/10/2017

A/C CODE: LDMV315

TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	T81070-48890 HEADLAMP UNIT LH	DB2CC2	1	1,200.00	1,200.00
2	T53101-48721 GRILLE	DB1K9	1	250.00	250.00
3	T52119-48C60-C0 BUMPER FR	DB2G	1	580.00	580.00
4	T52538-48020 FR SIDE RET LH	DU1D53	1	60.00	60.00
5	T52612-48030 FR BUMPER ABS LH	DU1AB30-1	1	35.00	35.00
6	T52536-48030 FR RET LH	DBS	1	55.00	55.00
7	T53879-30050 FENDER LINER RET X 4	DD1AS3-8	2	15.00	30.00
8	T47749-50090 CLIP	DD1A209	2	5.00	10.00
9	T81220-48050 FOGLAMP ASSY LH	DBAA9	1	130.00	130.00
10	T52161-16010 CLIP,FR BUMPER	DU1AD11-3	10	2.50	25.00
11	T53812-48190 FR FENDER LH	DB1D24	1	360.00	360.00
12	T53876-48120 FENDER LINER FR LH	QBEE21	1	180.00	180.00
13	T90467-07201 CLIP,COWLING	DD1AS3-6	10	2.50	25.00
14	T90467-07217 CLIP,SUPPORT TOP GARNISH	DST1606	10	2.50	25.00
TOTAL QUANTITY:			43	TOTAL	SIN 2,965.00
				ADD GST @ 7%	207.55
				GRAND TOTAL	<u>SIN 3,172.55</u>


15 FAN YOONG RD

Print / MT / 19/10/2017 4:54:22 PM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



E&OE
PARTS

GOODS RECEIVED BY

Shwartzel1017

14201

Volkswagen



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: MOVA AUTOMOTIVE PTE LTD


BLK 1008 #01-04
BUKIT MERAH LANE 3
SINGAPORE 159722
SKX9661B
JIA YU

NO: DLI9194859
PAGE: 1
DATE: 21/10/2017
A/C CODE: LDMV315
TERMS: CR

H7

Part No	Description	Location	Qty	Unit Price	Amount
1	T17894-37020	AIR RESONATOR	1	85.00	85.00
2	T17751-37130	A/C INLET	1	85.00	85.00
TOTAL QUANTITY:			2	TOTAL	SIN 170.00
				ADD GST @ 7%	11.90
				GRAND TOTAL	<u>SIN 181.90</u>

15 FAN YOONG




Print / MT / 21/10/2017 9:04:45 AM

SALESMAN: MT


This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



GOODS RECEIVED BY

Simon 21/10/17



Volkswagen