

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ernest Tay

Date: 07 Dec 2017

Preliminary Advice

Insured Vehicle No	: XE132S		
TP Vehicle No	: GBE9280Z	Accident Date	: 12/10/2017
Make	: TOYOTA DYNA 1.5T	Assignment Date	: 16/10/2017
Date of Inspection	: 24/10/2017	Est. Duration of Repair	: 3 days
Inspection At	: William's Auto Pte Ltd (HQ) BLK 3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE Singapore 677965		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesfront O/S... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,574.50
Revised Amount	:S\$	4,062.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,062.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.