

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department

Estimate No: EST1700793

Date: 12 Oct 2017

Policy No: 5079746245-01

Veh Reg No: GBE9280Z

Make/Model: TOYOTA DYNA 3.0
DIESEL TURBO M/T
2WD

Chassis No: KDY2318024140

Engine No: 1KD2601976

Reg. Date: 26/04/2016

Your Ref No: GBE9280Z

Claim Type: Third Party

Accident Date: 12/10/2017

TP Veh Reg No: XE132S

Estimate Repair Cost to Vehicle No : GBE9280Z

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Special Net				
1 FRONT DOOR PANEL ADDRESS STICKER - RH		1 PC	25.00	25.00
2 BODY LETTERING AND LOGO		1 SET	180.00	180.00
				205.00
List Price				
3 FRONT DOOR - RH		1 PC	985.20	985.20
4 FRONT DOORS SIGNA LAMP - RH		1 PC	145.30	145.30
5 FRONT DOOR SIGNAL HARNESS - RH		1 PC	179.20	179.20
6 FRONR DOOR SIDE MIRROR ASSY - RH		1 PC	384.70	384.70
7 FRONT DOOR HINGE - RH		2 PCS	83.10	166.20
8 FRONT DOOR LOCK - RH		1 PC	257.30	257.30
9 FRONT DOOR GLASS REGULATOR - RH		1 PC	289.70	289.70
10 FRONT HEADLAMP - RH (P I)		1 PC	1,589.50	1,589.50
11 FRONT DOOR LOWER STEP GARNISH - RH		1 PC	232.40	232.40
				4,229.50
Labour				
12 LABOUR TO REMOVE NECESSARY DAMAGED PARTS ENABLE TO STRAIGHTEN PANEL, PANEL BEAT & REPAIR AFFECTED PILLAR, PANEL TO THE SAME.		1 JOB	450.00	450.00
13 TO SPRAY PAINT ON REPLACEMENT PARTS AND AFFECTED AREAS.		1 JOB	500.00	500.00
14 LABOUR TO TRANSFER FRONT DAMAGED DOOR-RH ATTCHMENTS TO NEW DOOR.		1 JOB	80.00	80.00
15 WIRING JOB		1 JOB	30.00	30.00
16 LABOUR TO APPLY/SPRAY ANTI RUST PROOFING WHERE IS NECESSARY.		1 JOB	80.00	80.00
				1,140.00

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: waplsp21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01

AXA TOWER

SINGAPORE 068811

TEL: 63387288

FAX: 68804838,68804572

ATTN: Motor Claim Department

Estimate No: **EST1700793**

Date: 12 Oct 2017

Policy No: 5079746245-01

Veh Reg No: **GBE9280Z**

Make/Model: TOYOTA DYNA 3.0
DIESEL TURBO M/T
2WD

Chassis No: KDY2318024140

Engine No: 1KD2601976

Reg. Date: 26/04/2016

Your Ref No: GBE9280Z

Claim Type: Third Party

Accident Date: 12/10/2017

TP Veh Reg No: XE132S

Estimate Repair Cost to Vehicle No : GBE9280Z

Total	S\$ 5,574.50
Add GST @ 7%	390.22
Total Amount payable	S\$ 5,964.72

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED SIXTY FOUR AND CENTS SEVENTY TWO ONLY

For WILLIAM'S AUTO PTE LTD



AUTHORISED SIGNATURE

Tanpin 97445249
3 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: