Reference No.: NS INGIAO 19875 STD
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

1) Offic	ce Assign Form	Y-Date	N-Date	Y-Date	N-Date
С	Reference No.	V			
С	Customer Code				
N	Assign From				
С	Assign Date	~			
С	Veh No (Inspected)	V			
C	Veh No (Insured)	~			
С	D.O.A	V			Casemer .
С	Policy No	~			
С	Claim No	~			S
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	~			
С	Weekend Charges		-11/2-2		
Ν	Survey held at/Repairer	V			
C	Excess				
С	Vehicle No	~			
С	Regn Month/Year	~			
N	Vehicle Type	~			
N	Make & Model	~			
С	Engine Capacity. (C.C)	~			
N	Colour	~			
С	Odometer. (Sp.Reading)	~			
С	Chassis No	~			
N	General Condition	/			
N	Steering	~			
N	Brake	~			
N	Modification (Modi)				
С	Tyre Size	1			
N	Tyre Make				
С	Tyre Balance	~			
С	Date of Inspection	7			
N	Survey held			-	
N	Des.of Dama _l ges				
2) Syste	em - (Views/Merimen)				
C	Damaged Vehicle Photographs Uploaded	~			17 - 17 - 23
3) Wor	kshop Estimate/Assignment Form				
N	ALL Parts condition	1			
С	Market Value for OD cases				
С	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
С	Days of repair	~			
	Finalised Amount	/			
C	The state of the s				-
C	Re-inspection Cases to Finalize within 5 Days		10	1	
С	Re-inspection Cases to Finalize within 5 Days em - (Views/Merimen)				

Case Handler

Date



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTU	C INCOME INSUR	ANCE CO-OPERATIVE LTD	Ref:	NS/INC1701987	75/Srb
73 B #05-		O JNION HOUSESINGAPORE	Date:	16-10-2017	
			Code:	INC4	
1.		Policy Particulars	:- THIR	D PARTY CLAIM	
	Insured Veh.	SLH 7836A	Veh. I	nspected	SHF 377L
	Policy No.	5086367601	Cover	rage (\$)	0.00
	Claim No.		Exces	ss (\$)	0.00
	Assign From		Assig	n Date	16/10/2017
2.		Vehicle Parti	culars 8	& Condition	
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year	of Reg.	
	Chassis No.		Colou	ır	
	Odometer	5	Steer	ing	
	Brakes			ication	
	General				
3.		Condit	ions of	Tyres	
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.		Descript	ion of D	amages	
5.		Gener	al Inform	nation	
	Accident Date	13/10/2017	Inspe	ction Date	16/10/2017
	Survey held at	SMRT AUTOMOTIVE SERVIC	ES PTE I	LTD	
		60 WOODLANDS INDUSTRIA	L PARK E	E4 SINGAPORE 75	7705
5a.	Marie Ma		Remarks	3	
	A)THE INSPECTION	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS, V	ITHOUT WE HAVI	PREJUDICE" BASIS E NOT AUTHORISE	S. ED REPAIRS.

TP Claims against NTUC Income: Follow-Through Survey

ON/	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D.O.A	Estimate	Tentative repair cost
1	MT/0958426-002	SMRT BUSES LTD	SMB 1474U	SIQ 52348	20/8/2017	\$6,133.90	\$1,700.00
2	MT/0958554-002	SMRT TAXIS PTE LTD	SHB 167Y	SJR 8588E	21/8/2017	\$2,933.00	\$900.00
3	MT/0962276-001	SMRT BUSES LTD	SMB 5037Y	FT 9907Z	3/10/2016	\$1,588.00	\$1,241.00
4	MT/0909389-002	SMRT BUSES LTD	SMB 3164B	SGS 4739T	26/7/2016	\$1,068.00	\$615.00
2	MT/0967270-002	SMRT TAXIS PTE LTD	SHD 6454T	SKW 7041J	27/10/2017	\$9,846.94	\$2,350.00
9	MT/0966048-002	SMRT TAXIS PTE LTD	SHC 4634J	SLP 32332	17/10/2017	\$10,707.70	\$1,600.00
7	MT/0965873-002	SMRT TAXIS PTE LTD	SHF 377L	SLH 7836A	13/10/2017	\$10,301,23	\$2,600.00

Claim received from LKK Auto

eBaoTech	eBaoTech								Gener	ralClaim
Hello, NAC_PAYA_UBI_80	0601						Change La	nguage '	Change Passwore	d · Log Out
My Desktop	Polic	y Query								×
Notice of Loss	Policy N	io.				Date of Acc	ident	13/10/	2017 18:54	
	Vehicle	No.(For Motor)	SLH7836A							
						Search				
	Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5086367601	ULTRA SPEED ENTERPRISES	53051105C	GPC	drivo CLASSIC	5LH7836A	SLH7836A	21/11/2016	25/03/2018
						Continue				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCID	ENIT	COT A	4-17	NEW T
ACCID	-141	OIA	- 1	

13/10/2017 16:45 Date Of Report 13/10/2017 11:05 Date Of Accident

PARKWAY PARADE LOBBY TAXI STAND Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SHF377L Vehicle Registration Number

Insured/Policyholder

SMRT TAXIS PTE LTD Name Of Registered Owner

198905369K Co Reg No NOEMAIL Email Address

Mobile Phone No.

OFFICE-80000000 Alternative Phone No

Vehicle Particulars

CHEVROLET Manufacturer EPICA-2.0 (A) Model

Exact Purpose for which vehicle was being used at HIRE AND REWARD

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY If No, Please state action to be taken

TAXI Vehicle Category

Insurance Company

FIRST CAPITAL INSURANCE LTD Name of Insurance Company THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

NO

YES Fleet Policy

D-17087562MFSH Policy Number

Cover Note Number

Date Of Driving Pass

Driver

YEO YOKE JOO Name of Driver S0190310A NRIC No 24/06/1954 Date Of Birth OUTDOOR Occupation 25/09/1974

43 YEARS AND 0 MONTHS Driving Experience

MALE

Mobile Number Fax Number

Contact Number

NOEMAIL **EMail Address**

Page 1 of 13

· · · co: supplementA

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - RELIEF

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BOON TECK NEIGHBOURHOOD POLICE POST

ROAD: BLK 207 TOA PAYOH NORTH , POSTCODE: 310207 , COUNTRY:

SINGAPORE

Police Station Address Police Station Contact

TEL NO: 1800-2549999 - FAX NO: 63554310

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20171013/2099 On the 13/10/2017 at about 11.05am, while I was driving my taxi (SHF377L) at the Parkway Parade main lobby area to alight a female passenger at the taxi stand which was in front. Out of a sudden, I felt an impact from the left, causing me to swerve right and mount onto the curb, I then made a check and realized that a vehicle (Male Chinese) came out of the vehicle and took photos of the accident site. He then left without exchanging particulars. I have a built in car camera in the taxi which recorded the whole incident. I did not managed to take the particulars of my passenger as he left after paying the taxi fare. I went to seek medical treatment at Mount Alvernia Hospital and was given 7 days of medical leave. I then proceeded to lodge a traffic Accident report with regards to the accident.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE TOO LARGE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SI H7836A

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Page 2 of 13

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

YEO YOKE JOO

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHF377L

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Driver's Signature (If driver is not the policyholder) / Date Witnessed by Reporting Centre Personnel

Sketch Plan

A - SHF 377L

B - SCH 7 836A

ROPER	10	POUCE	REPORT	- y/2017-1013/	2-99	
	The second					
				100		
til				The second second		
OTHER PROPERTY.				and the Water East		
				-15 - W 35 - 50 - 10 - 1		
			C411-1-12-1-12-13-13-13-13-13-13-13-13-13-13-13-13-13-	The second second		
				The state of the s		
				SIBM XI - I I I		
		-114				
	_					
	-					
11-						
1000						
				The state of the s		
				The state of the s		
		110000000000000000000000000000000000000				
laration						
TE	and a state	and the days	tre true in every re	enact		
declate lue t	oteđaruč	particulars a	ire true in every re	apost.		
1						
1.1				/		\$5 MG
5				1		1 2/0/2
3				d		de 13/10/2
				K.		W
				1		
					The second second	
yholder's Sig	nature /	Date &	Driver's Signature	(F driver is not the policyholder	r) / Date Witnes	sed by Reporting Centre

Page 5 of 13





Police Station Of Origin:

Boon Teck NPP

207 Toa Payoh North #01-1231 SINGAPORE 310207

Tel No: 1800-2549999

1 of 3 Report No. T/20171013/2099

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/10/2017 15:25 Station Diary No.: Vide Report No.:

13/10/20	117 15:25			14		
Informa	nt's Particu	ulars	na a combina a a man	5. 在一个社会理解等逐步等等		
	Informant: KE JOO		Address:	REET 21 #06-235 SINGAPORE		
	/ ID No.: D / S01903	10A	Contact No.: Home/Office:	Mobile: 90294374		
National SINGAP	ity: ORE CITIZ	EN	Email:			
Sex: Male	Age: 63	Date of Birth: 24/06/1954	Type of Informant: Driver			
Race: Chinese			Language: Institution / School Name English			
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3,4,5	Date of Expiry:		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/10/2017 11:05	Type of Location Straight Road	
Location: Along Road 1 MARINE PAR before Parkwa	ADE ROAD ay Parade lobby ta)		it.	ENT S	
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light	
Type of Collis Between Mov		Swipe - Same Direction		Anyone conveyed by ambulance:	

Vehicle No.	Type	Make	Model - *	Color	Condition	No of Passenger
SHF377L	Car	CHEVROLET	EPICA 2.0DSL AT ABS D/AB 2WD 4DR	Maroon	Slightly Damaged	1
SLH7836A	Car	TOYOTA	COROLLA ALTIS 1.6 AUTO	Beige	Slightly Damaged	1

Sketch Plan Pg. 4





Police Station Of Origin: Boon Teck NPP 207 Toa Payoh North #01-1231 SINGAPORE

2 of 3 Report No. T/20171013/2099

310207

CONTINUATION OF REPORT

Tel No: 1800-2549999

Any Pedestrian Ir		and the second		eo.co.o.o.	and week	
No. of Pedestrian	s Injured: NIL		Use of Pe	destriar	Cross	ing: NA
Driver * ****	本等各种专用等	194 M HE 1962	de aprocess and appropriate		EL PHONE	The second second second
Name	YEO YOKE JOO			ID No	20 1	S0190310A
Related Vehicle	SHF377L (Car)			Conta	ct No.	90294374
Hospital/Clinic	MOUNT ALVERNIA	MOUNT ALVERNIA HOSPITAL		Class Drivin Licend Expin	g	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	13/10/2017	ver a la company	Date Disc	-	_	/2017
No. of Days gran	No. of Days granted Medical Leave 07			of Injury Slight		

Brief Details.

On the 13/10/2017 at about 11.05am, while I was driving my taxi (SHF377L) at the Parkway Parade main lobby area to alight a female passenger at the taxi stand which was in front. Out of a sudden, I felt and impact from the left, causing me to swerve right and mount onto the curb. I then made a check and realized that a vehicle (SLH7836A) hit the left side of my taxi. I went out of the taxi to check. The driver of the other vehicle (Male Chinese) came out of the vehicle and took photos of the accident site. He then left without exchanging particulars.

I have a built in car camera in the taxi which recorded the whole incident. I did not managed to take the particulars of my passenger as she left after paying the taxi fare. I went to seek medical treatment at Mount Alvernia Hospital and was given 7 days of medical leave. I then proceeded to lodge a Traffic Accident report with regards to the accident.





Police Station Of Origin: Boon Teck NPP 207 Toa Payoh North #01-1231 SINGAPORE 310207 CONTINUATION OF REPORT Tel No: 1800-2549999

Report No. T/20171013/2099

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E/ Staff Sgt MUHAMMAD ZAKIRUL ALIM BIN MUHIDDIN

Signature Of Interpreter: Not applicable

Officer In Charge Of Case: TP / AEIT / SSI KASMAWATI BTE SAMIAN Contact No.: 65476179

Authentication Stamp

NP168

Singapore Police Force

Signature Of Informant:

Date/Time: 13/10/2017 15:25

Classification Of Case:

Page 8 of 13

Enquire Transfer Fee

Vehicle No.	SHF377L
Navent Checker Charles	
Vehicle Type	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1	Air-Con (Taxi)
Vehicle Scheme	Taxi (Company)
Vehicle Make	CHEVROLET
Vehicle Model	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Chassis No.	KL1LA69RJBB134193
Propellant	Diesel
Engine No.	Z20S1463223K
Engine Capacity	1991 cc
Maximum Power Output	110.0 kW (147 bhp)
Maximum Laden Weight	2055 kg
Unladen Weight	1625 kg
Year Of Manufacture	2012
Original Registration Date	18 Dec 2012
Lifespan Expiry Date	17 Dec 2020
COE Category	A - Car (1600cc & below)
Quota Premium	\$47,537.00
COE Expiry Date	17 Dec 2020
Road Tax Expiry Date	17 Dec 2017
PARF Eligibility Expiry Date	17 Dec 2020
Inspection Due Date	17 Jun 2018
Intended Transfer Date	23 Nov 2017
CO2 Emission	28

The current road tax expiry is 17 Dec 2017. You may renew the road tax from 18 Sep 2017 with all prerequisite(s) fulfilled. If the road tax is renewed after 17 Dec 2017, late renewal fee(s) will be imposed. Please use <u>Enquire Road Tax Payable</u> to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 18 Dec 2017 to 17 Jun 2018)

	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee	11.00	**	11.00

4	Sub Total			11.00
	Nett Road Tax Amount (After Offsetting Over Payment)	1,930.00	120	1,930.00
	Total Amount Payable			1,941.00
	Message			

Message

This vehicle has a road tax Over Payment of \$705.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK Print



60 Woodlands Industrial Park E4, Singapore 757705.

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Niye

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHF377L

Ref. No

TAX/10/17/2080

Reg. Date

18/12/2012

Vehicle Type

TAXI

Make

CHEVROLET EPICA 2.0 VCDI

Model

EPICA-2.0

Name of Driver

YEO YOKE JOO

Type of Accident

SIDE SWIPE

Date / Time of Accident

13/10/2017 11:05:00 AM

Accident Reported Date / Time :

13/10/2017 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024092538

Special Instruction to ARC, if any :

SLH7836A

Prepared Date

: 13/10/2017 05:47:09 PM

Sebastian. 16/10/2017.

- Lup Sun Repair.
-Question Mark Jeun Photo.
- Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Section B - To be Completed by Service Advisor, Accident Repair Centre Chassis No: KL1LA69RJBB134193 Mileage Work Shop : Repair Completed Date / Time : Summary of Repair Estimates Quotation from ARC Adjusted by Surveyor, if applicable-0.00 **Total Labout Charges** 845.00 0.00 1,674.00 Total Spray Painting Charges 5,573.18 Total Material Charges 5,573.18 0.00 Other Charges 940.00 0.00 TOTAL 9,032.18 Lum Sum Total 9,050.00 0.00 0.00 5.00 No. of Repair Days 4 days. Prepared / Adjusted By Arc / Surveyor Sing Off Date : 14/10/2017 08:52:42 AM 01/01/1900 12:00:00 AM Prepared / Adjusted Date Remarks Prepared Date : 14/10/2017 08:52:42 AM Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair Quotation No Invoice No Quotation Date Invoice Date : Prepared Date: Invoice Amount :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applica		
TO REPAIR LH PORTION	845.00	0.90 600	-	
Total Labour	845.00	0.00	-	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 >60
TO RESPRAY VIEW MIRROR	180.00	0.00 20
TO RESPRAY ROCKER PANEL MOULDING	180.00 🗡	0.00
TO RESPRAY FRONT FENDER LH	378.00	0.90 200
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 56
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surv	veyor, if applicable
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60	
TO REMOVE AND REFIX WING MIRROR	120.00	0:00 30	
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0:00 30	
TO TRANSFER DOOR MECHANISM	120.00	0.00 🗸	- mande
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 36	
TO REMOVE AND REFIT TYRE	120.00	0.00 %	
TO REPLACE SUNDRY PARTS	100.00	0:00 20	- moneyabi
TO WASH AND VACUUM	60.00	0.00 ×	
Total Other Costs	940.00	0.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d		Photos Attached
96635577 [DOOR	6504596	PANEL LH FRONT DOOR	1	2,020.00	10.00	1,818.00	1,500	Replace R	No
-	DOOR		SMRT LOGO DOOR	1	60.00	0.00	60.00	Replace	Replace/NE	
	DOOR		CHECK FRONT DOOR LH	1	15.50	10.00	13.95	Replace	Replace 0	No.
	DOOR	A C	HINGE UPPER LH	1	75.00	10.00	67.50	Replace	Replace ?	No
	COMMO		HINGE LOWER, LH REAR	1	24.00	10.00	21.60	Replace	Replace 7	No
	COMMO	6505044	MIRROR LH	1	1 844.00	10.00	759.60	Replace	Replace K	refree representa
96634087	LEFT	6504608	MOLDING PANEL LH ROCKER		1 304.00	10.00	273.60	Replace	Replace	No
96636324	FRONT	6504580	PANEL FRT FENDER LH	1	1 606.00	10.00	545.40	Replace	Replace 0	750 300
	СОММО	6503708	TYRE	8.4	1 126.74	0.00	126.74	Replace	Replace	No
	COMMO	6504666	TYRE RIM		1 328.99	0.00	328.99	Replace	Replace	No.
96633939	-	6504582	LINER FENDER FRT LH (PROTECTOR)		1 49.00	10.00	44.10	Replace	Replace	No
93744489	FRONT	6504592	BUMPER FRT ASSY		1 1,238.00	10.00	1,114.20	Replace	Replace /	The Part of the Pa
96633983	-		BRACKET FRT BUMPER SIDE LH		1 9.00	10,00	8.10	Replace	Replace	No
96633984	4 FRONT		BRACKET FRT BUMPER SIDE RH		1 9.00	10.00	8.10	Replace	Replace 1	-en variations
96437321	1 FRONT	6504615	BEZEL FOG LAMP LH (COVER)		1 32.00	10.00	28.80	Replace	Replace	No
96644865	5 FRONT	6504617	LAMP FOG FRT LH		1 260.00	10.00	234.00	Replace	Replace 2	The Contract of the Contract o
	7 FRONT	_	LAMP HEAD LH		1 841.00	10.00	756.90	Replace	Replace	and another time
			TOTAL MATERIALS		- 1			6,209.5	58 6,209.58	
-		TOT	AL MATERIALS(Discou	inted	Λ			5,573.1	18 5,573.18	-

Added Spare Parts / Material Usage After Surveyor Signed off

Part	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
Number	TOTA	L SUPPLEMENTARY	MATERIA					-	

Page:



21-10-17/13:00

SMRT Automotive Service Pts Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662628

Accident Reporting Number : 68562672

	ent Vehicle Repair Estimates	17 /08:00
a -ti A. To be complete	ed by claims Advisor/Duty officer at Accident Repo	orting Centre
Reg. No.	SHF377L TAX/10/17/2080	
Reg. Date Vehicle Type	: 18/12/2012 : TAXI	- / 8
Make Model	CHEVROLET EPICA 2.0 VCDI	egeneral control of the control of t
Name of Driver	YEO YOKE JOO	
Type of Accident Date / Time of Accident Accident Reported Date / T	: 13/10/2017 11:05:00 AM	n consistent
Surveyor is Required? Survey by	: Yes : Sebastian	
Vehicle is Towed Back?	: No	
Towed Back Date/Time		Ommu - 6555 8888
Replacement Vehicle issue	The state of the s	NOTE THE PROPERTY OF THE PROPE
Special Instruction to ARC SLH7836A Muc L BEFORE PAINT PHOTO SURVEYOR SEBASTIAN LUMPSUM REPAIR Prepared Date	if any :	D REPLACE ITEM PLEASE CALL
Prepared Date		1 112 11 20 06 9 Some
		110/12 11.24 pass
Recording Camera		OC C
Radio Antenna 1 ⁵¹ winness M	Date 16-10-17	
2 nd wilness	Date	- 2004 - 245 - 246
590422	KM	
	,	
Contract to	LEE SHENG AUTO PT	ELTD
1 5	Vehicle Return Date: 19 (10	17
194 1p 3/4		4.49
	Vehicle Return Time: 17:0	O F. FF

GMRT staff eight -

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No :

KL1LA69RJBB134193

Mileage

0

Work Shop :

Repair Completed Date / Time :

10,301.23

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

845.00

600.00

Total Spray Painting Charges

1,674.00

700.00

Total Material Charges

1,100.54

1,719.60

Other Charges

940.00

-419.60

TOTAL

4,559.54

2,600.00

Lum Sum Total

0.00

0.00

No. of Repair Days

4.00

5.00

Prepared / Adjusted By

SEBASTIAN (LKK)

Arc / Surveyor Sing Off Date

: 14/10/2017 08:52:42 AM

16/10/2017 01:44:14 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 14/10/2017 08:52:42 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

QN-1710-0544

Invoice No

Quotation Date

Invoice Date :

Invoice Amount

Prepared Date:

Section D - Details of Repair Estimates

Part 1 - Labour Works

	Quotation from ARC	Adjusted by Surveyor, if applicable	
ob Scope TO REPAIR LH PORTION	845.00	600.00	
TO REPAIR LH PORTION			
Total Labour	845.00		

Part 2 - Spray Painting & Panel Beating Related Works

	Quotation from ARC	Adjusted by Surveyor, if applicable
Job Scope		200.00 /
TO RESPRAY FRONT DOOR LH	378.00	50.00
TO RESPRAY VIEW MIRROR	180.00	
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00
	378.00	200.00 /
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO REPSRAY FRONT BUMPER	180.00	50.00 /
TO RESPRAY RIM		700.00
Total Spray Painting & Panel Beating	1,674.00	700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses


	Quotation from ARC	Adjusted by Surveyor, if applicable
lob Scope	80.00	30.00
O CHECK WIRING AND SYSTEM FUNCTION	0.00	60.00
O APPLY RUST-PROOFING ON AFFECTED	100.00	,
AREA TO TRANSFER DOOR MECHANISM	120.00	30.00
TO REMOVE AND REFIX WING MIRROR	120.00	30.00
	100.00	0.00
TO REPLACE SUNDRY PARTS		30.00 /
TO WASH AND VACUUM	60.00	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20.00 /
TO REMOVE AND REFIT TYRE	120.00	0.00
	0.00	-619.60
Lump Sum Adjustment by Surveyor	940.00	-419.60
Total Other Costs	340.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
6635577	DOOR	6504596	PANEL LH FRONT DOOR	1	2,020.00	100.00	0.00	Marie Control	Repair	No R
			SMRT LOGO DOOR	1	60.00	0.00	60.00	replace	Replace	No /
	DOOR		CHECK FRONT	0	15.50	10.00	0.00	(topida)	Not given	No X
	DOOR		HINGE UPPER LH	0	75.00	10.00	0.00	1,500.000	Not given	No X
	соммо		HINGE LOWER, LH	0	24.00	10.00	0.00	i.i.ep.a.c.	Not given	No 2
	COMMO	6505044	MIRROR LH	1	844.00	100.00	0.00	Replace	Repair Not given	1
06634087	LEFT	6504608	MOLDING PANEL LH ROCKER	(304.00	10.00	0.00	Replace	Replace	No X
96636324	FRONT	6504580	PANEL FRT FENDER		606.00	10.00	545.40	Replace	Not given	No
	СОММО	6503708	TYRE		126.74	0.00	0.00	Replace	Repair	No A
	COMMO	6504666	TYRE RIM		1 328.99	100.00	0.00		Not given	No V
9663393	FRONT	8504582	LINER FENDER FRT LH (PROTECTOR)		0 49.00	10.00	0.00	Replace	Replace	No X
0274449	FRONT	6504592	BUMPER FRT ASSY		1 1,238.00	10.00	1.114.20	Replace		-
9663398	-	1	BRACKET FRT BUMPER SIDE LH		0 9.00	10.00	0.00	Replace	Not given	No X
9663398	4 FRONT		BRACKET FRT BUMPER SIDE RH		0 9.00	10.00	0.00	Replace	Not given	No V
9643732	1 FRONT	6504615	BEZEL FOG LAMP LH	1	0 32.00	10.00	0.00	Replace	Not given	^
0664496	5 FRONT	6504617	LAMP FOG FRT LH	T	0 260.00	10.00	0.00	Replace	100000	- A
	7 FRONT	100000000000000000000000000000000000000	LAMP HEAD LH		0 841.00	10.00	0.00	Replace	Not given	7.1
9004480	FRON	0001010	TOTAL MATERIALS					(A) (A)	0 1,719.60	
		TOT	AL MATERIALS(Disco	untec	3)			1,100.5	1,719.60)

Added Spare Parts / Material Usage After Surveyor Signed off

Part	Portion	Part Name	Oty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	Check
Number	TOTA	L SUPPLEMENTARY	MATERIA	ALS					



Page:



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ITUC	INCOME INSURA	ANCE CO-OPERATIVE LTD	Ref: NS/INC17019	875/Srbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556						
		Policy Particulars	:- THIRD PARTY CLA	IM		
•	Insured Veh.	SLH 7836A	Veh. Inspected	SHF 377L		
	Policy No.	5086367601	Coverage (\$)	0.00		
	Claim No.	MT/0965873-002	Excess (\$)	0.00		
	Assign From		Assign Date	16/10/2017		
2.		Vehicle Parti	iculars & Condition			
	Make & Model	CHEVROLET EPICA	c.c	1991		
	Engine No.	HIDDEN	Year of Reg.	2012		
	Chassis No.	KL1LA69RJBB134193	Colour	MAROON		
	Odometer	590356	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	NIL		
	General	FAIR				
3.		Condit	tions of Tyres	ESSIENTE DE LA		
		Size	Make	Balance		
	R/H Front Tyre	205/55 R15	FALKEN	6 mm		
	L/H Front Tyre	205/55 R15	FALKEN	6 mm		
	R/H Rear Tyre	205/55 R15	FALKEN	6 mm		
	L/H Rear Tyre	205/55 R15	FALKEN	6 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/10/2017	Inspection Date	16/10/2017		
	Survey held at	SMRT AUTOMOTIVE SERVICE				
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705					
5a.	Remarks					
	A)THE INSPECTI B)IN ACCORDAN	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BA WE HAVE NOT AUTHOR	ASIS. RISED REPAIRS.		
5b.	Estimate Days of Repair 4 Working Days					



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 377L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			03+50+9+0+00
1	PANEL FRT FENDER LH (DISC 10%)	DENTED	606.00	545.40
1	BUMPER FRT ASSY (DISC 10%)	CRACKED	1,238.00	1,114.20
1	SMRT LOGO DOOR (SN)	NECESSARY	60.00	60.00
	CHECK FRONT DOOR LH	NOT NECESSARY	15.50	-
	HINGE UPPER LH FRT	NOT NECESSARY	75.00	1.0
1	HINGE LOWER LH REAR	NOT NECESSARY	24.00	-
1	MOLDING PANEL LH ROCKER	NOT NECESSARY	304.00	-
	TYRE	NOT NECESSARY	126.74	8-
	LINER FENDER FRT LH (PTOTECTOR)	NOT NECESSARY	49.00	3 -
	BRACKET FRT BUMPER SIDE LH	NOT NECESSARY	9.00	
1	BRACKET FRT BUMPER SIDE RH	NOT NECESSARY	9.00	25-
	BEZEL FOG LAMP LH (COVER)	NOT NECESSARY	32.00	-
	LAMP FOG FRT LH	NOT NECESSARY	260.00	
	LAMP HEAD LH	NOT NECESSARY	841.00	
	PANEL LH FRONT DOOR	TO REPAIR	2,020.00	·
	MIRROR LH	TO REPAIR	844.00	
	TYRE RIM	TO REPAIR	328.99	
	THE NIM		6,842.23	1,719.60
	LABOUR		4 505 0	710.00
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,525.00	
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,774.00	760.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.0	* Description
	TO WASH AND VACUUM.		60.0	
	August 10 (18 Mario, Section 19 and 1		3,459.0	3/ 1/2000
	GRAND TOTAL		10,301.2	3,219.6
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,600.0

Report Ref No. NS/INC17019875/Srbn2





Report Ref No. NS/INC17019875/Srbn2

18

YEANG WAI KEEN

Automotive Assessor

The

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.