

ASS. REC. BY:

REF:

09 / FELI 7019904 / 7/1/02

Special Instruction:

condition

Surveior:

Taufikah.

ASSIGNMENT (Office)

From (Person): CWB Wureh Jaw

of

FEL

Date/Time: 16-10-2017 750 pm

Estimated Cost:

Bill to:

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 9807S

Insured:

SHA 9718D

at Workshop m/s

Falcon - Air

Tel:

6779 5665

of

No. 8 Pandan Loop (BLK K / BLK I)

Policy No:

Claim No:

017009752 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12-10-2017

CA / REV / REP. / REV 24 HRS

DB.

H.O.D. Endorsement:

Date/Time:

16-10-2017 9:05am

Person Contacted:

Andy

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLJ 9807S - X

SHA 9718D - NS / IN (170107) / M/WBm1

DA: 000617

Sent preli thru email

Surgeur: Taufik

REF:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4112K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

DS'

Vehicle: IN / OUT

Date: _____ Person Contacted: AndyVeh No: SCJ 9807S Yr Regn: 2015 / JulyType (M.Car) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hawier c.c. 1986Colour: Black A/C: Insured / Std / NI / NASp. Reading: 60 641 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU 600049616Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18R: 7BS / DUN / EXNOVA / GY / FS / LIZA (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 17/10/17Survey held at Falcon Air PardenDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.


Date / Time Action / Instruction

Confirm

913572.90

Red: \$ 1632.85, 111.

15 days - email to Andy



27/2/2018

RECORDED 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☒

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. SI

) Photos 011) Others 215/18

TOTAL

5X15=

170+75

50

50

115

1160

Report Format: TPLump Sum / H.B.I: (\$ 13572.90)Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17019904/T1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-10-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9718D	Veh. Inspected	SCJ 9807S
Policy No.		Coverage (\$)	0.00
Claim No.	D17009752MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	16/10/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/10/2017	Inspection Date	17/10/2017
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date 16-10-2017 **Our Ref No.** D170097501FESH

Accident Date 12-10-2017 **Claim Type.** Third Party

Insured Vehicle SHA9718D **Third Party Vehicle.** SCJ9807S

Survey Location NO. 8 PANDAN LOOP (BLK K / BLK 1)

Contact Person. ANDY

Contact No. 67795665/ 0 **Fax No.** 67791110

Survey Type DIRECT SETTLEMENT:

Appointed Surveyor LKK AUTO CONSULTANTS PTE LTD

Contact Person NA **Fax No.** 68416315

Contact Number. NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST




Cc : Workshop FALCON-AIR AUTO SERVICES PTE LTD **Attention.** NIL

Cc : TP Solicitor NA **TP Solicitor Fax No.** NA

Officer Incharge LURENE

IMPORTANT NOTE



Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229171)  PRI Documents  Close 	
---	--

PRI Header Details

Claim No	D17009752MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & FAI PTE LTI
Workshop Name	FALCON-AIR AUTO SERVICES PTE LTD (Contact Person : ANDY)	Survey Location & Contact Details	NO. 8 PANDAN LOOP (BLK K / BLK 1) Mobile: 0 , Phone: 67795665 , Fax: 6779111 EmailId: ANDY@FALCONAIR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9718D	TP Vehicle No	SCJ980
PRI Recieved Date	16-10-2017 04:28:08 PM	Surveyor Appointed Date	16-10-2017 07:49:57 PM	Surveyor Accept Date	17-10-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	17-10-2017	Upload Survey Report *:	
------------------------------------	---	-----------------------------	------------	--------------------------------	---

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009752MFSH

Our Ref: CS/FC117019904/T1rb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCJ 9807S

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/10/2017 at the premises of M/s FALCON-AIR AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 15,205.75 .
Revised Estimate Amount	: S\$ 13,572.90 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at rear portion.



Yours faithfully
TAUFIKH
Automotive Assessor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	4307F

Vehicle Details

Vehicle No.	SCJ9807S
Vehicle to be Exported	No
Intended De-registration Date	19 Oct 2017
Vehicle Make	TOYOTA
Vehicle Model	HARRIER PREMIUM 2.0 CVT
Primary Colour	Black
Manufacturing Year	2015
Engine No.	3ZRB587228
Chassis No.	ZSU600049616
Maximum Power Output	111.0 kW (148 bhp)
Open Market Value	\$30,183.00
Original Registration Date	14 Jul 2015
First Registration Date	14 Jul 2015
Transfer Count	0
Actual ARF Paid	\$29,257.00

Intended PARF Rebate Details


PARF Eligibility	Yes
PARF Eligibility Expiry Date	13 Jul 2025
PARF Rebate Amount	\$21,942.00

Intended COE Rebate Details

COE Expiry Date	13 Jul 2025
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$65,501.00
COE Rebate Amount	\$50,646.00
Total Rebate Amount	\$72,588.00

The information contained herein is correct as at 19 Oct 2017

OK



Toyota Harrier 2.0A Elegance **\$103,500** **\$12,780 /yr** **04-Mar-2015** **1,986 cc** **29,500**

Elegant Silver SUV, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Drive Away With Mini Flexible In House Loan Packages Available.

Prime Motor & Leasing

Posted: 16-Oct-2017

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$103,800** **\$12,630 /yr** **13-Feb-2015** **1,986 cc** **69,000**

Beautifully Kept! With 3-Digit New Number Plate. Good Condition. Only 1 Meticulous Owner. Lowest Driveaway \$10,400 Only Years Extended Warranty With Free Servicing Plus 24 Hrs R...

Posted: 16-Oct-2017

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic **\$103,800** **\$12,720 /yr** **05-Mar-2015** **1,986 cc** **-**

Classic Black ! Only \$10,380 Down Payment. Up To 90% Flexible Loan.Look No Further! We Provide Lowest Interest Rate In High Trade In Are Available. Package With Unrivalled Warra...

Classic Credit Pte Ltd

Posted: 16-Oct-2017

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier, Used Toyota



Toyota Harrier 2.0A Elegance Panoramic **\$114,800** **\$12,710 /yr** **29-Oct-2015** **1,986 cc** **13,994**

Super Low Mileage Done At 13994Km Only, Seldom Use, 1 Owner, Well Maintain And Regular Servicing, Almost Brand New C From Brand New Car, Why Wait, Call Now!

Henly Enterprises Co

Posted: 14-Oct-2017

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$118,800** **\$12,820 /yr** **08-Dec-2015** **1,986 cc** **32,000**

One Owner. Immaculate Condition. Well Maintained By MBM. 10%-20% Down Payment Scheme Available. Welcome Trade In More Details And Viewing Now.

Posted: 13-Oct-2017

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier, Used Toyota



Toyota Harrier 2.0A Premium **\$105,800** **\$12,770 /yr** **20-Mar-2015** **1,986 cc** **37,000**

Showroom Condition. Bank Loan In House Loan Available, Trade In Welcome.

Posted: 13-Oct-2017

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$115,500** **\$12,930 /yr** **10-Sep-2015** **1,986 cc** **19,800**

Elegant Silver SUV, Premium Model With High Specifications, One Owner Only, Low Mileage Done, Low Maintenance Cost, Ve Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 13-Oct-2017

Tags: 2015 Toyota Harrier, 2015 Toyota Harrier, Toyota Harrier, Toyota Harrier, Toyota, Harrier, Harrier, Used Toyota



Toyota Harrier 2.0A Premium Panoramic **\$118,800** **\$12,900 /yr** **27-Nov-2015** **1,986 cc** **35,000**

Our Promotion For October. 1.99% Interest Rate,Extended Warranty Up To 3years.,Free Urive A5 Dash Camera For Every Pu Condition Apply. Please Contact Our Sales Person For More Informati...

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/10/2017 12:11
Date Of Accident	12/10/2017 19:35
Exact Location Of Accident	AYE TOWARD JURONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCJ9807S
Insured/Policyholder	
Name Of Registered Owner	CHAI KIM YIN
NRIC No	S2554307F
Email Address	FONGZUN90@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96788592
Alternative Phone No	OFFICE-96788592

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR


Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5072731513-02
Cover Note Number	

Driver

Name of Driver	CHAI FONG ZUN
NRIC No	S9041799A
Date Of Birth	07/11/1990
Occupation	INDOOR
Date Of Driving Pass	30/05/2011
Driving Experience	6 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident happened at AYE toward Jurong
(after ERP toward City).
I was travelling on lane 1. Traffic was
heavy. The vehicles in front slowed down and
came to a halt. I also managed to slow
down and stop. Suddenly vehicle taxi No
SHA978D banged on to the rear of my
vehicle causing extensive damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

S 2554307F
Chai Kim YIN

Policyholder's Signature
Date & Time:

1116am
13/10/17
Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: B.K. NG
NRIC/FIN No.: 620048911





PAINT PROTECTION WARRANTY

Thank you for choosing our product.

This Agreement ("the guarantee") is made this 14 JULY 2015 ("The application date") between CS II UNIOLE ("The Company") whose address is 53 UBI AVE 1 #01-40 and the customer ("you"), whose details are shown below.

WHEREAS

- (1) The guarantee is supplemental to the sale to you by CS-II Dealership Process ("the treatment") to your vehicle on the application date and for the consideration of the sum paid for the treatment ("the treatment price")
- (2) The company has agreed to guarantee the due performance of the above process in the manner to the extent as listed below

The company hereby agree with you:

1. The 3 Year guarantee or part thereof (CS-II Paint Protection System Process)

- (a) You complete and send to the company the guarantee registration form within fourteen days of the application.
- (b) If within 36 months of the application date of the CS-II Paint Protection System to your vehicle, you notify the company in writing that your vehicle has suffered subsequent deterioration to its paintwork by reason of fading, climatically induced cracking or loss of gloss.
- (c) The other conditions contained herewith are satisfied then the company will retreat the application at no cost

2. Your Statutory Rights

The Guarantee is not intended to replace, modify or be a substitute for your statutory rights and the company shall not be responsible for any loss, damage, costs, expenses OR otherwise which may be incurred as a direct or indirect result of your purchase of the treatment.

3. Assignment of the Guarantee (CS-II Paint Protection System Process)

The CS-II warranty will remain the sole transferable property to owner. For term of customer benefit, we will not assign the CS-II warranty.

4. Regular Inspections

In order to maintain your paint preservation at its optimum level, an annual inspection is recommended. This inspection is normally carried out at your supplying dealer, if there are any major marks or scratches on the paintwork details should be noted on the guarantee. The CS-II dealership, at its own discretion, is entitled to request any inspection/grooming fee on each inspection and you are entitled to enquire whether any such fee will be charged and what the fee will be when you present your vehicle for inspection at the dealership. In the event that you wish to rely on this Guarantee to reclaim the treatment price, you will need to present to the company a duly completed Guarantee Card for the period of time from the application date to the date that you notify the company.

5. Limitations of liability for the company (CS-II Paint Protection System Process)

- a. This treatment must be applied at a CS-II approved dealership for the guarantee to be valid
- b. There must be no evidence of colour fading, flaking or climatically induced cracking prior to the process being applied.
- c. Any areas repaired or replaced through accident or damage must be retreated immediately by an authorized CS-II dealer and the detail noted on the guarantee.
- d. The guarantee shall be invalidated by reason of the following:
 - ☒ Vandalism: Any evidence of deliberate acts or omissions affecting the vehicle's bodywork or painted surface.
 - ☒ Stone Chip: Damage to the vehicle by any force capable of breaking the treatment's surface (i.e. pebbles, large stones, pieces of rock or other similar objects)
 - ☒ Acidic Stains: Bird poo, tree sap, acid rain, petroleum, etc must be washed off immediately or within 24 hours, otherwise etching or discolouration may occur. Failure to do this is likely to invalidate the guarantee on our inspection. No paint finish, however good, can withstand the prolonged effects of such corrosive matter

6. Important Notes

Old and dirty chemicals/leathers can cause streaks and other unsightly marks on otherwise perfect paintwork (especially on dark coloured vehicles). Such leathers and other dyeing/polishing cloths should be discarded and replaced on a regular basis. Regular use of mechanical car washes and jet washes will eventually damage the sealant.

Before any guarantee work is carried out, permission must be obtained from the company. The interior and exterior vinyl cleaners as well as leather treatment are available as optional extras. It should be noted that due to the nature of these materials no guarantee applies. If a claim is made on the Guarantee, the original guarantee certificate and number must be given to the company to confirm validity.

7. How to Make a Claim.

To submit a warranty claim, you must SUBMIT THIS ORIGINAL WARRANTY CARD AND ORIGINAL RECEIPT (or other proof of purchase acceptable to CS-II Paint Protection) for the product, along with a detailed description of the defect, to the authorized dealer from whom the product was purchased. All warranty claims must be approved by CS-II prior to commencement of any warranty service.

YOU MUST COMPLETELY FILL OUT AND RETAIN THIS WARRANTY CARD AND RESENT IT, TOGETHER WITH PROOF OF PURCHASE, TO VALIDATE YOUR WARRANTY.


Customer Information	Name	<u>MR. CHAI</u>		Telephone	<u>9181 1976 / 9683 2222</u>	
	Address			Zip/Postal Code	Country / Region	

Vehicle	No.	Make	Model	Color	Treatment Date	Day / Month / Year
	<u>9616</u>	<u>TOYOTA</u>	<u>HARRIER</u>	<u>BLACK</u>		<u>14. 07. 15</u>

Product Family (check one)	<input type="checkbox"/> Titanium Coating (3 Year)	<input type="checkbox"/> Ceramic Coating (3 Year)	<input type="checkbox"/> Glass Coating (3 Year)	<input checked="" type="checkbox"/> 2 Stages Coating
				<input checked="" type="checkbox"/> 24 mth <input type="checkbox"/> 18 mth

Applicator Name	Gloss Unit
<u>A. GUANG, ALVIN NATHAN</u>	<u>GU 89</u>

Dealership Information	Name	Telephone	
	Address	Zip/Postal Code	Country / Region



FALCON-AIR

CHAI KIM YIN
53 JALAN MAS PUTEH
128644

Attention : Motor Claim Department

Contact : 96788592

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003031

Date : 14/10/2017
Vehicle Num. : SCJ9807S
Make/Model : TOYOTA HARRIER
Chassis/Eng# : ZSU60-0049616
Accident Date : 12/10/2017
Claim No. :
Reference : TP NTUC VS FIRST CAPITAL
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	TAILGATE		-2,379.00 <i>bt</i> ✓
2.	1PC	TAILGATE LOCK		-974.00 <i>bt</i> ✓
3.	1PC	TAILGATE LOGO		-110.00 <i>rec</i> ✓
4.	1PC	TAILGATE GLASS MOULDING		-110.00 <i>rec</i> ✓
5.	1PC	TAILGATE WEATHERSTRIP		-441.30 <i>twi</i> ✓
6.	1PC	TAILGATE TRIM BOARD		-578.50 <i>de</i> ✓
7.	1PC	TAILGATE PULL HANDLE		-68.00 <i>mis</i> ✓
8.	1PC	SPARE TYRE PANEL		-925.00 <i>buc</i> ✓
9.	1PC	REAR END PANEL		-798.50 <i>bt</i> ✓
10.	1PC	REAR BUMPER TOP		-1,415.10 <i>de</i> ✓
11.	1PC	REAR BUMPER LOWER		-455.00 <i>de</i> ✓
12.	1PC	REAR BUMPER SPONGE		-125.00 <i>cra</i> ✓
13.	2PCS	REAR BUMPER SIDE RETAINER	85.00	-170.00 <i>rec</i> ✓
14.	2PCS	REAR BUMPER CENTRE RETAINER	90.00	-180.00 <i>de</i> ✓
15.	1PC	REAR END PANEL TOP GARNISH		-445.00 <i>de</i> ✓
16.	2PCS	REAR FENDER UNDERSHIELD LH/RH <i>LH-X, RH-de X nn</i>	169.80 <i>nn</i>	< 339.60 ✓
17.	1PC	REAR EXHAUST		-638.80 <i>bt</i> ✓
18.	2PCS	REAR EXHAUST RUBBER HOLDER	34.30	-68.60 <i>de</i> ✓
19.	1PC	REAR EXHAUST GASKET		-85.00 <i>rec</i> ✓
20.	1	SPARE TYRE CARPET		<i>nn</i> + 283.10 <i>de</i> ✓
21.	1	LUGGAGE BOARD A LH		-576.40 <i>de</i> ✓
22.	1	LUGGAGE BOARD B R		-487.80 <i>de</i> ✓

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

CHAI KIM YIN
53 JALAN MAS PUTEH
128644

Attention : Motor Claim Department
Contact : 96788592

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

Estimate : ES003031

Date : 14/10/2017
Vehicle Num. : SCJ9807S
Make/Model : TOYOTA HARRIER
Chassis/Eng# : ZSU60-0049616
Accident Date : 12/10/2017
Claim No. :
Reference : TP NTUC VS FIRST CAPITAL
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1	LUGGAGE BOARD C		/ 640.50 <i>de</i>
24.	1	LUGGAGE BOARD D		444.20 <i>x</i> <i>de</i>
25.	1	TAILGATE LOCK GARNISH		/ 46.20 <i>de</i>
26.	1PC	LH REAR FENDER AIR-DUCT		/ 174.80 <i>de</i>
27.	1PC	LH FLOOR PANEL		<i>nn</i> x 66.20 ?
28.	1PC	RH FLOOR PANEL		<i>nn</i> x 74.50 ?
29.	2	REINFORCEMENT REAR FLOOR PANEL	56.80	x 113.60 <i>de</i> <i>nn</i>
30.	2	EXTENSION REAR FLOOR	38.60	1 pcs 77.20 ? <i>bt</i>
31.	1	REAR FLOOR CROSS MEMBER		/ 312.80 ? <i>bt</i>
32.	1	ANTENNAE ELECTRICAL KEY		/ 158.00 <i>de</i>
33.	1	REAR FLOOR OUTER REINFORCEMENT		x 112.00 <i>bt</i> <i>nn</i>
34.	1	REAR FLOOR INNER REINFORCEMENT		/ 127.30 <i>bt</i>
List Total S\$:			12529.20	14,001.00
25.00% Discount S\$:			9396.90	3,500.25
				10,500.75
SPECIAL NETT ITEMS :				
1.	1PC	TAILGATE SEALANT		/ 40.00 <i>de</i>
2.	2PC	REVERSE SENSOR	200.00	/ 400.00 <i>nn</i>
3.	1PC	REAR NUMBER PLATE		/ 45.00 <i>de</i>
Special Nett Total S\$:				485.00 <i>485</i>

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

CHAI KIM YIN
53 JALAN MAS PUTEH
128644

Attention : Motor Claim Department
Contact : 96788592

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

Estimate : ES003031

Date : 14/10/2017
Vehicle Num. : SCJ9807S
Make/Model : TOYOTA HARRIER
Chassis/Eng# : ZSU60-0049616
Accident Date : 12/10/2017
Claim No. :
Reference : TP NTUC VS FIRST CAPITAL
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO REMOVE/REPLACE EXHAUST BOX	80.00	40/-
TO REMOVE/REFIX REAR WINDSCREEN GLASS	120.00	400/100
TO TRANSFER TAILGATE PARTS/MECHANISM	50.00	40/-
TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING	120.00	80/-
TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING	150.00	120/-
TO RUSTPROOF & WATER LEAKAGE TEST	150.00	100/-
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS	1,800.00	1500/-
TO CUT/OUT REWELD REAR END PANEL, SPARE TYRE PANEL, REINFORCEMENTS, FLOOR PANELS L/RH, REPAIR REAR CHASSIS RH/LH REAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS	1,750.00	1400/-
Labour Total S\$:	4,220.00	3380

+ Supplementary
Paint Protection 311.00

E. & O.E.

Total S\$: 15,205.75



for FALCON AIR AUTO SERVICES PTE LTD

Work Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tajik 97495749
- DS'
17/10/17 @ 1645.
sur @ 1/kkanto.com -
* Resurvey before paint.
13 days

15266.90

15516.76

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



UNIQUE CAR BEAUTY SHOP


No.2002607

53, Ubi Ave 1, Paya Ubi Industrial Park, #01-40, Singapore 408934
Tel: 6463 1311 (Enquiry) / 6844 2235 (Booking)
Website: www.cs2singapore.com Email: info@cs2singapore.com
GST Registration No: M90371726N

Delivery Order / Invoice
送货 / 发货单

Customer 顾客署名	FALCON	Contact No. 联系电话	
Chassis. No. 车架编号	SCT98705	Chassis. No. 车架编号	T. HARKER

<input checked="" type="checkbox"/>	CS-II Paint Protection System CS-II 密封胶	01	\$ 311
<input type="checkbox"/>	Nano 1 Technology (Polishing) 磨亮与打腊		
<input type="checkbox"/>	PDI (Pre-Delivery Inspection) 新车车身检查与准备		
<input type="checkbox"/>	Cushion Wash / Leather Wash 清洗古申/皮革		
<input type="checkbox"/>	Leather Repair / Leather Re-dye 维修皮革/重染		
<input type="checkbox"/>	Engine Bay Cleaning 清洗引擎室		
<input type="checkbox"/>	Window Film 贴膜		
<input type="checkbox"/>	Paint Protection Film (PPF) 汽车漆面保护膜		
<input type="checkbox"/>	Other Films 其他 玻璃膜		
<input type="checkbox"/>	Dent Repair 凹痕修复		
<input type="checkbox"/>	S.M.A.R.T Repair 喷漆		
<input type="checkbox"/>	Cabin Sterilization 车内消毒		
<input type="checkbox"/>	Anti-Bacteria 内部杀菌		
			\$ 311
			\$ 21
			\$ 332



Cash Card 现金卡	Yes/No 是/否	\$	
Parking Coupon 停车固本	Yes/No 是/否	\$	/ pcs
Other Valuable Items 其他珍贵项目	Yes/No 是/否		

☒ D= Dent S= Scratches C= Chips WM= Water mark
凹 花 甩花 水印

☒ Unique cannot be held responsible or liable for any loss or missing. All valuables and other items must be taken care of by the customer before the grooming services.
Unique 不能对任何丢失或遗失负责。所有贵重物品及其他物品必须在美容服务前，把所有贵重及宽松物品放在 Unique 负责不见物品。
☒ Due to rain, fog or other circumstances, we cannot clearly examine the car body for scratches or damages, so the examination under these circumstances are not accurate.
因雨天、阴暗地方或车身整洁问题，与特殊情况下，而不能看清楚车上的花痕、割痕或凹凸损坏，因此未能作组准。

Unique Signature 签署	Customer's Signature 顾客签署	Customer's Signature 顾客签署
	Date In 进车日期	Date Out 出车日期
	Time In 进车时间	Time Out 出车时间

Please present this Reception slip for confirmation of your vehicle.
取车时请出示此款收据

We accept Cash/Visa/Master/Amex
我们接受现金; Visa/Master/Amex





PAINT PROTECTION WARRANTY

Thank you for choosing our product.

This Agreement ("the guarantee") is made this 14 JULY 2015 ("The application date") between CS II UNIOLE ("The Company") whose address is 53 UBI AVE 1 #01-40 and the customer ("you"), whose details are shown below.

WHEREAS

- (1) The guarantee is supplemental to the sale to you by CS-II Dealership Process ("the treatment") to your vehicle on the application date and for the consideration of the sum paid for the treatment ("the treatment price")
- (2) The company has agreed to guarantee the due performance of the above process in the manner to the extent as listed below.

The company hereby agree with you: -

1. The 3 Year guarantee or part thereof (CS-II Paint Protection System Process)
- (a.) You complete and send to the company the guarantee registration form within fourteen days of the application.
- (b.) If within 36 months of the application date of the CS-II Paint Protection System to your vehicle, you notify the company in writing that your vehicle has suffered subsequent deterioration to its paintwork by reason of fading, climatically induced cracking or loss of gloss.
- (c.) The other conditions contained herewith are satisfied then the company will retreat the application at no cost.

2. Your Statutory Rights

The Guarantee is not intended to replace, modify or be a substitute for your statutory rights and the company shall not be responsible for any loss, damage, costs, expenses OR otherwise which may be incurred as a direct or indirect result of your purchase of the treatment.

3. Assignment of the Guarantee (CS-II Paint Protection System Process)

The Guarantee is only valid if the car is transferred from owner to owner. Car Agent to owner transfers are not valid under our Guarantee.

4. Regular Inspections

In order to maintain your paint preservation at its optimum level, an annual inspection is recommended. This inspection is normally carried out at your supplying dealer. If there are any major marks or scratches on the paintwork, details should be noted on the guarantee. The CS-II dealership, at its own discretion, is entitled to request any inspection/grooming fee on each inspection and you are entitled to enquire whether any such fee will be charged and what the fee will be when you present your vehicle for inspection at the dealership. In the event that you wish to rely on this Guarantee to reclaim the treatment price, you will need to present to the company a duly completed Guarantee Card for the period of time from the application date to the date that you notify the company.

5. Limitations of liability for the company (CS-II Paint Protection System Process)

- a. The treatment must be applied at a CS-II approved dealership for the guarantee to be valid.
- b. There must be no evidence of colour fading, flaking or climatically induced cracking prior to the process being applied.
- c. Any areas repaired or replaced through accident or damage must be retreated immediately by an authorized CS-II dealer and the detail noted on the guarantee.
- d. The guarantee shall be invalidated by reason of the following:
- ☒ i. Vandalism: Any evidence of deliberate acts or omissions affecting the vehicle's bodywork or painted surface.
 - ☒ ii. Stone Chip: Damage to the Vehicle by any force capable of breaking the treatment's surface i.e. pebbles, large stones, pieces of rock or other similar objects.
 - ☒ iii. Acidic Stains: Bird poo, tree sap, acid rain, petroleum, etc must be washed off immediately or within 24 hours, otherwise etching or discolouration may occur. Failure to do this is likely to invalidate the guarantee on our inspection. No paint finish, however good, can withstand the prolonged effects of such corrosive matter.

6. Important Notes

Old and dirty chamois leathers can cause streaks and other unsightly marks on otherwise perfect paintwork (especially on dark coloured vehicles). Such leathers and other dyeing/polishing cloths should be discarded and replaced on a regular basis. Regular use of mechanical car washes and jet washes will eventually damage the sealant.

Before any guarantee work is carried out, permission must be obtained from the company. The interior and exterior vinyl cleaner as well as leather treatment are available as optional extras. It should be noted that due to the nature of these materials no guarantee applies. If a claim is made on the Guarantee, the original guarantee certificate and number must be given to the company to confirm validity.

7. How to Make a Claim

To submit a warranty claim, you must SUBMIT THIS ORIGINAL WARRANTY CARD AND ORIGINAL RECEIPT (or other proof of purchase acceptable to CS-II Paint Protection) for the product, along with a detailed description of the defect, to the authorize dealer from whom the product was purchase. All warranty claims must be approved by CS-II prior to commencement of any warranty service.

YOU MUST COMPLETELY FILL OUT AND RETAIN THIS WARRANTY CARD AND RESENT IT, TOGETHER WITH PROOF OF PURCHASE, TO VALIDATE YOUR WARRANTY.

Customer Information

Name	<u>MR. CHAI</u>	Telephone	<u>9181 1976 / 9683 2222</u>
Address	Zip/Postal Code Country / Region		

Vehicle

No.	<u>9616</u>	Make	<u>TOYOTA</u>	Model	<u>HARRIER</u>	Color	<u>BLACK</u>	Treatment Date	Day / Month / Year
									<u>14. 07. 15</u>

Product Family (check one)

☐ Titanium Coating (3 Year)

☐ Ceramic Coating (3 Year)

☐ Glass Coating (3 Year)

☒ 2 Stages Coating
☒ 24 mth ☐ 18 mth

Applicator Name

A. GUANG, ALUX NANG

Gloss Unit

GU 89

Dealership Information

Name	Telephone		
Address	Zip/Postal Code	Country / Region	

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD #16-01 CITY HOUSE
SINGAPORE 068877

Attention : Motor Claim Department
Contact : 62222311 Fax No. : 65073849

Estimate : ES003031

Date : 14/10/2017
Vehicle Num. : SCJ9807S
Make/Model : TOYOTA HARRIER
Chassis/Eng# : ZSU60-0049616
Accident Date : 12/10/2017
Claim No. :
Reference : TP NTUC VS FIRST CAPITAL
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
<hr/>				
		LIST ITEMS :		2,379.00
1.	1PC	TAILGATE		974.00
2.	1PC	TAILGATE LOCK		110.00
3.	1PC	TAILGATE LOGO		110.00
4.	1PC	TAILGATE GLASS MOULDING		441.30
5.	1PC	TAILGATE WEATHERSTRIP		578.50
6.	1PC	TAILGATE TRIM BOARD		68.00
7.	1PC	TAILGATE PULL HANDLE		925.00
8.	1PC	SPARE TYRE PANEL		798.50
9.	1PC	REAR END PANEL		1,415.10
10.	1PC	REAR BUMPER TOP		455.00
11.	1PC	REAR BUMPER LOWER		125.00
12.	1PC	REAR BUMPER SPONGE	85.00	170.00
13.	2PCS	REAR BUMPER SIDE RETAINER	90.00	180.00
14.	2PCS	REAR BUMPER CENTRE RETAINER		445.00
15.	1PC	REAR END PANEL TOP GARNISH		X
16.	2PCS	REAR FENDER UNDERSHIELD LH/RH X		638.80
17.	1PC	REAR EXHAUST	34.30	68.60
18.	2PCS	REAR EXHAUST RUBBER HOLDER		85.00
19.	1PC	REAR EXHAUST GASKET		X
20.	1	SPARE TYRE CARPET X		576.40
21.	1	LUGGAGE BOARD A LH		487.80
22.	1	LUGGAGE BOARD B RH		

CONTINUE / ...

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD #16-01 CITY HOUSE
SINGAPORE 068877

Attention : Motor Claim Department

Contact : 62222311 Fax No. : 65073849

Estimate : ES003031

Date : 14/10/2017

Vehicle Num. : SCJ9807S

Make/Model : TOYOTA HARRIER

Chassis/Eng# : ZSU60-0049616

Accident Date : 12/10/2017

Claim No. :

Reference : TP NTUC VS FIRST CAPITAL

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1	LUGGAGE BOARD C		640.50
24.	1	LUGGAGE BOARD D X		X
25.	1	TAILGATE LOCK GARNISH		46.20
26.	1PC	LH REAR FENDER AIR-DUCT		174.80
27.	1PC	LH FLOOR PANEL X		X
28.	1PC	RH FLOOR PANEL X		X
29.	2	REINFORCEMENT REAR FLOOR PANEL X		X
30.	1	EXTENSION REAR FLOOR		38.60
31.	1	REAR FLOOR CROSS MEMBER		312.80
32.	1	ANTENNAE ELECTRICAL KEY		158.00
33.	1	REAR FLOOR OUTER REINFORCEMENT X		X
34.	1	REAR FLOOR INNER REINFORCEMENT		127.30
List TotalS\$:				12,529.20
25.00% Discount S\$:				3,132.30
				9,396.90
SPECIAL NETT ITEMS :				
1.	1PC	TAILGATE SEALANT		40.00
2.	2PC	REVERSE SENSOR	200.00	400.00
3.	1PC	REAR NUMBER PLATE		45.00
Special Nett Total S\$:				485.00

CONTINUE / ...

FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD #16-01 CITY HOUSE
SINGAPORE 068877

Attention : Motor Claim Department
Contact : 62222311 Fax No. : 65073849

Estimate : ES003031

Date : 14/10/2017
Vehicle Num. : SCJ9807S
Make/Model : TOYOTA HARRIER
Chassis/Eng# : ZSU60-0049616
Accident Date : 12/10/2017
Claim No. :
Reference : TP NTUC VS FIRST CAPITAL
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO REMOVE/REPLACE EXHAUST BOX		40.00
		TO REMOVE/REFIX REAR WINDSCREEN GLASS		100.00
		TO TRANSFER TAILGATE PARTS/MECHANISM		40.00
		TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING		80.00
		TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING		120.00
		TO RUSTPROOF & WATER LEAKAGE TEST		100.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS		1,500.00
		TO CUT/OUT REWELD REAR END PANEL, SPARE TYRE PANEL, REINFORCEMENTS, FLOOR PANELS LH/RH, REPAIR REAR CHASSIS RH/ LH REAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS		1,400.00
		Labour Total S\$:		3,380.00

E. & O.E. Total S\$: 13,261.90

for FALCON AIR AUTO SERVICES PTE LTD

SUPPLEMENTARY + 311.00
(PAINT PROTECTION)
13,572.90

15 DAYS

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile**FIRST CAPITAL INSURANCE LTD**

Ref : CS/FCI17019904/T1rbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-03-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9718D	Veh. Inspected	SCJ 9807S
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17009752MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	16/10/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	ZSU600049616	Colour	BLACK
Odometer	60641	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/10/2017	Inspection Date	17/10/2017
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCJ 9807S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	2,379.00	2,379.00
1	TAILGATE LOCK	BENT	974.00	974.00
1	TAILGATE LOGO	NECESSARY	110.00	110.00
1	TAILGATE GLASS MOULDING	NECESSARY	110.00	110.00
1	TAILGATE WEATHERSTRIP	TWISTED	441.30	441.30
1	TAILGATE TRIM BOARD	DEFORMED	578.50	578.50
1	TAILGATE PULL HANDLE	MISSING	68.00	68.00
1	SPARE TYRE PANEL	BUCKLED	925.00	925.00
1	REAR END PANEL	BENT	798.50	798.50
1	REAR BUMPER TOP	DEFORMED	1,415.10	1,415.10
1	REAR BUMPER LOWER	DEFORMED	455.00	455.00
1	REAR BUMPER SPONGE	CRACKED	125.00	125.00
2	REAR BUMPER SIDE RETAINER @\$85.00	NECESSARY	170.00	170.00
2	REAR BUMPER CENTRE RETAINER @\$90.00	DEFORMED	180.00	180.00
1	REAR END PANEL TOP GARNISH	DEFORMED	445.00	445.00
2	REAR FENDER UNDERSHIELD LH/RH @\$169.80	NOT NECESSARY	339.60	-
1	REAR EXHAUST	BENT	638.80	638.80
2	REAR EXHAUST RUBBER HOLDER @\$34.30	DEFORMED	68.60	68.60
1	REAR EXHAUST GASKET	NECESSARY	85.00	85.00
1	SPARE TYRE CARPET	NOT NECESSARY	283.10	-
1	LUGGAGE BOARD A LH	DEFORMED	576.40	576.40
1	LUGGAGE BOARD B R	DEFORMED	487.80	487.80
1	LUGGAGE BOARD C	DEFORMED	640.50	640.50
1	LUGGAGE BOARD D	NOT NECESSARY	444.20	-
1	TAILGATE LOCK GARNISH	DEFORMED	46.20	46.20
1	LH REAR FENDER AIR-DUCT	DEFORMED	174.80	174.80
1	LH FLOOR PANEL	NOT NECESSARY	66.20	-
1	RH FLOOR PANEL	NOT NECESSARY	74.50	-
2	REINFORCEMENT REAR FLOOR PANEL @\$56.80	NOT NECESSARY	113.60	-
2	EXTENSION REAR FLOOR @\$38.60	BENT	77.20	38.60
1	REAR FLOOR CROSS MEMBER	BENT	312.80	312.80

Report Ref No. CS/FCI17019904/T1rbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ANTENNA ELECTRICAL KEY	CRACKED	158.00	158.00
1	REAR FLOOR OUTER REINFORCEMENT	NOT NECESSARY	112.00	-
1	REAR FLOOR INNER REINFORCEMENT	BENT	127.30	127.30
	LESS 25% DISCOUNT		-3,500.25	-3,132.30
			10,500.75	9,396.90
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE SEALANT (SN)	NECESSARY	40.00	40.00
2	REVERSE SENSOR @\$200.00 (SN)	NOT WORKING	400.00	400.00
1	REAR NUMBER PLATE (SN)	BENT	45.00	45.00
			485.00	485.00
	<u>LABOUR</u>			
	TO REMOVE / REPLACE EXHAUST BOX.		80.00	40.00
	TO REMOVE/ REFIX REAR WINDSCREEN GLASS.		120.00	100.00
	TO TRANSFER TAILGATE PARTS/MECHANISM.		50.00	40.00
	TO REMOVE / REFIX REVERSE SENSOR & CHECK WIRING.		120.00	80.00
	TO REMOVE/ REFIX CUSHION SEAT, CARPET, GARNISH, WIRING.		150.00	120.00
	TO RUSTPROOF & WATER LEAKAGE TEST.		150.00	100.00
	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS.		1,800.00	1,500.00
	TO CUT/OUT REWELD REAR END PANEL, SPARE TYRE PANEL, REINFORCEMENTS, FLOOR PANELS, LH/RH, REPAIR REAR CHASSIS RH / LH REAR FENDER INCLUDES KNOCKING & REPLACEMENT OF PARTS.		1,750.00	1,400.00
	PAINT PROTECTION. (ADDITIONAL)		311.00	311.00
			4,531.00	3,691.00
GRAND TOTAL			15,516.75	13,572.90

RECOMMENDED COST OF REPAIRS**13,572.90**

Report Ref No. CS/FC117019904/T1rbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.