

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AXA17019918/R1PS3Q2

**Date:** 09/09/2020

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

**Claimant**

**Vehicle No :** SLQ6076K

**Insured Vehicle No :**

SHB7670P

Date of Loss: 09/10/2017

Nature of Claim:

TP

Claim No: C0455847

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SLQ6076K**

Make & Model:

HONDA VEZEL, 1.5 HYBRID (A)

Engine No:

HIDDEN

Reg. Date:

01/07/2017 (Man. Year: 2017)

Chassis No:

RU31213076

Colour:

Grey

Odometer:

4726 km

Engine Capacity:

1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

**Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	206.40	206.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	450.00	220.00	230.00	51.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>656.40</b>	<b>426.40</b>	<b>230.00</b>	<b>35.04</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>45.95</b>	<b>29.85</b>	<b>16.10</b>	<b>35.04</b>
<b>Nett Amount (S\$)</b>	<b>702.35</b>	<b>456.25</b>	<b>246.10</b>	<b>35.04</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 16/10/2017

Date Inspected: 17/10/2017 Inspected At:

World Auto Pte Ltd - Kranji (HQ)

No 1 Kranji Loop

Singapore 739535

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2020)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ6076K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH SIDE BUMPER (VEZEL)	Cut	258.00 FL	*258.00 FL
F=Franchise part. L=ListItemDisc.						
<b>Sub Total (S\$)</b>					<b>258.00</b>	<b>258.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>					51.60	51.60
<b>Total Parts (S\$)</b>					<b>206.40</b>	<b>206.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REPLACEMENT OF R/R SIDE BUMPER	New	200.00	100.00
2	TO RESPRAY R/R SIDE BUMPER	New	250.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>450.00</b>	<b>220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >