

ASS. REC. BY: Adrian King

REF:

CC3 / ALH 17019955 / Agbn2**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 210374476Claims No. 571744472154Sum Insured: _____ Excess: 600 23/10/17

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 17810

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 80% days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKH3206A Yr Regn: 2014 MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 SB c.c. 1395Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 35290 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2228V4EA130704Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 17/10/17Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFront o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ODAC.SKH 3206A -x23/10/17 @ 2.54pm Informed Lee Seng Ex \$ 600 by email.27/10/17 @ 1.36pm Confirmed with Mr Bob final fig \$577.96, 5 days.
(Add \$ 220.04, 30%)

RECEIVED 1-8 JAN 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) \$577.96Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

20010210




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD			Ref : CC3/AIG17019955/Aqb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120			Date : 17-10-2017	
			Code : AIG	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SKN 3206A	
Policy No. 2100374476	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		17/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 13/10/2017	Inspection Date		17/10/2017	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No: CU3/164/7019953/Agg
 Policy Type: OD / TP / TP RES / TL / EVA

SKN 3206R

Case Handler

Typist

Admin (Cater): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<input checked="" type="checkbox"/>			
-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 27 December, 2017 1:36 PM
To: Boo seng yak; SUR; Carrine Leong; Chang Chee Sing
Subject: RE: FINAL REVISION - SKN3206A - SURVEYED 17 OCT 17

Dear Mr Boo,

Confirm final fig \$5,222.96 before excess \$600.00 & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Monday, 11 December, 2017 9:04 AM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SKN3206A - SURVEYED 17 OCT 17

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$5222.96 @ 5 days of repairs.

Your early closure is well appreciated.

best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 23 October, 2017 2:54 PM
To: Claims; SUR
Subject: RE: OWN DAMAGE CLAIM FOR SKN 3206 A

Dear Kee Siang,

Please be informed that the excess of above vehicle is \$600.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 20 October, 2017 8:53 AM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OWN DAMAGE CLAIM FOR SKN 3206 A

Dear Kee Siang,

Please be informed that Adrian already informed authorisation at the time of inspection (see attached). The excess to be advice.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Thursday, 19 October, 2017 9:20 PM
To: 'Claims' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OWN DAMAGE CLAIM FOR SKN 3206 A

Hi All,

Any Update?

Best regards,

Claims Department

Kee Siang

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	9766C
Vehicle Details	
Vehicle No.	SKN3206A
Vehicle to be Exported	No
Intended De-registration Date	19 Oct 2017
Vehicle Make	AUDI
Vehicle Model	A3 SB 1.4 TFSI AMBIENTE
Primary Colour	Grey
Manufacturing Year	2014
Engine No.	CXS071608
Chassis No.	WAUZZZ8V4EA130704
Maximum Power Output	90.0 kW (120 bhp)
Open Market Value	\$26,173.00
Original Registration Date	29 May 2014
First Registration Date	29 May 2014
Transfer Count	0
Actual ARF Paid	\$13,643.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 May 2024
PARF Rebate Amount	\$10,232.00
Intended COE Rebate Details	
COE Expiry Date	28 May 2024
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$67,290.00
COE Rebate Amount	\$43,404.00
Total Rebate Amount	\$53,636.00

The information contained herein is correct as at 19 Oct 2017

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7419766C



Name:

TEO YUAN CHING

张缘清

Race:

CHINESE

Date of birth:

19-06-1974

Sex:

F

Country of birth:

SINGAPORE

S74187880

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7419766C

Name:

TEO YUAN CHING

Birth Date: 19 Jun 1974

Issue Date: 15 Mar 2004



001164462E



4969974

NRIC No: S7419766C



Date of Issue:

24-04-2013

Address:

17C JALAN ARIF
SINGAPORE 548827

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

01 Dec 1997

NP 428A



Licence No: S7419766C



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100374476-03000

OWN DAMAGE EXCESS \$5600.00 (1)
WINDSCREEN EXCESS \$5100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SKN3206A

TEO YUAN CHING

29 May 2017

28 May 2018

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

4) DATE OF EXPIRY OF INSURANCE

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION :40 years old and above

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY MayBank
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 25 Apr 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-222
PREMIUM LEASING - SS
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCGUK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKN 3206 A.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 //	
2	To dismantle and renew front bumper and RHS front fender. Re-organize front crash management components. Reinstall all parts removed.	\$ 1,500.00 1000 //	
3	To respray front bumper and RHS front fender.	\$ 1,500.00 1100 //	
4	To renew RHS front rim and carry out wheel alignment.	S/N \$ 280.00 //	
5	To carry out diagnostic checks.	S/N \$ 192.00 //	
TOTAL LABOUR CHARGES		: \$ 3,832.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 3206 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rebored</i>	\$ 1,546.00	✓ 1236.50
2	FRONT BUMPER GUIDE - RHS <i>Not Nec</i>	\$ 51.00	? x
3	FRONT FENDER - RHS <i>Dented</i>	\$ 708.00	✓ 566
4	FRONT FENDER INNER BRACKET - RHS <i>Not Nec</i>	\$ 40.00	? x
5	FRONT FENDER OUTER BRACKET - RHS <i>Not Nec</i>	\$ 23.00	? x
6	FRONT FENDER CLOSING ELEMENT - RHS <i>But</i>	\$ 52.00	✓ 40.46
7	FRONT FENDER BRACE - RHS <i>Not Nec</i>	\$ 81.00	? x
8	FRONT WHEEL HOUSE LINER - RHS	\$ 146.00	+ <i>2nd</i>
9	FRONT WHEEL HOUSE LINER ATTACHEMENT - RHS	\$ 75.00	+ <i>2nd</i>
10	FRONT ALUMINIUM RIM - RHS <i>cut</i>	\$ 559.00	✓ 447.20
11	SUNDRIES <i>Not Nec</i>	\$ 400.00	? x
TOTAL SPARE PARTS		\$ 3,681.00	
GRAND TOTAL SPARE PARTS		\$ 3,832.00	
TOTAL LABOUR		\$ 7,513.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lj*
Surveyed Date : *17/10/17*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorised Repairs, 05 days*

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1014/2017/JT
Date : 14-Oct-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
5 days - ok - jb - 11 Dec

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Teo Yuan Ching
Address : 17C Jalan Arif
Singapore 548827
Telephone : HP +65 9858 9765
Type of Claim : Own Damage Claims
Policy No. : 2100374476-03000
Vehicle No : **SKN 3206 A**
Model Code : Audi A3 SB 1.4 TFSI
Model / Year : May-17
Engine No : CXG 071608
Chassis No : WAUZZZ8V4EA130704
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Oct-17
Place of Accident : Outside 17C Jalan Arif

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKN 3206 A.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew front bumper and RHS front fender. Re-organize front crash management components. Reinstall all parts removed.		\$ 1,500.00	\$ 1,000.00
3	To respray front bumper and RHS front fender.		\$ 1,500.00	\$ 1,100.00
4	To renew RHS front rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
5	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 3,832.00</u>	<u>\$ 2,932.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 3206 A.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,546.00	\$ 1,236.80
2	FRONT BUMPER GUIDE - RHS	\$ 51.00	
3	FRONT FENDER - RHS	\$ 708.00	\$ 566.00
4	FRONT FENDER INNER BRACKET - RHS	\$ 40.00	
5	FRONT FENDER OUTER BRACKET - RHS	\$ 23.00	
6	FRONT FENDER CLOSING ELEMENT - RHS	\$ 52.00	\$ 40.96
7	FRONT FENDER BRACE - RHS	\$ 81.00	
8	FRONT WHEEL HOUSE LINER - RHS	\$ 146.00	
9	FRONT WHEEL HOUSE LINER ATTACHEMENT - RHS	\$ 75.00	
10	FRONT ALUMINIUM RIM - RHS	\$ 559.00	\$ 447.20
11	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		\$ 3,681.00	\$ 2,290.96
GRAND TOTAL SPARE PARTS		\$ 3,832.00	\$ 2,932.00
TOTAL LABOUR		\$ 7,513.00	\$ 5,222.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKN 3206 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1014/2017/MAS

11 Jan 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKN 3206 A, Audi A3 SB 1.4 TFSI

With reference to the above-mentioned vehicle, no **SKN 3206 A**, claimant, **Ms. Teo Yuan Ching**, please find the related document per attached.

1. A copy of the Original invoice no. 85012002 – S\$4,946.57
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKN 3206 A

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2017		17 Oct 2017 17:31 Edit Adj Rpt	S\$5,222.96 Edit Estimates	S\$5,222.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TEO YUAN CHING, ID: S7419766C, Tel: +6598589765, Email: NOEMAIL								
Vehicle Reg. No.:	SKN3206A		Date of Loss:	13/10/2017 07:00 - :59					
Claim Type:	OD / 5717444721SG		Policy/Cover Note No.:	2100374476 (Comprehensive)					
			Excess:	S\$600.00					
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/10/2017]								
Driver/Custodian:	TEO YUAN CHING (43 / Female), NRIC: S7419766C, Tel: +6598589765								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (20/10/2017): SKN3206A / OD / 13/10/2017 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN3206A (5717444721SG)
OD
Oct 13 2017 7:00AM
[TEO YUAN CHING]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
2	20/12/17 05:25	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
3	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
4	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
5	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
6	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
7	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
8	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
9	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
10	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
11	20/12/17 05:25	General View		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	19/10/17 12:06	Singapore Accident Statement		Load PDF			
2	19/10/17 12:06	Certificate of Insurance		Load PDF			
3	19/10/17 12:06	Drivers Driving License		Load PDF			
4	19/10/17 12:06	WORKSHOP ESTIMATE		Load PDF			
5	19/01/18 12:13	WORKSHOP INVOICE		Load PDF			
6	19/01/18 12:13	DISCHARGE VOUCHER		Load PDF			

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/17 13:25	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	13/10/17 13:22	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/10/17 13:18	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	13/10/17 13:18	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17019955/AQBN2

Date: 19/01/2018

REFERENCE

Insured/Claimant: TEO YUAN CHING Policy No: 2100374476
Date of Loss: 13/10/2017 Nature of Claim: OD Claim No: 5717444721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKN3206A
Make & Model: AUDI A3 SPORTBACK, 1.4 TFSI (A) Engine No: CXS071608
Reg. Date: 29/05/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V4EA130704
Colour: Grey Odometer: 35290 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$118,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,681.00	2,290.96	1,390.04	37.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,832.00	2,932.00	900.00	23.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,513.00	5,222.96	2,290.04	30.48
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,913.00	4,622.96	2,290.04	33.13
+ GST 7.00/7.00% (S\$)	483.91	323.61	160.30	33.13
Nett Amount (S\$)	7,396.91	4,946.57	2,450.34	33.13

INSPECTION

Date of Assignment: 17/10/2017

Date Inspected: 17/10/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,546.00 FS	*1,236.80 FS
2	1	*FRONT BUMPER GUIDE-RHS	Not Necessary	51.00 FS	*- FS
3	1	*FRONT FENDER-RHS	Dented	708.00 FS	*566.00 FS
4	1	*FRONT FENDER INNER BRACKET-RHS	Not Necessary	40.00 FS	*- FS
5	1	*FRONT FENDER OUTER BRACKET-RHS	Not Necessary	23.00 FS	*- FS
6	1	*FRONT FENDER CLOSING ELEMENT-RHS	Bent	52.00 FS	*40.96 FS
7	1	*FRONT FENDER BRACE-RHS	Not Necessary	81.00 FS	*- FS
8	1	*FRONT WHEEL HOUSE LINER-RHS	Not Necessary	146.00 FS	*- FS
9	1	*FRONT WHEEL HOUSE LINER ATTACHMENT-RHS	Not Necessary	75.00 FS	*- FS
10	1	*FRONT ALUMINIUM RIM-RHS	Cut	559.00 FS	*447.20 FS
11	1	*SUNDRIES	Not Necessary	400.00 FS	*- FS
Total Parts (S\$)				3,681.00	2,290.96

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,500.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			3,832.00	2,932.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >