

REC. BY:

REF:

CS/AWA17020055/Rhbz

Special Instruction:

Surveyor: RasuASSIGNMENT (Office)From (Person): Ben Tang of AWA Date/Time: 19.10.2017 459pm

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: ES 8813J Insured: FBH 5161Uat Workshop m/s Perfumanu Tel: 6319 0174of 303 Alexandra RdPolicy No: AVFmsB0000581702 Claim No: NSV1701167/SG

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 14.10.2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

24.10.2017 @ 11am owner awaiting

H.O.D. Endorsement:

Date/Time: 19.10.2017 5.12pm Person Contacted: Caroline Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>ES 8813J x</u>
	<u>FBH 5161U - x</u>
<u>26/3/2018</u>	<u>Part by Part \$3,948 (\$2488.85, 0.38%) Repair 5 days</u>
<u>26/3/2018</u>	<u>File pass to typist</u>





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17020055/R1gb

(SINGAPORE BRANCH)  
60 ANSON ROAD ,#08-01 (9th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 19-10-2017



Code : AWA

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBH 5161U	Veh. Inspected	ES 8813J
Policy No.	AVFMSB0000591702	Coverage (\$)	0.00
Claim No.	NSV1701167/SG	Excess (\$)	0.00
Assign From	BEN TANG	Assign Date	19/10/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	14/10/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Survey Department Check List (Case Handler)

Reference No. : CS/AWA17020055/R1  
 Policy Type: OD / (TP) TP RES / TL / EVA

Case Handler Rita Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are ACCURATE.

**(1) Office Assign Form**

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

**(2) System - (Views/Merimen)**

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

**(3) Workshop Estimate/Assignment Form**

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days


**(4) System - (Views/Merimen)**

- C Resurvey photo Uploaded

--	--	--	--

Check By: Rita 26/3/2018  
 Case Handler Date

**Catherine Chong (LKK Auto)**

---

**From:** Tang, Ben <Ben.Tang@awac.com> on behalf of Motorsurvey  
<Motorsurvey@awac.com>  
**Sent:** Thursday, 19 October, 2017 4:59 PM  
**To:** assignments@lkkauto.com  
**Cc:** 'SUR'; 'PBSP'  
**Subject:** TP Survey assignment for ES 8813J - DOA: 14/10/2017 Our ref: NSV1701167/SG

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Mohamad Taufikh / Mr Mohammed Rasul** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 <sup>rd</sup> Party Vehicle	:	ES 8813 J
Insured Vehicle	:	FBH 5161 U
Policy Number	:	AVFMSB0000591702
Name of Workshop	:	Performance Motors Limited
Contact Number	:	6319 0174
Person to Contact	:	Caroline
Estimated Cost of repairs	:	\$ 6,881.01

Regards,  
Claims Division

Copy to Performance Motors Limited via Email

Note -

- (X)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
  2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
  3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
  4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards  
Motor Claims  
Claims Group

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/10/2017 10:09
Date Of Accident	14/10/2017 12:10
Exact Location Of Accident	SLIP RD OFF EAST COAST RD (OPPOSITE SIGLAP CENTRE)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	ES8813J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM HOU-BOON
NRIC No	S7619659A
Email Address	LIMHOUBOON@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91827605
Alternative Phone No	OFFICE-91827605

### Vehicle Particulars

Manufacturer	BMW
Model	318I
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1941277
Cover Note Number	

### Driver

Name of Driver	LIM HOU-BOON
NRIC No	S7619659A
Date Of Birth	06/07/1976
Occupation	INDOOR
Date Of Driving Pass	08/06/1996
Driving Experience	21 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91827605
Fax Number	
Contact Number	OFFICE-91827605
Email Address	LIMHOUBOON@YAHOO.COM

Address	96B UPPER EAST COAST ROAD
Postcode	455234
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBH5161U
Vehicle Make/Model/Colour	RED MOTORCYCLE
Details Of Properties	MCDONALD DELIVERY
Name of Driver	GAO JIAN
NRIC/Passport Number	G8563644N
Contact Number	83932052/64494179 (MS LYN PHUA, MCDONALD BRANCH MANAGER)
Address	SIGLAP CENTRE MCDONALDS
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

#### Details of Witness

Name	
Phone Number	
Email Address	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Q: 16/01/17  
8:25 am  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**





Sketch Plan Pg. 2

Describe Circumstances of the Accident

My car (ES8813J) was reversing into a parallel parking lot.


Motorcycle (FBH 5161U) was riding against traffic on a one-way street. To avoid an ~~on~~ on-coming car, the motorcycle swerved into my parking lot while I was reversing.

My cars rear collided with the motorcycles rear, resulting in damage to my cars rear bumper and boot.


There were no visible damage to the motorcycle.

Declaration

We declare the foregoing particulars are true in every respect.

 16/10/17  
Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date

  
Witnessed by Reporting Centre

24.10.17 @ 11.00 am  
Survey only  
(waiting)

BMW Dealer

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

17 OCT 2017

Estimate No. : b1 44503  
Date Estimated : 17/10/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 2

### - ESTIMATE REPAIR FOR -

Lim Hou-Boon  
96B

Singapore 455234

### - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
ES8813J	A019954	29/05/2017	318iA/4Dr	0

### DESCRIPTION

To replace rear bumper, repair boot lid and attachments including knock out dent area cause by accident.

1700 2,550.00

Painting rear bumper and boot lid.

1868 2,076.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

Sundries.

rec? 80.00

Total Labour 1: 5,060.00

### DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT  
REAR BUMPER CENTRE GUIDE  
REAR BUMPER TOWING EYE COVER PRIMED  
GUIDE FOR BUMPER SIDE RH  
REAR BUMPER PANEL PRIMED (BASIS)  
SET MOUNTING PDC/PMA SENSOR REAR  
(DG) ADHESIVE SET K6

QTY	PRIC	VALUE
1	64.50	64.50
1	31.30	31.30
1	30.40	30.40
1	55.65	55.65
1	1,073.45	1,073.45
1	62.50	62.50
1	53.05	53.05

Total Parts : 1,370.85

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

**E S T I M A T E**

Estimate No. : b1 44503  
Date Estimated : 17/10/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
ES8813J	A019954	29/05/2017	318iA/4Dr	0

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

24/10/17 @ 1115  
Rasul  
900 10068

5 days

*[Signature]*  
25/10/17

6430.85

Labour 1	:	5,060.00
Parts	:	1,370.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	450.16
Grand Total	:	<b>6,881.01</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 44503  
Date Estimated : 17/10/2017  
Prepared By : Inthiran A/L Thurasamy

Page No. :

### REPAIR FOR -

Lim Hou-Boon  
96BUPPER EAST COAST ROAD

Singapore 455234

### - ACCOUNT - 705

Allied World Assurance Company, Ltd SG br  
60 Anson Road  
#09-01 Mapletree Anson  
Singapore 079914

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
ES8813J	A019954	29/05/2017	318iA/4Dr	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To make good the rear bumper, boot lid include removing attachments to facilitate repairs and knocking out dents caused by the accident	1700.00		1,700.00	✓
To spray paint rear bumper and boot lid	1868.00		1,868.00	✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	✓
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	✓
Sundries.	80.00		80.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

### # SUPPLEMENTARY ITEMS

Total Labour :	3,948.00
Total Parts :	0.00
Total Labour & Parts :	3,948.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,948.00
GST @7%:	276.36
Grand Total :	4,224.36

$$6430.85 - 3948.00 = 2488.85$$

$$2488.85 \div 6430.85 = 0.38\%$$




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD			Ref : CS/AWA17020055/R1ngbe2	
(SINGAPORE BRANCH) 60 ANSON ROAD ,#08-01 (9th FLOOR) MAPLETREE ANSON SINGAPORE 079914			 Date : 02-04-2018  Code : AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	FBH 5161U	Veh. Inspected	ES 8813J	
Policy No.	AVFMSB0000591702	Coverage (\$)	0.00	
Claim No.	NSV1701167/SG	Excess (\$)	0.00	
Assign From	BEN TANG	Assign Date	19/10/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	B.M.W. 318I LED NAV	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA8E32060A019954	Colour	WHITE	
Odometer	6715	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	DUNLOP	6 mm	
L/H Front Tyre	225/50 R17	DUNLOP	6 mm	
R/H Rear Tyre	225/50 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/50 R17	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/10/2017	Inspection Date	24/10/2017	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. ES 8813J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	RR BUMPER BOTTOM REINFORCEMENT (SN)	SERVICEABLE	64.50	-
1	REAR BUMPER CENTRE GUIDE (SN)	SERVICEABLE	31.30	-
1	REAR BUMPER TOWING EYE COVER PRIMED (SN)	SERVICEABLE	30.40	-
1	GUIDE FOR BUMPER SIDE RH (SN)	SERVICEABLE	55.65	-
1	REAR BUMPER PANEL PRIMED (BASIS) (SN)	TO REPAIR SEE LABOUR	1,073.45	-
1	SET MOUNTING PDC / PMA SENSOR REAR (SN)	SERVICEABLE	62.50	-
1	(DG) ADHESIVE SET K6 (SN)	SERVICEABLE	53.05	-
			1,450.85	80.00
<b>LABOUR</b>				
	TO REPLACE REAR BUMPER, REPAIR BOOT LID ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER PANEL PRIMED (BASIS).		2,550.00	1,700.00
	PAINTING REAR BUMPER AND BOOT LID.		2,076.00	1,868.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
			4,980.00	3,868.00
<b>GRAND TOTAL</b>			<b>6,430.85</b>	<b>3,948.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>3,948.00</b>
------------------------------------	--	--	-----------------

Report Ref No. CS/AWA17020055/R1ngbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.