

ASS. REC. BY:

REF:

REF: 03/MSG17020218/Gmb

Special Instruction:

Surveyor: GQ

main

From (Person): Muhammad Ashik

of

msu

Date/Time:

23-102017 1:24pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 4003T

Insured:

GZ 8119U

at Workshop m/s

CL Auto

Tel:

6795 6125 Peter

of

48 Ton Guan Rd East #02-125

9151 6839 - Vincent

Policy No:

AJ88 51638mKC

Claim No:

532521

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05-10-2017

CA / REV / REP. / REV 24 HRS WPI

25.10.2017 @ 12pm

H.O.D. Endorsement:

Date/Time

23.10.2017 2:46pm

Person Contacted:

Michael

Vehicle IN 1612

Date/Time	Action/Instruction (✓) Estimate
	3LA 403T x
	GZ 3119U x

REF. MSIG

ASSIGNMENT

From: Date 25/10/2017

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 4003 T

at Workshop m/s CL Auto

of 4870h Guan Rd East #02-125

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading:

Eng No:

C No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R. Bal.

L. Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Rear

R. Bal.

L. Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

26/10/17 REV preli in memmer.

17/11 Finalised \$3100 with Peter (Red. 6321.40, 67%)

RECEIVED

Date/Time File Pass to:

☐

: Preli. Report

☐

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee

Transportation

Fuel & Petrol

Phone

Other

TOTAL

Date/Time File Return to:

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Tech. Ins. \$

☐

Workshop \$

Report Format: TP

Lump Sum / I.B.I: \$3100

200
10
210

Survey Department Check List (Case Handler)

Reference No. : CE/MSG1702078/Emb.
Policy Type: OD / TP / RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Guo Qiang): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

Catherine | 18/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/20:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17020218/Ggb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 23-10-2017		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 8119U	Veh. Inspected	SLA 4003T	
Policy No.	A28851638MKC	Coverage (\$)	0.00	
Claim No.	532521	Excess (\$)	0.00	
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	23/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/10/2017	Inspection Date	25/10/2017	
Survey held at	C L AUTO PTE LTD 48 TOH GUAN ROAD EAST #02-127 ENTERPRISE HUP SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Oct 2017		23 Oct 2017 13:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]			
Insured:	PAPER FUSION PTE LTD, Co. Reg. No.: 200409300D				
Main Claimant:	PAN KIT KWANG, ID: S0896231F				
Vehicle Reg. No.:	SLA4003T	Date of Loss:	09/10/2017 18:00 - :59		
Claim Type:	TP / 532521	Policy/Cover Note No.:	A28851638MKC (Comprehensive) Coverage: 16/11/2016 - 15/11/2017		
Vehicle Reg. No. (Insured):	GZ8119U	Policy No. (Claimant):			
		Excess:			
Repairer:	C L Auto Pte Ltd (HQ) 48 Toh Guan Road East, #02-125 Enterprise Hub, 608586 Jurong East - Tel: 67956125				
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/10/2017]				
Driver/Custodian (Insured):	KOW ENG CHYE BERNARD (), NRIC: S1620284C, Tel: +6596875736				

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

<input type="checkbox"/> ALL ASSOCIATED TASKS									
<div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 26 Oct 2017

Preliminary Advice

Insured Vehicle No : GZ8119U

TP Vehicle No : SLA4003T

Accident Date : 09/10/2017

Make : HONDA VEZEL

Assignment Date : 23/10/2017

Date of Inspection : 25/10/2017

Est. Duration of Repair : 5.00

Inspection At : C L AUTO PTE LTD (HQ)

48 TOH GUAN ROAD EAST, #02-125 ENTERPRISE HUB
SINGAPORE 608586**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,421.44
Revised Amount	:S\$	3,887.84
Check Items (Estimated)	:S\$	1,756.96
Total	:S\$	5,644.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6231F

Vehicle Details

Vehicle No.: SLA4003T

Vehicle to be Exported: No

Intended De-registration Date: 18 Jan 2018

Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X CVT

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: L15B4027524

Chassis No.: RU11107522

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$19,068.00

Original Registration Date: 29 Feb 2016

First Registration Date: 29 Feb 2016

Transfer Count: 0

Actual ARF Paid: \$9,068.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Feb 2026

PARF Rebate Amount: \$6,801.00

Intended COE Rebate Details

COE Expiry Date: 28 Feb 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$37,848.00
Total Rebate Amount:	\$44,649.00

The information contained herein is correct as at 18 Jan 2018

OK

Enquire Transfer Fee

Vehicle Details

Vehicle No.	SLA4003T
Vehicle Type	P11 - Passenger Station Wagon/Jeep/Land Rover
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	HONDA
Vehicle Model	VEZEL 1.5X CVT
Chassis No.	RU11107522
Propellant	Petrol
Engine No.	L15B4027524
Engine Capacity	1496 cc
Maximum Power Output	96.0 kW (128 bhp)
Maximum Laden Weight	1465 kg
Unladen Weight	1190 kg
Year Of Manufacture	2015
Original Registration Date	29 Feb 2016
Lifespan Expiry Date	-
COE Category	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium	\$46,651.00
COE Expiry Date	28 Feb 2026
Road Tax Expiry Date	28 Feb 2018
PARF Eligibility Expiry Date	28 Feb 2026
Inspection Due Date	28 Feb 2019
Intended Transfer Date	26 Oct 2017
CO2 Emission	117.00 (g/km)
CEVS Rebate Utilised Amount	\$10,000.00

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

Amount Before GST
(S\$)

GST Amount
(S\$)

Amount After GST
(S\$)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2017 16:12
Date Of Accident	09/10/2017 18:30
Exact Location Of Accident	ALONG BUKIT BATOK EAST AVE 3 TOWARDS TOH TUCK AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA4003T
Insured/Policyholder	
Name Of Registered Owner	PAN KIT KWANG
NRIC No	S0896231F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96249716
Alternative Phone No	OTHERS-96249716

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number MTPV01003056

Cover Note Number

Driver

Name of Driver PAN KIT KWANG

NRIC No S0896231F

Date Of Birth 16/07/1951

Occupation INDOOR

Date Of Driving Pass 18/03/1988

Driving Experience 29 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96249716

Fax Number

Contact Number OTHERS-96249716

EMail Address NOEMAIL

Address	BLK 29 CHAI CHEE AVE #11-86
Postcode	460029
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO SKETCH PLAN & ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ8119U
Vehicle Make/Model/Colour	FIAT DOBLO
Details Of Properties	
Name of Driver	BERNARD KOW ENG CHYE
NRIC/Passport Number	S1620284C
Contact Number	96875736
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Sketch Plan Pg. 2

On the 09/10/2017 at about 1830hrs, I was driving my car no. SLA4003T and travelling on the leftmost lane along Bukit Batok East Ave 3 towards Toh Tuck Avenue. At the point of time, the traffic was heavy. After the bus stop ID 42319, a vehicle in front my car stopped due to red light and I slowed down and stopped at a safe distance. Out of a sudden, I felt an impact from behind which resulted in my car jerking forward. After which, I and the other driver stepped out of our cars and checked the damages. I saw a van no. GZ8119U (Fiat) had collided into the rear of my car. The rear bumper and rear boot cover of my car was dented and shifted. At the same time, the driver of GZ8119U apologized to me and offered to compensate my car repair cost. However, I felt that the repair will be costly. Hence, I rejected the offer and he furnished me with his particulars. The driver of GZ8119U was informed and he asked me to claim against his insurance policy.


Third Party Details :

Name : Bernard Kow Eng Chye

ID No. : S1620284C

Contact No. : +65-9687 5736

Third Party Insurance : MSIG Insurance (Singapore)



Refer to attached statement.

<p>You had been advised by the workshop that in the event that you wish to claim against your own policy (OD claim), there is a <u>Fourteen (14) days clause</u> whereby the claim must be made within the stipulated timeframe from the day of occurrence.</p>	<input type="checkbox"/>	Reporting Only
	<input type="checkbox"/>	Claim OD
	<input type="checkbox"/>	Claim TP
	<input checked="" type="checkbox"/>	Claim OD/TP at other workshop

	Reporting Only
	Claim OD
	Claim TP
✓	Claim <u>OD/TP</u> at other workshop

We declare the foregoing particulars are true in every respect.

10/10/17

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel



中英汽車(私人)有限公司 シーエルオート PTE LTD

CL AUTO PTE LTD

(ACRA No. 198800292M)

48 Toh Guan Road East, #02-125 / #02-127 Enterprise Hub, Singapore 608586

Website: www.clauto.com.sg

Email: ks@clauto.com.sg

Tel: 67956125

Fax: 67950920

M/S : MR.PAN KIT KWANG
29 CHAI CHEE AVE
#11-86
SINGAPORE 460029

ATTN: MR.PAN KIT KWANG

Your Ref No: SLA4003T
Claim Type: Third Party
Accident Date: 09/10/2017

Estimate No: EST1700188
Date: 10 Oct 2017
Policy No: MTPV01003056
Veh Reg No: SLA4003T
Make/Model: HONDA VEZEL 1.5X
CVT
Chassis No: RU11107522
Engine No: L15B4027522
Reg. Date: 29/02/2016
Payment Term: 30 DAYS

Estimate Repair Cost to Vehicle No :SLA4003T

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
Special Net:			
1 REAR NUMBER PLATE	1 PC	45.00 X	
2 REAR NUMBER PLATE HOLDER	1 PC	25.00 X	
3 REAR GLASS SEALANT	2 TUBE	48.00 /	
4 PRIMER & CLEANER	1 SET	60.00 /	
		178.00	178.00
List Price:			
5 REAR BOOT COVER	1 PC	1,100.90 /	
6 REAR BUMPER	1 PC	863.70 /	
7 REAR BUMPER LOWER GARNISH	1 PC	128.30 X	
8 REAR GLASS MOULDING	1 SET	140.00 /	
9 REAR BOOT LOCK	1 PC	180.00 /	
10 REAR BOOT LOCK CATCH	1 PC	35.00 X	
11 REAR BUMPER LOWER PANEL LH	1 PC	173.40 X	
12 REAR BUMPER LOWER PANEL RH	1 PC	173.40 X	
13 REAR END PANEL	1 PC	514.00 X	
14 REAR BOOT SPARE TOOLS SPONGE	1 PC	230.00 X	
15 REVERSE SENSOR	1 SET	270.00 /	
16 REAR END PANEL GARNISH	1 PC	98.00 X	
17 VEZEL EMBLEM	1 SET	56.20 /	
18 REAR INNER TAIL LAMP LH	1 PC	412.20 X	
19 REAR INNER TAIL LAMP RH	1 PC	412.20 X	
20 REAR BOOT INNER GARNISH	1 PC	220.00 X	
21 REAR REVERSE SENSOR	1 SET	350.00 X	
22 REAR GLASS RH SEAL	1 PC	35.00 X	
23 REAR GLASS LH SEAL	1 PC	35.00 X	
		5,429.30	
		20%: 2088.64	
		Less 20%	4,343.44

Labour Charges:

24 TO REMOVE & REFIX REAR GLASS	1 -	250.00	100.
25 TO REMOVE & TRANSFER REAR WIPER MOTOR, WIRE, TRIM BOAT, HANDLE, GARNISH & CHECK WATER LEAK AND VACCUM	1 -	300.00	60.
26 TO UNDERCOATING	1 -	450.00	60.
27 TO COATING PAINT	1 -	400.00	X NN
28 TO REMOVE & REPLACE REVERSE SENSOR & WIRING	1 -	280.00	60.
29 TO RESPRAY PAINT REAR BOOT COVER INNER (BLACK) & OUTER TO	1 -	580.00	200.



中英汽車(私人)有限公司 シーエルオート PTE LTD

C L AUTO PTE LTD

(ACRA No. 198800292M)

48 Toh Guan Road East, #02-125 / #02-127 Enterprise Hub, Singapore 608586

Website: www.clauto.com.sg

Email: ks@clauto.com.sg

Tel: 67956125

Fax: 67950920

M/S : MR.PAN KIT KWANG
29 CHAI CHEE AVE
#11-86
SINGAPORE 460029

ATTN: MR.PAN KIT KWANG

Your Ref No: SLA4003T
Claim Type: Third Party
Accident Date: 09/10/2017

Estimate No: EST1700188
Date: 10 Oct 2017
Policy No: MTPV01003056
Veh Reg No: SLA4003T
Make/Model: HONDA VEZEL 1.5X
CVT
Chassis No: RU11107522
Engine No: L15B4027522
Reg. Date: 29/02/2016
Payment Term: 30 DAYS

Estimate Repair Cost to Vehicle No :SLA4003T

Description	Quantity	List Price	Amount
		SS	SS
30 TO RESPRAY PAINT TOP SPOILER & TO POLISH	1 -	280.00	X 4 NN
31 TO RESPRAY PAINT REAR BOOT COVER CENTRE & OUTER GARNISH & POLISH	1 -	200.00	X NN
32 TO RESPRAY PAINT REAR BUMPER & TO POLISH	1 -	380.00	X NN
33 TO RESPRAY PAINT REAR LOWER PANEL, REAR RH & LH TAIL LAMP BASE, INNER & OUTER FLOOR BOARD & FLOOR BOARD SEALING	1 -	480.00	200 400
34 TO REMOVE REAR BOOT COVER, CUT & WELDING REAR LOWER PAD, KNOCKING FLOOR BOARD, ADJUST BOOT COVER, RH & LH TAIL BASE & REAR BUMPER	1 -	1,300.00	600 800
		4,900.00	1680
		Total	SS 9,421.44

TOTAL: SINGAPORE DOLLAR NINE THOUSAND FOUR HUNDRED TWENTY ONE AND CENTS FORTY FOUR ONLY

Lump Sum Repair.

After paint photos.

5 Days.

Guo Qiang - 82880282

25/10/17

For C L Auto Pte Ltd

876.64

20%: 3100

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2017		23 Oct 2017 13:24 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PAPER FUSION PTE LTD , Co. Reg. No.: 200409300D		
Main Claimant:	PAN KIT KWANG , ID: S0896231F		
Vehicle Reg. No.:	SLA4003T	Date of Loss:	09/10/2017 18:00 - :59
Claim Type:	TP / 532521	Policy/Cover Note No.:	A28851638MKC (Comprehensive) Coverage: 16/11/2016 - 15/11/2017
Vehicle Reg. No. (Insured):	GZ8119U	Policy No. (Claimant):	
		Excess:	
Repairer:	C L Auto Pte Ltd (HQ) 48 Toh Guan Road East, #02-125 Enterprise Hub, 608586 Jurong East - Tel: 67956125		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/11/2017]		
Driver/Custodian (Insured):	KOW ENG CHYE BERNARD (), NRIC: S1620284C, Tel: +6596875736		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLA4003T (532521)**
[GZ8119U]
TP
PAN KIT KWANG
Oct 9 2017 6:00PM
[PAPER FUSION PTE LTD]
C L Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	20/10/17 15:25	Accident Statement <small>From: SC - Reg. No: GZ8119U, Claimant: PAPER FUSION PTE LTD</small>	1 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	26/10/17 17:58	Adjuster Immediate Advice	1 Load HTM		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
2	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
3	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
4	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
5	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
6	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
7	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
8	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
9	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
10	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
11	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
12	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
13	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
14	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
15	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
16	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
17	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
18	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
19	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
20	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
21	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
22	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
23	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
24	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
25	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
26	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
27	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
28	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
29	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	
30	26/10/17 17:54	General View	1 Load JPG	<input checked="" type="checkbox"/>	

					<input checked="" type="checkbox"/>
31	26/10/17 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
32	26/10/17 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
33	26/10/17 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
34	26/10/17 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
35	26/10/17 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
36	26/10/17 17:54	General View		Load JPG	<input checked="" type="checkbox"/>
37	15/01/18 10:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	15/01/18 10:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	15/01/18 10:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	15/01/18 10:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	15/01/18 10:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	15/01/18 10:26	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/10/17 15:25	SLA4003T E-FILE, CERT OF INS, DL & IC From: SC - Reg. No: GZ8119U, Claimant: PAPER FUSION PTE LTD		Load PDF	
2	20/10/17 15:33	PRI from Chow Ng Partnership		Load PDF	
3	23/10/17 13:25	Survey Agree in SJE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; height: 40px; width: 100%;"></div> <div style="text-align: right;"> </div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020218/GGBE2

Date: 19/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28851638MKC
 Claimant Vehicle No: SLA4003T Insured Vehicle No: GZ8119U
 Date of Loss: 09/10/2017 Nature of Claim: TP Claim No: 532521

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA4003T
 Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4027524
 Reg. Date: 29/02/2016 (Man. Year: 2015) Chassis No: RU11107522
 Colour: Black Odometer: 36405 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,521.44	2,196.64	2,324.80	51.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,680.00	3,220.00	65.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,421.44	3,876.64	5,544.80	58.85
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	9,421.44	3,100.00	6,321.44	67.10

INSPECTION

Date of Assignment: 23/10/2017
 Date Inspected: 25/10/2017 Inspected At: C L Auto Pte Ltd (HQ)
 48 Toh Guan Road East, #02-125
 Enterprise Hub
 Singapore 608586
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2018)
Parts: M1-SUV HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLA4003T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
2	1		*REAR NUMBER PLATE HOLDER	Not Necessary	25.00 FS	*- FS
3	2		*REAR GLASS SEALANT	Necessary	48.00 FS	*48.00 FS
4	1		*SET PRIMER & CLEANER	Necessary	60.00 FS	*60.00 FS
5	1		*REAR BOOT COVER	Buckled	1,100.90 FL	*1,100.90 FL
6	1		*REAR BUMPER	Deformed	863.70 FL	*863.70 FL
7	1		*REAR BUMPER LOWER GARNISH	Not Necessary	128.30 FL	*- FL
8	1		*SET REAR GLASS MOULDING	Necessary	140.00 FL	*140.00 FL
9	1		*REAR BOOT LOCK	Bent	180.00 FL	*180.00 FL
10	1		*REAR BOOT LOCK CATCH	Not Necessary	35.00 FL	*- FL
11	1		*REAR BUMPER LOWER PANEL LH	Not Necessary	173.40 FL	*- FL
12	1		*REAR BUMPER LOWER PANEL RH	Not Necessary	173.40 FL	*- FL
13	1		*REAR END PANEL	Repair	514.00 FL	*- FL
14	1		*REAR BOOT SPARE TOOLS SPONGE	Not Necessary	230.00 FL	*- FL
15	1		*SET REVERSE SENSOR	Damaged	270.00 FL	*270.00 FL
16	1		*REAR END PANEL GARNISH	Not Necessary	98.00 FL	*- FL
17	1		*SET VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
18	1		*REAR INNER TAIL LAMP RH	Not Necessary	413.20 FL	*- FL
19	1		*REAR BOOT INNER GARNISH	Not Necessary	220.00 FL	*- FL
20	1		*SET REAR REVERSE SENSOR	Repeated	350.00 FL	*- FL
21	1		*REAR GLASS RH SEAL	Not Necessary	35.00 FL	*- FL
22	1		*REAR GLASS LH SEAL	Not Necessary	35.00 FL	*- FL
23	1		*REAR INNER TAIL LAMP LH	Not Necessary	413.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,607.30	2,718.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,085.86	522.16
Total Parts (\$\$)	4,521.44	2,196.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR GLASS	New	250.00	100.00
2	TO REMOVE & TRANSFER REAR WIPER MOTOR, WIRE, TRIM BOAT, HANDLE, GARNISH & CHECK WATER LEAK AND VACUUM	New	300.00	60.00
3	TO UNDERCOATING	New	450.00	60.00
4	TO COATING PAINT	New	400.00	0.00
5	TO REMOVE & REPLACE REVERSE SENSOR & WIRING	New	280.00	60.00
6	TO RESPRAY PAINT REAR BOOT COVER INNER (BLACK) & OUTER. TO POLISH REAR BOOT COVER OUTER	New	580.00	200.00
7	TO RESPRAY PAINT TOP SPOILER & TO POLISH	New	280.00	0.00
8	TO RESPRAY PAINT REAR BOOT COVER CENTRE & OUTER GARNISH & POLISH	New	200.00	0.00
9	TO RESPRAY PAINT REAR BUMPER & TO POLISH	New	380.00	0.00
10	TO RESPRAY PAINT REAR LOWER PANEL, REAR RH & LH TAIL LAMP BASE, INNER & OUTER FLOOR BOARD & FLOOR BOARD SEALING	New	480.00	400.00
11	TO REMOVE REAR BOOT COVER, CUT & WELDING REAR LOWER PAD, KNOCKING FLOOR BOARD, ADJUST BOOT COVER, RH & LH TAIL BASE & REAR BUMPER	New	1,300.00	800.00
Gross Labour Cost (\$\$)			4,900.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >