



彭陳汽車維修中心

PANG & TAN VEHICLE SERVICE CENTRE

160 Sin Ming Drive #04-03 Sin Ming AutoCity Singapore 575722

Tel: 6255 5811 Admin: 6255 5711 Fax: 6255 5700

Co. Reg. No.: 52851972K GST Reg. No.: M9-0354735-P

Page 1 / 3

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00
IOB BUILDING SINGAPORE 049711

Attention: Motor Claim Department

Contact: 63476100 Fax No.: 62244174

Estimate: ES000119

Date: 20/11/2017

Vehicle Num.: SJY9467C

Make/Model: VOLKSWAGEN

Chassis/Eng#:

Accident Date: 23/10/2017

Claim No.:

Reference: LCH.rj/SMPT-70849.17

Policy No.: 5081497613-01

Not Authorised

1/1/17 @ 7

Resurvey After Paint

16 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:				
1.	1PC	FRONT BUMPER		410.00
2.	1PC	FRONT BUMPER CLIPS		18.00
3.	2PCS	FRONT BUMPER SIDE RETAINER (LH/RH)		60.00
4.	1PC	FRONT BUMPER PROTECTOR		78.00
5.	2PCS	FRONT BUMPER CHROME MOULDING (LH/RH)		210.00
6.	1PC	FRONT BUMPER FOG LAMP		80.00
7.	1PC	FRONT BUMPER FOG LAMP GARNISH		70.00
8.	1PC	FRONT BUMPER LOWER LID		135.00
9.	1PC	FRONT GRILLE		180.00
10.	1PC	FRONT GRILLE LOGO		65.00
11.	1PC	FRONT GRILLE BASE		210.00
12.	1PC	FRONT GRILLE LOWER GRILLE		330.00
13.	1PC	HEADLAMP ASSY		240.00
14.	1PC	WIPER WASHER TANK		58.00
15.	1PC	WIPER WASHER TANK MOTOR		60.00
16.	1PC	FRONT FENDER		210.00
17.	1PC	FRONT FENDER INNER SHIELD		55.00
18.	1PC	FRONT FENDER INNER SHIELD CLIPS		21.00
19.	1PC	FRONT FENDER INNER PANEL		485.00
20.	1PC	FRONT DOOR PILLAR 'A'		785.00
21.	1PC	ROCKER PANEL LOWER SKIRTING		100.00
22.	1PC	ROCKER PANEL LOWER SKIRTING CLIPS		9.00
23.	1PC	FRONT DOOR		510.00
24.	1PC	FRONT DOOR GLASS CHROME MOULDING (BOTTOM)		85.00
25.	1PC	FRONT DOOR HINGE (TOP)		48.00
26.	1PC	FRONT DOOR HINGE (BOTTOM)		115.00
27.	1PC	FRONT DOOR CHECKER		58.00

CONTINUE / ...

LKK Auto Consultants hereby notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary details must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



彭陳汽車維修中心

PANG & TAN VEHICLE SERVICE CENTRE

180 Sin Ming Drive #04-03 Sin Ming AutoCity Singapore 575722

Tel: 6255 5811 Admin: 6255 5711 Fax: 6255 5700

Co. Reg. No.: 52851972K GST Reg. No.: M9-0364735-P

Page 2 / 3

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00
IOB BUILDING SINGAPORE 049711

Attention : Motor Claim Department

Contact : 63476100 Fax No. : 62244174

Estimate : ES000119

Date : 20/11/2017

Vehicle Num. : SJY9467C

Make/Model : VOLKSWAGEN

Chassis/Eng# :

Accident Date : 23/10/2017

Claim No. :

Reference : LCH.ry/SMPT-70849.17

Policy No. : 5081497613-01

S/N	Quantity	Particular	Unit Price	Amount S\$
28.	1PC	FRONT DOOR LOCK	DD	240.00 ✓
29.	1PC	FRONT DOOR LOCK CATCH	R	18.00 X
30.	1PC	FRONT DOOR WEATHERSTRIP	LT	122.00 ✓
31.	1PC	FRONT DOOR WEATHERSTRIP FRAME	SVC	450.00 X
32.	1PC	FRONT DOOR INNER TRIMBOARD	SVC	500.00 X
33.	1PC	FRONT DOOR INNER TRIMBOARD CLIPS	37 NN	18.00 X
34.	1PC	FRONT DOOR REGULATOR GEAR	IN	165.00 ✓
35.	1PC	FRONT DOOR REGULATOR MOTOR	IN	385.00 ✓
36.	1PC	FRONT DOOR GARNISH	SVC	125.00 X
37.	6PCS	FRONT DOOR GARNISH CLIPS	5.00 NN	30.00 X
38.	1PC	REAR DOOR	LT	590.00 ✓
39.	1PC	REAR DOOR CHROME MOULDING	SVC	125.00 X
40.	1PC	REAR DOOR LOCK	R	195.00 X
41.	1PC	REAR DOOR WEATHERSTRIP	SVC	122.00 X
42.	1PC	REAR DOOR TOP HINGE	R	58.00 X
43.	1PC	REAR DOOR BOTTOM HINGE	R	115.00 X
44.	1PC	REAR FENDER	LT	900.00 ✓
45.	1PC	REAR FENDER INNER SHIELD	DIT	110.00 ✓
46.	1PC	REAR FENDER INNER SHIELD CLIPS	IN	27.00 ✓
47.	1PC	REAR WINDSCREEN GLASS MOULDING	IN	123.00 ✓
48.	1PC	REAR WINDSCREEN GLASS SEALANT	IN	100.00 ✓
49.	1PC	REAR WINDSCREEN GLASS DAMPING SEAL	IN	58.00 3012
50.	1PC	ERP BRACKET	NN	23.00 X
51.	1PC	REAR BUMPER	0d/wap	440.00 ✓
52.	8PCS	REAR BUMPER CLIPS	5.00 IN	40.00 ✓
53.	2PCS	REAR BUMPER SIDE RETAINER (LH/RH)	cl/m	28.00 ✓
54.	1PC	FRONT WINDSCREEN GLASS MOULDING	NN	56.00 ✓
55.	1PC	FRONT WINDSCREEN GLASS SEALANT	NN	72.00 X
56.	1PC	FRONT WINDSCREEN DAMPING SEAL	NN	100.00 X
			NN	125.00 X

CONTINUE / ...



彭陳汽車維修中心

PANG & TAN VEHICLE SERVICE CENTRE

160 Sin Ming Drive #04-03 Sin Ming AutoCity Singapore 575722

Tel: 6255 5811 Admin: 6255 5711 Fax: 6255 5700

Co. Reg. No.: 52851972K GST Reg. No.: M9-0364735-P

Page 3 / 3

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET #05-00
IOB BUILDING SINGAPORE 049711

Attention: Motor Claim Department
Contact: 63476100 Fax No: 62244174

Estimate : ES000119

Date: 20/11/2017
Vehicle Num: SJY9467C
Make/Model: VOLKSWAGEN
Chassis/Eng#:
Accident Date: 23/10/2017
Claim No.:
Reference: LCH ry/SMPT-70849.17
Policy No: 5081497813-01

SN	Quantity	Particular	Unit Price	Amount S\$
----	----------	------------	------------	------------

57	1PC	FRONT ENGINE LOWER COVER
58	1PC	FRONT TYRE
59	1PC	FRONT RIM
60	1PC	FRONT SHOCK ABSORBER
61	1PC	FRONT SHOCK ABSORBER MOUNTING
62	1PC	FRONT SHOCK ABSORBER BEARING
63	1PC	FRONT LOWER ARM (RH)
64	1PC	FRONT LOWER ARM BALL JOINT
65	1PC	FRONT KNUCKLE ARM
66	1PC	FRONT KNUCKLE ARM BEARING
67	1PC	FRONT WHEEL BEARING HUB
68	1PC	FRONT TIE ROD
69	1PC	FRONT TIE ROD END
70	1PC	FRONT STABILIZER BAR LINKAGE
71	1PC	FRONT DRIVE SHAFT (RH)
72	1PC	STEERING RACK & PINION
73	1PC	STEERING CROSS MEMBER
74	1PC	REAR TYRE
75	1PC	REAR RIM

Unit Total S\$

LABOUR

TO REMOVE & REFIX FRONT DASHBOARD
TO REMOVE & REFIX FRONT & REAR WINDSCREEN GLASS
TO REMOVE & REFIX FRONT UNDERCARRIAGE
TO DISMANTLE & REPLACE DAMAGED PARTS/PANEL BEATING
TO RESPRAY PAINT ON AFFECTED PORTION

Labour Total S\$

135SN

CR1	78.00	✓
LT	225.00	60% SN
RD	650.00	✓
B1	140.00	✓
A1	52.00	✓
RA	20.00	✓
RA	140.00	✓
RA	65.00	✓
RA	250.00	✓
RA	195.00	✓
RA	235.00	✓
SVC	45.00	X
SVC	55.00	X
DIS	45.00	✓
BT	1 095.00	✓
SVC	1 900.00	X
SVC	850.00	X
SVC	225.00	X
RD	650.00	✓

17 033.00

NN

NN	250.00	X
NN	290.00	120%
NN	380.00	280%
NN	1 600.00	150%
NN	1 300.00	✓

3 810.00

E & O E

Total S\$

20 843.00



Michelle

for PANG & TAN VEHICLE SERVICE CENTRE