

ASS. REC BY

REF

CS/SMO17020306/Atbnz

Special Inspection

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person)

Irene Henry

SMO

Date/Time 24/10/2017 @ 11:05a.m

Estimated Cost

Bill by

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLH 5630 P

Insured

SKT 9797 P

at Workshop no/s

YSK Auto Workshop

Tel

9007 5148

at No. 1 Kaki Bkt Ave 6 # 01-71 Autobuy 417883

Policy No

Claim No

CMTD1703738 / NSW

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A. 21/10/2017

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement

Date/Time

24/10/17 @ 11:37a.m

Person Contacted

Ah chui

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLH 5630 P - NA / TMI 17020260 / h4 - D.O.A. : 21/10/2017

SKT 9797 P - NA / TMI 17020260 / h4 - D.O.A. : 21/10/2017

Lump Sum \$11,300/- (Red: 19070.64! 62%)

Surveyor:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLH 5630P Yr Regn: 2016

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV C.C. 1496

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: / T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRU 1830 GX200937

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 60 R16

R: 215 / 60 R16

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 24/10/17

Survey held at YSK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Samp.

RECEIVED 10 JAN 2017

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) 10/1 Typist
Date/Time, File Return to?

2) _____

Report Format :

Lump Sum / I.B.I: (\$ 11,300/-)

Days Of Repair: 10

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS, \$ SI

Photos

Others

TOTAL

450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|--------------------------|---|
| SOMPO INSURANCE SINGAPORE PL | | Ref : CS/SMO17020306/Atb | |
| 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623 | | Date : 24-10-2017 |  |
| | | Code : SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SKT 9797P | Veh. Inspected | SLH 5630P |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | CMTD1703738/NSW | Excess (\$) | 0.00 |
| Assign From | IRENE HENRY | Assign Date | 24/10/2017 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 21/10/2017 | Inspection Date | |
| Survey held at | Y S K AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | |

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17020306/Atb

Nivitha (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Tuesday, 24 October, 2017 11:05 AM
To: assignments
Cc: Admin-D (LKKAuto)
Subject: FW: ***SPAM*** RE: PRI
Attachments: PRI-24102017104256.pdf; PRI-Tenet -YSK.DOCX

Importance: High

Our Reference: CMTD1703738/NSW

Hi,

Kindly assign your motor surveyor, Mr Ma Chin Fook, to conduct motor survey of the mentioned (SLH 5630P).

Please refer to the email attachment as above.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: irene@centrollc.com.sg [mailto:irene@centrollc.com.sg]

Sent: Tuesday, 24 October, 2017 10:49 AM

To: Henry, Irene James <irene.henry@sompo.com.sg>

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>

Subject: RE: ***SPAM*** RE: PRI

Importance: High

WITHOUT PREJUDICE

Dear Sir/Madam,

Surveyor selected. Kindly refer to attached document.

To confirm we have selected surveyor Ma Chin Fook to do a direct settlement.

Please send your surveyor soon.

Thank you.

Regards,
Irene Seow

Centro-Legal Law Corporation Advocates & Solicitors

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel : 6235 0633
Fax : 6235 6939
Hp : 90301020

From: Henry, Irene James [mailto:irene.henry@sompo.com.sg]
Sent: Tuesday, 24 October 2017 10:42 AM
To: irene@centrollc.com.sg
Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>
Subject: ***SPAM*** RE: PRI

Our Reference: CMTD1703738/NSW
Your Reference: SLH 5630P

Date: 24TH October 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S CENTRO-LEGAL LAW CORPORATION

ACCIDENT INVOLVING SKT 9797P & SLH 5630P ON 21 OCTOBER 2017

Dear Sir

We refer to your Notice of Accident dated 24.10.2017.

Please be informed that Shawn Ngo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

| | Motor Surveyor | Surveyor | Selection (Indicate as tick) |
|---|----------------------------------|---------------------------|------------------------------|
| 1 | Raleigh Services | Andrew Ow Yong | |
| | | Vincent Ng | |
| 2 | LKK Auto Consultants | Kenneth Kong (North area) | |
| | | Marcus Chua (East area) | |
| | | Ma Chin Fook (North area) | |
| | | Mohd Rasul (West area) | |
| | | Mohd Taufikh (West area) | |
| 3 | Priority Services | Lawrence Ng | |
| | | Jeffery Ong | |
| 4 | JP Knights Adjusters & Surveyors | Jason Lek | |
| 5 | In House surveyor | Teo See Ling | |
| | | | |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: irene@centrollc.com.sg [mailto:irene@centrollc.com.sg]

Sent: Tuesday, 24 October, 2017 9:35 AM

To: Motor Survey <MotorSurvey@sompo.com.sg>

Subject: PRI

Importance: High

WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly refer to the above enclose document and arrange a PRI soon.

Thank you.

Regards,
Irene Seow

Centro-Legal Law Corporation Advocates & Solicitors

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel : 6235 0633
Fax : 6235 6939
Hp : 90301020

irene@centrolc.com.sg

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Tuesday, 24 October 2017 10:42 AM
To: irene@centrolc.com.sg
Cc: Ngo, Sau Wei Shawn
Subject: ***SPAM*** RE: PRI

Our Reference: CMTD1703738/NSW
Your Reference: SLH 5630P

Date: 24TH October 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S CENTRO-LEGAL LAW CORPORATION

ACCIDENT INVOLVING SKT 9797P & SLH 5630P ON 21 OCTOBER 2017

Dear Sir

We refer to your Notice of Accident dated 24.10.2017.

Please be informed that Shawn Ngo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

| | Motor Surveyor | Surveyor | Selection (Indicate as tick) |
|---|-----------------------|---------------------------|-------------------------------------|
| 1 | Raleigh Services | Andrew Ow Yong | |
| | | Vincent Ng | |
| 2 | LKK Auto Consultants | Kenneth Kong (North area) | |
| | | Marcus Chua (East area) | |
| | | Ma Chin Fook (North area) | ✓ |
| | | Mohd Rasul (West area) | |

151 Chin Swee Road

Singapore 169876

Tel: 6235 0633

Fax: 6235 6939

ADVOCATES AND SOLICITORS

Your ref : To be advised

Our ref : SLH5630P

24 OCTOBER 2017

SOMPO INSURANCE PTE LTD
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Fax: 6221 3147

BY FAX & HAND

Attn: **Officer-In-Charge**

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-
ACTION PROTOCOL FOR NIMA CASE**

We act for POH YOU LENG, the owner of motor vehicle **SLH5630P**, who has appointed us to act on his behalf to claim against your insured's vehicle no SKT9797P in regards to the road traffic accident on 21.10.2017.

Please be informed that the said motor vehicle can be inspected at:-

YSK AUTO WORKSHOP

No. 1 Kaki Bukit Ave 6
#01-71 AutoBay, Singapore 417883
Tel: 9007 5148 | Fax: 6556 0801
Email: dannyskyeo@gmail.com

Kindly contact **Ah Chai** h/p : 9007 5148

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

CENTRO-LEGAL LAW CORPORATION
Cc Ah Chai Fax: 6752 9868

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|-----------------------------|
| Date Of Report | 23/10/2017 17:24 |
| Date Of Accident | 21/10/2017 22:00 |
| Exact Location Of Accident | AMK AVE 6 JUNCTION OF AVE 3 |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SLH5630P |
| Insured/Policyholder | |
| Name Of Registered Owner | MR POH YOU LENG |
| NRIC No | S1560532D |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-97617361 |
| Alternative Phone No | OFFICE-97617361 |

Vehicle Particulars

| | |
|--|----------------|
| Manufacturer | HONDA |
| Model | HRV 1.5 LX CVT |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 16-MV010463-R00 |
| Cover Note Number | - |

Driver

| | |
|----------------------|----------------------|
| Name of Driver | MR POH YOU LENG |
| NRIC No | S1560532D |
| Date Of Birth | 10/07/1962 |
| Occupation | INDOOR |
| Date Of Driving Pass | 08/09/1980 |
| Driving Experience | 37 YEARS AND 1 MONTH |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-97617361 |
| Fax Number | |
| Contact Number | OFFICE-97617361 |
| Email Address | NOEMAIL |

| | |
|---|----------------------------------|
| Address | BLK 359A ADMIRALTY DRIVE #12-216 |
| Postcode | 751359 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|----------------------------|
| Type Of Accident | COLLISION - CROSS JUNCTION |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Was any body injured in the Accident? | YES |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 4 |

Details of Police Action

| | |
|---|---|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| Police Station Name | TRAFFIC POLICE DIVISION HQ |
| Police Station Address | ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE |
| Police Station Contact | TEL NO: 65470000 - FAX NO: |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

PLEASE REFER TO POLICE REPORT.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|----------|
| Vehicle Registration Number | SKT9797P |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

Details of Witness

| | |
|--------------|--|
| Name | |
| Phone Number | |

Email Address

DETAILS OF INJURED PERSON 1

Name POH YOU LENG
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SLH5630P
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name DONALD YIP KIAT SENG
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SLH5630P
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 3

Name CHUA MEOW KIANG
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SLH5630P
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 4

Name CHUA MEOW HUANG
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SLH5630P
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance?
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

IA 2LH5630P
B SK19791P

Accident Sketch Plan


Describe Circumstances of the Accident

Attach police report T/20171021/2181


Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20171021/2181

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20171021/2181

REPORT OF A TRAFFIC ACCIDENT

| | | | | | |
|--|------------|--|------------------------------|----------------------------|--|
| Date/Time Report Made: 21/10/2017 23:55 | | Vide Report No.: | | Station Diary No.: | |
| Informant's Particulars | | | | | |
| Name of Informant: POH YOU LENG | | Address: 359A ADMIRALTY DRIVE #12-216 HDB-SEMBAWANG SINGAPORE 751359 | | | |
| ID Type / ID No. NRIC NO / S1560532D | | Contact No.: | | Mobile: 97617361 | |
| Nationality: SINGAPORE CITIZEN | | Email: | | | |
| Sex: Male | Age: 55 | Date of Birth: 10/07/1962 | Type of Informant: Driver | | |
| Race: Chinese | | Language: English | | Institution / School Name: | |
| Occupation: SELF-EMPLOYED | | Driving Licence Information: Class: 3 | | Date of Expiry: | |

General Information of the Accident

| | | | | |
|--|---------------------------------|------------------------------------|---|---|
| Type of Accident: | Injury Conveyed By Ambulance | Drink Drive: No | Date/Time of Accident: 21/10/2017 22:00 | Type of Location: X-Junction |
| Location: ANG MO KIO AVENUE 6 ANG MO KIO AVE 6 JUNCTION OF AVE 3 | | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: |
| Traffic Flow: Dual Carriage Way | | Traffic Control: Not Controlled | | Traffic Volume: Moderate |
| Type of Collision: | | | | Anyone conveyed by ambulance: Yes |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|-------|-------------------|--------|---------------------|-----------------|
| SKT9797P | Car | | | | Slightly Damaged | 0 |
| SLH5630P | Car | HONDA | HRV 1.5 LX CVT | Silver | Slightly Damaged | 3 |

Details of Vehicle Insurance

| Vehicle No. | Insurance Company | Insurance No | Effective | Expiry Date |
|-------------|--|--------------|------------|-------------|
| SLH5630P | TOKIO MARINE INSURANCE SINGAPORE LTD. | MV010463 | 09/11/2016 | 08/11/2018 |

POLICE REPORT



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No. 65470000



T/20171021/2181

2 of 3

Report No. T/20171021/2181

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE MENTIONED DATE, TIME AND LOCATION

I(SLH5630P) WAS TRAVELLING ALONG ANG MO KIO AVE 6 TOWARDS YISHUN. THE TRAFFIC LIGHT WAS GREEN AND WAS IN MY FAVOUR WHEN I AM APPROACHING THE JUNCTION OF ANG MO KIO AVE 6 JUNCTION OF AVE 3. THEREFORE I CONTINUE DRIVING AHEAD. HOWEVER AFTER MY VEHICLE HAD SLIGHTLY WENT-PASS THE JUNCTION, SUDDENLY A VEHICLE(SKT9797P) FROM THE OPPOSITE-SIDE OF THE ROAD WENT ON TO TURN-RIGHT INTO ANG MO KIO AVE 3. THIS RESULTED IN THE FRONT OF MY VEHICLE HITTING ON TO THE LEFT-SIDE OF SKT9797P. AFTER THAT THE DRIVER OF SKT9797P CONTINUED DRIVING AHEAD, AND HE WAS SPOTTED BY WITNESS COMING OUT OF VEHICLE AHEAD OF THE ROAD TO INSPECT FOR DAMAGES ON HIS CAR BEFORE DRIVING OFF AGAIN. THE ACCIDENT RESULTED IN 2 OF MY PASSENGERS CONVEYED TO THE HOSPITAL. I THEN CALLED THE POLICE, AND I WAS TOLD TO HEAD DOWN TO TPHQ FOR INVESTIGATION. THAT'S ALL.

POLICE REPORT



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171021/2181

3 of 3

Report No. T/20171021/2181

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
KEVAN ANG ZI SHENG

Signature Of Interpreter:
Not applicable


Officer In Charge Of Case:
TP / GIT /
Insp NORHIDAWATI BINTE AHMAD
Contact No.: 65476310

Authentication Stamp
NP188

Signature Of Informant:

Date/Time:
21/10/2017 23:55

Classification Of Case:



ESTIMATE

YSK Auto Workshop

No. 1 Kaki Bukit Avenue 6, #01-49 Autobay

Singapore 417883

Date 25/10/2017

TP Sampa

Vehicle Number : SLH5630P

Make/Model : HONDA HRV

Chassis : JHMRU1830GX200937

Drive

| No. | Parts Descriptions | Qty | Unit Price | Amount |
|-----|---|-----|------------|-------------------|
| 1 | Bonnet <i>Repair</i> | 1 | \$992.30 | \$992.30 ✓ |
| 2 | Bonnet lock <i>3 new</i> | 1 | \$117.70 | \$117.70 ✓ |
| 3 | Bonnet hinges | 2 | \$71.50 | \$143.00 ✓ |
| 4 | Front bumper <i>Distorted</i> | 1 | \$559.80 | \$559.80 ✓ |
| 5 | Front bumper clip <i>new</i> | 10 | \$5.00 | \$50.00 <i>30</i> |
| 6 | Front bumper lower lid <i>Repld</i> | 1 | \$295.60 | \$295.60 ✓ |
| 7 | Front bumper lower trim <i>new</i> | 1 | \$106.80 | \$106.80 ✓ |
| 8 | Front bumper side retainer RH <i>new</i> | 1 | \$24.40 | \$24.40 ✓ |
| 9 | Front bumper side retainer LH <i>new</i> | 1 | \$24.40 | \$24.40 ✓ |
| 10 | Front bumper reinforcement <i>Best</i> | 1 | \$286.60 | \$286.60 ✓ |
| 11 | Front bumper reinforcement bracket RH <i>3 new</i> | 1 | \$31.80 | \$31.80 ✓ |
| 12 | Front bumper reinforcement bracket LH <i>3 new</i> | 1 | \$31.80 | \$31.80 ✓ |
| 13 | Front bumper lower grille <i>missing</i> | 1 | \$77.50 | \$77.50 ✓ |
| 14 | Front grille base <i>cracked</i> | 1 | \$381.80 | \$381.80 ✓ |
| 15 | Front grille chrome <i>new</i> | 1 | \$75.00 | \$75.00 ✓ |
| 16 | Front grille garnish <i>new</i> | 1 | \$385.00 | \$385.00 ✓ |
| 17 | Front grille garnish "Honda" logo <i>new</i> | 1 | \$28.40 | \$28.40 ✓ |
| 18 | Front grille centre upper beam <i>new</i> | 1 | \$88.70 | \$88.70 ✓ |
| 19 | Front grille clip <i>new</i> | 10 | \$5.00 | \$50.00 <i>15</i> |
| 20 | Headlamp RH <i>cracked</i> | 1 | \$1,854.50 | \$1,854.50 ✓ |
| 21 | Headlamp LH <i>new</i> | 1 | \$1,854.50 | \$1,854.50 ✓ |
| 22 | Headlamp lower bracket RH <i>new</i> | 1 | \$35.00 | \$35.00 ✓ |
| 23 | Headlamp lower bracket LH <i>cracked</i> | 1 | \$35.00 | \$35.00 ✓ |
| 24 | Headlamp upper side grille RH <i>new</i> | 1 | \$29.60 | \$29.60 ✓ |
| 25 | Headlamp upper side grille LH <i>new</i> | 1 | \$29.60 | \$29.60 ✓ |
| 26 | Fog lamp RH <i>missing</i> | 1 | \$387.70 | \$387.70 ✓ |
| 27 | Fog lamp LH <i>missing</i> | 1 | \$387.70 | \$387.70 ✓ |
| 28 | Fog lamp garnish RH <i>missing</i> | 1 | \$75.00 | \$75.00 ✓ |
| 29 | Fog lamp garnish LH <i>missing</i> | 1 | \$75.00 | \$75.00 ✓ |
| 30 | Support panel <i>Distorted</i> | 1 | \$526.00 | \$526.00 ✓ |
| 31 | Support panel garnish <i>new</i> | 1 | \$81.60 | \$81.60 ✓ |
| 32 | Support panel garnish clip <i>new</i> | 8 | \$5.00 | \$40.00 ✓ |
| 33 | Front stay panel <i>new</i> | 1 | \$39.40 | \$39.40 ✓ |
| 34 | Front door LH <i>Repair</i> | 1 | \$897.50 | \$897.50 ✓ |
| 35 | Front fender LH <i>Buckled</i> | 1 | \$458.30 | \$458.30 ✓ |
| 36 | Front fender wheel arch LH <i>Repld</i> | 1 | \$172.10 | \$172.10 ✓ |
| 37 | Front fender weatherstrip LH <i>Inner Shield Deformed</i> | 1 | \$138.80 | \$138.80 ✓ |
| 38 | Front fender weatherstrip clip <i>Inner Shield new</i> | 10 | \$5.00 | \$50.00 <i>25</i> |
| 39 | Front wheelhouse panel LH <i>Repair</i> | 1 | \$655.00 | \$655.00 ✓ |
| 40 | Front wheelhouse panel extension - inner <i>Distorted</i> | 1 | \$142.50 | \$142.50 ✓ |
| 41 | Front wheelhouse panel extension - outer <i>Distorted</i> | 1 | \$110.20 | \$110.20 ✓ |
| 42 | Radiator <i>Best</i> | 1 | \$1,287.50 | \$1,287.50 ✓ |
| 43 | Radiator fan motor <i>new</i> | 1 | \$346.70 | \$346.70 ✓ |

ESTIMATE

YSK Auto Workshop

No. 1 Kaki Bukit Avenue 6, #01-49 Autobay

Singapore 417883

| No. | Parts Descriptions | Qty | Unit Price | Amount |
|-----|--|-----|------------|--------------|
| 44 | Radiator fan cowling <i>Not New</i> | 1 | \$156.00 | \$156.00 X |
| 45 | Air-con condenser <i>Best</i> | 1 | \$530.80 | \$530.80 ✓ |
| 46 | Air-con condenser fan motor <i>2 years</i> | 1 | \$340.10 | \$340.10 X |
| 47 | Air-con condenser fan cowling <i>2 years</i> | 1 | \$156.00 | \$156.00 X |
| 48 | Front chassis LH <i>Rear</i> | 1 | \$797.10 | \$797.10 X |
| 49 | Front air deflector RH <i>Not New</i> | 1 | \$61.60 | \$61.60 X |
| 50 | Front air deflector LH <i>Behind</i> | 1 | \$61.60 | \$61.60 ✓ |
| 51 | Horn <i>2 years</i> | 2 | \$48.50 | \$97.00 X |
| 52 | Air duct <i>2 years</i> | 1 | \$77.50 | \$77.50 X |
| 53 | Front absorber LH <i>Best</i> | 1 | \$444.70 | \$444.70 ✓ |
| 54 | Front knuckle arm LH <i>Best</i> | 1 | \$288.80 | \$288.80 ✓ |
| 55 | Front knuckle arm bearing LH <i>New</i> | 1 | \$185.50 | \$185.50 ✓ |
| 56 | Front lower arm LH <i>Best</i> | 1 | \$405.70 | \$405.70 ✓ |
| 57 | Front crossmember <i>Not New</i> | 1 | \$790.00 | \$790.00 X |
| 58 | Steering rack <i>Best</i> | 1 | \$1,272.40 | \$1,272.40 ✓ |
| 59 | Front stabilizer bar <i>Not New</i> | 1 | \$104.80 | \$104.80 X |
| 60 | Front driveshaft LH <i>New</i> | 1 | \$1,104.10 | \$1,104.10 X |
| 61 | Front tie rod LH <i>Broken</i> | 1 | \$98.70 | \$98.70 ✓ |
| 62 | Front tie rod end LH <i>Best</i> | 1 | \$81.80 | \$81.80 ✓ |
| 63 | Front linkage LH <i>Not New</i> | 1 | \$67.40 | \$67.40 X |
| 64 | Engine under cover <i>Behind</i> | 1 | \$106.80 | \$106.80 ✓ |
| 65 | Engine under cover RH <i>New</i> | 1 | \$76.50 | \$76.50 ✓ |
| 66 | Engine under cover LH <i>Behind</i> | 1 | \$76.50 | \$76.50 ✓ |
| 67 | Fuse box assy <i>Not New</i> | 1 | \$793.10 | \$793.10 X |
| 68 | Reasonator <i>Coiled</i> | 1 | \$807.00 | \$807.00 ✓ |
| 69 | Radar sensor <i>Not New</i> | 1 | \$5,897.00 | \$5,897.00 X |

\$28,338.30

Parts Less 20% \$5,667.66

Sub Total 1 \$22,670.64

Special Nett

| | | | | |
|---|--|---|--------------------|-------------------|
| 1 | Front tyre LH <i>2 years</i> | 1 | \$650.00 | \$650.00 X |
| 2 | Front sports rim LH | 1 | \$750.00 | \$750.00 X |
| 3 | Front number plate <i>2 years</i> | 1 | \$35.00 | \$35.00 25 |
| 4 | Front number plate casing <i>2 years</i> | 1 | \$35.00 | \$35.00 25 |
| 5 | Fog lamp cable RH <i>2 years</i> | 1 | \$150.00 | \$150.00 X |
| 6 | Fog lamp cable LH | 1 | \$150.00 | \$150.00 X |
| 7 | Coolant <i>New</i> | 1 | \$80.00 | \$80.00 40 |
| | | | Sub-Total 2 | \$1,850.00 |

Labour Charges

| | | | |
|---|---|------------|------|
| 1 | Panel beating, cut, weld, straighten and repair and replace damaged parts. | \$2,000.00 | 1300 |
| 2 | Anti-rust undercoat. | \$220.00 | 60 |
| 3 | To putty and spray paint the repaired and replaced parts, cleaning and sanding of surfaces, final polishing and waxing. | \$2,000.00 | 1000 |
| 4 | Check wiring. | \$250.00 | 50 |
| 5 | Check and align wheels with computerized wheel alignment. | \$120.00 | 80 |
| 6 | Remove and replace front support panel and front wheelhouse panel. | \$350.00 | X |

| No. | Parts Descriptions | Qty | Unit Price | Amount |
|-----|--------------------|-----|------------|--------|
|-----|--------------------|-----|------------|--------|

ESTIMATE

YSK Auto Workshop

No. 1 Kaki Bukit Avenue 6, #01-49 Autobay

Singapore 417883

| | | | |
|---|--|---------------|--------------------|
| 7 | Remove and replace damaged air-con condenser and to vacuum air-con system and charge up air-con gas. | \$280.00 | 60 |
| 8 | Remove and replace radiator and electric fans and to conduct pressure test. | \$280.00 | 60 |
| 9 | Remove and replace front undercarriage. | \$350.00 | 280 |
| | | Labour | \$5,850.00 |
| | | TOTALS | \$30,370.64 |

total 14113.44
+ 11.3K
10 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17020306/Atbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 15-01-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-----------------|----------------|------------|
| Insured Veh. | SKT 9797P | Veh. Inspected | SLH 5630P |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | CMTD1703738/NSW | Excess (\$) | 0.00 |
| Assign From | IRENE HENRY | Assign Date | 24/10/2017 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HONDA HRV | c.c | 1496 |
| Engine No. | HIDDEN | Year of Reg. | 2016 |
| Chassis No. | JHMRU1830GX200937 | Colour | SILVER |
| Odometer | - | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm |
| L/H Front Tyre | 215/60 R16 | DUNLOP | 6 mm |
| R/H Rear Tyre | 215/60 R16 | DUNLOP | 6 mm |
| L/H Rear Tyre | 215/60 R16 | DUNLOP | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|---|-----------------|------------|
| Accident Date | 21/10/2017 | Inspection Date | 24/10/2017 |
| Survey held at | Y S K AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883 | | |

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 5630P

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | BONNET | TO REPAIR SEE LABOUR | 992.30 | - |
| 1 | BONNET LOCK | NOT NECESSARY | 117.70 | - |
| 2 | BONNET HINGES @\$71.50 | NOT NECESSARY | 143.00 | - |
| 1 | FRONT BUMPER | DISTORTED | 559.80 | 559.80 |
| 10 | FRONT BUMPER CLIP @\$5.00 | NECESSARY | 50.00 | 30.00 |
| 1 | FRONT BUMPER LOWER LID | DEFORMED | 295.60 | 295.60 |
| 1 | FRONT BUMPER LOWER TRIM | NOT NECESSARY | 106.80 | - |
| 1 | FRONT BUMPER SIDE RETAINER RH | NECESSARY | 24.40 | 24.40 |
| 1 | FRONT BUMPER SIDE RETAINER LH | NECESSARY | 24.40 | 24.40 |
| 1 | FRONT BUMPER REINFORCEMENT | BENT | 286.60 | 286.60 |
| 1 | FRONT BUMPER REINFORCEMENT BRACKET RH | NOT NECESSARY | 31.80 | - |
| 1 | FRONT BUMPER REINFORCEMENT BRACKET LH | NOT NECESSARY | 31.80 | - |
| 1 | FRONT BUMPER LOWER GRILLE | MISSING | 77.50 | 77.50 |
| 1 | FRONT GRILLE BASE | CRACKED | 381.80 | 381.80 |
| 1 | FRONT GRILLE CHROME | NOT NECESSARY | 75.00 | - |
| 1 | FRONT GRILLE GARNISH | CUT | 385.00 | 385.00 |
| 1 | FRONT GRILLE GARNISH "HONDA" LOGO | NECESSARY | 28.40 | 28.40 |
| 1 | FRONT GRILLE CENTRE UPPER BEAM | NOT NECESSARY | 88.70 | - |
| 10 | FRONT GRILLE CLIP @\$5.00 | NECESSARY | 50.00 | 15.00 |
| 1 | HEADLAMP RH | CRACKED | 1,854.50 | 1,854.50 |
| 1 | HEADLAMP LH | CUT | 1,854.50 | 1,854.50 |
| 1 | HEADLAMP LOWER BRACKET RH | NOT NECESSARY | 35.00 | - |
| 1 | HEADLAMP LOWER BRACKET LH | CRACKED | 35.00 | 35.00 |
| 1 | HEADLAMP UPPER SIDE GRILLE RH | NOT NECESSARY | 29.60 | - |
| 1 | HEADLAMP UPPER SIDE GRILLE LH | NOT NECESSARY | 29.60 | - |
| 1 | FOG LAMP RH | MISSING | 387.70 | 387.70 |
| 1 | FOG LAMP LH | MISSING | 387.70 | 387.70 |
| 1 | FOG LAMP GARNISH RH | MISSING | 75.00 | 75.00 |
| 1 | FOG LAMP GARNISH LH | MISSING | 75.00 | 75.00 |
| 1 | SUPPORT PANEL | DISTORTED | 526.00 | 526.00 |
| 1 | SUPPORT PANEL GARNISH | NOT NECESSARY | 81.60 | - |
| 8 | SUPPORT PANEL GARNISH CLIP @\$5.00 | NOT NECESSARY | 40.00 | - |
| 1 | FRONT STAY PANEL | NOT NECESSARY | 39.40 | - |

Report Ref No. CS/SMO17020306/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| 1 | FRONT DOOR LH | TO REPAIR SEE LABOUR | 897.50 | - |
| 1 | FRONT FENDER LH | BUCKLED | 458.30 | 458.30 |
| 1 | FRONT FENDER WHEEL ARCH LH | DEFORMED | 172.10 | 172.10 |
| 1 | FRONT FENDER INNER SHIELD LH | DEFORMED | 138.80 | 138.80 |
| 10 | FRONT FENDER INNER SHIELD CLIP @\$5.00 | NECESSARY | 50.00 | 25.00 |
| 1 | FRONT WHEELHOUSE PANEL LH | TO REPAIR SEE LABOUR | 655.00 | - |
| 1 | FRONT WHEELHOUSE PANEL EXTENSION-INNER | DISTORTED | 142.50 | 142.50 |
| 1 | FRONT WHEELHOUSE PANEL EXTENSION-OUTER | DISTORTED | 110.20 | 110.20 |
| 1 | RADIATOR | BENT | 1,287.50 | 1,287.50 |
| 1 | RADIATOR FAN MOTOR | NOT NECESSARY | 346.70 | - |
| 1 | RADIATOR FAN COWLING | NOT NECESSARY | 156.00 | - |
| 1 | AIR-CON CONDENSER | BENT | 530.80 | 530.80 |
| 1 | AIR-CON CONDENSER FAN MOTOR | NOT NECESSARY | 340.10 | - |
| 1 | AIR-CON CONDENSER FAN COWLING | NOT NECESSARY | 156.00 | - |
| 1 | FRONT CHASSIS LH | TO REPAIR SEE LABOUR | 797.10 | - |
| 1 | FRONT AIR DEFLECTOR RH | NOT NECESSARY | 61.60 | - |
| 1 | FRONT AIR DEFLECTOR LH | DEFORMED | 61.60 | 61.60 |
| 2 | HORN @\$48.50 | NOT NECESSARY | 97.00 | - |
| 1 | AIR DUCT | NOT NECESSARY | 77.50 | - |
| 1 | FRONT ABSORBER LH | BENT | 444.70 | 444.70 |
| 1 | FRONT KNUCKLE ARM LH | BENT | 288.80 | 288.80 |
| 1 | FRONT KNUCKLE ARM BEARING LH | NECESSARY | 185.50 | 185.50 |
| 1 | FRONT LOWER ARM LH | BENT | 405.70 | 405.70 |
| 1 | FRONT CROSSMEMBER | NOT NECESSARY | 790.00 | - |
| 1 | STEERING RACK | BENT | 1,272.40 | 1,272.40 |
| 1 | FRONT STABILIZER BAR | NOT NECESSARY | 104.80 | - |
| 1 | FRONT DRIVESHAFT LH | NOT NECESSARY | 1,104.10 | - |
| 1 | FRONT TIE ROD LH | BROKEN | 98.70 | 98.70 |
| 1 | FRONT TIE ROD END LH | BENT | 81.80 | 81.80 |
| 1 | FRONT LINKAGE LH | NOT NECESSARY | 67.40 | - |
| 1 | ENGINE UNDER COVER | DEFORMED | 106.80 | 106.80 |
| 1 | ENGINE UNDER COVER RH | NOT NECESSARY | 76.50 | - |
| 1 | ENGINE UNDER COVER LH | DEFORMED | 76.50 | 76.50 |
| 1 | FUSE BOX ASSY | NOT NECESSARY | 793.10 | - |

Report Ref No. CS/SMO17020306/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|---------------|---------------------------|-------------------|
| 1 | REASONATOR | CRACKED | 807.00 | 807.00 |
| 1 | RADAR SENSOR | NOT NECESSARY | 5,897.00 | - |
| | LESS 20% DISCOUNT | | -5,667.66 | -2,799.72 |
| | | | 22,670.64 | 11,198.88 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | FRONT TYRE LH (SN) | NOT NECESSARY | 650.00 | - |
| 1 | FRONT SPORTS RIM LH (SN) | NOT NECESSARY | 750.00 | - |
| 1 | FRONT NUMBER PLATE (SN) | DAMAGED | 35.00 | 25.00 |
| 1 | FRONT NUMBER PLATE CASING (SN) | DAMAGED | 35.00 | 25.00 |
| 1 | FOG LAMP CABLE RH (SN) | NOT NECESSARY | 150.00 | - |
| 1 | FOG LAMP CABLE LH (SN) | NOT NECESSARY | 150.00 | - |
| 1 | COOLANT (SN) | NECESSARY | 80.00 | 40.00 |
| | | | 1,850.00 | 90.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING,CUT,WELD,STRAIGHTEN AND REPAIR AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF BONNET,FRONT DOOR LH,FRONT WHEELHOUSE PANEL LH AND FRONT CHASSIS LH. | | 2,000.00 | 1,300.00 |
| | ANTI-RUST UNDERCOAT. | | 220.00 | 60.00 |
| | TO PUTTY AND SPRAY PAINT THE REPAIRED AND REPLACED PARTS,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING. | | 2,000.00 | 1,000.00 |
| | CHECK WIRING. | | 250.00 | 50.00 |
| | CHECK AND ALIGN WHEELS WITH COMPUTERIZED WHEEL ALIGNMENT. | | 120.00 | 80.00 |
| | REMOVE AND REPLACE FRONT SUPPORT PANEL AND FRONT WHEELHOUSE PANEL. | NOT NECESSARY | 350.00 | - |
| | REMOVE AND REPLACE DAMAGED AIR-CON CONDENSER AND TO VACUUM AIR-CON SYSTEM AND CHARGE UP AIR-CON GAS. | | 280.00 | 60.00 |
| | REMOVE AND REPLACE RADIATOR AND ELECTRIC FANS AND TO CONDUCT PRESSURE TEST. | | 280.00 | 60.00 |
| | REMOVE AND REPLACE FRONT UNDERCARRIAGE. | | 350.00 | 280.00 |
| | - | | - | - |
| | - | | - | - |
| | - | | - | - |
| | | | 5,850.00 | 2,890.00 |
| | GRAND TOTAL | | 30,370.64 | 14,178.88 |

Report Ref No. CS/SMO17020306/Atbn2



| | | | |
|---|--|--|-----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 11,300.00 |
|---|--|--|-----------|

Report Ref No. CS/SMO17020306/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.