

SUB TOTAL PRICE \$ 4,533.03

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>HE m</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
2	BOOTLID SEALANT <i>HE m</i>	1	\$ 100.00	\$ 100.00 <i>+</i>
3	BOOTLID EMBLEM 'C&C' <i>m</i>	1	\$ 52.00	\$ 52.00 <i>36</i>
4	REAR BUMPER CLIP (SET) <i>HE m</i>	1	\$ 20.00	\$ 20.00 <i>-</i>
5	REAR BUMPER LOWER LID <i>Deland</i>	1	\$ 800.00	\$ 800.00 <i>600.</i>
6	TAIL LAMP CLIP (SET) <i>m</i>	1	\$ 25.00	\$ 25.00 <i>10.</i>
7	REAR END PANEL TOP GARNISH CLIPS (SET) <i>m</i>	1	\$ 20.00	\$ 20.00 <i>10</i>
8	REAR END PANEL INSULATION SEAL <i>NEU</i>	1	\$ 120.00	\$ 120.00 <i>60</i>
9	REAR FLOOR PANEL INSULATION SEAL <i>HE m</i>	1	\$ 120.00	\$ 120.00 <i>+</i>
10	REVERSE SENSOR <i>Penged</i>	1	\$ 220.00	\$ 220.00 <i>-</i>

956

TOTAL \$ 1,527.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	<i>800.</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>800.</i>	
3	TUFF COAT	\$ 180.00	<i>40</i>	
4	WIRING CHECK	\$ 150.00	<i>30</i>	
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	<i>50</i>	
6	TRANSFER BOOTLID MECHANISM	\$ 120.00	<i>X</i>	
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>	

TOTAL

\$3,690.00

1720

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,060.03
 TOTAL LABOUR COST : \$ 3,690.00
 TOTAL REPAIR COST : \$ 9,750.03

APPROVED DETAILS

SURVEYOR :
 CONTACT NO :
 PART BY PART / LUMP SUM :
 NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj

L/s 20/10/17.

L/s \$2.5K

Obdays.

total: 5585.88

L/s: 2.5K