

ASS. REC. BY

REF: CS/MSG17020339/Drb 9

Muimen

Mr. MA

ASSIGNMENT (Office)

Irene Tan

MSIG

Date/Time 24/10/17 @ 12:51pm

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLR 3213X

Insured: SFD 1882 Y

at Workshop n/s

EM-1 Auto

Tel: 6452 3298

of Blk 8 Sin Ming Ind Est Sec C, #01-68, 575643

Policy No. S27853248 SMF

Claim No. 533811

Sum Insured

Excess

Make of Veh:

(Client's Record)

D.O.A. 22/10/2017

CA / REV / REP. / REV 24 HRS

'wp'

Date/Time 24/10/17 @ 1:48pm

Person Contacted

Nicole

H.O.D. Endorsement

Vehicle IN OUT

Date/Time Action/Instruction (✓) Estimate

SLR 3213X - X

SFD 1882 Y - X

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or Ne

CA / REV / REP. / 24 HRS

'wp'

Vehicle: IN / OUT

Date:

Person Contacted:

TOYO / YOKO or

Front

R/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

22/10/2017

Rear

R/Bal.

8

mm

L/Bal.

8

mm

D.O.I.

24/10/2017

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/7

Continued LS \$4250/- with Nicole. (Red 3842, 10, 472)

RECEIVED 25 JUL 2018

25/7 Part prices check by Simon thru VIEROS system.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

\$ + RS \$

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$ 4250/-)

Celine Fong (LKKAuto)

From: Celine Fong (LKKAuto)
Sent: Thursday, 28 June 2018 3:05 PM
To: 'Chia Sin Muk'
Cc: SUR
Subject: RE: OUTSTANDING CASES

Dear Mr Chia,

WITHOUT PREJUDICE

PC 3065M - Offer Lump Sum \$7,550.00 @ 7 working days.

SJJ 9645J - Offer Lump Sum \$6,000.00 (repair limit) @ 7 working days

SLD 7443X - Offer Lump Sum \$12,650.00 @ 14 working days

SJZ 1933X - Offer Lump Sum \$5,700.00 @ 6 working days

SLR 3213X - Offer Lump Sum \$4,250.00 @ 6 working days

SKV 1013K - Offer Lump Sum \$6,000.00 @ 4 working days

Kindly confirmed.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chia Sin Muk [mailto:em1autopteltd@gmail.com]

Sent: Wednesday, 30 May 2018 5:57 PM

To: SUR <sur@lkkauto.com>

Subject: OUTSTANDING CASES

WITHOUT PREJUDICE

Dear Serene,

Please find the attached outstanding statement

Total 74 cases.

SGCARMART.COM
THE ONLY PLACE FOR SMART CAR BUYERSSGCARMART
APP DOWNLOAD

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS

**MYCARFORUM**
MARKETPLACE

Buy / Sell Parts & Accessories

> click here to visit now!

Username / Email Add
password
Login
Connect Sign Up New Account
Forgot Password

honda freed

Price Range

Depreciation

2017

Vehicle Type

Search

Advanced
Search

Home » Used Cars » Trust Motoring » Honda Freed Hybrid 1.5A G Honda Sensing

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.
Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale?
Click here to see all Auspicious Number!

Honda Freed Hybrid 1.5A G Honda Sensing

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details


Price	\$103,800
Depreciation	\$10,360 /yr View models with similar depreciation
Reg Date	01-Aug-2017 (9yrs 9mths 8days COE left)
Manufactured	2017
Mileage	-
Transmission	Auto
Engine Cap	1,496 cc
Curb Weight	1,430 kg
Fuel type	Petrol-Electric
Features	4 Cylinder In Line DOHC I-VTEC, 101kW (135Bhp), Sport Hybrid Intelligent Dual-Clutch Drive (I-DCD), ABS, Fuel Consumption Of 27.2km/L
Accessories	Honda Sensing, Lane Departure Alert, ECO Mode, Cruise Control, Audio/Bluetooth Function On Steering Wheel, Dual Power Sliding Doors
Description	Facelift Model, Low Fuel Consumption, Almost New Honda Hybrid With Honda Sensing. 10% Down Payment, 10 Years Repayment, In House Loan Or Balloon Scheme Available! Lowest Interest Rate In Town! Lowest Depreciation Ever! Make And Assemble In Japan. 3 Years Or 100000km Warranty! View To Appreciate. Call Now!
COE	\$50,110
OMV	\$26,183
ARF	\$5,000
Derog Value	\$52,734 as of today (change)
No. of Owners	1
Type of Veh	MPV
Category	PARF Car, Almost New Car, Premium Ad Car, Hybrid Cars
Availability	Available

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note



Seller Information

Company	Trust Motoring • dealer's pricelist • 22 vehs sold 44 vehs available
Address	15 Commonwealth Lane Lot 29 Search cars nearby this location
Location	Commonwealth Car Mall
Office No	64723025 / 64755332
Contact Person(s)	Goh 82986966 JC 98576607 Sy 93666621

Posted on: 22-Oct-2017 | Last Updated on: 22-Oct-2017

Tags: Honda Freed, Honda Freed Hybrid, Honda Freed Hybrid 1.5A G, Honda Freed Hybrid 1.5A G Honda Sensing, Honda Freed Hybrid 1.5A G Honda Sensing, Honda Freed Hybrid 1.5A G Honda Sensing

Compare

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number: **SLR 3213X**
 Vehicle Model: **HONDA FREED**
 Accident Date: **22.10.2017**
 Original Reg Date: **10.08.2017**

Date: **23.10.2017**
 Chassis: **GB71020803**
 TP INS. **MSIG**

ESTIMATE

1	1 pc	Tailgate	/		
2	1 pc	Tailgate Badge	/		
3	1 pc	Tailgate Emblem FREED	/		
4	1 pc	Tailgate Emblem HYBRID	/		
5	1 pc	Tailgate Pocket Handle	X		
6	1 pc	Tailgate Inner Trim	7		
7	1 set	Tailgate Inner Trim Clips	/		
8	1 pc	Tailgate Inner Lock	/		
9	1 pc	Tailgate Lock Catch	X		
10	1 pc	Tailgate Weatherstrip	/		
11	1 pc	Tailgate Windscreen Moulding	/		
12	1 pc	Tailgate Windscreen Inner Seal	/		
13	1 pc	Rear Bumper	/		
14	2 pcs	Rear Bumper Side Retainers	/		
15	2 pcs	Rear Bumper Attachment Retainers	/		
16	1 set	Rear Bumper Clips	/		
17	1 pc	End Panel	7		
18	1 pc	End Panel Top Trim	7		
19	1 set	End Panel Top Trim Clips	X		

Special Netts

1	1 pc	Rear Windscreen Sealant		60.00
2	1 set	Reverse Sensor		250.00
3	1 set	Body Panel Joint Sealant		120.00

Labour charge

Panel Beating		1,000.00
Spray painting		1,000.00
Check Wiring		50.00
Anti rust		100.00
Remove and install rear windscreen.		140.00
Remove and install tailgate parts		90.00
Remove and install carpet and seat		120.00
Remove and install reverse camera		150.00
Remove and install reverse sensor		90.00

1,490.20	60.00	600.00
62.00	220.00	600.00
68.00	80.00	30.00
68.00		60.00
		120.00
325.00		60.00
40.00		60.00
275.00		80.00
		60.00

Total List Price	\$	4,693.40
Discount		20%
List Price	\$	3,754.72
Total Nett Price	\$	-
Discount		20%
Nett Price	\$	-
Total Special Nett	\$	360.00
Total Labour	\$	1,670.00
Grand Total	\$	5,784.72
Discount 20%		20%
Lump Sum	\$	4,627.78

Columns	List Price
A	Nett Price
C	Special Nett
D	Labour
E	

File No
5126

Vehicle No.
SLR 3213X

Model
HONDA FREED

LOU 6 days

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number: SLR 3213X
Vehicle Model : HONDA FREED
Accident Date : 22.10.2017
Original Reg Date : 10.08.2017

Date : 23.10.2017
Chassis : GB71020803
TP INS. MSIG

ESTIMATE

1	1 pc	Tailgate	✓		1490.00
2	1 pc	Tailgate Badge	✓		62.00
3	1 pc	Tailgate Emblem FREED	✓		68.00
4	1 pc	Tailgate Emblem HYBRID	✓		68.00
5	1 pc	Tailgate Pocket Handle	X		50.50
6	1 pc	Tailgate Inner Trim	✓		325.00
7	1 set	Tailgate Inner Trim Clips	✓		40.00
8	1 pc	Tailgate Inner Lock	✓		275.00
9	1 pc	Tailgate Lock Catch	X		46.00
10	1 pc	Tailgate Weatherstrip	✓		198.00
11	1 pc	Tailgate Windscreen Moulding	✓		132.00
12	1 pc	Tailgate Windscreen Inner Seal	✓		60.00
13	1 pc	Rear Bumper	✓		1029.50
14	2 pcs	Rear Bumper Side Retainers	✓		104.00
15	2 pcs	Rear Bumper Attachment Retainers	✓		96.00
16	1 set	Rear Bumper Clips	✓		50.00
17	1 pc	End Panel	✓		636.00
18	1 pc	End Panel Top Trim	✓		139.00
19	1 set	End Panel Top Trim Clips	✓		30.00

X
CRA
X
X R
CRA
NEC

Special Netts

1	1 pc	Rear Windscreen Sealant	✓	60	60.00
2	1 set	Reverse Sensor	✓	220	250.00
3	1 set	Body Panel Joint Sealant	✓	90	120.00

✓ New
220 DM
90? Net

Labour charge

Panel Beating	600	1,000.00
Spray painting	600	1,000.00
Check Wiring	30	50.00
Anti rust	60	100.00
Remove and install rear windscreen.	120	140.00
Remove and install tailgate parts	60	90.00
Remove and install carpet and seat	60	120.00
Remove and install reverse camera	30	150.00
Remove and install reverse sensor	60	90.00

600
600
30
60
120
60
60
80
60

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2017		24 Oct 2017 12:51 Edit Adj Rpt	S\$4,250.00 Edit Estimates	S\$4,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHIA SENG POH, ID: S7225074E								
Main Claimant:	LEE YIM LING SINDY, ID: S1608428Z								
Vehicle Reg. No.:	SLR3213X	Date of Loss:	22/10/2017 11:00 - :59 [2 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 533811	Policy/Cover Note No.:	S27853248SMF (Comprehensive) Coverage: 07/03/2017 - 06/03/2018						
Vehicle Reg. No. (Insured):	SFD1882Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Em-1 Auto Pte Ltd (HQ) Blk 8 Sin Ming Industrial Estate Sector C, #01-68, 575643 Sin Ming - Tel: 64523298								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Imm.Advice due 25/10/2017]								
Driver/Custodian (Insured):	CHIA EMMA ROBERTSON (), NRIC: S6983243A								
Adj Asg. Remarks:	Please Assign surveyor Adrian Ling								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR3213X (533811)
[SFD1882Y]

TP

LEE YIM LING SINDY

Oct 22 2017 11:00AM

[CHIA SENG POH]

Em-1 Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	24/10/17 12:51	Accident Statement From: SC - Reg. No: SFD1882Y, Claimant: CHIA SENG POH	 Load HTM		
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/10/17 17:03	General View	 Load JPG	☒	
2	25/10/17 17:03	General View	 Load JPG	☒	
3	25/10/17 17:03	General View	 Load JPG	☒	
4	25/10/17 17:03	General View	 Load JPG	☒	
5	25/10/17 17:03	General View	 Load JPG	☒	
6	25/10/17 17:03	General View	 Load JPG	☒	
7	25/10/17 17:03	General View	 Load JPG	☒	
8	25/10/17 17:03	General View	 Load JPG	☒	
9	25/10/17 17:03	General View	 Load JPG	☒	
10	25/10/17 17:03	General View	 Load JPG	☒	
11	25/10/17 17:03	General View	 Load JPG	☒	
12	25/10/17 17:03	General View	 Load JPG	☒	
13	25/10/17 17:03	General View	 Load JPG	☒	
14	25/10/17 17:03	General View	 Load JPG	☒	
15	25/10/17 17:03	General View	 Load JPG	☒	
16	25/10/17 17:03	General View	 Load JPG	☒	
17	25/10/17 17:03	General View	 Load JPG	☒	
18	25/10/17 17:03	General View	 Load JPG	☒	
19	25/10/17 17:03	General View	 Load JPG	☒	
20	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
21	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
22	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
23	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
24	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
25	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
26	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
27	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
28	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
29	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
30	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
31	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
32	25/07/18 09:24	Photographs of Damaged Parts	 Load JPG	☒	
33	25/07/18 09:25	Photo After Spray	 Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	25/07/18 09:25	Photo After Spray	 Load JPG	☒
35	25/07/18 09:25	Photo After Spray	 Load JPG	☒
36	25/07/18 09:25	Photo After Spray	 Load JPG	☒
37	25/07/18 09:25	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/10/17 10:36	TP GIA Rep - SLR 3213X	 Load PDF	
2	24/10/17 10:37	Fax Frm Third Party	 Load PDF	
3	24/10/17 12:51	Email from TP	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020339/M1GBQ2

Date: 26/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: S27853248SMF

Claimant Vehicle No: SLR3213X

Insured Vehicle No: SFD1882Y

Date of Loss: 22/10/2017

Nature of Claim: TP

Claim No: 533811

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR3213X

Make & Model: HONDA FREED, 1.5 G (A)

Engine No: LEB5544771

Reg. Date: 10/08/2017 (Man. Year: 2017)

Chassis No: GB71020803

Colour: Black

Odometer: 7121 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Dunlop 8 mm

Rear Left Side: Dunlop 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,352.10	3,693.52	1,658.58	30.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,670.00	1,070.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,092.10	5,363.52	2,728.58	33.72
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	8,092.10	4,250.00	3,842.10	47.48
+ GST 7.00/7.00% (S\$)	566.45	297.50	268.95	47.48
Nett Amount (S\$)	8,658.55	4,547.50	4,111.05	47.48

INSPECTION

Date of Assignment: 24/10/2017

Date Inspected: 24/10/2017 Inspected At:

Em-1 Auto Pte Ltd (HQ)
Blk 8 Sin Ming Industrial Estate Sector C,
#01-68
Singapore 575643

Estimated Period of Repair: 6.0 days

Adjuster: MA CHIN FOOK**Manager:** LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jul 2018)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR3213X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,490.20 F	*1,490.20 FL
2	1		*TAILGATE BADGE	Necessary	62.00 F	*62.00 FL
3	1		*TAILGATE EMBLEM FREED	Necessary	68.00 F	*68.00 FL
4	1		*TAILGATE EMBLEM HYBRID	Necessary	68.00 F	*68.00 FL
5	1		*TAILGATE POCKET HANDLE	Serviceable	52.50 F	*- FL
6	1		*TAILGATE INNER TRIM	Cracked	325.00 F	*325.00 FL
7	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	40.00 F	*40.00 FL
8	1		*TAILGATE INNER LOCK	Bent	275.00 F	*275.00 FL
9	1		*TAILGATE LOCK CATCH	Serviceable	46.20 F	*- FL
10	1		*TAILGATE WEATHERSTRIP	Necessary	198.20 F	*198.20 FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	132.00 F	*132.00 FL
12	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 F	*60.00 FL
13	1		*REAR BUMPER	Deformed	1,029.50 F	*1,029.50 FL
14	2		*REAR BUMPER SIDE RETAINERS	Necessary	104.00 F	*104.00 FL
15	2		*REAR BUMPER ATTACHMENT RETAINERS	Necessary	96.00 F	*96.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*END PANEL	Repair	656.50 F	*- FL
18	1		*END PANEL TOP TRIM	Cracked	139.00 F	*139.00 FL
19	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 F	*30.00 FL
20	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
21	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*220.00 FS
22	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,352.10	4,526.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	833.38
Total Parts (\$\$)	5,352.10	3,693.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	600.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	100.00	60.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
7	REMOVE AND INSTALL CARPET AND SEAT	New	120.00	60.00
8	REMOVE AND INSTALL REVERSE CAMERA	New	150.00	80.00
9	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	60.00
Gross Labour Cost (\$\$)			2,740.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >