

REF:

REF:

CC3 / ALH17020454 / A16n2

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 999994958

Claims No. 081851620584

Sum Insured: _____ Excess: \$1200/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 1181C

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 88% days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKX8410R- Yr Regn: 2015 / Dec

Type: MCAR / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 C.C. 1395.

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 23346 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU228u16R047257.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R17.

R: 235/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Survey held at

Des. of Damages FR / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 25/10/17

Premium.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 A16

SKX 8410R - X

Part by Part \$4,819/- (Red: 1690; 25%)

RECEIVED 25 JAN 2013

Date/Time, File Pass to?

1) 001 Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: 200

Transportation: 10

S + RS SI

Photos

Others

TOTAL

210

Report Format: OD

Lump Sum / I/E: (\$ 4819)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17020454/Atb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 25-10-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKX 8410R
Policy No. 999994958	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	25/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/10/2017	Inspection Date	25/10/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8937840J



Name
CORERA BASIL VINODH
YUHENG

宇 恒

Race
INDIAN

Date of birth
30-10-1989 M

Country of birth
SINGAPORE

S8937840J

REPUBLIC OF SINGAPORE DRIVING LICENCE



Starkey Number S8937840J

NAME
CORERA BASIL VINODH
YUHENG

Birth Date 30 Oct 1989

Valid Date 19 Feb 2013



3647546

NRIC No. S8937840J



Date of issue
10-12-2004

Address


APT BLK 130 GEYLANG EAST AVENUE 1
#10-297
SINGAPORE 380130

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 19 Feb 2013

NP 428A



Licence No: S8937840J



HOTLINE TEL (65) 6419-3000
FAX (65) 6419-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

MZ402

COMPREHENSIVE COMMERCIAL MOTOR

CERTIFICATE NO. 999994958/100781659-00000

OWN DAMAGE EXCESS S\$1,200.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED S\$1.00

INSURING WITH COE/PARF YES

1) VEHICLE REGISTRATION NO.

SKX8410R

2) NAME OF INSURED

Premium Leasing Pte Ltd

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

21 Jul 2017

4) DATE OF EXPIRY OF INSURANCE

20 Jul 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

Any person who is driving on the Insured's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle

6) LIMITATION AS TO USE *

Use for the carriage of passengers or goods in connection with the Insured's business.
Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.
The Policy does not cover

- 1) Use for racing, pace-making, reliability trial or speed-testing
- 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.
- 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired

LOSS OF USE NOT INCLUDED

* NAMED DRIVER N/A

HIRE PURCHASE COMPANY MayBank

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued At Singapore 6 Sep 2017

AIG ASIA PACIFIC INSURANCE PTE. LTD.

504108-222
PREMIUM AUTOMOBILES PTE LTD
55 UBI ROAD 1
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 408699

Authorised Representative

ORIGINAL

SSPKYH

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1042/2017/PH
Date	:	21-Oct-17

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	M/S Premium Leasing Pte Ltd
Address	:	9 Leng Kee Road Singapore 159090
Telephone	:	(hp) 91113330- Corera
Type of Claim	:	Own Damage Claims
Policy No.	:	999994958/100781659-00000
Vehicle No	:	SKX 8410 R
Model Code	:	Audi Q3 1.4 TFSI
Model / Year	:	Dec-15
Engine No	:	CZD218521
Chassis No	:	WAUZZZ8U1GR047257
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Oct-17
Place of Accident	:	CTE highway (exit before PIE)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 8410 R.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 480.00 ✓	✓
2	To remove front fittings, remove & reinstall front bumper. Renew radiator grille, re-organise frontal crash management components. Reinstall all parts removed. Renew both wheel arc trim.	\$ 900.00 500 ✓	✓
3	To respray paint front bumper and both wheel arc trim-code SD6	\$ 800.00 ✓	✓
5	To carry out diagnostic check.	S.N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,372.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 8410 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>deformed</i>	\$ 1,630.00	✓ 1304
2	GRILLE <i>Not Nec</i>	\$ 180.00	? X
3	RADIATOR GRILLE <i>crushed</i>	\$ 993.00	✓ 794
4	WHEEL COVER - LH FRONT <i>3 new</i>	\$ 453.00	✓ 362
5	WHEEL COVER - RH FRONT	\$ 453.00	✓ 362
6	STRIKER PLATE <i>Not Nec</i>	\$ 103.00	? X
7	FRONT NO PLATE <i>Best</i>	S/N \$ 25.00	✓ ✓
8	SUNDRIES <i>Not Nec</i>	\$ 300.00	? X
TOTAL SPARE PARTS		: \$ 4,137.00	
TOTAL LABOUR CHARGE		: \$ 2,372.00	
GRAND TOTAL		: <u>\$ 6,509.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 25/10/17
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised repairs, 03 Days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1042/2017/PH
Date	:	21-Oct-17

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

3 days - ok - jb - 12 Dec

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	M/S Premium Leasing Pte Ltd
Address	:	9 Leng Kee Road Singapore 159090
Telephone	:	(hp) 91113330- Corera
Type of Claim	:	Own Damage Claims
Policy No.	:	999994958/100781659-00000
Vehicle No	:	SKX 8410 R
Model Code	:	Audi Q3 1.4 TFSI
Model / Year	:	Dec-15
Engine No	:	CZD218521
Chassis No	:	WAUZZZ8U1GR047257
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	19-Oct-17
Place of Accident	:	CTE highway (exit before PIE)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 8410 R.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	480.00	\$ 480.00
2	To remove front fittings, remove & reinstall front bumper. Renew radiator grille, re-organise frontal crash management components. Reinstall all parts removed. Renew both wheel arc trim.	\$	900.00	\$ 500.00
3	To respray paint front bumper and both wheel arc trim-code SD6	\$	800.00	\$ 800.00
5	To carry out diagnostic check.	S.N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 2,372.00</u>	<u>\$ 1,972.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKX 8410 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,630.00	\$ 1,304.00
2	GRILLE	\$ 180.00	
3	RADIATOR GRILLE	\$ 993.00	\$ 794.00
4	WHEEL COVER - LH FRONT	\$ 453.00	\$ 362.00
5	WHEEL COVER - RH FRONT	\$ 453.00	\$ 362.00
6	STRIKER PLATE	\$ 103.00	
7	FRONT NO PLATE	S/N \$ 25.00	\$ 25.00
8	SUNDRIES	\$ 300.00	
	TOTAL SPARE PARTS	\$ 4,137.00	\$ 2,847.00
	TOTAL LABOUR CHARGE	\$ 2,372.00	\$ 1,972.00
	GRAND TOTAL	\$ 6,509.00	\$ 4,819.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKX 8410 R

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1042/2017/MAS

19 Jan 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKX 8410 R, Audi Q3 1.4 TFSI S-TRO

With reference to the above-mentioned vehicle, no **SKX 8410 R**, claimant, **Premium Leasing Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85012018- S\$3,872.33
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG - SKX 8410 R

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	25 Oct 2017		25 Oct 2017 16:50 Edit Adj Rpt	S\$4,819.00 Edit Estimates	S\$4,819.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured:	PREMIUM LEASING PTE LTD, Co. Reg. No.: 2001009676M																							
Vehicle Reg. No.:	SKX8410R	Date of Loss:	19/10/2017 19:00 - :59																					
Claim Type:	OD / 0818516205SG	Policy/Cover Note No.:	999994958 (Comprehensive) Coverage: 21/07/2017 - 20/07/2018																					
		Excess:	S\$1,200.00																					
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911																							
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/11/2017]																							
Driver/Custodian:	CORERA BASIL VINODH YUHENG (27 / Male), NRIC: S8937840J, Tel: +6591113330																							
View All Compose Case Mail																								
ASSOCIATED MAIL RECEIVED																								
• AIG_SG (26/10/2017): SKX8410R / OD / 19/10/2017 / Coverage & Excess update																								
ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SKX8410R (0818516205SG)
OD
Oct 19 2017 7:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
Photos/Images												3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	25/01/18 12:03	General View											Load JPG	☒			
2	25/01/18 12:03	General View											Load JPG	☒			
3	25/01/18 12:03	General View											Load JPG	☒			
4	25/01/18 12:03	General View											Load JPG	☒			
5	25/01/18 12:03	General View											Load JPG	☒			
6	25/01/18 12:03	General View											Load JPG	☒			
7	25/01/18 12:03	General View											Load JPG	☒			
8	25/01/18 12:03	General View											Load JPG	☒			
9	25/01/18 12:03	General View											Load JPG	☒			
10	25/01/18 12:03	General View											Load JPG	☒			
11	25/01/18 12:03	General View											Load JPG	☒			
12	25/01/18 12:03	General View											Load JPG	☒			
13	25/01/18 12:03	General View											Load JPG	☒			
14	25/01/18 12:03	General View											Load JPG	☒			
15	25/01/18 12:03	General View											Load JPG	☒			
16	25/01/18 12:03	General View											Load JPG	☒			
Documentation												1 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	26/10/17 11:50	Singapore Accident Statement											Load PDF				
2	26/10/17 11:50	Estimate											Load PDF				
3	26/10/17 11:50	Drivers Driving License											Load PDF				
4	26/10/17 11:50	Certificate of Insurance											Load PDF				
5	25/01/18 14:30	WORKSHOP INVOICE											Load PDF				
6	25/01/18 14:30	DISCHARGE VOUCHER											Load PDF				

Linked Accident Report Documents

Assessment Reports			View Use Viewer	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1 per page	☒
1	20/10/17 15:15	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/10/17 15:10	Accident Photo	Load JPG	☒
2	20/10/17 15:10	Accident Photo	Load JPG	☒
3	20/10/17 15:10	Accident Photo	Load JPG	☒
4	20/10/17 15:10	Accident Photo	Load JPG	☒
5	20/10/17 15:10	Accident Photo	Load JPG	☒
6	20/10/17 15:10	Accident Photo	Load JPG	☒
7	20/10/17 15:10	Accident Photo	Load JPG	☒
8	20/10/17 15:10	Accident Photo	Load JPG	☒
9	20/10/17 15:10	Accident Photo	Load JPG	☒

Documentation			1 per page ▾	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	20/10/17 15:08	Sketch Plan	 Load JPG	☒
2	20/10/17 15:08	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17020454/ATBN2
Date: 25/01/2018

REFERENCE

Insured/Claimant: PREMIUM LEASING PTE LTD Policy No: 999994958
Date of Loss: 19/10/2017 Nature of Claim: OD Claim No: 0818516205SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX8410R Engine No: CZD218521
Make & Model: AUDI Q3, 1.4 TFSI (A) Chassis No: WAUZZZ8U1GR047257
Reg. Date: 29/12/2015 (Man. Year: 2015) Odometer: 23346 km
Colour: Black
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$118,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55R17 Rear Tyre Size: 235/55R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,137.00	2,847.00	1,290.00	31.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,372.00	1,972.00	400.00	16.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,509.00	4,819.00	1,690.00	25.96
- Excess (S\$)	1,200.00	1,200.00	0.00	0.00
(S\$)	5,309.00	3,619.00	1,690.00	31.83
+ GST 7.00/7.00% (S\$)	371.63	253.33	118.30	31.83
Nett Amount (S\$)	5,680.63	3,872.33	1,808.30	31.83

INSPECTION

Date of Assignment: 25/10/2017
Date Inspected: 25/10/2017 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,630.00 FS	*1,304.00 FS
2	1		*GRILLE	Not Necessary	180.00 FS	*- FS
3	1		*RADIATOR GRILLE	Cracked	993.00 FS	*794.00 FS
4	1		*WHEEL COVER-LH FRONT	Necessary	453.00 FS	*362.00 FS
5	1		*WHEEL COVER-RH FRONT	Necessary	453.00 FS	*362.00 FS
6	1		*STRIKER PLATE	Not Necessary	103.00 FS	*- FS
7	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
8	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (S\$)					4,137.00	2,847.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	480.00	480.00
2	TO REMOVE FRONT FITTINGS,REMOVE & REINSTALL FRONT BUMPER.RENEW RADIATOR GRILLE,RE-ORGANISE FRONTAL CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.RENEW BOTH WHEEL ARC TRIM	New	900.00	500.00
3	TO RESPRAY PAINT FRONT BUMPER AND BOTH WHEEL ARC TRIM-CODE SD6	New	800.00	800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,372.00	1,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >