

ASS. REC. BY:

REF: CS/MSG17020497/Aqber

Special Instruction:

SURV. BY
Mentem

Adrian

ASSIGNMENT (Office)

From (Person):

Vimmala

of

MSG

Date/Time:

26/10/17 @ 8.41a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GBG 3356T

Insured:

at Workshop no:

N-51 Automotive

Tel:

68420051/84870051

at

Blk 2 kaki Bukit, # 01-17/18 kaki Bukit 417921

Policy No:

A28993175 MKC

Claim No:

533652

Sum Insured:

Excess:

\$ 600.00

Make of Veh.

(Client's Record)

D.O.A

20/10/2017

CA / ☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

26/10/17 @ 9.20a.m

Person Contacted:

Amely

Vehicle:

☒ IN ☐ OUT

Date/Time

Action/Instruction (☒ Estimate)

GBG 3356 T- NA/MSG1702 0159 /24-D.O.A: 20/10/2017

26/10/17 @

18.00am revert to Vimmala via Mentem.

07/11/17 @

11.12am Chen How informed C/A on P/P unless there are special considerations via Receiver.

08/11/17 @

11.12am informed Au Yong C/A not more than \$40k on P/P. If must to repair unless have special consideration & we need get approve from insurance & ex: to fix car amount.

MSIG

ASSIGNMENT

From: Date 26/10/17

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No. GBG 3356T

at Workshop n/a N-51 Automotive

at Blk 2 Kaki Bukit, # 01-17/18 Autohub, 417921

Insured

Policy No.

Claims No.

Sum Insured: Excess: \$600.00

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 30K.

QDAD Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 21 days Fee: Yes or No

Lump Sum: % B Val: Yes or No

QA / (REV) / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Van No. GBG 3356T Reg. 2017 July.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Nissae NV350 2488

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 14712 T. Radio: Insured / Std / NI / NA

Eng. No.

O/Vo: JN1MC2F26Z0008006

Gen. Cond: Good Fair / Poor / Burnt

Steering: (norden) Jammed / Leaked / Burnt or

Brake: (norden) Jammed / Leaked / Burnt or

Mod: Nil / Si Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / (PUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front

R. Bal: 06 mm

L. Bal: 06 mm

D.O.A. 26/10/17.

Survey held at: N51.

Des. of Damages: (Fr) / Rear / O/S / (NS) / (U/C) / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

OD MS/6. Lump Sum Repairs.

13/11/17 @ 3.06pm 2nd request to Kuanarua via Kuanarua. (supplementary)
 within 2018 - till 14/11/17 on 5 off have check with MSIG the status of approval (in-memo)
 15/11/17 @ 12.18pm Huey Ni informed approve at \$14700 & negotiate with Kuanarua
 at \$14700 due to their internal adjuster & investigator adjusted cost.
 15/11/17 @ 2.30 pm offer to N-51 at \$14700 before \$1500 as approved by MSIG.
 28/11/17 @ 11.40am Elynn (N-51) informed that they are negotiate the matter with Kuanarua.
 If have any result with informed us.

RECEIVED 9 NOV 2017

Case Time File Pass to: ☒ Prelim. Report29/11/17 ☐ Final Report

Case Time File Return to:

Days Of Repair: 21

Resurvey No. of Trip: 1

Survey Fee:

Insurance:

Taxes:

Other:

Total:

Total:

Total:

Add Fee: ☐ Site Insp: \$☐ Interview: \$☐ Tech. Insp: \$☐ Repairs: \$

Report Format: MEK-09

Lump Sum / B / :

300

1

311

OP vehicle no: GBE 3356 T MSLG SD DSR: 20/10/17.

CS/MSG 170 20497/Agb.

28/11/19 @ 4.14pm Winnie Chua called up to ask us to submit our report as their in-house surveyor / technical staff, Kumar will take over the case.

28/11/19 Submit ^{\$28565.23} ~~to \$14700~~ (unconfirmed).
as prelim. report.


28/11/2019

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17020497/Aqb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-10-2017



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	GBG 3356T
Policy No. A28993175MKC	Coverage (\$)	0.00
Claim No. 533652	Excess (\$)	600.00
Assign From MERIMEN (VIMMALA)	Assign Date	26/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/10/2017	Inspection Date	26/10/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Esc Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2017		26 Oct 2017 08:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BUDGETCARS PTE LTD, Co. Reg. No.: 201618239Z		
Vehicle Reg. No.:	GBG3356T	Date of Loss:	20/10/2017 12:00 - :59
Claim Type:	OD / 533652	Policy/Cover Note No.:	A28993175MKC (Comprehensive) Coverage: 20/07/2017 - 19/07/2018
		Excess:	S\$600.00
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/10/2017]		
Driver/Custodian:	MOHAMMAD ZAINUDDIN BIN MOHAMED ZAIN (27 / Male), NRIC: S9003949, Tel: +6588664674		
Adj Asg. Remarks:	Please revert and survey by today. Please check on the market value and rebate if the vehicle is economical to repair. Thank you.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 November 2019 11:36 AM
To: Elynn (N-51)
Cc: SUR
Subject: RE: Supplementary items of GBG3356T

Dear Sir/Madam,

Can finalise?

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 15 November 2019 2:30 PM
To: Elynn (N-51) <elynn@n51.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Supplementary items of GBG3356T

Dear Sir/Madam,

WITHOUT PREJUDICE

We have received the mandate approval from MSIG, the repair cost at Lump Sum \$14,700.00 (all in, including check and supplementary items, and including excess \$600).

Let's us have your confirmation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 21 November 2017 9:43 AM
To: Elynn (N-51) <elynn@n51.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Supplementary items of GBG3356T

Dear Elyn,

Please be informed that the MSIG insurance just allowed to replace 1 pc of DIESEL TANK BRACKET (No.3), FRONT STEERING GEAR (No.5) and REAR RH SHOCK ABSORBER (No.6) are not allowed.

Please contact our surveyor, Adrian if you have any enquiries.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elynn (N-51) [<mailto:elynn@n51.com.sg>]

Sent: Monday, 6 November, 2017 5:05 PM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Re: Supplementary items of GBG3356T

Hi,

Please help to forward the attachment to Mr.Adrian.

Thanks.

Regards,

Elynn

N-51 Automotive Pte Ltd

Office : 6842 0051 Fax : 6741 0510

www.n51.com.sg



----- Forwarded message -----

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Date: Fri, Nov 3, 2017 at 11:12 AM

Subject: VEHICLE GBG 3356T (DOA: 20/10/2017)

To: "sales@n51.com.sg" <sales@n51.com.sg>

Cc: SUR <sur@lkkauto.com>

Dear Ah Yong,

As spoken with you.

As instructed by our client **MSIG Insurance**, please proceed to repair the insured vehicle **GBG 3356T** at **repair cost not more than S\$40,000.00** on part by part basis. (If you insist to do Lump Sum repair unless there are special considerations. We still need to get insurance approval.) (Excess S600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

To: Elynn (N-51)
Cc: SUR
Subject: RE: Supplementary items of GBG3356T

Dear Sir/Madam,

WITHOUT PREJUDICE

We have received the mandate approval from MSIG, the repair cost at Lump Sum \$14,700.00 (all in, including check and supplementary items, and including excess \$600).

Awaiting for your confirmation.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 21 November 2017 9:43 AM
To: Elynn (N-51) <elynn@n51.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Supplementary items of GBG3356T

Dear Elyn,

Please be informed that the MSIG insurance just allowed to replace 1 pc of DIESEL TANK BRACKET (No.3), FRONT STEERING GEAR (No.5) and REAR RH SHOCK ABSORBER (No.6) are not allowed.

Please contact our surveyor, Adrian if you have any enquiries.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elynn (N-51) [<mailto:elynn@n51.com.sg>]
Sent: Monday, 6 November, 2017 5:05 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: Supplementary items of GBG3356T

Hi,

Please help to forward the attachment to Mr.Adrian.

Thanks.

Shiau Chan (LKKAuto)

From: Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Sent: Friday, 15 November 2019 12:21 PM
To: Shiau Chan (LKKAuto)
Cc: Vimmala D/O Raja Singam
Subject: RE: GBG 3356T (YOUR REF: 533652)

Hi Shiau,

Our internal investigation and adjuster had adjusted the repair cost to Lump sum repair \$14700.00 (all in, including check and supplementary items, and including excess \$600).

Please negotiate this with the repairer. Thanks

Huey Ni

From: Eng Huey Ni
Sent: Wednesday, 13 November 2019 11:12 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; Vimmala D/O Raja Singam <vimmala_rajasingam@sg.msig-asia.com>
Subject: RE: GBG 3356T (YOUR REF: 533652)

Hi Shiau Chan,

We will try to approve by this week.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 13 November 2019 11:11 AM
To: Vimmala D/O Raja Singam <vimmala_rajasingam@sg.msig-asia.com>
Cc: Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: GBG 3356T (YOUR REF: 533652)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Vimmala,

As spoken with you.

Any status for mandate approval of GBG 3356T? Can we close the case before next Monday as we have discussion on outstanding at your premises.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 31 October 2019 10:25 AM



Vehicle No. GBG 3356T
Date of Accident 20/10/2017
Date of Survey 26/10/2017

**DISAGREEMENT TO ADOPT "COST-PLUS" REPAIR BY WORKSHOP
(OWN DAMAGE CLAIM)**

I, KOH KAY YONG (workshop's Service Advisor),
hereby confirm that TWINCAR AUTOMOTIVE PTE LTD (name of Workshop)
is not agreeable to adopt "Cost-Plus" basis for the settlement of the own
damage claim for vehicle number GBG 3356T.

Surveyor

Signature

Name

Date/Time

AS
Adrian Ling
27/10/17

Workshop's Service Advisor

Signature

Name

Date/Time

KOH KAY YONG
26/10/2017

Reason for not signing this form by Workshop's Service Advisor, if applicable
(To be completed by Surveyor):

Shiau Chan (LKKAUTO)

From: Vimimala D/O Raja Singam <vimmala_rajasingam@sg.msig-asia.com>
Sent: Tuesday, 4 December 2018 9:03 AM
To: Shiau Chan (LKKAUTO)
Cc: Rajah Kumar; SUR
Subject: GBG3356T
Attachments: index.pdf

Importance: High

Hi Shiau Chan,

We refer to your adjuster mandate for the above vehicle.

Please forward us the marked estimate as of today.

Refer to the attachment. Please reply to our email dated 17/11/2017.

Thank you.

Regards,

Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala_rajasingam@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on :    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAUTO)

To: Vimimala D/O Raja Singam
Cc: Eng Huey Ni
Subject: RE: GBG 3356T (YOUR REF: 533652) & SDJ 496C (YOUR REF: 481099)

Dear Vimimala,

As spoken with you earlier.

We have checked and reviewed the case. The item no. 5 is not allowed replacement.

Hence, the cost of the said item is not including in repair cost.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vimimala D/O Raja Singam <vimmala_rajasingam@sg.msig-asia.com>
Sent: Tuesday, 22 October 2019 3:20 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>
Subject: RE: GBG 3356T (YOUR REF: 533652) & SDJ 496C (YOUR REF: 481099)
Importance: High

Hi Shiau Chan,

Please refer to the attachment.

Have you replied to the email query raised by Jocelyn on 21/11/2017 for item no 5?

Please advice

Regards,

Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala_rajasingam@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

From: Eng Huey Ni

Shiau Chan (LKKAUTO)

From: Vimmala D/O Raja Singam <vimmala_rajasingham@sg.msig-asia.com>
Sent: Tuesday, 22 October 2019 3:20 PM
To: Shiau Chan (LKKAUTO)
Cc: Eng Huey Ni
Subject: RE: GBG 3356T (YOUR REF: 533652) & SDJ 496C (YOUR REF: 481099)
Attachments: index.pdf

Importance: High

the item is not allowed replacement. Hence, the cost of the item is not including in repair cost

Hi Shiau Chan,

Please refer to the attachment.

Have you replied to the email query raised by Jocelyn on 21/11/2017 for item no 5?

Please advice

Regards,

Mala (Ms)

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6594 2471 | Direct fax +65 6225 7402 | vimmala_rajasingham@sg.msig-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

From: Eng Huey Ni

Sent: Friday, 9 August 2019 1:24 PM

To: Shiau Chan (LKKAUTO); Vimmala D/O Raja Singam

Subject: RE: GBG 3356T (YOUR REF: 533652) & SDJ 496C (YOUR REF: 481099)

Hi Shiau Chan,

For this case, we have settled with the repairer at the following:

COR \$69,500.00

Less excess \$ 1,500.00

Nett \$68,000.00 plus GST

We have authorised the repair in merimen early this year and your end has submitted the survey report based on the above.

Thanks

Huey Ni

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]

Sent: Wednesday, 7 August 2019 3:15 PM

To: Eng Huey Ni <HueyNi_Eng@sg.msig-asia.com>; Vimmala D/O Raja Singam
<vimmala_rajasingam@sg.msigasiasia.com>

Subject: RE: GBG 3356T (YOUR REF: 533652) & SDJ 496C (YOUR REF: 481099)
EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Huey Ni,

Any updates of GBG 3356T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 30 Nov 2018

Preliminary Advice

Vehicle No	: GBG3356T	Accident Date	: 20/10/2017
Make	: NISSAN NV350	Policy No.	: A28993175MKC
Assignment Date	: 26/10/2017	Excess	: S\$600.00
Date of Inspection	: 26/10/2017	Est. Duration of Repair	: 21.00
Inspection At	: N-51 AUTOMOTIVE PTE LTD (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & n/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	50,648.32	(ESTIMATE \$40,908.51 + SUPPLEMENTARY \$9,739.81)
Revised Amount	:S\$	28,565.23	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	28,565.23	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	29,503.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,497.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.

Shiau Chan (LKKAUTO)

From: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Sent: Friday, 17 November, 2017 1:48 PM
To: Shiau Chan (LKKAUTO)
Cc: SUR; Vimmala D/O Raja Singam
Subject: RE: Request for photos of supplementary Item -GBG3356T (MSIG Ref: 533652)

Dear Shiau Chan,

No. 3 - Diesel Tank Bracket (refer photo 254-257) – We will pay for 1 bracket as we only found 1 bracket damaged
No. 5 – Front Steering Gear (refer photo 151-153) – Please advise where is the bent of the steering gear X
No.6 – Rear RH Shock Absorber (refer photo 234-238) - please don't pay for it as we noted that can be reused.

Thank you
Have a great week ahead!

Jocelyn Ng
Executive, Claims Services
D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 16 November, 2017 3:38 PM
To: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; Vimmala D/O Raja Singam <vimmala_rajasingam@sg.msig-asia.com>
Subject: RE: Request for photos of supplementary Item -GBG3356T (MSIG Ref: 533652)

Dear Jacelyn,

No. 3 - Diesel Tank Bracket (refer photo 254-257) – from the photos it does not look bent & only shows 1 bracket
Please note that the protruding brackets where the screws are tightened are already twisted out of position.

No. 5 – Front Steering Gear (refer photo 151-153) – is the term referring to rack & pinion?
- which part is damaged?

The steering gear in this instance does not refer to the rack and pinion.
The shaft of the steering gear is bent.

No.6 – Rear RH Shock Absorber (refer photo 234-238) - Which part is bent?

The graze marks along the shaft and outer cover of the shock absorber show that shock absorber must have abraded against certain objects when the vehicle mounted the kerb.

No 3 : Please note that the protruding brackets where the screws are tightened are already twisted out of position.

No 5 : The steering gear in this instance does not refer to the rack and pinion.

The shaft of the steering gear ~~is~~^{is} bent.

No 6 : The graze marks along the shell and outer cover of the shock absorber show that shock absorber must have abraded against certain objects when the vehicle mounted the kerb.

~~No 8 :~~

Shiau Chan (LKKAUTO)

From: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Sent: Wednesday, 15 November, 2017 5:11 PM
To: Shiau Chan (LKKAUTO)
Cc: SUR; Vimmala D/O Raja Singam
Subject: RE: Request for photos of supplementary Item -GBG3356T (MSIG Ref: 533652)

Dear Shiau Chan,

Please advise :-

No. 3 - Diesel Tank Bracket (refer photo 254-257) - from the photos it does not look bent & only shows 1 bracket
No. 5 - Front Steering Gear (refer photo 151-153) - is the term referring to rack & pinion?
- which part is damaged?
No. 6 - Rear RH Shock Absorber (refer photo 234-238) - Which part is bent?
No. 8 - Rear RH Axle Shaft Bearing (refer photo 239-241) - which part is damaged? (understand that the bearing is inside & shaft)
No. 9 - Rear Axle Carriage (refer photo 224-229) - Please seek our mandate if need to replace

Thank you
Have a great week ahead!

Jocelyn Ng
Executive, Claims Services
D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 15 November, 2017 11:23 AM
To: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; Vimmala D/O Raja Singam <vimmala_rajasigam@sg.msig-asia.com>
Subject: RE: Request for photos of supplementary Item -GBG3356T (MSIG Ref: 533652)

Dear Jocelyn,

According to our surveyor, he already advised repairer to try and reuse the rear axle without compromising repair standards.

The rear axle was put up probably as a precautionary measure.

Best Regards,

Shiau Chan (LKKAuto)

From: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Sent: Tuesday, 14 November, 2017 1:58 PM
To: Shiau Chan (LKKAuto)
Cc: SUR; Vimimala D/O Raja Singam
Subject: RE: Request for photos of supplementary Item -GBG3356T (MSIG Ref: 533652)

Dear Shiau Chan,

Please advise whether the rear axle carriage (item no 9) is necessary to change?

Thank you
Have a great week ahead!

*To already advised requires to try and reuse the rear axle without compromising repair standards.
The rear axle was put up probably as a precautionary measure.*

Jocelyn Ng
Executive, Claims Services
D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, 14 November, 2017 11:37 AM
To: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; Vimimala D/O Raja Singam <vimimala_rajasigam@sg.msig-asia.com>
Subject: RE: Request for photos of supplementary Item -GBG3356T (MSIG Ref: 533652)

Dear Jocelyn,

Please refer to the photographs at Merimen.

No. 3 - Diesel Tank Bracket (refer photo 254-257)
No.4 - Diesel Tank Bracket Rubber (refer photo 254-257)
No. 5 - Front Steering Gear (refer photo 151-153)
No.6 - Rear RH Shock Absorber (refer photo 234-238)
No.8 - Rear RH Axle Sharf Bearing (refer photo 239-241)
No.9 - Rear Axle Carriage (refer photo 224-229)

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Jocelyn Ng <jocelyn_ng@sg.msig-asia.com>
Sent: Monday, 13 November, 2017 5:06 PM
To: Shiau Chan (LKKAUTO)
Subject: Request for photos of supplementary Item -GBG3356T (MSIG Ref: 533652)

Dear Shiau Chan,

Can you please advise which are the photos for the below supplementary parts you have attached at Merimen?

No. 3 - Diesel Tank Bracket { 254-257
No.4 - Diesel Tank Bracket Rubber 151-153
No. 5 - Front Steering Gear 234-238
No.6 - Rear RH Shock Absorber 239-241
No.8 - Rear RH Axle Sharf Bearing 224-229
No.9 - Rear Axle Carriage

Thank you
Have a great week ahead!

Jocelyn Ng
Executive, Claims Services
D: +65 6594 2539 | F: +65 6225 7402 | jocelyn_ng@sg.msig-asia.com



MSIG



CLAIMS
AWARDS
ASIA-PACIFIC

Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmla D/O Raja Singam

Date: 13 Nov 2017

Preliminary Advice

Vehicle No	: GBG3356T	Accident Date	: 20/10/2017
Make	: NISSAN NV350	Policy No.	: A28993175MKC
Assignment Date	: 26/10/2017	Excess	: S\$600.00
Date of Inspection	: 26/10/2017	Est. Duration of Repair	: 21.00
Inspection At	: N-51 AUTOMOTIVE PTE LTD (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & n/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	50,648.32	(ESTIMATE \$40,908.51 + SUPPLEMENTARY \$9,739.81)
Revised Amount	:S\$	18,931.41	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	23,840.21	
Total	:S\$	42,771.62	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	29,503.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,497.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 3 November, 2017 11:12 AM
To: sales@n51.com.sg
Cc: SUR
Subject: VEHICLE GBG 3356T (DOA: 20/10/2017)

Dear Ah Yong,

As spoken with you.

As instructed by our client **MSIG Insurance**, please proceed to repair the insured vehicle **GBG 3356T** at repair cost not more than **\$40,000.00** on part by part basis. (If you insist to do Lump Sum repair unless there are special considerations. We still need to get insurance approval.) (Excess \$600/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	23 Oct 2017 11:47	Cim Veh Model Changed	(203394) NISSAN NV350 2.5 D Panel Van (M).	[I] Vimmala D/O Raja Singam
2	23 Oct 2017 11:47	Cim Created	Reg No: GBG3356T, Policy No: A28993175MKC. Acct Date: 2017/10/20. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MNA117139407	[I] Vimmala D/O Raja Singam
3	26 Oct 2017 08:28	Notification Status Changed	Ins.Status => Incoming Claim	[I] Vimmala D/O Raja Singam
4	26 Oct 2017 08:28	Cim Registration Modified	Setl.Type:3->0, Rep:1137->200239. Claim Type:SC->OD. Init.Est.:>40,000 - 50,000.	[I] Vimmala D/O Raja Singam
5	26 Oct 2017 08:41	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert and survey by today. Please check on the market value and rebate if the vehicle is economical to repair. Thank you.	[I] Vimmala D/O Raja Singam
6	26 Oct 2017 08:41	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/10/27	[I] Vimmala D/O Raja Singam
7	26 Oct 2017 08:41	Adj Mandate Set	Approved:25000.00,Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
8	26 Oct 2017 08:57	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	26 Oct 2017 13:15	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
10	26 Oct 2017 17:27	Adj Rpt Initiated		[A] SHIAU CHAN
11	26 Oct 2017 18:03	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/25	[A] SHIAU CHAN
12	26 Oct 2017 18:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/25	[A] SHIAU CHAN
13	26 Oct 2017 18:04	Adj Mandate Request	Cur.Req:35225.53:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER ASKING REPAIR THE VEHICLE ON LUMP SUM BASIS. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
14	02 Nov 2017 11:10	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/25	[I] NG CHEN HOW
15	02 Nov 2017 11:10	Adj Mandate Set	Approved:35225.53.	[I] NG CHEN HOW
16	02 Nov 2017 11:12	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2017/11/25. Mandate Remarks: We stick to part-by-part repairs unless there are special considerations.	[I] NG CHEN HOW
17	02 Nov 2017 11:12	Adj Mandate Set	Approved:17514.62:We stick to part-by-part repairs unless there are special considerations.	[I] NG CHEN HOW

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1621351	26/10/2017 17:27	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBG3356T		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmla D/O Raja Singam

Date: 26 Oct 2017

Preliminary Advice

Vehicle No	: GBG3356T	Accident Date	: 20/10/2017
Make	: NISSAN NV350	Policy No.	: A28993175MKC
Assignment Date	: 26/10/2017	Excess	: S\$600.00
Date of Inspection	: 26/10/2017	Est. Duration of Repair	: 21.00
Inspection At	: N-51 AUTOMOTIVE PTE LTD (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & n/s portion, undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,908.51
Revised Amount	:S\$	17,514.62
Check Items (Estimated)	:S\$	17,710.91
Total	:S\$	35,225.53

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	29,503.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,497.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
REPAIRER ASKING REPAIR THE VEHICLE ON LUMP SUM BASIS.
WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	8239Z
Vehicle Details	
Vehicle No.	GBG3356T
Vehicle to be Exported	Yes
Intended De-registration Date	26 Oct 2017
Vehicle Make	NISSAN
Vehicle Model	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour	White
Manufacturing Year	2016
Engine No.	YD25416286A
Chassis No.	JN1MC2E26Z0008006
Maximum Power Output	-
Open Market Value	\$24,409.00
Original Registration Date	20 Jul 2017
First Registration Date	20 Jul 2017
Transfer Count	0
Actual ARF Paid	\$1,221.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	19 Jul 2027
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$36,879.00
COE Rebate Amount	\$29,503.00
Total Rebate Amount	\$29,503.00

The information contained herein is correct as at 26 Oct 2017.

OK




Username / Email Add

password

[Connect](#) • [Sign Up New Account](#)
• [Forgot Password](#)

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Subaru Tribeca At \$348.


 1 Careful Owner:
 Direct Owner (Stock)

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Sort by Date Posted

20 results/page

13 vehicles

NV350

Advanced Search

	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	NV350	Any	Any	2017	Any	Any	Any	Available
	Nissan NV350 2.5M	\$81,000	\$8,760 /yr	23-Jan-2017	2,488 cc	18 km	Van	Available
	Fuel Type: Diesel Almost Brand New Nissan NV350 Panel Van 2.5 SMT Euro V. 5 Years Or 140,000Km Warranty By Tan Chong Motor Sales. Free 3 x Servicing. Posted: 15-Oct-2017 Tags: 2017 Nissan NV350, 2017 Nissan NV350, Nissan NV350, Nissan NV350, Nissan, NV350, NV350, Used Nissan							Details
	Nissan NV350 2.5M	\$72,800	\$7,870 /yr	25-Jan-2017	2,488 cc	9,000 km	Van	Available
	Fuel Type: Petrol Check This Outstanding Unit! 1 Single Owner Only, Low Mileage Done, Under Agent Tan Chong 3 Plus 2 Years Or 140k Km Warranty, Made In Japan Model Making It Reliable Durable Long Lasting. Owner Upgrade... Posted: 04-Sep-2017 Tags: 2017 Nissan NV350, 2017 Nissan NV350, Nissan NV350, Nissan NV350, Nissan, NV350, NV350, Used Nissan							Details
	Nissan NV350 2.5M	\$79,900	\$8,500 /yr	22-Mar-2017	2,488 cc	-	Van	Available
	Fuel Type: Diesel Less Than 7 Days Handover, Fast And Easy Transaction, No Extra Charges, Full Accessories, High Loan, Warranty, Servicing All By Agent, Call Now, Don't Miss This. Abwin Bus Pte Ltd Posted: 23-Oct-2017 Tags: 2017 Nissan NV350, 2017 Nissan NV350, Nissan NV350, Nissan NV350, Nissan, NV350, NV350, Used Nissan							Details
	Nissan NV350 2.5M	\$78,888	\$8,370 /yr	28-Mar-2017	2,488 cc	50 km	Van	Available
	Fuel Type: Diesel Almost Brand New Unit Selling At The Lowest Come With 3 Year Warranty And Many More Call Now For More Enquiries Before It Is Sold. Posted: 03-Oct-2017 Tags: 2017 Nissan NV350, 2017 Nissan NV350, Nissan NV350, Nissan NV350, Nissan, NV350, NV350, Used Nissan							Details

[Car Buying](#)
[Car Selling](#)
[Car Aftermarket](#)
[Buying a pre-owned Car, But Unsure of its Condition?](#)
[Get STA Car Evaluation](#)
[Car Ownership](#)
[On The Move](#)
[Lifestyle](#)

	Nissan NV350 2.5M	\$81,000	\$8,470 /yr	20-May-2017	2,488 cc	28 km	Van	Available
	Fuel Type: Diesel Almost New Nissan NV350 Panel Van 2.5 SMT Euro V. 5 Years Or 140,000Km Warranty By Tan Chong Motor Sales. Free 3 x Servicing. Posted: 02-Oct-2017 Tags: 2017 Nissan NV350, 2017 Nissan NV350, Nissan NV350, Nissan NV350, Nissan, NV350, NV350, Used Nissan							Details
	Nissan NV350 2.5M	\$81,900	\$8,530 /yr	02-Jun-2017	2,488 cc	-	Van	Available
	Fuel Type: Diesel Clearance Sales! Brand New Nissan NV350 SDoor Manual Warranty By Tan Chong Motor 5 Years/140Km, Free 3 Times Services/Logo/Front And Back Camera, 100% Loan 2.8% 7-9yrs High Trade In Available. Why Wait... Victory Automotives Pte Ltd Posted: 07-Oct-2017 Tags: 2017 Nissan NV350, 2017 Nissan NV350, Nissan NV350, Nissan NV350, Nissan, NV350, NV350, Used Nissan							Details
	Nissan NV350 2.5M	\$81,000	\$8,380 /yr	24-Jun-2017	2,488 cc	18 km	Van	Available
	Fuel Type: Diesel Newly Registered Nissan NV350 Panel Van 2.5 SMT Euro V. 5 Years Or 140,000Km Warranty By Tan Chong Motor Sales. Free 3 x Servicing. Posted: 04-Sep-2017 Tags: 2017 Nissan NV350, 2017 Nissan NV350, Nissan NV350, Nissan NV350, Nissan, NV350, NV350, Used Nissan							Details

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2017 11:55
Date Of Accident	20/10/2017 12:30
Exact Location Of Accident	MOUNTNBATTEN RD TWDS OLD AIRPORT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG3356T
Insured/Policyholder	
Name Of Registered Owner	BUDGETCARS PTE LTD
Co Reg No	201618239Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91593833
Alternative Phone No	OFFICE-91593833

Vehicle Particulars

Manufacturer	NISSAN
Model	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28993175MKC
Cover Note Number	

Driver

Name of Driver	MOHAMMAD ZAINUDDIN BIN MOHAMED ZAIN
NRIC No	S9003949J
Date Of Birth	10/02/1990
Occupation	OUTDOOR
Date Of Driving Pass	23/03/2017
Driving Experience	0 YEAR AND 6 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-88664674
Fax Number	
Contact Number	OFFICE-88664674
Email Address	NOEMAIL

Address	BLK 718 BEDOK RESERVOIR ROAD #11-4576
Postcode	470718
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PROPERTY
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name	MOHAMMAD ZAINUDDIN BIN MOHAMED ZAIN
------	-------------------------------------

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

GBG3356T

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time


Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Accident Sketch Plan

SKETCH PLAN

Manhattan Road toward 101st Street Road



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above date and time, I was driving along Manhattan Road toward 101st Street Road. I have a 4 lane road. I was driving along Manhattan Road and I had a car in front of me. I was driving slowly as I approached the intersection. I suddenly saw a vehicle and I hit it. The front portion of my vehicle hit the rear of the other vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Date & Time:



 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Person's Signature
 Name:
 Address:

Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
DIESEL TANK <i>Distorted</i>	1	1174.70	✓ 1,174.70
FRONT BUMPER <i>Distorted</i>	1	541.00	✓ 541.00
FRONT BUMPER FOGLAMP COVER L/R <i>Lit CR, RH missing</i>	2	114.20	✓ 228.40
FRONT BUMPER LOWER COVER <i>lit</i>	1	65.10	✓ 65.10
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	667.10	✓ 667.10
FRONT BUMPER REINFORCEMENT BRACKET L/R <i>Not New</i>	2	110.90	✗ 221.80
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	155.60	✓ 311.20
FRONT BUMPER UPPER BEAM <i>Not New</i>	1	222.40	✗ 222.40
FRONT CORNER PANEL LH <i>Dented</i>	1	535.50	✓ 535.50
FRONT DOOR GLASS LH <i>lit</i>	1	760.00	✓ 760.00
FRONT DOOR LH <i>Dented</i>	1	1232.90	✓ 1,232.90
FRONT DOOR OUTER PILLAR RH <i>Repair Dented</i>	1	1388.90	✗ 1,388.90
FRONT HEADLAMP PANEL L/R <i>Repair</i>	2	353.10	✗ 706.20
FRONT INSTRUMENT PANEL <i>new</i>	1	1237.50	+ 1,237.50
FRONT LOWER PANEL <i>Repair</i>	1	353.10	+ 353.10
FRONT PANEL <i>Dented.</i>	1	1352.50	✓ 1,352.50
REAR BUMPER <i>Good</i>	1	632.70	✓ 632.70
REAR LH FENDER <i>Dented</i>	1	2010.30	✓ 2,010.30

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

SLIDING DOOR LH	<i>done</i>	1	1525.30	✓	1,525.30
			Subtotal before discount		15,166.60
			Percentage discount 30%		4,549.98
			Sub-total 1		10,616.62
AIRCON BLOWER AIR DUCT	<i>see in</i>	1	88.70	<i>✓</i>	88.70
AIRCON BLOWER AIR DUCT CASING	<i>see in</i>	1	63.60	<i>✓</i>	63.60
DIESEL TANK FLOAT	<i>see in</i>	1	299.05	<i>✓</i>	299.05
DIESEL TANK HEAT SHIELD	<i>see in</i>	1	82.20	<i>✓</i>	82.20
DIESEL TANK LOWER COVER	<i>see in</i>	1	297.30	<i>✓</i>	297.30
ENGINE CROSS MEMBER - NO:1	<i>see in</i>	1	415.65	<i>✓</i>	415.65
ENGINE CROSS MEMBER - NO:2	<i>see in</i>	1	415.65	<i>✓</i>	415.65
ENGINE OIL SUMP	<i>see in</i>	1	214.30	<i>✓</i>	214.30
ENGINE UNDER COVER	<i>missing</i>	1	273.60	<i>✓</i>	273.60
FRONT ABS SENSOR L/R	<i>see in</i>	2	409.50	<i>✓</i>	819.00
FRONT BUMPER TOW HOOK COVER	<i>missing</i>	1	21.10	<i>✓</i>	21.10
FRONT CENTER BODY CROSS MEMBER	<i>see in</i>	1	392.30	<i>✓</i>	392.30
FRONT DOOR ARCH WEATHER STRIP LH	<i>see in</i>	1	42.90	<i>✓</i>	42.90
FRONT DOOR ARCH WEATHER STRIP LH	<i>see in</i>	1	42.90	<i>✓</i>	42.90

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

FRONT DOOR GLASS CHANNEL LH	<i>For new</i>	1	87.50	<i>X</i>	87.50
FRONT DOOR GLASS CHANNEL LH	<i>For new</i>	1	67.50	<i>X</i>	67.50
FRONT DOOR OUTER MOULDING LH	<i>Int</i>	1	142.60	<i>✓</i>	142.60
FRONT DOOR SIDE MIRROR GLASS LH	<i>Int</i>	1	53.30	<i>✓</i>	53.30
FRONT DOOR SIDE MIRROR LH	<i>Missing</i>	1	516.80	<i>✓</i>	516.80
FRONT DOOR STEP GARNISH L/R	<i>Not in RH 2nd</i>	2	94.50	<i>X</i>	189.00 <i>94.50</i>
FRONT DOOR WEATHER STRIP LH	<i>Not in</i>	1	91.10	<i>X</i>	91.10
FRONT GRILLE	<i>Missing</i>	1	463.30	<i>✓</i>	463.30
FRONT GRILLE 'LOGO' EMBLEM	<i>in</i>	1	64.60	<i>✓</i>	64.60
FRONT HEADLAMP L/R	<i>LH cracked, RH cracked</i>	2	373.00	<i>373</i>	746.00 <i>746</i>
FRONT INSTRUMENT PANEL REINFORCEMENT	<i>For new</i>	1	497.20	<i>X</i>	497.20
FRONT INTER COOLER	<i>Detected</i>	1	2050.40	<i>✓</i>	2,050.40
FRONT INTER COOLER CENTER PIPE	<i>Bent</i>	1	479.00	<i>2</i>	479.00
FRONT INTER COOLER PIPE BRACKET	<i>For new</i>	1	69.60	<i>X</i>	69.60
FRONT KNUCKLE ARM L/R	<i>Bent</i>	2	409.00	<i>✓</i>	818.00
FRONT LINKAGE L/R	<i>For new</i>	2	93.80	<i>X</i>	187.60
FRONT LOWER ARM L/R	<i>Bent</i>	2	283.50	<i>2</i>	567.00
FRONT RH INTER COOLER HOSE	<i>Int</i>	1	141.80	<i>✓</i>	141.80

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

FRONT SIDE MIRROR COVER LH	MISSING	1	105.00	✓	105.00
FRONT STABILIZER BAR	Best.	1	360.90	✓	360.90
FRONT STABILIZER BAR BRACKET L/R	Free	2	19.40	✓	38.80
FRONT STABILIZER BAR BUSHING L/R	New	2	18.50	✓	37.00
FRONT STEERING RACK & PINION	None	1	1995.20	X	1,995.20
FRONT STEERING TIE ROD END L/R	None	2	79.50	X	159.00
FRONT STEERING TIE ROD L/R	None	2	115.20	X	230.40
FRONT UPPER ARM L/R	None	2	297.50	X	595.00
FRONT WHEEL RIM L/R	None	2	257.10	X	514.20
FRONT WIPER GARNISH	cut	1	227.48	✓	227.48
FRONT WIPER GARNISH SIDE RUBBER L/R	None	2	38.10	+	76.20
FRONT WIPER LINKAGE	None	1	325.00	+	325.00
REAR BUMPER SIDE HOLDER CLIPS L/R	None	6	17.50	30	105.00
REAR LH TAILLAMP	cut	1	208.70	✓	208.70
Subtotal before discount					15,678.43
Percentage discount 10%					1,567.84
Sub-total 2					14,110.59
AIRCON BLOWER MOTOR	cracked	1	575.90	✓	575.90

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

AIRCON CONDENSER	<i>Bent.</i>	1	501.10	✓	501.10
AIRCON CONDENSER BRACKET L/R	<i>new</i>	2	56.60	+	113.20
AIRCON CONDENSER FAN MOTOR	<i>new</i>	1	247.50	+	247.50
AIRCON CONDENSER FAN MOTOR BLADE	<i>new</i>	1	31.40	*	31.40
AIRCON CONDENSER FAN MOTOR COWLING	<i>out</i>	1	107.80	✓	107.80
AIRCON CONDENSER FAN MOTOR GRILLE	<i>new</i>	1	66.50	*	66.50
AIRCON CONDENSER LOWER GARNISH	<i>new</i>	1	55.90	+	55.90
AIRCON COOLING UNIT	<i>crushed.</i>	1	1846.40	✓	1,846.40
BRAKE FLUID	<i>2L</i>	1	40.00	✓	40.00
DIESEL TANK LOWER COVER CLIPS - SET	<i>2L</i>	1	30.00	✓	30.00
ENGINE MOUNTING L/R	<i>storn</i>	2	76.30	✓	152.60
ENGINE OIL	<i>new</i>	1	300.00	+	300.00
ENGINE OIL SUMP SEALANT	<i>new</i>	1	50.00	+	50.00
FRONT 195/15 TYRES L/R	<i>at</i>	2	300.00	360	600.00
FRONT BUMPER CLIPS - SET	<i>new</i>	1	50.00	-	50.00
FRONT BUMPER FOGLAMP L/R	<i>LH at, RH missing</i>	2	310.90	✓	621.80
FRONT DOOR 'COMPANY DETAIL' STICKER - SET	<i>new</i>	1	160.00	60	160.00
FRONT DOOR ARCH PANEL GARNISH CLIPS L/R - SET	<i>new</i>	2	30.00	*	60.00

*** This is a computer-generated document which requires no signature. ***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

FRONT DOOR INNER TRIM BOARD CLIPS L/R - SET <i>den</i>	2	50.00	<i>30</i> 100.00
FRONT DOOR STEP GARNISH CLIPS L/R - SET <i>den</i>	2	30.00	<i>4</i> 60.00
FRONT GRILLE CLIPS - SET <i>den</i>	1	50.00	<i>20</i> 50.00
FRONT KNUCKLE ARM BEARING L/R <i>Den</i>	2	155.50	<i>2</i> 311.00
FRONT LOWER ARM BALL JOINT L/R <i>den</i>	2	93.70	<i>X</i> 187.40
FRONT NUMBER PLATE <i>Den</i>	1	25.00	<i>✓</i> 25.00
FRONT SHOCK ABSORBER L/R <i>Den</i>	2	128.70	<i>2</i> 257.40
FRONT WHEEL HUB L/R <i>Den</i>	2	452.00	<i>✓</i> 904.00
FRONT WINDSCREEN E.R.P BRACKET <i>den</i>	1	50.00	<i>+</i> 50.00
FRONT WINDSCREEN E.R.P BRACKET STICKER <i>den</i>	1	15.00	<i>+</i> 15.00
FRONT WINDSCREEN SEALANT <i>den</i>	1	100.00	<i>60</i> 100.00
FRONT WIPER GARNISH CLIPS - SET <i>den</i>	1	50.00	<i>20</i> 50.00
PROPELLER SHAFT COUPLING <i>den</i>	1	97.50	<i>20</i> 97.50
REAR BUMPER CLIPS - SET <i>den</i>	1	50.00	<i>30</i> 50.00
REAR LH AXLE SHAFT <i>den</i>	1	283.20	<i>X</i> 283.20
REAR LH AXLE SHAFT BEARING <i>den</i>	1	82.00	<i>X</i> 82.00
REAR LH SHOCK ABSORBER <i>Den</i>	1	128.70	<i>✓</i> 128.70
REAR LH TAILLAMP CLIPS - SET <i>den</i>	1	30.00	<i>10</i> 30.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

SLIDING DOOR LH INNER TRIM BOARD CLIPS - SET	1	50.00	30 50.00
Subtotal before discount			8,441.30
Percentage discount 0%			0.00
Sub-total 3			8,441.30
Parts-total			33,168.51

LABOUR

To lifting up vehicle from kerb, drain and towing.	150 200.00
To remove, change air con parts, vacuums, refill air con gas.	120 180.00
To reset system after repair works	30 300.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	70 140.00
To remove, reinstall windscreen. (to FR)	120 180.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	420 500.00
To remove, reinstall brake parts, brake line, brake pump and bleeding brake system.	60 180.00
To road test driving, check and resetting wheel alignments system.	80 120.00
To remove, change petrol tank.	80 120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	50 140.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80 180.00
To remove, change dashboard fascia and transfer where necessary.	220 300.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1800 2,400.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

BUDGETCARS PTE LTD

65 UBI CRESCENT #03-03 HOLA CENTRE

SINGAPORE 408559

Contact : 91593833, 88664674

ESTIMATE

Repair Code : CLM13885

Date in : 20/10/2017

Vehicle Num. : GBG3356T

Model : NISSAN NV350 PANEL VAN 2.5 5MT 5DR EURO V

Chassis/Eng# : JN1MC2E26Z0008006/YD25416286A

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

2207 2,900.00

Labour Total

7,740.00

Parts & Labour Total

40,908.51

30648-32

*** This is a computer-generated document which requires no signature.***

page 8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Luy
#5 26/10/17.

21 days.

Excess \$600

Not Authorised

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921
 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

Final prg @ 28565.23

Budgetcars PteLtd

65 Ubi Crescent #03-03
 Hala Centre
 Singapore 408559

Repair Code: CLM13885

Date in: 20/10/2017

Vehicle No.: GBG3356T

Model: NISSAN NV350 PANEL VAN 2.5 SMT SDR EURO V

Chassis/Eng#: JN1MC2E26Z0008006/YD25416286A

Contact: 91593833, 88664674

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	Front Wiper Motor <i>fit on</i>	N	1	\$ 352.00	\$ 352.00
2	Rear Leaf Spring L/R <i>fit on</i>	N	2	\$ 885.40	\$ 1,770.80
3	Diesel Tank Bracket <i>sent</i>	N	2	\$ 95.20	\$ 190.40
4	Diesel Tank Bracket Rubber <i>on</i>	N	2	\$ 41.50	\$ 83.00
5	Front Steering Gear <i>fit on</i>	N	1	\$ 1,066.70	\$ 1,066.70
Sub total before discount:					\$ 3,462.90
Percentage discount 10%:					\$ 346.29
Sub-total 1:					\$ 3,116.61
6	Rear RH Shock Absorber <i>sent</i>	S/N	1	\$ 128.70	\$ 128.70
7	Rear RH Axle Shaft <i>fit on</i>	S/N	1	\$ 283.20	\$ 283.20
8	Rear RH Axle Shaft Bearing <i>on</i>	S/N	1	\$ 82.00	\$ 82.00
9	Rear Axle Carriage <i>fit on</i>	S/N	1	\$ 6,129.30	\$ 6,129.30
Sub-total 2:					\$ 6,623.20
Parts Total:					\$ 9,739.81

Adrian

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2017		26 Oct 2017 08:41 Edit Adj Rpt	S\$28,565.23 Edit Estimates	S\$28,565.23 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by Insurer]

Insured:	BUDGETCARS PTE LTD, Co. Reg. No.: 201618239Z		
Vehicle Reg. No.:	GBG3356T	Date of Loss:	20/10/2017 12:00 - :59 [3 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / 533652	Policy/Cover Note No.:	A28993175MKC (Comprehensive) Coverage: 20/07/2017 - 19/07/2018
		Excess:	S\$600.00
Repairer:	N-S1 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/11/2017]		
Driver/Custodian:	MOHAMMAD ZAINUDDIN BIN MOHAMED ZAIN (27 / Male) , NRIC: S9003949J, Tel: +6588664674 Email: NOEMAIL		
Adj Asg. Remarks:	Please revert and survey by today. Please check on the market value and rebate if the vehicle is economical to repair. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (15/11/2019): Alert - Adj Mandate Approved (S\$14700.00) - GBG3356T - Claim Handler: Vimmala D/...
- MSIG_SG (01/11/2018): GBG3356T (533652)
- MSIG_SG (21/11/2017): Alert - Adj Mandate Revoked - GBG3356T - Claim Handler: Vimmala D/O Raja Singam
- MSIG_SG (02/11/2017): Alert - Adj Mandate Approved (S\$17514.62) - GBG3356T - Claim Handler: Vimmala D/...
- MSIG_SG (02/11/2017): Alert - Adj Mandate Approved (S\$35225.53) - GBG3356T - Claim Handler: Vimmala D/...
- MSIG_VIM (02/11/2017): Re: AUTHORISATION OF GBG 3356T (YOUR REF: 533652)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG3356T (533652)
OD
Oct 20 2017 12:00PM
[BUDGETCARS PTE LTD]
N-51 Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/10/17 14:45	Accident Statement	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/17 18:03	Adjuster Immediate Advice	Load HTM	
2	13/11/17 15:05	Adjuster Immediate Advice	Load HTM	
3	30/11/18 14:14	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
12	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
13	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
14	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
15	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
16	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
17	21/10/17 14:42	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/17 17:59	General View	Load JPG	☒
2	26/10/17 17:59	Chassis Number	Load JPG	☒
3	26/10/17 17:59	General View	Load JPG	☒
4	26/10/17 17:59	General View	Load JPG	☒
5	26/10/17 17:59	General View	Load JPG	☒
6	26/10/17 17:59	General View	Load JPG	☒
7	26/10/17 17:59	General View	Load JPG	☒
8	26/10/17 17:59	General View	Load JPG	☒
9	26/10/17 17:59	General View	Load JPG	☒
10	26/10/17 17:59	General View	Load JPG	☒
11	26/10/17 17:59	General View	Load JPG	☒
12	26/10/17 17:59	General View	Load JPG	☒
13	26/10/17 17:59	General View	Load JPG	☒
14	26/10/17 17:59	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
15	26/10/17 17:59	General View	 Load JPG	☒
16	26/10/17 17:59	General View	 Load JPG	☒
17	26/10/17 17:59	General View	 Load JPG	☒
18	26/10/17 17:59	General View	 Load JPG	☒
19	26/10/17 17:59	General View	 Load JPG	☒
20	26/10/17 17:59	General View	 Load JPG	☒
21	26/10/17 17:59	General View	 Load JPG	☒
22	26/10/17 17:59	General View	 Load JPG	☒
23	26/10/17 17:59	General View	 Load JPG	☒
24	26/10/17 17:59	General View	 Load JPG	☒
25	26/10/17 17:59	General View	 Load JPG	☒
26	26/10/17 17:59	General View	 Load JPG	☒
27	26/10/17 17:59	General View	 Load JPG	☒
28	26/10/17 17:59	General View	 Load JPG	☒
29	26/10/17 17:59	General View	 Load JPG	☒
30	26/10/17 17:59	General View	 Load JPG	☒
31	26/10/17 17:59	General View	 Load JPG	☒
32	26/10/17 17:59	General View	 Load JPG	☒
33	26/10/17 17:59	General View	 Load JPG	☒
34	26/10/17 17:59	General View	 Load JPG	☒
35	26/10/17 17:59	General View	 Load JPG	☒
36	26/10/17 17:59	General View	 Load JPG	☒
37	26/10/17 17:59	General View	 Load JPG	☒
38	26/10/17 17:59	General View	 Load JPG	☒
39	26/10/17 17:59	General View	 Load JPG	☒
40	26/10/17 17:59	General View	 Load JPG	☒
41	26/10/17 17:59	General View	 Load JPG	☒
42	26/10/17 17:59	General View	 Load JPG	☒
43	26/10/17 17:59	General View	 Load JPG	☒
44	26/10/17 17:59	General View	 Load JPG	☒
45	26/10/17 17:59	General View	 Load JPG	☒
46	26/10/17 17:59	General View	 Load JPG	☒
47	26/10/17 17:59	General View	 Load JPG	☒
48	26/10/17 17:59	General View	 Load JPG	☒
49	26/10/17 17:59	General View	 Load JPG	☒
50	26/10/17 17:59	General View	 Load JPG	☒
51	26/10/17 17:59	General View	 Load JPG	☒
52	26/10/17 17:59	General View	 Load JPG	☒
53	26/10/17 17:59	General View	 Load JPG	☒
54	26/10/17 17:59	General View	 Load JPG	☒
55	26/10/17 17:59	General View	 Load JPG	☒
56	26/10/17 17:59	General View	 Load JPG	☒
57	26/10/17 17:59	General View	 Load JPG	☒
58	26/10/17 17:59	General View	 Load JPG	☒
59	26/10/17 17:59	General View	 Load JPG	☒
60	26/10/17 17:59	General View	 Load JPG	☒
61	26/10/17 17:59	General View	Load JPG	☒
62	26/10/17 17:59	General View	Load JPG	☒
63	26/10/17 17:59	General View	Load JPG	☒
64	26/10/17 17:59	General View	Load JPG	☒
65	26/10/17 17:59	General View	Load JPG	☒
66	26/10/17 17:59	General View	Load JPG	☒
67	26/10/17 17:59	General View	Load JPG	☒
68	26/10/17 17:59	General View	Load JPG	☒
69	26/10/17 17:59	General View	Load JPG	☒
70	26/10/17 17:59	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
71	26/10/17 17:59	General View	 Load JPG	☒
72	26/10/17 17:59	General View	 Load JPG	☒
73	26/10/17 17:59	General View	 Load JPG	☒
74	26/10/17 17:59	General View	 Load JPG	☒
75	26/10/17 17:59	General View	 Load JPG	☒
76	26/10/17 17:59	General View	 Load JPG	☒
77	26/10/17 17:59	General View	 Load JPG	☒
78	26/10/17 17:59	General View	 Load JPG	☒
79	26/10/17 17:59	General View	 Load JPG	☒
80	26/10/17 17:59	General View	 Load JPG	☒
81	26/10/17 17:59	General View	 Load JPG	☒
82	26/10/17 17:59	General View	 Load JPG	☒
83	26/10/17 17:59	General View	 Load JPG	☒
84	26/10/17 17:59	General View	 Load JPG	☒
85	26/10/17 17:59	General View	 Load JPG	☒
86	26/10/17 17:59	General View	 Load JPG	☒
87	26/10/17 17:59	General View	 Load JPG	☒
88	26/10/17 17:59	General View	 Load JPG	☒
89	26/10/17 17:59	General View	 Load JPG	☒
90	26/10/17 17:59	General View	 Load JPG	☒
91	26/10/17 17:59	General View	 Load JPG	☒
92	26/10/17 17:59	General View	 Load JPG	☒
93	26/10/17 17:59	General View	 Load JPG	☒
94	26/10/17 17:59	General View	 Load JPG	☒
95	26/10/17 17:59	General View	 Load JPG	☒
96	26/10/17 17:59	General View	 Load JPG	☒
97	26/10/17 17:59	General View	 Load JPG	☒
98	26/10/17 17:59	General View	 Load JPG	☒
99	26/10/17 17:59	General View	 Load JPG	☒
100	26/10/17 17:59	General View	 Load JPG	☒
101	26/10/17 17:59	General View	 Load JPG	☒
102	26/10/17 17:59	General View	 Load JPG	☒
103	26/10/17 17:59	General View	 Load JPG	☒
104	26/10/17 17:59	General View	 Load JPG	☒
105	26/10/17 17:59	General View	 Load JPG	☒
106	26/10/17 17:59	General View	 Load JPG	☒
107	26/10/17 17:59	General View	 Load JPG	☒
108	26/10/17 17:59	General View	 Load JPG	☒
109	26/10/17 17:59	General View	 Load JPG	☒
110	26/10/17 17:59	General View	 Load JPG	☒
111	26/10/17 17:59	General View	 Load JPG	☒
112	26/10/17 17:59	General View	 Load JPG	☒
113	26/10/17 17:59	General View	 Load JPG	☒
114	26/10/17 17:59	General View	 Load JPG	☒
115	26/10/17 17:59	General View	 Load JPG	☒
116	26/10/17 17:59	General View	 Load JPG	☒
117	26/10/17 17:59	General View	 Load JPG	☒
118	26/10/17 17:59	General View	 Load JPG	☒
119	26/10/17 17:59	General View	 Load JPG	☒
120	26/10/17 17:59	General View	 Load JPG	☒
121	26/10/17 17:59	General View	 Load JPG	☒
122	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
123	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
124	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
125	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
126	13/11/17 15:07	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
127	13/11/17 15:07	Reinspection Photo		☒
128	13/11/17 15:07	Reinspection Photo		☒
129	13/11/17 15:07	Reinspection Photo		☒
130	13/11/17 15:07	Reinspection Photo		☒
131	13/11/17 15:07	Reinspection Photo		☒
132	13/11/17 15:07	Reinspection Photo		☒
133	13/11/17 15:07	Reinspection Photo		☒
134	13/11/17 15:07	Reinspection Photo		☒
135	13/11/17 15:07	Reinspection Photo		☒
136	13/11/17 15:07	Reinspection Photo		☒
137	13/11/17 15:07	Reinspection Photo		☒
138	13/11/17 15:07	Reinspection Photo		☒
139	13/11/17 15:07	Reinspection Photo		☒
140	13/11/17 15:07	Reinspection Photo		☒
141	13/11/17 15:07	Reinspection Photo		☒
142	13/11/17 15:07	Reinspection Photo		☒
143	13/11/17 15:07	Reinspection Photo		☒
144	13/11/17 15:07	Reinspection Photo		☒
145	13/11/17 15:07	Reinspection Photo		☒
146	13/11/17 15:07	Reinspection Photo		☒
147	13/11/17 15:07	Reinspection Photo		☒
148	13/11/17 15:07	Reinspection Photo		☒
149	13/11/17 15:07	Reinspection Photo		☒
150	13/11/17 15:07	Reinspection Photo		☒
151	13/11/17 15:07	Reinspection Photo		☒
152	13/11/17 15:07	Reinspection Photo		☒
153	13/11/17 15:07	Reinspection Photo		☒
154	13/11/17 15:07	Reinspection Photo		☒
155	13/11/17 15:07	Reinspection Photo		☒
156	13/11/17 15:07	Reinspection Photo		☒
157	13/11/17 15:07	Reinspection Photo		☒
158	13/11/17 15:07	Reinspection Photo		☒
159	13/11/17 15:07	Reinspection Photo		☒
160	13/11/17 15:07	Reinspection Photo		☒
161	13/11/17 15:07	Reinspection Photo		☒
162	13/11/17 15:07	Reinspection Photo		☒
163	13/11/17 15:07	Reinspection Photo		☒
164	13/11/17 15:07	Reinspection Photo		☒
165	13/11/17 15:07	Reinspection Photo		☒
166	13/11/17 15:07	Reinspection Photo		☒
167	13/11/17 15:07	Reinspection Photo		☒
168	13/11/17 15:07	Reinspection Photo		☒
169	13/11/17 15:07	Reinspection Photo		☒
170	13/11/17 15:07	Reinspection Photo		☒
171	13/11/17 15:07	Reinspection Photo		☒
172	13/11/17 15:07	Reinspection Photo		☒
173	13/11/17 15:07	Reinspection Photo		☒
174	13/11/17 15:07	Reinspection Photo		☒
175	13/11/17 15:07	Reinspection Photo		☒
176	13/11/17 15:07	Reinspection Photo		☒
177	13/11/17 15:07	Reinspection Photo		☒
178	13/11/17 15:07	Reinspection Photo		☒
179	13/11/17 15:07	Reinspection Photo		☒
180	13/11/17 15:07	Reinspection Photo		☒
181	13/11/17 15:07	Reinspection Photo		☒
182	13/11/17 15:07	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
183	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
184	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
185	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
186	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
187	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
188	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
189	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
190	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
191	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
192	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
193	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
194	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
195	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
196	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
197	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
198	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
199	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
200	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
201	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
202	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
203	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
204	13/11/17 15:07	Reinspection Photo	 Load JPG	☒
205	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
206	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
207	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
208	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
209	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
210	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
211	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
212	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
213	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
214	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
215	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
216	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
217	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
218	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
219	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
220	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
221	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
222	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
223	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
224	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
225	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
226	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
227	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
228	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
229	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
230	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
231	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
232	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
233	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
234	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
235	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
236	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
237	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
238	13/11/17 15:08	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
239	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
240	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
241	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
242	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
243	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
244	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
245	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
246	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
247	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
248	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
249	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
250	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
251	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
252	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
253	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
254	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
255	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
256	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
257	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
258	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
259	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
260	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
261	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
262	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
263	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
264	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
265	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
266	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
267	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
268	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
269	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
270	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
271	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
272	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
273	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
274	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
275	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
276	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
277	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
278	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
279	13/11/17 15:08	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/10/17 08:21	Estimate from repairer	 Load PDF	
2	26/10/17 08:38	PARF & COE Rebate details	 Load PDF	
3	26/10/17 08:40	Road tax expiry date- 19/01/2018	 Load PDF	
4	22/10/19 16:30	Final repair bill+DV	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubl)	Thumbnail	Print
1	21/10/17 14:40	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	21/10/17 14:40	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/17 17:58	WORKSHOP ESTIMATE	 Load PDF	
2	27/10/17 16:10	DISAGREEMENT TO ADOPT 'COST PLUS' REPAIR BY WORKSHOP (OD CLAIM)	 Load PDF	
3	13/11/17 15:00	SUPPLEMENTARY LIST	 Load PDF	
4	30/11/18 14:07	SUPPLEMENTARY LIST-	 Load PDF	
5	04/12/18 09:43	REVISED ESTIMATE	 Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	21/10/17 14:45	Accident Statement		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	21/10/17 14:42	Accident Photo		Load JPG	☒
2	21/10/17 14:42	Accident Photo		Load JPG	☒
3	21/10/17 14:42	Accident Photo		Load JPG	☒
4	21/10/17 14:42	Accident Photo		Load JPG	☒
5	21/10/17 14:42	Accident Photo		Load JPG	☒
6	21/10/17 14:42	Accident Photo		Load JPG	☒
7	21/10/17 14:42	Accident Photo		Load JPG	☒
8	21/10/17 14:42	Accident Photo		Load JPG	☒
9	21/10/17 14:42	Accident Photo		Load JPG	☒
10	21/10/17 14:42	Accident Photo		Load JPG	☒
11	21/10/17 14:42	Accident Photo		Load JPG	☒
12	21/10/17 14:42	Accident Photo		Load JPG	☒
13	21/10/17 14:42	Accident Photo		Load JPG	☒
14	21/10/17 14:42	Accident Photo		Load JPG	☒
15	21/10/17 14:42	Accident Photo		Load JPG	☒
16	21/10/17 14:42	Accident Photo		Load JPG	☒
17	21/10/17 14:42	Accident Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	21/10/17 14:40	Accident Sketch Plan		Load JPG	☒
2	21/10/17 14:40	Accident Sketch Plan		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Notes: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17020497/AQBE2

Date: 29/11/2019

REFERENCE

Insured/Claimant:	BUDGETCARS PTE LTD	Policy No:	A28993175MKC	Claim No:	533652
Date of Loss:	20/10/2017	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3356T		Engine No:	YD25416286A
Make & Model:	NISSAN NV350, 2.5 D Panel Van (M)		Chassis No:	JN1MC2E26Z0008006
Reg. Date:	20/07/2017 (Man. Year: 2016)		Odometer:	14712 km
Colour:	White			
Engine Capacity:	2488 cc			
Market Value/New Car Price:	S\$80,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	42,908.32	23,115.23	19,793.09	46.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,740.00	5,450.00	2,290.00	29.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,648.32	28,565.23	22,083.09	43.60
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	50,048.32	27,965.23	22,083.09	44.12
+ GST 7.00/7.00% (S\$)	3,503.38	1,957.57	1,545.81	44.12
Nett Amount (S\$)	53,551.70	29,922.80	23,628.90	44.12

INSPECTION

Date of Assignment: 26/10/2017

Date Inspected: 26/10/2017 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 21.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Nov 2019)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3356T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DIESEL TANK	Distorted	1,174.70 FL	*1,174.70 FL
2	1		*FRONT BUMPER	Distorted	541.00 FL	*541.00 FL
3	2		*FRONT BUMPER FOGLAMP COVER L/R	N/S Cut / O/S Missing	228.40 FL	*228.40 FL
4	1		*FRONT BUMPER LOWER COVER	Cut	65.10 FL	*65.10 FL
5	1		*FRONT BUMPER REINFORCEMENT	Bent	667.10 FL	*667.10 FL
6	2		*FRONT BUMPER REINFORCEMENT BRACKET L/R	Not Necessary	221.80 FL	*- FL
7	2		*FRONT BUMPER SIDE RETAINER L/R	Necessary	311.20 FL	*311.20 FL
8	1		*FRONT BUMPER UPPER BEAM	Not Necessary	222.40 FL	*- FL
9	1		*FRONT CORNER PANEL LH	Dented	535.50 FL	*535.50 FL
10	1		*FRONT DOOR GLASS LH	Cut	760.00 FL	*760.00 FL
11	1		*FRONT DOOR LH	Dented	1,232.90 FL	*1,232.90 FL
12	1		*FRONT DOOR OUTER PILLAR RH	Dented	1,388.90 FL	*1,388.90 FL
13	2		*FRONT HEADLAMP PANEL L/R	Repair	706.20 FL	*- FL
14	1		*FRONT INSTRUMENT PANEL	Not Necessary	1,237.50 FL	*- FL
15	1		*FRONT LOWER PANEL	Repair	353.10 FL	*- FL
16	1		*FRONT PANEL	Dented	1,352.50 FL	*1,352.50 FL
17	1		*REAR BUMPER	Cracked	632.70 FL	*632.70 FL
18	1		*REAR LH FENDER	Dented	2,010.30 FL	*2,010.30 FL
19	1		*SLIDING DOOR LH	Dented	1,525.30 FL	*1,525.30 FL
20	1		*AIRCON BLOWER AIR DUCT	Not Necessary	88.70 FN	*- FN
21	1		*AIRCON BLOWER AIR DUCT CASING	Not Necessary	63.60 FN	*- FN
22	1		*DIESEL TANK FLOAT	Not Necessary	299.05 FN	*- FN
23	1		*DIESEL TANK HEAT SHIELD	Not Necessary	82.20 FN	*- FN
24	1		*DIESEL TANK LOWER COVER	Cut	297.30 FN	*297.30 FN
25	1		*ENGINE CROSS MEMBER - NO:1	Bent	415.65 FN	*415.65 FN
26	1		*ENGINE CROSS MEMBER - NO:2	Bent	415.65 FN	*415.65 FN
27	1		*ENGINE OIL SUMP	Not Necessary	214.30 FN	*- FN
28	1		*ENGINE UNDER COVER	Missing	273.60 FN	*273.60 FN
29	2		*FRONT ABS SENSOR L/R	Not Necessary	819.00 FN	*- FN
30	1		*FRONT BUMPER TOW HOOK COVER	Missing	21.10 FN	*21.10 FN
31	1		*FRONT CENTER BODY CROSS MEMBER	Not Necessary	392.30 FN	*- FN
32	1		*FRONT DOOR ARCH WEATHER STRIP LH	Cut	42.90 FN	*42.90 FN
33	1		*FRONT DOOR ARCH WEATHER STRIP LH	Cut	42.90 FN	*42.90 FN
34	1		*FRONT DOOR GLASS CHANNEL LH	Not Necessary	87.50 FN	*- FN
35	1		*FRONT DOOR GLASS CHANNEL LH	Not Necessary	67.50 FN	*- FN
36	1		*FRONT DOOR OUTER MOULDING LH	Cut	142.60 FN	*142.60 FN
37	1		*FRONT DOOR SIDE MIRROR GLASS LH	Cut	53.30 FN	*53.30 FN
38	1		*FRONT DOOR SIDE MIRROR LH	Missing	516.80 FN	*516.80 FN
39	1		*FRONT DOOR STEP GARNISH L/R	O/S Deformed	189.00 FN	*94.50 FN
40	1		*FRONT DOOR WEATHER STRIP LH	Not Necessary	91.10 FN	*- FN
41	1		*FRONT GRILLE	Missing	463.30 FN	*463.30 FN

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT GRILLE LOGO EMBLEM	Necessary	64.60 FN	*64.60 FN
43	2		*FRONT HEADLAMP L/R	Cracked	746.00 FN	*746.00 FN
44	1		*FRONT INSTRUMENT PANEL REINFORCEMENT	Not Necessary	497.20 FN	*- FN
45	1		*FRONT INTER COOLER	Dented	2,050.40 FN	*2,050.40 FN
46	1		*FRONT INTER COOLER CENTER PIPE	Bent	479.00 FN	*479.00 FN
47	1		*FRONT INTER COOLER PIPE BRACKET	Not Necessary	69.60 FN	*- FN
48	2		*FRONT KNUCKLE ARM L/R	Bent	818.00 FN	*818.00 FN
49	2		*FRONT LINKAGE L/R	Not Necessary	187.60 FN	*- FN
50	2		*FRONT LOWER ARM L/R	Bent	567.00 FN	*567.00 FN
51	1		*FRONT RH INTER COOLER HOSE	Cut	141.80 FN	*141.80 FN
52	1		*FRONT SIDE MIRROR COVER LH	Missing	105.00 FN	*105.00 FN
53	1		*FRONT STABILIZER BAR	Bent	360.90 FN	*360.90 FN
54	2		*FRONT STABILIZER BAR BRACKET L/R	Necessary	38.80 FN	*38.80 FN
55	2		*FRONT STABILIZER BAR BUSHING L/R	Necessary	37.00 FN	*37.00 FN
56	1		*FRONT STEERING RACK & PINION	Not Necessary	1,995.20 FN	*- FN
57	2		*FRONT STEERING TIE ROD END L/R	Not Necessary	159.00 FN	*- FN
58	2		*FRONT STEERING TIE ROD L/R	Not Necessary	230.40 FN	*- FN
59	2		*FRONT UPPER ARM L/R	Not Necessary	595.00 FN	*- FN
60	2		*FRONT WHEEL RIM L/R	Not Necessary	514.20 FN	*- FN
61	1		*FRONT WIPER GARNISH	Cut	227.48 FN	*227.48 FN
62	2		*FRONT WIPER GARNISH SIDE RUBBER L/R	Not Necessary	76.20 FN	*- FN
63	1		*FRONT WIPER LINKAGE	Not Necessary	325.00 FN	*- FN
64	6		*REAR BUMPER SIDE HOLDER CLIPS L/R	Necessary	105.00 FN	*30.00 FN
65	1		*REAR LH TAILLAMP	Cut	208.70 FN	*208.70 FN
66	1		*AIRCON BLOWER MOTOR	Cracked	575.90 FS	*575.90 FS
67	1		*AIRCON CONDENSER	Dented	501.10 FS	*501.10 FS
68	2		*AIRCON CONDENSER BRACKET L/R	Not Necessary	113.20 FS	*- FS
69	1		*AIRCON CONDENSER FAN MOTOR	Not Necessary	247.50 FS	*- FS
70	1		*AIRCON CONDENSER FAN MOTOR BLADE	Not Necessary	31.40 FS	*- FS
71	1		*AIRCON CONDENSER FAN MOTOR COWLING	Cut	107.80 FS	*107.80 FS
72	1		*AIRCON CONDENSER FAN MOTOR GRILLE	Not Necessary	66.50 FS	*- FS
73	1		*AIRCON CONDENSER LOWER GARNISH	Not Necessary	55.90 FS	*- FS
74	1		*AIRCON COOLING UNIT	Cracked	1,846.40 FS	*1,846.40 FS
75	1		*BRAKE FLUID	Necessary	40.00 FS	*40.00 FS
76	1		*SET DIESEL TANK LOWER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
77	2		*ENGINE MOUNTING L/R	Torn	152.60 FS	*152.60 FS
78	1		*ENGINE OIL	Not Necessary	300.00 FS	*- FS
79	1		*ENGINE OIL SUMP SEALANT	Not Necessary	50.00 FS	*- FS
80	2		*FRONT 195/15 TYRES L/R	Cut	600.00 FS	*360.00 FS
81	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
82	2		*FRONT BUMPER FOGLAMP L/R	N/S Cut / O/S Missing	621.80 FS	*621.80 FS
83	1		*SET FRONT DOOR COMPANY DETAIL STICKER	Necessary	160.00 FS	*60.00 FS
84	2		*SET FRONT DOOR ARCH PANEL GARNISH CLIPS L/R	Not Necessary	60.00 FS	*- FS
85	2		*SET FRONT DOOR INNER TRIM BOARD CLIPS L/R	Necessary	100.00 FS	*30.00 FS
86	2		*SET FRONT DOOR STEP GARNISH CLIPS L/R	Not Necessary	60.00 FS	*- FS
87	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*20.00 FS
88	2		*FRONT KNUCKLE ARM BEARING L/R	Damaged	311.00 FS	*311.00 FS
89	2		*FRONT LOWER ARM BALL JOINT L/R	Not Necessary	187.40 FS	*- FS
90	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
91	2		*FRONT SHOCK ABSORBER L/R	Bent	257.40 FS	*257.40 FS
92	2		*FRONT WHEEL HUB L/R	Damaged	904.00 FS	*904.00 FS
93	1		*FRONT WINDSCREEN E.R.P BRACKET	Not Necessary	50.00 FS	*- FS
94	1		*FRONT WINDSCREEN E.R.P BRACKET STICKER	Not Necessary	15.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
95	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
96	1		*SET FRONT WIPER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
97	1		*PROPELLER SHAFT COUPLING	Not Necessary	97.50 FS	*- FS
98	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
99	1		*REAR LH AXLE SHAFT	Not Necessary	283.20 FS	*- FS
100	1		*REAR LH AXLE SHAFT BEARING	Not Necessary	82.00 FS	*- FS
101	1		*REAR LH SHOCK ABSORBER	Bent	128.70 FS	*128.70 FS
102	1		*SET REAR LH TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
103	1		*SET SLIDING DOOR LH INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
104	1		*FRONT WIPER MOTOR	Not Necessary	352.00 FN	*- FN
105	2		*REAR LEAF SPRING L/R	Not Necessary	1,770.80 FN	*- FN
106	2		*DIESEL TANK BRACKET	Bent	190.40 FN	*190.40 FN
107	2		*DIESEL TANK BRACKET RUBBER	Necessary	83.00 FN	*83.00 FN
108	1		*FRONT STEERING GEAR	Not Necessary	1,066.70 FN	*- FN
109	1		*REAR RH SHOCK ABSORBER	Bent	128.70 FS	*128.70 FS
110	1		*REAR RH AXLE SHAFT	Not Necessary	283.20 FS	*- FS
111	1		*REAR RH AXLE SHAFT BEARING	Necessary	82.00 FS	*82.00 FS
112	1		*REAR AXLE CARRIAGE	Not Necessary	6,129.30 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

	Sub Total (S\$)	49,372.43	27,735.68
- List Item Discount on L Items 30.00/30.00% (S\$)	4,549.98	3,727.68	
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,914.13	892.77	
Total Parts (S\$)	42,908.32	23,115.23	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LIFTING UP VEHICLE FROM KERB, DRAIN AND TOWING	New	200.00	150.00
2	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS	New	180.00	120.00
3	TO RESET SYSTEM AFTER REPAIR WORKS	New	300.00	0.00
4	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	100.00	70.00
5	TO REMOVE, REINSTALL WINDSCREEN (TO FR)	New	150.00	120.00
6	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	500.00	420.00
7	TO REMOVE, REINSTALL BRAKE PARTS, BRAKE LINE, BRAKE PUMP AND BLEEDING BRAKE SYSTEM	New	150.00	60.00
8	TO REMOVE, CHANGE PETROL TANK	New	120.00	80.00
9	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	50.00
10	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	New	180.00	80.00
11	TO REMOVE, CHANGE DASHBOARD FASCIA AND TRANSFER WHERE NECESSARY	New	300.00	220.00
12	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	2,400.00	1,800.00
13	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,900.00	2,200.00
14	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM	New	120.00	80.00
Gross Labour Cost (\$\$)			7,740.00	5,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >