

ASS. REC. BY:

REF. CS/MSG17020535/Sgb

Special Instruction:

SURVEYOR
Munim

Sebastian

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time: 26/10/17 @ 3.41pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SLG 9282 P

Insured: SDM 9328 E

at Workshop m/s:

World Auto

Tel: 97588347

of No. 1 Kranji Loop, 739535

Policy No: 71510393 QMY

Claim No: 534354

Sum Insured:

Excess:

Make of Veh:

(Client's Record):

D.O.A. 24/10/2017

CA / REV / REP. / REV 24 HRS

Wup

27/10/17

R.O.D. Endorsement:

Date/Time: 26/10/17 @ 4.13pm

Person Contacted:

Mr. Sim

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimating

SLG 9282 P - x

SDM 9328 E - CC3/AIG13006117/Rpm 3g2 - D.O.A: 30/3/13

31/10/17 @ 4.14pm revised to Monica Chung via Munim.

11/1/18 @ 2.37pm Sebastian finalised with Mr Sim final fig \$5029.60 thru email.
(Red \$1988.48, 28%)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17020535/Sqb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-10-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDM 9328E	Veh. Inspected	SLG 9282P
Policy No.	71510393QMY	Coverage (\$)	0.00
Claim No.	534354	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	26/10/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages**5. General Information**

Accident Date	24/10/2017	Inspection Date
Survey held at	NO.1 KRANJI LOOP, 739535	
Repairer	WORLD AUTO PTE LTD	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Reference No.: C01M5G17070838 / Syb
Policy Type: OD / TP / TP RES / TL / EVA

SLG 9282P

Typist

(1) Office Assign Form

C	Reference No.	✓		
C	Customer Code	✓		
N	Assign From	✓		
C	Assign Date	✓		
C	Veh No (Inspected)	✓		
C	Veh No (Insured)	✓		
C	D.O.A	✓		
C	Policy No	✓		
C	Claim No	✓		
C	Insurance Authorisation (CA /REV/REP)			
C	Report Type	✓		
C	Weekend Charges			
N	Survey held at/Repairer	✓		
C	Excess			

(1) Assignment Form

[illegible]

C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

N	ALL Parts condition
C	Market Value for OD cases
C	Estimate Repair Cost for PRI (RSI, TMI, MSI/G)
C	Days of repair
C	Finalised Amount
C	Re-inspection Cases to Finalize within 5 Days

✓	
✓	
✓	

C Resurvey photo Uploaded

--	--

Case Handler Ch Date 2/11/18

Case Handler

Date _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2017		26 Oct 2017 15:41 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	LEONG KUM SENG , ID: S1172973H		[Created by insurer]	
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K			
Vehicle Reg. No.:	SLG9282P	Date of Loss:		24/10/2017 10:00 - :59
Claim Type:	TP / 534354	Policy/Cover Note No.:		71510393QMY (Comprehensive)
Vehicle Reg. No. (Insured):	SDM9328E	Policy No. (Claimant):		Coverage: 20/03/2017 - 19/03/2018
		Excess:		
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/10/2017]			
Driver/Custodian (Insured):	LIM SIEW LEE () , NRIC: S2674575F, Tel: +6582339738			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Nur Amirah Binte Mohamed Yunos

From: Rashitha Binte Shahuthuman
Sent: Thursday, October 26, 2017 2:07 PM
To: Nur Amirah Binte Mohamed Yunos
Cc: Tan Jin Hao
Subject: FW: 3rd party survey for SLG 9282P

Follow Up Flag: Follow up
Flag Status: Flagged

From: Rashitha Binte Shahuthuman
Sent: Thursday, 26 October, 2017 2:02 PM
To: 'Sim' <sim@worldauto.com.sg>
Cc: Monica Chung <Monica_Chung@sg.msigg-asia.com>; Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msigg-asia.com>
Subject: RE: 3rd party survey for SLG 9282P

OUR REF - TBC

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Thank you.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of  INSURANCE GROUP

From: sim@worldauto.com.sg [<mailto:sim@worldauto.com.sg>]

Sent: 26 October 2017 11:27

To: Claims <claims@sg.msig-asia.com>

Subject: Re: 3rd party survey for SLG 9282P

Dear sir

Please arrange a 3rd party surveyor to survey the following car

Our client: SLG 9282P

Your Insured: SDM 9328E

Date of accident: 24/10/17

Regards

S.T.Sim

World Auto Pte Ltd

No 1 Kranji Loop

Singapore 739535

Mobile: 97588347

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAuto)

From: sim@worldauto.com.sg
Sent: Thursday, 11 January, 2018 2:32 PM
To: Sebastian Yeang (LKK Auto)
Cc: Shiau Chan (LKKAuto)
Subject: RE: SLG9282P finalization

Without Prejudice

Dear sir

Ok confirm \$5,029.60

Regards

From: Sebastian Yeang (LKK Auto) [mailto:SebastianYeang@lkkauto.com]
Sent: Wednesday, January 10, 2018 3:01 PM
To: sim@worldauto.com.sg
Cc: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: SLG9282P finalization

Dear Sim

Please refer to attachment for the finalization.

Thank You

CS/MSG17020535/Sqb

Best Regards,

Sebastian | Automotive Assessor

LKK Auto Consultants

phone: 6256-3561 | email: sebastianyeang@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 31 Oct 2017

Preliminary Advice

Insured Vehicle No	: SDM9328E	Accident Date	: 24/10/2017
TP Vehicle No	: SLG9282P	Assignment Date	: 26/10/2017
Make	: HONDA VEZEL	Est. Duration of Repair	: 7.00
Date of Inspection	: 27/10/2017		
Inspection At	: WORLD AUTO PTE LTD - KRANJI (HQ) NO 1 KRANJI LOOP SINGAPORE 739535		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,667.68
Revised Amount	:S\$	5,350.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,350.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	4597K
Vehicle Details	
Vehicle No.	SLG9282P
Vehicle to be Exported	No
Intended De-registration Date	31 Oct 2017
Vehicle Make	HONDA
Vehicle Model	VEZEL HYBRID 1.5 A
Primary Colour	Silver
Manufacturing Year	2016
Engine No.	LEB5911018
Chassis No.	RU31211007
Maximum Power Output	112.0 kW (150 bhp)
Open Market Value	\$23,374.00
Original Registration Date	18 Oct 2016
First Registration Date	18 Oct 2016
Transfer Count	1
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	17 Oct 2026
PARF Rebate Amount	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date	17 Oct 2026
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,010.00
COE Rebate Amount	\$51,094.00
Total Rebate Amount	\$54,844.00

The information contained herein is correct as at 31 Oct 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2017 17:57
Date Of Accident	24/10/2017 10:00
Exact Location Of Accident	OLD AIRPORT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG9282P
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81016628

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	LOH CHIN WEE
NRIC No	S7244588J
Date Of Birth	29/01/1972
Occupation	OUTDOOR
Date Of Driving Pass	02/02/1993
Driving Experience	24 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PAID DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDM9328E
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

 24/10/17 1240 hrs
Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident

On 24/10/17 Time 1000hrs at Old Airport Road Junction
toward Stadium Boulevard, I was at the third lane, turning
right to Manhattan Road, I was waiting for the traffic light to change
green, The Vehicle SDU 532RE hit my Vehicle SG 9262P
from behind.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time



 24/10/17 1240hrs
Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Attention : Motor Claim Department

Estimate : ES00514

Date : 24/10/2017

Vehicle Num. : SLG 9282P (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/10/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR TAILGATE (VEZEL) ✓ DT	1100	1,450.00
2.	1	REAR TAILGATE HYBRID EMBLEM (VEZEL) ✓ NEC		86.80
3.	1	REAR TAILGATE VEZEL EMBLEM(VEZEL) ✓ NEC		86.80
4.	1	REAR WINDSCREEN GLASS MOULDING(VEZEL) ✓ NEC	170	195.00
5.	1	REAR TAILGATE WEATHERSTRIP (VEZEL) ✓ CUT		155.00
6.	1	REAR END PANEL TOP GARNISH (VEZEL) ✓ CRK		155.00
7.	1	REAR END PANEL (VEZEL) ✓ DT	630	830.00
8.	1	REAR BUMPER ASSY (VEZEL) ✓ DT		955.00
List Total S\$:				3,913.60
20.00% Discount S\$:				782.72
				3,130.88

SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR (VEZEL) ✓ DMG		280.00 200
2.	8	REAR END TOP PANEL TOP GARNISH CLIPS (VEZEL) ✓ NEC	9.80	78.40 30
3.	8	REAR BUMPER CLIPS (VEZEL) ✓ NEC	9.80	78.40 30
4.	1	REAR WINDSCREEN SEALANT ✓ NEC		160.00 40
Special Nett Total S\$:				596.80
LABOUR :				
TRANSFER TAILGATE DOOR MECHANISM (VEZEL)				120.00 50

CONTINUE / ...


 Sebastian
 29/10/2017
 - Part by part repair
 - Question Mark Item
 Photo
 - Photo Before Paint
 90036121

Sebastiangeang@lkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD**Estimate : ES00514**

Date : 24/10/2017

Vehicle Num. : SLG 9282P (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/10/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

REMOVE AND INSTALL REAR WINDSCREEN (VEZEL)

To labour charge for removing rear tailgate, rear bumper and end panel out to facilitate repairs and replacement of damaged part

To respray rear tailgate, rear bumper, end panel

To deactivate and activate high voltage hybrid battery as a requirement for safety precautions

To conduct a standard of operating procedure post repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs

Labour Total S\$:

160.00 170

1,000.00 700

900.00 600

380.00 250

380.00 200

2,940.00

E. & O.E.**Total S\$:****6,667.68**

=====

for WORLD AUTO PTE LTD

7018.08

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Attention : Motor Claim Department

Estimate : ES00514

Date : 24/10/2017

Vehicle Num. : SLG 9282P (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/10/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE (VEZEL) ✓ DT		1,450.00 1100
2.	1	REAR TAILGATE HYBRID EMBLEM (VEZEL) ✓ NRC		86.80
3.	1	REAR TAILGATE VEZEL EMBLEM (VEZEL) ✓ NRC		86.80
4.	1	REAR WINDSCREEN GLASS MOULDING (VEZEL) ✓ NRC		195.00 170
5.	1	REAR TAILGATE WEATHERSTRIP (VEZEL) ✓ CUT		155.00
6.	1	REAR END PANEL TOP GARNISH (VEZEL) ✓ CRK		155.00
7.	1	REAR END PANEL (VEZEL) ✓ DT		830.00 630
8.	1	REAR BUMPER ASSY (VEZEL) ✓ DT		955.00
List Total S\$:				3,913.60
20.00% Discount S\$:				782.72
				3,130.88
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR (VEZEL) ✓ DMC		280.00 200
2.	8	REAR END TOP PANEL TOP GARNISH CLIPS (VEZEL) ✓ NRC	9.80	78.40 30
3.	8	REAR BUMPER CLIPS (VEZEL) ✓ NRC	9.80	78.40 30
4.	1	REAR WINDSCREEN SEALANT ✓ NRC		160.00 40
Special Nett Total S\$:				596.80
LABOUR :				
TRANSFER TAILGATE DOOR MECHANISM (VEZEL)				120.00 50

CONTINUE / ...

Sebastian.
27/10/2017
- Part by part repair.
- Question Mark Item
Photo
- Photo Before Paint
90076121

Sebastiangeang@lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 677200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES00514

Date : 24/10/2017

Vehicle Num. : SLG 9282P (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/10/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND INSTALL REAR WINDSCREEN (VEZEL)		160.00 120
		To labour charge for removing rear tailgate, rear bumper and end panel out to facilitate repairs and replacement of damaged part		1,000.00 700
		To respray rear tailgate, rear bumper, end panel		900.00 600
		To deactivate and activate high voltage hybrid battery as a requirement for safety precautions		380.00 250
		To conduct a standard of operating procedure post repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs	1920	380.00 200
		Labour Total S\$:		2,940.00

E. & O.E.

Total S\$:

6,667.68

for WORLD AUTO PTE LTD

1) Parts : \$ 2,670.88

2) S/Nett : \$ 300.00

3) Labour : \$ 1,920.00

4) Supplementary \$ 138.72

\$ 5,029.60 @ 4 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2017		26 Oct 2017 15:41 Edit Adj Rpt	S\$5,029.60 Edit Estimates	S\$5,029.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	LEONG KUM SENG, ID: S1172973H	
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K	
Vehicle Reg. No.:	SLG9282P	Date of Loss: 24/10/2017 10:00 - :59
Claim Type:	TP / 534354	Policy/Cover Note No.: 71510393QMY (Comprehensive) Coverage: 20/03/2017 - 19/03/2018
Vehicle Reg. No. (Insured):	SDM9328E	Policy No. (Claimant):
		Excess:
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 25/11/2017]	
Driver/Custodian (Insured):	LIM SIEW LEE (), NRIC: S2674575F, Tel: +6582339738	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SLG9282P (534354)
[SDM9328E]
TP
LCRF PTE LTD
Oct 24 2017 10:00AM
[LEONG KUM SENG]
World Auto Pte Ltd - Kranji

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports				3 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/10/17 16:14	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/01/18 10:29	General View		Load JPG	☒
2	02/01/18 10:29	General View		Load JPG	☒
3	02/01/18 10:29	General View		Load JPG	☒
4	02/01/18 10:29	General View		Load JPG	☒
5	02/01/18 10:29	General View		Load JPG	☒
6	02/01/18 10:29	General View		Load JPG	☒
7	02/01/18 10:29	General View		Load JPG	☒
8	02/01/18 10:29	General View		Load JPG	☒
9	02/01/18 10:29	General View		Load JPG	☒
10	02/01/18 10:29	General View		Load JPG	☒
11	02/01/18 10:29	General View		Load JPG	☒
12	02/01/18 10:29	General View		Load JPG	☒
13	02/01/18 10:29	General View		Load JPG	☒
14	02/01/18 10:29	General View		Load JPG	☒
15	02/01/18 10:29	General View		Load JPG	☒
16	02/01/18 10:29	General View		Load JPG	☒
17	02/01/18 10:29	General View		Load JPG	☒
18	02/01/18 10:29	General View		Load JPG	☒
19	02/01/18 10:29	General View		Load JPG	☒
20	02/01/18 10:29	General View		Load JPG	☒
21	02/01/18 10:29	General View		Load JPG	☒
22	02/01/18 10:29	General View		Load JPG	☒
23	02/01/18 10:29	General View		Load JPG	☒
24	02/01/18 10:29	General View		Load JPG	☒
25	02/01/18 10:29	General View		Load JPG	☒
26	02/01/18 10:29	General View		Load JPG	☒
27	10/01/18 14:59	PHOTO BEFORE PAINT		Load JPG	☒
28	10/01/18 14:59	PHOTO BEFORE PAINT		Load JPG	☒
29	10/01/18 14:59	PHOTO BEFORE PAINT		Load JPG	☒
30	10/01/18 14:59	PHOTO BEFORE PAINT		Load JPG	☒
31	10/01/18 14:59	PHOTO BEFORE PAINT		Load JPG	☒
32	10/01/18 14:59	PHOTO BEFORE PAINT		Load JPG	☒

33	10/01/18 14:59	PHOTO BEFORE PAINT		Load JPG	☒
Documentation					
			1 per page		☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	26/10/17 15:13	Email from Third Party		Load PDF	
2	26/10/17 15:14	OI GIA Rep - SDM 9328E		Load PDF	
3	26/10/17 15:14	TP GIA Rep - SLG 9282P		Load PDF	
4	26/10/17 15:44	TP WORKSHOP NOMINATE LKK TO BE THE SJE		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/02/18 10:39	SUPPLEMENTARY PART		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020535/SQBQ2

Date: 01/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 71510393QMY
 Claimant Vehicle No: SLG9282P Insured Vehicle No: SDM9328E
 Date of Loss: 24/10/2017 Nature of Claim: TP Claim No: 534354

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG9282P
 Make & Model: HONDA VEZEL, 1.5 HYBRID (A) Engine No: LEB5911018
 Reg. Date: 18/10/2016 (Man. Year: 2016) Chassis No: RU31211007
 Colour: Silver Odometer: 75292 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,078.08	3,109.60	968.48	23.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	1,920.00	1,020.00	34.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,018.08	5,029.60	1,988.48	28.33
+ GST 7.00/7.00% (S\$)	491.27	352.07	139.20	28.33
Nett Amount (S\$)	7,509.35	5,381.67	2,127.68	28.33

INSPECTION

Date of Assignment: 26/10/2017
 Date Inspected: 27/10/2017 Inspected At: World Auto Pte Ltd - Kranji (HQ)
 No 1 Kranji Loop
 Singapore 739535
 Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG9282P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE (VEZEL)	Dented	1,450.00 FL	*1,100.00 FL
2	1	*REAR TAILGATE HYBRID EMBLEM (VEZEL)	Necessary	86.80 FL	*86.80 FL
3	1	*REAR TAILGATE VEZEL EMBLEM (VEZEL)	Necessary	86.80 FL	*86.80 FL
4	1	*REAR WINDSCREEN GLASS MOULDING (VEZEL)	Necessary	195.00 FL	*170.00 FL
5	1	*REAR TAILGATE WEATHERSTRIP (VEZEL)	Cut	155.00 FL	*155.00 FL
6	1	*REAR END PANEL TOP GARNISH (VEZEL)	Cracked	155.00 FL	*155.00 FL
7	1	*REAR END PANEL (VEZEL)	Dented	830.00 FL	*630.00 FL
8	1	*REAR BUMPER ASSY (VEZEL)	Dented	955.00 FL	*955.00 FL
9	1	*REVERSE SENSOR (VEZEL)	Damaged	280.00 FS	*200.00 FS
10	8	*REAR END TOP PANEL TOP GARNISH CLIPS (VEZEL)	Necessary	78.40 FS	*30.00 FS
11	8	*REAR BUMPER CLIPS (VEZEL)	Necessary	78.40 FS	*30.00 FS
12	1	*REAR WINDSCREEN SEALANT	Necessary	160.00 FS	*40.00 FS
13	1	*REAR RH SIDE BUMPER (VEZEL)	Deformed	258.00 FL	*173.40 FL
14	1	*REAR RH FENDER SIDE AIR VENTILATOR (VEZEL)	Not Necessary	180.00 FL	*- FL
				Sub Total (S\$)	4,948.40 3,812.00
				- List Item Discount on L Items 20.00/20.00% (S\$)	870.32 702.40
				Total Parts (S\$)	4,078.08 3,109.60

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER TAILGATE DOOR MECHANISM (VEZEL)	New	120.00	50.00
2	REMOVE AND INSTALL REAR WINDSCREEN (VEZEL)	New	160.00	120.00
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR BUMPER AND END PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,000.00	700.00
4	TO RESPRAY REAR TAILGATE ,REAR BUMPER ,END PANEL	New	900.00	600.00
5	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	380.00	250.00
6	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	380.00	200.00
Gross Labour Cost (S\$)			2,940.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >