

INS. REC. BY:

REF:

CS/ECU17020583 / St b27

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Siti

of

ECN

Date/Time:

26/10/2017 8:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLS 11481X

Insured:

SJH 6605K

at Workshop m/s

Kah motor

Tel:

8288 6319

of

6A Munda Estate

Policy No:

Claim No:

SJH 6605K / SE / plsa

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

27/10/2017 9:20am

Person Contacted:

JASON.

Vehicle IN / OUT

26263 44

Date/Time	Action/Instruction (✓) Estimate
	SLS 11481X - X
	SJH 6605K - X
	Part by part \$17,387.00 (Red: 8876.30 1339.)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLS 1481X Yr Regn: 11/9/2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Honda Odyssey C.C. 2356
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 2926 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: J4MRC18864C 203563*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Dunlop

Front	Rear
R/Bal. <u>1</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>12/10/2017</u>	D.O.I. <u>17/10/2017</u>

Survey held at Kah motor

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

RECEIVED

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) S + RS. SI

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

Report Format : TP

Lump Sum / I.B.I. (\$) 17387.06

TOTAL

390



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI17020583/Stb		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 27-10-2017		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 6605K	Veh. Inspected	SLS 1481X	
Policy No.		Coverage (\$)	0.00	
Claim No.	SJG6605K/SE/pl.sa	Excess (\$)	0.00	
Assign From	SITI	Assign Date	27/10/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/10/2017	Inspection Date		
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
5a. Remarks				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SJG6605K/SE/pl.sa
Our Ref: CS/EG117020583/Stb

Date: 29/12/2017

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SLS 1481X.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/10/2017 at the premises of M/s Kah Motor and have the following to report:-

Workshop Estimate Amount	: S\$ 25,712.94
Revised Estimate Amount	: S\$ 17,387.06
"Check" Items Amount	: S\$ -
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages
At front and rear portion.



Repair days: 12 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully
Kenneth
Automotive Assessor

Catherine Chong (LKK Auto)

From: Siti A Thikah AB Rahman <siti.rahman@ergo.com.sg>
Sent: Thursday, 26 October, 2017 8:44 PM
To: Catherine Chong (LKK Auto) (admin-d@lkkauto.com)
Subject: RE: SJG 6605K | TP: SLS 1481X | LKK | DOA: 22.10.2017 - PRS | OUR REF: SJG6605K/SE/pl.sa
Attachments: 0248_001.pdf

Hi Catherine,

Attached the estimate.

Thank you.

Warmest regards
Siti A Thikah
Claims Department
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 (Ext: 170)
Fax: 65 6829 9247
Email: siti.rahman@ergo.com.sg
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.

 **BUY NOW**

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re, one of the world's leading reinsurers and risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

From: Siti A Thikah AB Rahman
Sent: Thursday, 26 October, 2017 8:42 PM
To: Catherine Chong (LKK Auto) (admin-d@lkkauto.com)
Subject: OI: SJG 6605K | TP: SLS 1481X | LKK | DOA: 22.10.2017 - PRS | OUR REF: SJG6605K/SE/pl.sa
Importance: High

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company LKK Auto Consultants Pte Ltd to be the "Single Joint Expert".

Please conduct this survey request and confirm direct settlement the repairer.

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest regards
Siti A' thikah
Claims Department
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 (Ext: 170)
Fax: 65 6829 9247
Email: siti.rahman@ergo.com.sg
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte Ltd

 **BUY NOW**

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re, one of the world's leading reinsurers and risk carriers.

From: Jason Heng [<mailto:jasonheng@honda.com.sg>]

Sent: Thursday, 26 October, 2017 2:59 PM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO: SLS1481X AGAINST SJG6605K. Accident date on 22/10/2017

Importance: High

Dear Pei Li,

My clients wants to do the survey tomorrow. Please advise if the PRS is assigned to Formteam or LKK.

Thank you.

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: Jason Heng

Sent: Wednesday, 25 October, 2017 4:04 PM

To: 'ERGO Insurance Pte. Ltd. (Claims Department)' <claims@ergo.com.sg>

Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO: SLS1481X AGAINST SJG6605K. Accident date on 22/10/2017

Dear Pei Li

We refer to the above accident and your e-mail on 25/10/2017.

We confirm that liability was clear and fully in our client's favour and he is wishing to do a direct settlement with ERGO Insurance with regard to the above accident.

With this agreement, Kah Motor will proceed with the repairs to our client's vehicle and thereafter submit our final repair invoice and other supporting documents in relation to our client's claim.

Propose to use either FormTeam or LKK to conduct the PRS.

Thank you.

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: ERGO Insurance Pte. Ltd. (Claims Department) [mailto:claims@ergo.com.sg]

Sent: Wednesday, 25 October, 2017 3:45 PM

To: Jason Heng <jasonheng@honda.com.sg>

Subject: RE: DIRECT SETTLEMENT OF VEHICLE NO: SLS1481X AGAINST SJG6605K. Accident date on 22/10/2017

WITHOUT PREJUDICE

Dear Sirs,

We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed

Please find enclosed surveyor list for your action. Kindly indicate your selection in the box * upon completion, please email back for our action.

Await reply within 2 working days.

For PRS request, kindly reply via claims@ergo.com.sg.

Appreciated your co-operation.

Thank you.

Best Regards

Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel : 65 6829 9199 / DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



Have you tried our new travel insurance product yet?
TravelProtect comes with comprehensive benefits at some of the most affordable prices available in the market.

ERGO
TravelProtect
your Global Safety Net

TravelProtect is underwritten by ERGO Insurance Pte. Ltd.

 **BUY NOW**

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re, one of the world's leading reinsurers and risk carriers.

From: Jason Heng [<mailto:jasonheng@honda.com.sg>]

Sent: Wednesday, 25 October, 2017 3:40 PM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Subject: FW: DIRECT SETTLEMENT OF VEHICLE NO: SLS1481X AGAINST SJG6605K. Accident date on 22/10/2017

Dear Officer-in-charge,

Please see revised attachments. There was a typo error on the third party claim vehicle number.

Regards,
Jason

Mandai Body & Paint Centre
Kah Motor Sdn Bhd
Mobile: 82886309

From: Jason Heng

Sent: Wednesday, 25 October, 2017 2:52 PM

To: 'ERGO Insurance Pte. Ltd. (Claims Department)' <claims@ergo.com.sg>

Subject: DIRECT SETTLEMENT OF VEHICLE NO: SLS1481X AGAINST SGQ2317B. Accident date on 22/10/2017

Dear Officer-in-charge,

Kindly refer to the attachments for third party direct settlement.

Vehicle is not in our premise. Please advised a suitable date for a survey.

Meanwhile, kindly get back to me once liability has establish.

Thank you very much

Regards,
Jason

Jason Heng
Kah Motor Body & Paint Centre
6A Mandai Estate
Singapore 729903
DID: 65145248
Mobile: 82886309
Email: jasonheng@honda.com.sg

KAHMOTOR
(A MEMBER OF ORIENTAL HOLDINGS BERHAD)

HONDA
The Power of Dreams

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2017 19:48
Date Of Accident	22/10/2017 13:50
Exact Location Of Accident	PIE TOWARDS CHANGI (AFT ADAM FLYOVER)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS1481X
Insured/Policyholder	
Name Of Registered Owner	GOH CHERN-YU CHRISTOPHER
NRIC No	S7329011B
Email Address	CHRISTOPHERGOHCY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81023110
Alternative Phone No	OTHERS-81023110

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY-2.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V10633/R0
Cover Note Number	

Driver

Name of Driver	GOH CHERN-YU CHRISTOPHER
NRIC No	S7329011B
Date Of Birth	01/08/1973
Occupation	INDOOR
Date Of Driving Pass	21/10/1991
Driving Experience	26 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81023110
Fax Number	
Contact Number	OTHERS-81023110
Email Address	CHRISTOPHERGOHCY@GMAIL.COM

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name CHOA CHU KANG NPC
Police Station Address ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 ,
COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: OWNER HAVE NOT SUBMITTED AT TIME OF FILING
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGQ2317B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver PEH SIONG KEE
NRIC/Passport Number S7243947C
Contact Number 92219979
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJG6605K

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver MUHAMMAD IMRAN BIN AHMAD

NRIC/Passport Number S9002299G

Contact Number 91259584

Address

Postcode

Insurance Company Name ERGO INSURANCE PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SCG5208Y

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver LIM CHENG ZHONG, PAUL MATTHEW

NRIC/Passport Number S8835819H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJG6605K

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Vehicle No SLS 1481X**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Refer to attached

Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No <u>SLS1481X</u>	Annex E	
Describe Circumstances of the Accident		
<p>Refer to attached statement.</p>		
Declaration		
We declare the foregoing particulars are true in every respect.		
Policyholder's Signature / Date & Time	Driver's Signature (If driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT17004370	Page	1
	5 TEMASEK BOULEVARD	Date	: 25. Oct 2017		
	#04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	SINGAPORE 038985	Svc Advisor	: JASON HENG		
Registration No	: SLS1481X	Engine No	: K24W72041169		
Chassis No	: JHMRC1880HC203523	Date Time	: 25. Oct 2017 10:09:31 AM		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Surveyor Name	:		
Owner's Name	: GOH CHERN-YU CHRISTOPHER	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	THIRD PARTY CLAIMS (J/NO:)						
	OWNER: GOH CHERN-YU CHRISTOPHER						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 22/10/17						
	SURVEYED BY:						
	DATE:						
	TP INSURER: ERGO INSURANCE PTE LTD						
	TP VEH: SJG6605K						
	REF:						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) ✓ BT ✓	1	45.00		45.00 ✓	3.15	48.15
04711-T6A-000ZZ	FACEFR.BUMPER ✓ cut ✓	1	677.60	25	508.20 ✓	35.57	543.77
71105-T6A-003	GRILLEFR.BUMPER LOWER X NW	1	75.30	25	X 56.47	3.95	60.42
71151-T6A-003	BASEMID GRILLE ✓ CRK	1	215.10	25	161.32 ✓	11.29	172.61
71152-T6A-003	UPPER MOLDINGMID GRILLE ? BT -	1	86.00	25	64.50 ✓	4.52	69.02
71153-T6A-003	LOWER MOLDINGMID GRILLE ? x NW	1	86.00	25	X 64.50	4.52	69.02
71121-T6A-003	BASEFR.GRILLE ✓ CRK ? Deform - NW	1	165.70	25	X 124.27	8.70	132.97
71122-T6A-003	MOLDINGFR.GRILLE ✓ cut ✓	1	258.10	25	193.57 ✓	13.55	207.12
75700-TA0-A00	EMBLEMFR. ✓ NEC ✓	1	25.30	25	18.97 ✓	1.33	20.30
90301-ST0-003	NUTPUSH 3MM ✓ NEC ✓	2	1.90	25	2.85 ✓	0.20	3.05
71193-T6A-003	SPACERR.FR.BUMPER SIDE ✓ NEC ✓	1	11.60	25	8.70 ✓	0.61	9.31
71198-T6A-003	SPACERL.FR.BUMPER SIDE ✓ NEC ✓	1	11.60	25	8.70 ✓	0.61	9.31
91505-TM8-003	CLIPBUMPER ✓ NEC ✓	16	2.00	25	24.00 ✓	1.68	25.68
71104-T6A-003	GARNISHR.FR.BUMPER ? x NW	1	40.90	25	X 30.67	2.15	32.82
71109-T6A-003	GARNISHL.FR.BUMPER ? x NW	1	40.90	25	X 30.67	2.15	32.82
60100-T6A-000ZZ	HOOD COMP ✓ DT ✓	1	658.30	25	493.72 ✓	34.56	528.28
19043-PNB-A00	LABELCOOLANT INFORMATION ? x NW	1	4.90	25	X 3.67	0.26	3.93
80050-SP0-000	LABELAIR CONDITIONER CAUTION ? x NW	1	1.80	25	X 1.35	0.09	1.44
60210-T6A-300ZZ	FENDER COMPR.FR. R	1	537.80	25	X 403.35	28.23	431.58
60260-T6A-300ZZ	FENDER COMPL.FR. R	1	537.80	25	X 403.35	28.23	431.58
71140-T6A-003	BEAMR.FR.BUMPER UPPER ? x NW	1	34.20	25	X 25.65	1.80	27.45

2673.48



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 OSUNTEC TOWER FIVE
SINGAPORE 038985
Registration No : SLS1481X
Chassis No : JHMRC1880HC203523
Model : ODYSSEY 2.4 EX-S 17YM (EURO 6)
Owner's Name : GOH CHERN-YU CHRISTOPHER
Ins Policy No. :
Date of Accident :

Document No. : SQT17004370 **Page** 2
Date : 25. Oct 2017
Customer No. : WZN004
Svc Advisor : JASON HENG
Engine No : K24W72041169
Date | Time : 25. Oct 2017 10:09:31 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
71190-T6A-003	BEAML.FR.BUMPER UPPER ? x 3	1	34.20	25	X 25.65	1.80	27.45
33100-T6A-Q01	HEADLIGHT ASSYR. ? x 3	1	886.30	25	X 664.72	46.53	711.25
33150-T6A-Q01	HEADLIGHT ASSYL. ? x 3	1	886.30	25	X 664.72	46.53	711.25
71130-T6A-310ZZ	BEAM COMP.FR.BUMPER ? x 1 DT ✓	1	291.80	25	214.57	15.32	234.17
80111-T6A-003	CONDENSER COMP ? x 3	1	668.60	25	X 501.45	35.10	536.55
19010-5X6-J02	RADIATOR COMP ? x 1	1	1320.90	25	X 990.67	69.35	1060.02
04715-T6A-000ZZ	FACERR.BUMPER ✓ Deform ✓	1	527.00	25	395.25 ✓	27.67	422.92
71502-T6A-003ZG	FACER.RR.BUMPER GARNISH Deform ✓	1	75.30	25	56.47 ✓	3.95	60.42
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ✓ DMG ✓	1	320.00		320.00 ✓	22.40	342.40
33505-SLJ-013	REFLECTOR ASSYR.RR. ? x 1 ✓	1	44.50	25	33.37 ✓	2.34	35.71
71593-T6A-003	SPACERR.RR.BUMPER SIDE ✓ NEC ✓	1	18.70	25	14.02 ✓	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE ✓ NEC ✓	1	18.70	25	X 14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER ✓ NEC ✓	9	2.00	25	13.50 ✓	0.95	14.45
68100-T6A-Q10ZZ	TAILGATE COMP ✓ DT ✓	1	1049.80	25	787.35 ✓	55.11	842.46
75701-T6A-000	EMBLEMH ✓ NEC ✓	1	25.80	25	19.35 ✓	1.35	20.70
74440-T6A-003	WEATHERSTRIPTAILGATE ✓ Deform ✓	1	115.10	25	86.32 ✓	6.04	92.36
74827-S2G-010	PROTECTORLICENSE PLATE ✓ NEC ✓	2	2.00	25	3.00 ✓	0.21	3.21
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN ? x 1	1	172.10	25	X 29.07	9.03	138.10
74800-TF0-J02	LOCKTAILGATE ✓ 3m ✓	1	181.70	25	136.27 ✓	9.54	145.81
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL ? x 1 Deform.	1	10.50	25	7.87 ✓	0.55	8.42
33500-T6A-003	TAILLIGHT ASSYR. ? x 3	1	821.80	25	X 616.35	43.14	659.49
33550-T6A-003	TAILLIGHT ASSYL. ? x 3	1	821.80	25	X 616.35	43.14	659.49
34150-T6A-003	LIGHT ASSYR.LID ✓ CRK ✓	1	378.60	25	283.95 ✓	19.88	303.83
34155-T6A-003	LIGHT ASSYL.LID ✓ CRK ✓	1	378.60	25	283.95 ✓	19.88	303.83
84640-T6A-003ZA	LINING ASSYRR.PANEL ? Deform	1	101.60	25	76.20 ✓	5.33	81.53
84643-T6A-Q01ZA	COMP LIDTOOL ? x 1	1	60.20	25	45.15	3.16	48.31
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER ? Deform	1	202.20	25	151.65 ✓	10.62	162.27
66100-T6A-300ZZ	PANEL COMPRR. ? DT	1	451.80	25	338.85 ✓	23.72	362.57
04656-T6A-310ZZ	PAN SET,3RD SEAT ? DT	1	337.90	25	253.42 ✓	17.74	271.16
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE ✓ NEC	2	17.60	25	26.40 ✓	1.85	28.25

Printed on 25/10/2017 2:46:25 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: ERGO INSURANCE PTE LTD	Document No.	: SQT17004370	Page	3
	5 TEMASEK BOULEVARD	Date	: 25. Oct 2017		
	#04-01 OSUNTEC TOWER FIVE	Customer No.	: WZN004		
	SINGAPORE 038985	Svc Advisor	: JASON HENG		
Registration No	: SLS1481X	Engine No	: K24W72041169		
Chassis No	: JHMRC1880HC203523	Date Time	: 25. Oct 2017 10:09:31 AM		
Model	: ODYSSEY 2.4 EX-S 17YM (EURO 6)	Surveyor Name	:		
Owner's Name	: GOH CHERN-YU CHRISTOPHER	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	:				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount Incl GST
73215-T6A-003	MOLDINGRR.WINDSHIELD CORNER ✓ NEC /	1	16.60	25	12.45 ✓	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER ✓ NEC /	1	16.60	25	12.45 ✓	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD ✓ NEC /	4	3.90	25	11.70 ✓	0.82	12.52
73225-TM8-000	RUBBER A/WINDSHIELD DAM ✓ NEC /	1	3.60	25	2.70 ✓	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5 ✓ NEC /	2	8.30	25	12.45 ✓	0.87	13.32
76711-T6A-003	CAPPVOT ✓ NEC /	1	4.70	25	3.52 ✓	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ✓ NEC /	2	60.00		120.00	8.40	128.40
Sum Item					10622.94	743.61	11,366.55

BOSUN	SUNDRIES	1	50.00		✓ 30 50.00	3.50	53.50
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	280.00		✓ 280.00 ✓	19.60	299.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	230.00		✓ 230.00 ✓	16.10	246.10
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	160.00		✓ 160.00 ?	11.20	171.20
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	3000.00		✓ 1680 3000.00	210.00	3210.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00		✓ 2250 2500.00	175.00	2675.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	280.00		✓ 280.00 ✓	19.60	299.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00		✓ 80.00 ✓	5.60	85.60
BOJSE	BODY JOINT SEALANT FOR TAILGATE (N)	1	80.00		✓ 80.00 ✓	5.60	85.60
BOJSE	BODY JOINT SEALANT FOR END PANEL (N)	1	80.00		✓ 80.00 ✓ ?	5.60	85.60
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL (N)	1	80.00		✓ 80.00 ✓ ?	5.60	85.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		✓ 250.00 ✓ ?	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00		✓ 160.00 ✓	11.20	171.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00		✓ 160.00 ✓	11.20	171.20
BOMISC1	REMOVE & INSTALL TAILGATE SPOILER (N)	1	140.00		✓ 140.00 ✓	9.80	149.80
BOMISC1	RESET & CALIBRATE REAR VIEW CAMERA (N)	1	140.00		✓ 140.00 ✓	9.80	149.80
BOMISC1	RESET & CALIBRATE VEHICLE SMART LOCKING SYSTEM (N)	1	140.00		✓ 140.00 ✓	9.80	149.80
BMU30A	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM. (N)	1	280.00		✓ 280.00 ?	19.60	299.60

Printed on 25/10/2017 2:46:25 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 OSUNTEC TOWER FIVE
SINGAPORE 038985
Registration No : SLS1481X
Chassis No : JHMRC1880HC203523
Model : ODYSSEY 2.4 EX-S 17YM (EURO 6)
Owner's Name : GOH CHERN-YU CHRISTOPHER
Ins Policy No. :
Date of Accident :

Document No. : SQT17004370 **Page** 4
Date : 25. Oct 2017
Customer No. : WZN004
Svc Advisor : JASON HENG
Engine No : K24W72041169
Date | Time : 25. Oct 2017 10:09:31 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
BKRP02B	CUT OFF & RENEW RR FLOOR PANEL FENDERS.STRAIGHTEN	1	4000.00	3360	4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3000.00	2250	3000.00	210.00	3210.00
Sum Labor					15090.00	1,056.30	16,146.30

Survey By

Date & Time

Excess

Status

Signature

- With floor panel - 13 repair days.
- with out floor panel - 10 repair days.

Total Amount 25,712.94 1,799.91 27,512.85

Total (Inclusive of GST) 27,512.85

Rear Labour. - \$ 3360 (6 days)

- With floor & end panel - \$ 1680 (3 days)
- only end panel - \$ 1680 (3 days)

Rear Painting.

- with floor & end panel tailgate, bumper, fender(2x) - \$ 2250
- with end panel, tailgate, bumper, fender(2x) - \$ 1800

26263-44

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian 27/10/2017.

- Part by part repair.
- Question Mark Item Photo.
- Photo before paint.

90036121 sebastian@lkkauto.com.

Printed on 25/10/2017 2:46:25 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZN004 / ERGO INSURANCE	Document No:	SVO17068131
Chassis No:	JHMRC1880HC203523	Printed By:	JASONHENG
License No:	SLS1481X	Order Date:	27. October 2017
Mileage:	1046	Order Time:	1:58:24 PM
Engine No:	K24W72041169	Service Advisor:	JASON HENG

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	GST Amt	Amount Incl GST
	THIRD PARTY CLAIMS (J/NO: 10163) OWNER: GOH CHERN-YU CHRISTOPHER OWNER INSURER: LIBERTY INSURANCE ACC DATE: 22/10/17 SURVEYED BY: SEBASTIAN DATE: 27/10/17 TP INSURER: ERGO INSURANCE PTE LTD TP VEH: SJG6605K REF: ADDITIONAL PART						
35070	LINING COMP,R.RR.SIDE / <i>Deform (A)</i>	1	734.00 S	25	550.50	38.54	589.04
	SUM EXCESS:				550.50	38.54	589.04
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) / <i>UT</i>	1	45.00 ✓		45.00	3.15	48.15
04711-T6A-000ZZ	FACEFR.BUMPER / <i>Deform</i>	1	677.60 ✓	25	508.20	35.57	543.77
71151-T6A-003	BASEMID GRILLE / <i>Deform</i>	1	215.10 ✓	25	161.32	11.29	172.61
71152-T6A-003	UPPER MOLDINGMID GRILLE / <i>DT</i>	1	86.00 ✓	25	64.50	4.52	69.02
71122-T6A-003	MOLDINGFR.GRILLE / <i>cut</i>	1	258.10 ✓	25	193.57	13.55	207.12
75700-TA0-A00	EMBLEMFR. / <i>NEC</i>	1	25.30 ✓	25	18.97	1.33	20.30
90301-ST0-003	NUTPUSH 3MM / <i>NEC</i>	2	1.90 ✓	25	2.85	0.20	3.05
71193-T6A-003	SPACERR.FR.BUMPER SIDE / <i>NEC</i>	1	11.60 ✓	25	8.70	0.61	9.31
71198-T6A-003	SPACERL.FR.BUMPER SIDE / <i>NEC</i>	1	11.60 ✓	25	8.70	0.61	9.31
91505-TM8-003	CLIPBUMPER / <i>NEC</i>	16	2.00 ✓	25	24.00	1.68	25.68
60100-T6A-000ZZ	HOOD COMP / <i>DT</i>	1	658.30 ✓	25	493.72	34.56	528.28
71130-T6A-305ZZ	BEAM COMPFR.BUMPER / <i>DT</i>	1	286.10 ✓	25	214.57	15.02	229.59
04715-T6A-000ZZ	FACERR.BUMPER / <i>DT</i>	1	527.00 ✓	25	395.25	27.67	422.92
71502-T6A-003ZD	FACER.RR.BUMPER GARNISH / <i>Deform</i>	1	75.30 ✓	25	56.47	3.95	60.42
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR / <i>sumg</i>	1	320.00 ✓		320.00	22.40	342.40
33505-SLJ-013	REFLECTOR ASSYR.RR. / <i>CKK</i>	1	44.50 ✓	25	33.37	2.34	35.71
71593-T6A-003	SPACERR.RR.BUMPER SIDE / <i>NEC</i>	1	18.70 ✓	25	14.02	0.98	15.00
91505-TM8-003	CLIPBUMPER / <i>NEC</i>	9	2.00 ✓	25	13.50	0.95	14.45
68100-T6A-Q10ZZ	TAILGATE COMP / <i>DT</i>	1	1,049.80 ✓	25	787.35	55.11	842.46
75701-T6A-000	EMBLEMH / <i>NEC</i>	1	25.80 ✓	25	19.35	1.35	20.70
74440-T6A-003	WEATHERSTRIPTAILGATE / <i>NEC</i>	1	115.10 ✓	25	86.32	6.04	92.36
74827-S2G-010	PROTECTORLICENSE PLATE / <i>NEC</i>	2	2.00 ✓	25	3.00	0.21	3.21
74800-TF0-J02	LOCKTAILGATE / <i>TM</i>	1	181.70 ✓	25	136.27	9.54	145.81
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL / <i>Deform</i>	1	10.50 ✓	25	7.87	0.55	8.42
34150-T6A-003	LIGHT ASSYR.LID / <i>CKK</i>	1	378.60 ✓	25	283.95	19.88	303.83
34155-T6A-003	LIGHT ASSYL.LID / <i>CKK</i>	1	378.60 ✓	25	283.95	19.88	303.83
84640-T6A-003ZA	LINING ASSYRR.PANEL / <i>Deform</i>	1	101.60 ✓	25	76.20	5.33	81.53
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER / <i>Deform</i>	1	202.20 ✓	25	151.65	10.62	162.27
66100-T6A-300ZZ	PANEL COMPRR. / <i>DT</i>	1	451.80 ✓	25	338.85	23.72	362.57
04656-T6A-310ZZ	PAN SET,3RD SEAT / <i>DT</i>	1	337.90 ✓	25	253.42	17.74	271.16
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE / <i>NEC</i>	2	17.60 ✓	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER / <i>NEC</i>	1	16.60 ✓	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER / <i>NEC</i>	1	16.60 ✓	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD / <i>NEC</i>	4	3.90 ✓	25	11.70	0.82	12.52
73225-TM8-000	RUBBER AWINDSHIELD DAM / <i>NEC</i>	1	3.60 ✓	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5 / <i>NEC</i>	2	8.30 ✓	25	12.45	0.87	13.32
76711-T6A-003	CAPPVOT / <i>NEC</i>	1	4.70 ✓	25	3.52	0.25	3.77

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZN004 / ERGO INSURANCE
Chassis No: JHMRC1880HC203523
License No: SLS1481X
Mileage: 1046
Engine No: K24W72041169

Document No: SVO17068131
Printed By: JASONHENG
Order Date: 27. October 2017
Order Time: 1:58:24 PM
Service Advisor: JASON HENG

BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00 ✓	120.00	8.40	128.40
			SUM PARTS:	5,206.56	364.47	5,571.03
BOSUN	0701 SUNDRIES	1	30.00 ✓	30.00	2.10	32.10
BMA01D	1757 REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)	1	280.00 ✓	280.00	19.60	299.60
BMC01D	1757 REMOVE & INSTALL RADIATOR WITH FITTINGS. PRESSURE TEST COOLING SYSTEM.(N)	1	230.00 ✓	230.00	16.10	246.10
BKBH01S	0671 STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1,680.00 ✓	1,680.00	117.60	1,797.60
BP05R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,250.00 ✓	2,250.00	157.50	2,407.50
BG02R	1757 REPLACE RR. WINDSCREEN.(N)	1	280.00 ✓	280.00	19.60	299.60
BODAMKIT	0701 WINDSCREEN DAM KIT.	1	80.00 ✓	80.00	5.60	85.60
BOJSE	1374 BODY JOINT SEALANT FOR TAILGATE (N)	1	80.00 ✓	80.00	5.60	85.60
BOJSE	1374 BODY JOINT SEALANT FOR END PANEL (N)	1	80.00 ? ✓	80.00	5.60	85.60
BOJSE	1374 BODY JOINT SEALANT FOR FLOOR PANEL (N)	1	80.00 ? ✓	80.00	5.60	85.60
BP00R	1374 APPLY BODY UNDERSIDE COATING (N).	1	250.00 ? ✓	250.00	17.50	267.50
BML02I	0671 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00 ✓	120.00	8.40	128.40
BA02R	0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00 ✓	160.00	11.20	171.20
BOMISC1	0671 REMOVE & INSTALL TAILGATE SPOILER (N)	1	140.00 ✓	140.00	9.80	149.80
BOMISC1	0671 RESET & CALIBRATE REAR VIEW CAMERA (N)	1	140.00 ✓	140.00	9.80	149.80
BOMISC1	0671 RESET & CALIBRATE VEHICLE SMART LOCKING SYSTEM (N)	1	140.00 ✓	140.00	9.80	149.80
BKRP02B	0671 CUT OFF & RENEW RR FLOOR PANEL FENDERS.STRAIGHTEN ALIGN RR CHASSIS & RENEW DAMAGE PARTS.	1	3,360.00 ✓	3,360.00	235.20	3,595.20
BP06R	1610	1	2,250.00 ✓	2,250.00	157.50	2,407.50



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZN004 / ERGO INSURANCE

Chassis No: JHMRC1880HC203523

License No: SLS1481X

Mileage: 1046

Engine No: K24W72041169

Document No: SVO17068131

Printed By: JASONHENG

Order Date: 27. October 2017

Order Time: 1:58:24 PM

Service Advisor: JASON HENG

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS. (6P)

SUM LABOUR:	11,630.00	814.10	12,444.10
--------------------	------------------	---------------	------------------

TOTAL SGD	17,387.06	1,217.11	18,604.17
------------------	------------------	-----------------	------------------

Total Payable (SGD)	18,604.17
----------------------------	------------------

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: S7329011B / GOH CHERN-YU
Chassis No: JHMRC1880HC203523
License No: SLS1481X
Mileage: 1048
Engine No: K24W72041169

Document No: SVO17068131
Printed By: JASONHENG
Order Date: 27. October 2017
Order Time: 1:58:24 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount Incl GST
35070	SUPPLEMENTARY PARTS LINING COMP,R.RR.SIDE	1	734.00	25	550.50	38.54	589.04
SUM EXCESS:					550.50	38.54	589.04
TOTAL SGD					550.50	38.54	589.04
Total Payable (SGD)							589.04

GST Amount is calculated from individual line(s)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI17020583/Stbe2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 11-01-2018	
			Code : EGI	
1. Policy Particulars - THIRD PARTY CLAIM				
Insured Veh.	SJG 6605K	Veh. Inspected	SLS 1481X	
Policy No.		Coverage (\$)	0.00	
Claim No.	SJG6605K/SE/pl.sa	Excess (\$)	0.00	
Assign From	SITI	Assign Date	27/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2356	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JHMRC1880HC203523	Colour	SILVER	
Odometer	2926	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	DUNLOP	6 mm	
L/H Front Tyre	215/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/10/2017	Inspection Date	27/10/2017	
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 1481X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	NUMBER PLATE WITH CASING (SN)	BENT	45.00	45.00
1	FACEFR.BUMPER (SN)	CUT	508.20	508.20
1	GRILLEFR.BUMPER LOWER (SN)	NOT NECESSARY	56.47	-
1	BASEMID GRILLE (SN)	CRACKED	161.32	161.32
1	UPPER MOLDINGMID GRILLE (SN)	BENT	64.50	64.50
1	LOWER MOLDINGMID GRILLE (SN)	NOT NECESSARY	64.50	-
1	BASEFR.GRILLE (SN)	NOT NECESSARY	124.27	-
1	MOLDINGFR.GRILLE (SN)	CUT	193.57	193.57
1	EMBLEMFR (SN)	NECESSARY	18.97	18.97
2	NUTPUSH 3MM (SN)	NECESSARY	2.85	2.85
1	SPACERR.FR.BUMPER SIDE (SN)	NECESSARY	8.70	8.70
1	SPACERL.FR.BUMPER SIDE (SN)	NECESSARY	8.70	8.70
16	CLIPBUMPER (SN)	NECESSARY	24.00	24.00
1	GARNISHR.FR.BUMPER (SN)	NOT NECESSARY	30.67	-
1	GARNISHL.FR.BUMPER (SN)	NOT NECESSARY	30.67	-
1	HOOD COMP (SN)	DENTED	493.72	493.72
1	LABELCOOLANT INFORMATION (SN)	NOT NECESSARY	3.67	-
1	LABELAIR CONDITIONER CAUTION (SN)	NOT NECESSARY	1.35	-
1	FENDER COMPR.FR (SN)	TO REPAIR SEE LABOUR	403.35	-
1	FENDER COMPL.FR (SN)	TO REPAIR SEE LABOUR	403.35	-
1	BEAMR.FR.BUMPER UPPER (SN)	NOT NECESSARY	25.65	-
1	BEAML.FR.BUMPER UPPER (SN)	NOT NECESSARY	25.65	-
1	HEADLIGHT ASSYR (SN)	NOT NECESSARY	664.72	-
1	HEADLIGHT ASSYL (SN)	NOT NECESSARY	664.72	-
1	BEAM COMP ,FR BUMPER (SN)	DENTED	218.85	214.57
1	CONDENSER COMP (SN)	NOT NECESSARY	501.45	-
1	RADIATOR COMP (SN)	NOT NECESSARY	990.67	-
1	FACERR.BUMPER (SN)	DEFORMED	395.25	395.25
1	FACER.RR.BUMPER GARNISH (SN)	DEFORMED	56.47	56.47

Report Ref No. CS/EGI17020583/Stbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Estimate By (\$)
4	ACT RR SENSOR (SN)	DAMAGED	320.00	320.00
1	REFLECTOR ASSYR.RR (SN)	CRACKED	33.37	33.37
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	14.02	14.02
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	14.02	-
9	CLIPBUMPER (SN)	NECESSARY	13.50	13.50
1	TAILGATE COMP (SN)	DENTED	787.35	787.35
1	EMBLEMH (SN)	NECESSARY	19.35	19.35
1	WEATHERSTRIPTAILGATE (SN)	DEFORMED	86.32	86.32
2	PROTECTOR LICENSE PLATE (SN)	NECESSARY	3.00	3.00
1	MOLDING ASSYRR.LICENSE GARN (SN)	NOT NECESSARY	129.07	-
1	LOCK TAILGATE (SN)	JAMMED	136.27	136.27
1	POCKETTAILGATE LINING PULL (SN)	DEFORMED	7.87	7.87
1	TAILLIGHT ASSY R (SN)	NOT NECESSARY	616.35	-
1	TAILLIGHT ASSY L (SN)	NOT NECESSARY	616.35	-
1	LIGHT ASSYR.LID (SN)	CRACKED	283.95	283.95
1	LIGHT ASSYL.LID (SN)	CRACKED	283.95	283.95
1	LINING ASSYRR. PANEL (SN)	DEFORMED	76.20	76.20
1	COMP LID TOOLS (SN)	NOT NECESSARY	45.15	-
1	LINING ASSYTAILGATE LOWER (SN)	DEFORMED	151.65	151.65
1	PANEL COMPRR (SN)	DENTED	338.85	338.85
1	PAN SET, 3RD SEAT (SN)	DENTED	253.42	253.42
2	MOLDINGRR.WINDSHIELD SIDE (SN)	NECESSARY	26.40	26.40
1	MOLDING.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
1	MOLDING.RR.WINDSHIELD CORNER (SN)	NECESSARY	12.45	12.45
4	SPACERRR.W/SHIELD (SN)	NECESSARY	11.70	11.70
1	RUBBR AWINDSHIELD DAM (SN)	NECESSARY	2.70	2.70
2	DAMPERSTD 5X5 (SN)	NECESSARY	12.45	12.45
1	CAPPVOT (SN)	NECESSARY	3.52	3.52
2	WINDSCREEN SEALANT @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SUNDRIES (SN)	NECESSARY	50.00	30.00
1	LINING COMP,R.RR.SIDE (SN) (ADDITIONAL)	DEFORMED	550.50	550.50
			11,223.44	5,787.06

Report Ref No. CS/EGI17020583/Stbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimated by Workshop: (S)	Recommended by (S)
	LABOUR			
	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.		280.00	280.00
	REMOVE & INSTALL RADIATOR WITH FITTINGS.		230.00	230.00
	INSPECT FR LIGHTING MECHANISMS & FOCUS.	NOT NECESSARY	160.00	-
	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.		3,000.00	1,680.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)		2,500.00	2,250.00
	REPLACE RR.WINDSCREEN.		280.00	280.00
	WINDSCREEN DAM KIT.		80.00	80.00
	BODY JOINT SEALANT FOR TAILGATE.		80.00	80.00
	BODY JOINT SEALANT FOR END PANEL.		80.00	80.00
	BODY JOINT SEALANT FOR FLOOR PANEL.		80.00	80.00
	APPLY BODY UNDERSIDE COATING.		250.00	250.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		160.00	120.00
	REMOVE & RENEW REVERSE SENSOR - 4 PCS.		160.00	160.00
	REMOVE & INSTALL TAILGATE SPOILER.		140.00	140.00
	RESET & CALIBRATE REAR VIEW CAMERA.		140.00	140.00
	RESET & CALIBRATE VEHICLE SMART LOCKING SYSTEM.		140.00	140.00
	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM.	NOT NECESSARY	280.00	-
	CUT OFF & RENEW RR FLOOR PANEL FENDERS STRAIGHTEN. INCLUSIVE OF THE REPAIR OF FENDER COMPR.FR AND FENDER COMPL.FR.		4,000.00	3,360.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)		3,000.00	2,250.00
			15,040.00	11,600.00
	GRAND TOTAL		26,263.44	17,387.06

RECOMMENDED COST OF REPAIRS

Report Ref No. CS/EGI17020583/Stbe2

YEANG WAI KEEN**Automotive Assessor****ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser****DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.