

15/5/2010

INS. CASE OWNER:

CC 4/AXA1702

0588, K 16/10/12

LKK:

IDAC:

Surveyor:

FSL

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Name of Insured :

Insured Tel No. :

Excess Sec II :SS

Is driver the owner?

(YES / NO)

HP:

D.O.A:

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

SHC 6576L



INSRS:

WSP:

Tel :

Liability :

RMKS:

Trans
cab

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE

Date/Time:

21/10/12

Sent By:

Dre

Confirm by:

REALIZATION

Date/Time:

Confirm with:

Email

Call

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

If NO or B 28, Ass. Lia :

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

G.A/LTA Search

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Total Cost

SS

Total:

SS

Global Sum \$S:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
18/12/2020

1) Claim status: Normal/Reject/Private Settle (up)

2) Report Format:

3) Survey fee:

\$250.00

ASS. REC. BY:

REF: AAAKennerth**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 55762Yr Regn: 09, 14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perant Lot. Tuduc.c. 1995Colour n. white 1Ry

A/C: Insured / Std / NI / NA

Sp. Reading 60684

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABCL15ANC 279338Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 155/60R14R: Revol

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 9 mmL/Bal. 8 mmL/Bal. 9 mmD.O.A. 24/10/17D.O.I. 26/10/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/10 File pass to Corkum
n 1/12/18 8/1504

(Reel # 33199.69 / 9561)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

S + RS \$

☐ : Interview (\$)

Photos

☐ : Tech Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO GST REG NO. 201019626G
SHC5576L -

AAD1710-239

Not Authorised
11 Sep @ 1850h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5576L - JHOW
 VF1ABL15AUC279338
 RENAULT
 LATITUDE
 24.10.2017
 AXA

		PART		LIST	
1	1	BUMPER COVER REAR	\$	Bumper 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	Wd Lwr 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	Sm 113.47	}
4	1	BUMEPR BRACKET SIDE RH REAR	\$	Sm 135.97	
5	1	BUMEPR RETAINER RH REAR	\$	Sm 44.99	
6	1	BUMPER REFLECTOR RH	\$	Sm 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	Sm 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	Sm 44.99	
9	1	BUMPER REFLECTOR LH	\$	Sm 43.61	
10	1	BUMPER BEAM REAR	\$	R 777.52	
11	1	BUMPER BEAM BRACKET LH REAR	\$	R 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	\$	R 225.95	
13	1	BOOT REAR	\$	R 2,872.68	
14	1	BOOT FINISHER	\$	Sm 470.06	
15	1	BOOT WHEATERSTRIP	\$	Sm 323.05	
16	1	BOOT REFLECTOR LAMP LH	\$	Sm 493.35	
17	1	BOOT REFLECTOR LAMP RH	\$	Sm 493.35	
18	1	BOOT BADGE 'RENAULT'	\$	Sm 225.36	}
19	1	BOOT BADGE	\$	Sm 225.36	
20	1	FENDER PANEL REAR LH	\$	R 3,299.13	
21	1	FENDER PANEL REAR RH	\$	R 3,299.13	
22	1	TAILLAMP RH	\$	Sm 552.55	
23	1	TAILLAMP PANEL RH	\$	R 986.70	
24	1	TAILLAMP LH	\$	Sm 552.55	
25	1	TAILLAMP PANEL LH	\$	R 986.70	
26	1	OUTER PANEL REAR (End Panel)	\$	R 1,471.77	
27	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sm 404.56	
28	1	EXHAUST REAR	\$	R 7,489.05	
29	1	EXHAUST CAP REAR	\$	R 230.49	

TOTAL	\$	28,045.19
10%	\$	2,804.52
	\$	25,240.67

...CLAIM SUBFOLDER...(New Assignment)

Non-Reporting

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2017		25 Oct 2017 17:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	TRANS-CAB SERVICES PTE LTD		
Vehicle Reg. No.:	SHC5576L	Date of Loss:	24/10/2017 08:00 - :59
Claim Type:	TP / C0456773	Policy/Cover Note No.:	P1931030 (Comprehensive)
Vehicle Reg. No. (Insured):	SKS5935P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Trans-cab Services Pte Ltd- Ang Mo Kio (HQ) No. 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Tan Kwee May]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 03/11/2017]		
Adj Asg. Remarks:	ARC - Yes		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

- AXA_SG (25/10/2017): WP / New TP Assignment - C0456773/P1931030

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

veh not in

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO GST REG NO. 201019626G

SHC5576L -**AAD1710-239****Specical Nett**

1	1SET	PARKING AID	\$	Sn 700.00 X
2	1SET	REAR BUMPER CLIP	\$	nn 66.00 —
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn 33.00 —
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	nn 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	nn 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	nn 66.00 —
10	1	EXHAUST MOUNTING REAR	\$	Sn 17.82
11	1SET	BOOT FINISHER CLIP	\$	nn 24.20
12	1	BOOT STICKER "Trans-cab"	\$	nn 30.00
13	1	BOOT STICKER "6555-3333"	\$	nn 30.00
14	1	BOOT INNER TRIM CLIP	\$	nn 45.00
15	1	TAILLAMP CLIP RH	\$	nn 5.00
16	1	TAILLAMP CLIP LH	\$	nn 5.00
17	2	REAR WINDSCREEN SELANT	\$	nn 80.00
18	1	WINDSCREEN MOULDING	\$	Sn 100.00
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn 385.00
21	1	SPARE TYRE	\$	Sn 330.00

TOTAL	\$	2,099.02
TOTAL PARTS	\$	27,339.69

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00 2201
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
Towing Fees	\$	nn 120.00 X

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO GST REG NO. 201019626G
SHC5576L -

AAD1710-239

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X

TOTAL	\$	7,710.00
Over All Total	\$	35,049.69 <i>TH</i>

(PARTS BY PARTS)
Repair Days

10 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3878K

Vehicle Details

Vehicle No.	SHC5576L
Vehicle to be Exported	Yes
Intended De-registration Date	24 Oct 2017
Vehicle Make	RENAULT
Vehicle Model	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour	Red
Manufacturing Year	2014
Engine No.	M9R8839C001974
Chassis No.	VF1ABL15AUC279338
Maximum Power Output	127.0 kW (170 bhp)
Open Market Value	\$19,998.00
Original Registration Date	15 Sep 2014
First Registration Date	15 Sep 2014
Transfer Count	0
Actual ARF Paid	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	14 Sep 2022
PARF Rebate Amount	\$9,373.00

Intended COE Rebate Details

COE Expiry Date	14 Sep 2022
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$50,704.00
COE Rebate Amount	\$30,999.00
Total Rebate Amount	\$40,372.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 24 Oct 2017

Print Received Message

This mail is associated with :

***SHC5576L (C0456773)**
[SKS5935P]

TP

TRANS-CAB SERVICES PTE LTD

Oct 24 2017 8:00AM

[HITACHI CAPITAL ASIA PACIFIC PTE LTD]

Trans-cab Services Pte Ltd- Ang Mo Kio

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 26/02/2020 14:20 PM.
To LKK_HQ
CC AXA_SG
Subject Re: Fw: Direct Settlement - Accident Involving SKS5935P (OI : AXA - C0456773) and SHC5576L (TP : LKK REF - CC4/AXA17020588/Khb3) on 24/10/2017



Dear Shu Pei

Our insured has yet to report to us and we are sending final reminder to our insured. Please submit your report with survey photographs.

Regards

Saw Theng

<-- Original Message -->

From: LKK_HQ
To: stacey.ng@axa.com.sg; motor.doc@axa.com.sg
CC: AXA_SG
Sent On: 14/05/2019 12:16 PM
Subject: Fw: Direct Settlement - Accident Involving SKS5935P (OI : AXA - C0456773) and SHC5576L (TP : LKK REF - CC4/AXA17020588/Khb3) on 24/10/2017

Dear Sir / Madam,

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Please advice also whether we can proceed for direct settlement for this case.
Thank you.

Best Regards,

Shu Pei | Admin

<-- Original Message -->

From: LKK_HQ
To: kweemay.tan@axa.com.sg
CC: AXA_SG; vicalpeh@lkkauto.com; AsherSng@lkkauto.com; admin-a@lkkauto.com
Sent On: 15/11/2017 10:51 AM
Subject: Direct Settlement - Accident Involving SKS5935P (OI : AXA - C0456773) and SHC5576L (TP : LKK REF - CC4/AXA17020588/Khb3) on 24/10/2017

Dear Kwee May,

Kindly advice whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Please advice also whether we can proceed for direct settlement for this case.
Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366 0055 | email: shupeil@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Non-Reporting

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2017		25 Oct 2017 17:04 Edit Adj Rpt	S\$1,850.00 Edit Estimates	S\$1,850.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHC5576L	Date of Loss:	24/10/2017 08:00 - :59 [37 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0456773	Policy/Cover Note No.:	P1931030 (Comprehensive)
Vehicle Reg. No. (Insured):	SKS5935P	Policy No. (Claimant):	VFX/P1680520
		Excess:	S\$0.00
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Khor Saw Theng - 6880 4754]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 03/11/2017]		
Adj Asg. Remarks:	ARC - Yes		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (26/02/2020): Re: Fw: Direct Settlement - Accident Involving SKS5935P (OI : AXA - C0456773) an...
- AXA_SG (25/10/2017): WP / New TP Assignment - C0456773/P1931030

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

*SHC5576L (C0456773)
[SKS5935P]
TP
TRANS-CAB SERVICES PTE LTD
Oct 24 2017 8:00AM
[HITACHI CAPITAL ASIA PACIFIC PTE LTD]
Trans-cab Auto Services Pte Ltd

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&objid=650643&extid=254727&corole=4&... 1/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17020588/KPA3S2
Date: 01/04/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1931030
Claimant Vehicle No: SHC5576L Insured Vehicle No: SKS5935P
Date of Loss: 24/10/2017 Nature of Claim: TP Claim No: C0456773

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5576L Engine No: M9R8839C001974
Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Chassis No: VF1ABL15AUC279338
Reg. Date: 15/09/2014 (Man. Year: 2014) Odometer: 60687 km
Colour: Metallic White/Red
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Linglong 8 mm Rear Left Side: Rovel 9 mm
Front Right Side: Linglong 8 mm Rear Right Side: Rovel 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,339.67	1,854.57	25,485.10	93.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,710.00	480.00	7,230.00	93.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,049.67	2,334.57	32,715.10	93.34
Approved Total (Overridden) (S\$)		1,850.00		
(S\$)	35,049.67	1,850.00	33,199.67	94.72
+ GST 7.00/7.00% (S\$)	2,453.48	129.50	2,323.98	94.72
Nett Amount (S\$)	37,503.15	1,979.50	35,523.65	94.72

INSPECTION

Date of Assignment: 25/10/2017
Date Inspected: 26/10/2017 Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111
Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

2

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Apr 2020)

Parts: 143 RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5576L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER REAR (CONSISTENT)	Buckled / Dented	1,108.46 FL	*1,108.46 FL
2	1	*BUMPER LOWER REAR (CONSISTENT)	Dented / Cut	768.84 FL	*768.84 FL
3	1	*BUMPER BRACKET CTR REAR (CONSISTENT)	Serviceable	113.47 FL	*- FL
4	1	*BUMPER BRACKET SIDE RH REAR (CONSISTENT)	Serviceable	135.97 FL	*- FL
5	1	*BUMPER RETAINER RH REAR (CONSISTENT)	Serviceable	44.99 FL	*- FL
6	1	*BUMPER REFLECTOR RH (CONSISTENT)	Serviceable	43.61 FL	*- FL
7	1	*BUMPER BRACKET SIDE LH REAR (CONSISTENT)	Serviceable	135.97 FL	*- FL
8	1	*BUMPER RETAINER LH REAR (CONSISTENT)	Serviceable	44.99 FL	*- FL
9	1	*BUMPER REFLECTOR LH (CONSISTENT)	Serviceable	43.61 FL	*- FL
10	1	*BUMPER BEAM REAR (CONSISTENT)	Repair	777.52 FL	*- FL
11	1	*BUMPER BEAM BRACKET LH REAR (CONSISTENT)	Repair	225.95 FL	*- FL
12	1	*BUMPER BEAM BRACKET RH REAR (CONSISTENT)	Repair	225.95 FL	*- FL
13	1	*BOOT REAR (CONSISTENT)	Repair	2,872.68 FL	*- FL
14	1	*BOOT FINISHER (CONSISTENT)	Serviceable	470.06 FL	*- FL
15	1	*BOOT WEATHERSTRIP (CONSISTENT)	Serviceable	323.05 FL	*- FL
16	1	*BOOT REFLECTOR LAMP LH (CONSISTENT)	Serviceable	493.35 FL	*- FL
17	1	*BOOT REFLECTOR LAMP RH (CONSISTENT)	Serviceable	493.35 FL	*- FL
18	1	*BOOT BADGE RENAULT (CONSISTENT)	Not Necessary	225.36 FL	*- FL
19	1	*BOOT BADGE (CONSISTENT)	Not Necessary	225.36 FL	*- FL
20	1	*FENDER PANEL REAR LH (CONSISTENT)	Repair	3,299.13 FL	*- FL
21	1	*FENDER PANEL REAR RH (CONSISTENT)	Repair	3,299.13 FL	*- FL
22	1	*TAILLAMP RH (CONSISTENT)	Serviceable	552.55 FL	*- FL
23	1	*TAILLAMP PANEL RH (CONSISTENT)	Repair	986.70 FL	*- FL
24	1	*TAILLAMP LH (CONSISTENT)	Serviceable	552.55 FL	*- FL
25	1	*TAILLAMP PANEL LH (CONSISTENT)	Repair	986.70 FL	*- FL
26	1	*OUTER PANEL REAR (END PANEL) (CONSISTENT)	Repair	1,471.77 FL	*- FL
27	1	*OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	Serviceable	404.56 FL	*- FL
28	1	*EXHAUST REAR (CONSISTENT)	Repair	7,489.05 FL	*- FL
29	1	*EXHAUST CAP REAR (CONSISTENT)	Repair	230.49 FL	*- FL
30	1	*SET PARKING AID (CONSISTENT)	Serviceable	700.00 FS	*- FS
31	1	*SET REAR BUMPER CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
32	1	*SET BUMPER BRACKET CTR CLIP (CONSISTENT)	Necessary	33.00 FS	*33.00 FS
33	1	*SET BUMPER BRACKET SIDE CLIP RH RR (CONSISTENT)	Not Necessary	10.00 FS	*- FS
34	1	*SET BUMPER RETAINER RH CLIP RR (CONSISTENT)	Not Necessary	20.00 FS	*- FS
35	1	*SET BUMPER BRACKET SIDE CLIP LH RR (CONSISTENT)	Not Necessary	10.00 FS	*- FS
36	1	*SET BUMPER RETAINER CLIP LH RR (CONSISTENT)	Not Necessary	20.00 FS	*- FS
37	1	*SET BUMPER LOWER REAR RIVET (CONSISTENT)	Not Necessary	22.00 FS	*- FS
38	1	*SET BUMPER LOWER REAR CLIP (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
39	1	*EXHAUST MOUNTING REAR (CONSISTENT)	Serviceable	17.82 FS	*- FS
40	1	*SET BOOT FINISHER CLIP (CONSISTENT)	Not Necessary	24.20 FS	*- FS
41	1	*BOOT STICKER TRANS-CAB (CONSISTENT)	Not Necessary	30.00 FS	*- FS
42	1	*BOOT STICKER 6555-3333 (CONSISTENT)	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*BOOT INNER TRIM CLIP (CONSISTENT)	Not Necessary	45.00 FS	*- FS
44	1		*TAILLAMP CLIP RH (CONSISTENT)	Not Necessary	5.00 FS	*- FS
45	1		*TAILLAMP CLIP LH (CONSISTENT)	Not Necessary	5.00 FS	*- FS
46	2		*REAR WINDSCREEN SEALANT (CONSISTENT)	Not Necessary	80.00 FS	*- FS
47	1		*WINDSCREEN MOULDING (CONSISTENT)	Serviceable	100.00 FS	*- FS
48	1		*REAR WINDSCREEN INNER SPONGE SEAL (CONSISTENT)	Not Necessary	100.00 FS	*- FS
49	1		*SPARE TYRE RIM (ROUE 7J 16H 2547) (CONSISTENT)	Serviceable	385.00 FS	*- FS
50	1		*SPARE TYRE (CONSISTENT)	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,144.19	2,042.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,804.52	187.73
Total Parts (\$\$)	27,339.67	1,854.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	220.00
2	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,800.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
7	TOWING FEES.	New	120.00	0.00
8	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
9	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
11	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
12	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
Gross Labour Cost (S\$)			7,710.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >