

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO GST REG NO. 201019626G

SHC5576L -

AAD1710-239

Not Authorised
11 Sep @ 1830h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5576L- JHOW

VF1ABL15AUC279338

RENAULT

LATITUDE

24.10.2017

AXA

PART**LIST**

1	1	BUMPER COVER REAR	\$	<i>Bumper</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Wd Ltr</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47	}
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 44.99	
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61	
10	1	BUMPER BEAM REAR	\$	<i>R</i> 777.52	
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
13	1	BOOT REAR	\$	<i>R</i> 2,872.68	}
14	1	BOOT FINISHER	\$	<i>Sm</i> 470.06	
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05	
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35	
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35	
18	1	BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 225.36	
19	1	BOOT BADGE	\$	<i>Sm</i> 225.36	
20	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
21	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
22	1	TAILLAMP RH	\$	<i>Sm</i> 552.55	}
23	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
24	1	TAILLAMP LH	\$	<i>Sm</i> 552.55	
25	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
26	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	
27	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 404.56	
28	1	EXHAUST REAR	\$	<i>R</i> 7,489.05	
29	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49	

TOTAL	\$	28,045.19
10%	\$	2,804.52
	\$	25,240.67

TRANS-CAB AUTO SERVICES PTE LTD

AAD1710-239

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO GST REG NO. 201019626G

SHC5576L -

Specical Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	nn	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	
13	1	BOOT STICKER "6555-3333"	\$	nn	30.00	
14	1	BOOT INNER TRIM CLIP	\$	nn	45.00	
15	1	TAILLAMP CLIP RH	\$	nn	5.00	
16	1	TAILLAMP CLIP LH	\$	nn	5.00	
17	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
18	1	WINDSCREEN MOULDING	\$	Sn	100.00	
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	}
21	1	SPARE TYRE	\$	Sn	330.00	

TOTAL	\$	2,099.02
TOTAL PARTS	\$	27,339.69

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	2001
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
Towing Fees	\$	nn 120.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1710-239**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO GST REG NO. 201019626G

SHC5576L -

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>~ 170.00 X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>~ 170.00 X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>~ 380.00 X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>~ 170.00 X</i>
To check steering geometry and computer wheel alignment	\$	<i>~ 220.00 X</i>

TOTAL	\$	7,710.00
Over All Total	\$	35,049.69

(PARTS BY PARTS)**Repair Days****10 Days***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: