

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BATTERY <i>Plugged</i>	168.00
2	1	FRONT NUMBER PLATE W/CASING <i>distorted</i>	35.00
Sub Total (S\$)			203.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00 <i>800</i>
Labour Items			
2	TO KNOCK OUT DENTS; STRAIGHTEN FRONT CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	1,000.00 <i>800</i>
3	TO CHECK WIRING	New	20.00 ✓
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00 ✓
5	TO LIFT UP ENGINE	New	80.00 ✓
6	TO REMOVE; REPLACE FRONT ENGINE MOUNTINGS	New	150.00 ✓
7	TO REMOVE; REPLACE LH FUSE BOX ASSY; AIRCLEANER BOX ASSY AND RELATED PARTS	New	250.00 <i>180</i>
Gross Labour Cost (S\$)			2,600.00

Progressive Automotive Pte Ltd/SJJ2100K/27/10/2017 12:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

*Adrian King -
2/s 27/10/17.*

*total:
4/sisk*

Not Authorised.

Excess \$800.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____