

ASS. REC. BY:

REF:

CS/FCL17020627/Rigb02

Special Instruction:

Surveyor:

KASU

ASSIGNMENT (Office)

From (Person):

CNS

Karen Tan

of

PCL

Date/Time:

20.10.2017 5:40pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCR 8866K

Insured:

SHC 2146P

at Workshop m/s

Cycle & Carriage Automotive

Tel:

6568 4501

of

209 Pandan Garden

Policy No:

Claim No:

D17009716MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 17.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'D91

20.11.2017 @ after 9am

H.O.D. Endorsement:

Date/Time:

23.10.2017

10:50am Person Contacted:

Don

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SCR 8866K - PCL/170607003103 / RES
	SHC 2146P - CC3 / EQ216015522 / H1149302
07/11/17 @ 3.40pm	revised to Karen by email.
21/5/18 @ 4.48pm	confirmed with Jo Jo final fig 62853.00, 5 days.
	Per 19.59, 412)

REF: FCI

16374

ASSIGNMENT

From: _____ Date: **5/11/17**

Estimated Cost: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SCR 8866 K**

at Workshop mis **Cycle & Carriage Automotive**

of **204 Pender Gardens**

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

After 9am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **5** days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **1DS**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Veh No: **SCR 8866 K** Yr Reg: **2015 Anh**

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **MITSUBISHI Outlander 2.4** 2360

Colour: **Green** A/C Insured / Std / NI / NA

So Reading: **036147** T. Radio: Insured / Std / NI / NA

Eng No: _____

C/No: **SMY XT6FS W42000708**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **225/55 R18**R: **225/55 R18**

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R. Bal. **6** mmR. Bal. **6** mmL. Bal. **6** mmL. Bal. **6** mmD.O.A. **14/10/17**D.O.I. **06/11/17**Survey held at **CBC CPA**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR o/s

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 22 MAY 2018

Date/Time File Pass to? ☐ : Prel. ReportDate/Time File Return to? ☐ : Final ReportDays Of Repair: **5**

Resurvey No. of Trip: _____

Survey Fee

Transportation

9 ____ \$ + 10 ____ \$

10 ____ \$

11 ____ \$

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Workshop (\$)

Report Format: **TP**

Lump Sum / I.B.I. (\$)

2853

135

50

50

27

262



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17020627/R1qb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-10-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2146P	Veh. Inspected	SCR 8866K
Policy No.		Coverage (\$)	0.00
Claim No.	D17009716MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	20/10/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	12/10/2017	Inspection Date	30/10/2017
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17009716MFSH

Date: 07th November 2017

Our Ref: CS/FCI17020627/R1qb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCR 8866K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/11/2017 at the premises of M/s CYCLE & CARRIAGE. and have the following to report:-

Workshop Estimate Amount	: S\$ 4,812.00 .
Revised Estimate Amount	: S\$ 2,853.00 .
"Check" Items Amount	: S\$ 294.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Yours faithfully

Mohd Rasul
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	13-10-2017	Our Ref No.	D17009716MFSH
Accident Date	12-10-2017	Claim Type.	Third Party
Insured Vehicle	SHC2146P	Third Party Vehicle.	SCR8866K
Survey Location	209 PANDAN GARDENS		
Contact Person.	DON BONG		
Contact No.	65684501/ 0	Fax No.	65651240
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229127)



PRI Documents



Close



PRI Header Details

Claim No	D17009716MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CYC AUTOM
Workshop Name	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Contact Person : DON BONG)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 0 , Phone: 65684501 , Fax: 6565124 EmailId: KIONGHUA.BONG@CYCLECARRIAGE		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC2146P	TP Vehicle No	SCR880
PRI Recieved Date	13-10-2017 07:33:29 PM	Surveyor Appointed Date	20-10-2017 05:40:19 PM	Surveyor Accept Date	17-10-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	27-10-2017	Upload Survey Report *:	
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 21 May 2018 4:48 PM
To: Cheng Jo Jo; Rasul (LKKAUTO)
Cc: Vivian Lau (LKKAUTO); Admin A; Loi Ai Ting; Yusof Bin Hashim; Andre Chow En De; Lauro Araos Songcuan Jr; SUR
Subject: RE: FINALISE - SCR8866K (MIT) *** LKK REF: CS/FCI17020627/R1qb

Dear Jo Jo,

Confirm final fig \$2,853.00 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 14 May 2018 1:21 PM
To: Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>; Yusof Bin Hashim <yusof.hashim@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>; Lauro Araos Songcuan Jr <lauro.songcuan@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: FINALISE - SCR8866K (MIT) *** LKK REF: CS/FCI17020627/R1qb

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/FCI17020627/R1qb	Shiau Chan

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheng Jo Jo [<mailto:jojo.cheng@cyclecarriage.com.sg>]
Sent: Monday, 14 May, 2018 11:57 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Loi Ai Ting

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 7 November, 2017 3:40 PM
To: 'Karen Tan'; 'Claim Workflow System'; assignments
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D17009716MFSH/1
Attachments: CSFCI17020627R1qb.pdf

Dear Karen,

Enclosed herewith preliminary advice of SCR 8866K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan [mailto:karentan@first-insurance.com.sg]
Sent: Friday, 27 October, 2017 4:41 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17009716MFSH/1

Dear Catherine,

Unable to get you on the phone.

The workshop just called me to say that survey is still not done. He said had spoken to you and you claimed that you have not received this assignment. Can you contact them for clarifications and to arrange the survey asap.

Best Regards,

Karen Tan

Motor Claims Dept.

First Capital Insurance Ltd | A FAIRFAX Company

36 Robinson Road #16-01 City House | Singapore 068877 | Reg. No. 195000106C

D: 6507 3582 | M: 6507 3848 | F: 6507 3849

W: www.first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data.

Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

GIA
Receipt



18311190 TEL: (65) 6412-8000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1989 (MALAYSIA)

MX1

MITSUBISHI AUTO PROTECTOR

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00

CERTIFICATE NO. 210042578 K-01000

(For policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARE Yes

1) VEHICLE REGISTRATION NO.

SCR8866K

2) NAME OF INSURED

Oh Han Khuen

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

21 Aug 2016

4) DATE OF EXPIRY OF INSURANCE

20 Aug 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION : All Age Condition

a) The Insured

b) Any other person who is driving on the Insured's order or with his permission

This policy will indemnify the insured or any authorized driver only if he/she meets the age condition.

A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorized Driver (named or unnamed) if You are or the said

Authorized Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf then driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trial, speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / MITSUBISHI AUTHORISED REPAIRERS

1. Cycle & Carriage Pandan Garden Service Centre - 209 Pandan Gdn (Tel: 6568 4555)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engg - 205 Beadell Rd (Tel: 6383 7118) 3. Ebu - 30 Bukit Batok Cres (Tel: 6654 7777)

4. Glass-Fix - 52 Ubi Ave 3 (Tel: 6278 0887) - For windscreen only 5. Kan Fook Sing Motor - 61 Delfi Lane 12 (Tel: 6747 0560)

6. Lai Hatt (Mong Kee) Motor - 21 Sin Ming Ind (Tel: 6453 8110) 7. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 6272 3892)

8. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 6741 5336) 9. SMF Motor - 1 Kaki Bukit Ave 6 Bld B (Tel: 6747 6166)

LOSS OF USE 15 Days Replacement Car only for repairs at C&C - Refer to policy wordings for details

NAMED DRIVER NA

HIRE PURCHASE COMPANY / EMPLOYER'S LOAN DBS BANK LTD

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I, We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 21 Jul 2016

AIG Asia Pacific Insurance Pte. Ltd.

500726 781
CYCLE & CARRIAGE - REVIEW MET
299 ALEXANDRA ROAD
SINGAPORE 119956
ANSPAD FOR

AUTHORISED REPRESENTATIVE

ORIGINAL

001/2016

AIG Logo No. 001/2016-KW10

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1611637H



Name

OH HUAN KHOON

胡 煥 群

FOR C&C USE ONLY

Race

CHINESE

Date of birth

01-12-1963

Sex

M

S1611637H

Country/Place of birth

SINGAPORE

5607302



NRIC No. S1611637H



FOR C&C USE ONLY

Date of issue

02-06-2016

Address

85 AMBER ROAD
#05-13
SINGAPORE 439895

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S1695933B**

Name: **ONG SWEE LENG**

Birth Date: **19 Jun 1965**

Issue Date: **15 Sep 2003**

000834709B

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1695933B**

Name: **ONG SWEE LENG**

王瑞玲

Race: **CHINESE**

Date of birth: **19-06-1965**

Country/Place of birth: **SINGAPORE**

Sex: **F**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **13 Nov 1990**

Licence No: **S1695933B**

NP 426A

5617029

FOR C&C USE ONLY

NRC No: **S1695933B**

Date of issue: **30-06-2016**

Address: **85 AMBER ROAD
#05-13
SINGAPORE 439895**

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
OH HUAN KHOON	Cust No/Name /MR OH HUAN KHOON
85 AMBER RD	Reg No/Reg Date SCR8866K / 21/08/201
#05-13	Date In/Mileage / 0
439895	Chassis No JMYXTGF3WGZ000708
Contact No Mobile: 90105545	Engine No 4B12PT7891
	Make/Model MIT/OUTLANDER 2.4 CVT AWD 16MY (E12
	Colour/Trim A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	13/10/2017/ 11:39	QUD	247 / DonBong	15152

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REAR REINFORCEMENT, LH TAILAMP, REPAIR LH REAR FENDER				550 1650.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST				100.00
E PNT98000 PAINT WORK SPRAY REAR BUMPER, LH REAR FENDER PANEL AND AFFECTED PORTION				840 1260.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				20 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY SUPPLY PARKING SENSOR				1x 220.00
M SUNDRY SUNDRIES				20 50.00
M REINFORCEMENT,RR BUMPER,LH	1.00	74.00	00.00	74.00
M REINFORCEMENT,RR BUMPER,RH	1.00	74.00	00.00	74.00
M BRKT,R/BMPR FACE SIDE,LH	1.00	11.00	00.00	11.00
M BRKT,R/BMPR FACE SIDE,RH	1.00	11.00	00.00	11.00
M CLIP,FR BUMPER	10.00	2.00	00.00	20.00
M FACE,RR BUMPER	1.00	873.00	00.00	873.00
M EXTENSION,RR BUMPER	1.00	219.00	00.00	219.00
M LAMP ASSY,COMB,RR LH	1.00	0.00	00.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SURVEYOR NAME: *Fah*

SURVEYOR SIGNATURE: *Hi 90010068*

DATE: *06/11/17 @ 1210*

REMARKS: *4-5 days*

Confirm & accepted by *Reay 64 part*

Nett	4,812.00
7% GST on	4812.00
Total Payable	5,148.84

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

VEHICLE NO : SCR8866K
MODEL : MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)
WIP : 15152

Material	:	\$	<u>1,123.00</u>
Labour	:	\$	<u>1,730.00</u>
Sub-Total	:	\$	<u>2,853.00</u>
	:		<u> </u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>2,853.00</u>
GST 7%	:	\$	<u>199.71</u>
Grand Total	:	\$	<u>3,052.71</u>
Finalise By/Date	:		<u>JoJo / 11/05/2018</u>

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS + 2 Days (1) Weekends
+ Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 7

☐ TP claim 1ST CAPITAL - SHC2146P

☐ Claim GIA / LTA fee \$ -

☐ Claim Loss ☐ Use ☐ Rental

☐ Claim Medical Fee / Others \$ -

☐ Third Party Report \$ -

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No 65073848 06/11/	Cust No/Name	KCV07482/MR OH HUAN KHOON
	Reg No/Reg Date	SCR8866K / 21/08/2015
	Date In/Mileage	09/11/2017/ 36147
	Chassis/Package	JMYXTGF3WGZ00070E /FS514C
	Engine No	4B12PT7891
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD 16MY (E12)
	Colour/Trim	A03 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KFX00006	Credit	11/05/2018/ 16:41	TLD	881 / Jojo Cheng	15152		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							✓550.00
RENEW DAMAGED PARTS ON REAR BUMPER FACE, REPAIR LH REAR FENDER							
E PNT88000							✓100.00
REMOVE AND INSTALL PARKING ASSIST							
E PNT98000							✓840.00
SPRAY PAINT REAR BUMPER, LH REAR FENDER PANEL AND AFFECTED PORTION							
A 54900099							✓20.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
A 10028901							✓200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY							✓20.00
SUNDRIES							
X	BRKT,R/BMPR FACE SIDE,LH		1.00	11.00	00.00		✓11.00
X	CLIP,FR BUMPER		10.00	2.00	00.00		✓20.00
X	FACE,RR BUMPER		1.00	873.00	00.00		✓873.00
X	EXTENSION,RR BUMPER		1.00	219.00	00.00		✓219.00
Z TEXT							
TP FIRST CAPITAL							
DOA 12.10.2017							
SURVEYOR RASUL (LKK) 6.11.2017							
"Guarantee your warranty, maintain with Cycle & Carriage."							

Parts	1,123.00		Nett	2,853.00
Labour	1,710.00	7% GST on	2853.00	199.71
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	3,052.71
Diagnostics Job	0.00			
Sundry/Others	20.00			
Total(w/o GST)	2,853.00			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17020627/R1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2146P	Veh. Inspected	SCR 8866K	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17009716MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	20/10/2017	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI OUTLANDER 2.4	c.c	2360	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JMYXTGF3WGWZ000708	Colour	GREY	
Odometer	36147	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	GOODYEAR	6 mm	
L/H Front Tyre	225/55 R18	GOODYEAR	6 mm	
R/H Rear Tyre	225/55 R18	GOODYEAR	6 mm	
L/H Rear Tyre	225/55 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/10/2017	Inspection Date	06/11/2017	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCR 8866K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REINFORCEMENT,RR BUMPER,LH (SN)	SERVICEABLE	74.00	-
1	REINFORCEMENT,RR BUMPER,RH (SN)	SERVICEABLE	74.00	-
1	BRKT,R/BMPR FACE SIDE,LH (SN)	NECESSARY	11.00	11.00
1	BRKT,R/BMPR FACE SIDE,RH (SN)	NOT NECESSARY	11.00	-
10	CLIP,FR BUMPER (SN)	NECESSARY	20.00	20.00
1	FACE,RR BUMPER (SN)	DEFORMED	873.00	873.00
1	EXTENSION,RR BUMPER (SN)	SCRATCHED	219.00	219.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	PARKING SENSOR (SN)	NOT NECESSARY	220.00	-
			1,552.00	1,143.00
LABOUR				
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE,REAR REINFORCEMENT,LH TAILAMP,REPAIR LH REAR FENDER.			1,650.00	550.00
REMOVE AND INSTALL PARKING ASSIST.			100.00	100.00
PAINT WORK SPRAY REAR BUMPER,LH REAR FENDER PANEL AND AFFECTED PORTION.			1,260.00	840.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.			50.00	20.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.			200.00	200.00
			3,260.00	1,710.00
GRAND TOTAL			4,812.00	2,853.00
RECOMMENDED COST OF REPAIRS				2,853.00

Report Ref No. CS/FC117020627/R1qbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.