

APP. RES. BR.

REF: CS/FCI/7020691/Sgbn2

ASSIGNMENT (Office)

CWS

Sebastian

From (Person)

Sithara

FCI

Date/Time 2.20pm @ 30/10/17

Estimated Cost

Bill to

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SKE 8323J

Insured

SHC 0883 H

at Workshop no

Eurokars Leasing

Tel

6360 2445

of 12 Sungai kerdut Avenue

Policy No

Claim No

D17010011MFSH

Sum Insured

Excess

23/10/2017

Make of Veh

D.O.A

24/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

1/11/17 @ 11am owner waiting

H.O.D. Endorsement

Date/Time

2.24pm @ 30/10/17

Person Contacted

Tommy

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKE 8323J - X
	SHC 0883 H - X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17020691/Sgb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 30-10-2017

Code : FCI2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 0883H	Veh. Inspected	SKE 8323J
Policy No.		Coverage (\$)	0.00
Claim No.	D17010011MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	30/10/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/10/2017	Inspection Date	
Survey held at	EUROKARS HABITAT PTE LTD NO.12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	25-10-2017	Our Ref No. D17010011MFSH
Accident Date	24-10-2017	Claim Type. Third Party
Insured Vehicle	SHC0883H	Third Party Vehicle. SKE8323J
Survey Location	12 SUNGEI KADUT AVENUE	
Contact Person.	RICK TEO	
Contact No.	63602445/ 0	Fax No. 63602899
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EUROKARS LEASING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229475)



PRI Documents



Close



PRI Header Details

Claim No	D17010011MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & EUROKAR:
Workshop Name	EUROKARS LEASING PTE LTD (Contact Person : RICK TEO)	Survey Location & Contact Details	12 SUNGEI KADUT AVENUE Mobile: 0 , Phone: 63602445 , Fax: 63602899 EmailId: RICKTEO@EUROKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0883H	TP Vehicle No	SKE8323J
PRI Recieved Date	26-10-2017 06:52:41 PM	Surveyor Appointed Date	30-10-2017 02:19:22 PM	Surveyor Accept Date	30-10-2017 0.

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-10-2017	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Thursday, 2 November, 2017 5:06 PM
To: 'Claim Workflow System'
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010011MFSH/1
Attachments: SKE 8323J.pdf

Dear Sithara,

Enclosed herewith preliminary advise of vehicle SKE 8323J.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 30 October, 2017 2:28 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17010011MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Monday, 30 October, 2017 2:19 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17010011MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010011MFSH

Date: 02-11-2017

Our Ref: CS/FCI17020691/Sgb

The Motor Claims Department
First Capital Insurance Ltd

Without Prejudice

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKE 8323J.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01-11-2017 at the premises of M/s EUROKARS HABITAT and have the following to report:-

Workshop Estimate Amount	: S\$ 14,348.46
Revised Estimate Amount	: S\$ 7,341.48
"Check" Items Amount	: S\$ 5,356.98
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

Sebastian Yeang
Automotive Assessor

ESTIMATED COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 30 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877		NAME : Mdm Lim Kiau Moi ADDRESS : Blk 364 Tampines Street 34 #09-133 Singapore 520364		WIP : 28699 DATE: 25.10.2017	
ATTN :	MOTOR CLAIMS DEPT	TEL :			
FAX :	65073849				
VEH NO :	SKE8323J	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP1ZZZ95ZFLB60350	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SHC883H
MODEL :	Macan S	DATE REG :	11.11.2014	POLICY NO :	

NATURE OF WORKS

[illegible]

Labour Description

1	TO REMOVE / REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.		\$ 2,800.00
2	TO SPRAY PAINT REAR BUMPER		\$ 1,400.00
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.	NETT	\$ 250.00
4	TO REMOVE / REPLACE EXHAUST SYSTEM INCLUDE CHECK FOR LEAKAGE.		\$ 2,100.00
5	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES	NETT	\$ 600.00

	AFTER ACCIDENT REPAIR.		
6	TO SUPPLY 1 PC NO PLATE \$70.00 EA <i>✓ cut</i>	NETT	\$ 70.00
7	SUNDRIES <i>new</i>		\$ 100.00
		TOTAL LABOUR	\$ 7,320.00
		TOTAL PARTS	\$ 7,028.46
		GRAND TOTAL	\$ 14,348.46

Please note that this is **only an estimate**, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Prepared By

Acknowledge By

Sebastian.
1/11/2017.
 - Part by part repair.
 - Question Mark Item Photo.
 - Photo Before Paint.
 90036121
 Sebastianyeang@lkauto.com.

6 days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

[Signature]
3/11/17.

FINALIZATION COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 30 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877		NAME : Mdm Lim Kiau Moi ADDRESS : Blk 364 Tampines Street 34 #09-133 Singapore 520364		WIP : 28699 DATE: 25.10.2017	
ATTN :	MOTOR CLAIMS DEPT	TEL :			
FAX :	65073849				
VEH NO :	SKE8323J	DATE IN :		CONTACT PERSON :	RICK 63602445
CHASSIS NO :	WP1ZZZ95ZFLB60350	MILEAGE :		TYPE OF CLAIM :	TP AGAINST SHC883H
MODEL :	Macan S	DATE REG.:	11.11.2014	POLICY NO. :	

NATURE OF WORKS

[illegible]

Labour Description

	Labour Description		
1	TO REMOVE / REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.	\$ 2,100.00	\$ 2,800.00
2	TO SPRAY PAINT REAR BUMPER	\$ 1,200.00	\$ 1,400.00
3	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.	\$ 250.00	\$ 250.00
4	TO REMOVE / REPLACE EXHAUST SYSTEM INCLUDE CHECK FOR LEAKAGE.	\$ 1,400.00	\$ 2,100.00

5	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES	NETT	\$ 600.00	\$ 600.00
	AFTER ACCIDENT REPAIR.			
6	TO SUPPLY 1 PC NO PLATE \$70.00 EA	NETT	\$ 70.00	\$ 70.00
7	SUNDRIES.		\$ 50.00	\$ 100.00
			TOTAL LABOUR	\$ 5,670.00 / \$ 7,320.00
			TOTAL PARTS	\$ 6,759.00 \$ 7,028.46
			GRAND TOTAL	\$ 12,429.00 \$ 14,348.46
			GST 7 %	\$ 870.03
			TOTAL AFTER GST	\$ 13,299.03

**NUMBER OF DAYS: 7 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,
SATURDAY,SUNDAY AND PUBLIC HOLIDAY**

LOSS OF USE ; \$180.00 X 9 DAYS = \$1,620.00

LTA SEARCH FEES : \$5.35



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 8323J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	P95B-807-417-D-G2X/BUMPER	CUT	774.70	774.70
1	SPOILER	CUT	251.30	251.30
1	COVER	DENTED	167.60	167.60
1	DAMPING PART LH	NECESSARY	31.80	31.80
1	DAMPING PART RH	NECESSARY	31.80	31.80
1	BRACKET	NOT NECESSARY	299.40	-
1	P95B-945-725-E-/REFLECTOR REAR (LEFT)	CRACKED	269.60	269.60
1	P95B-253-612-AY-/REAR MUFFLER	BENT	1,890.70	1,890.70
1	REAR MUFFLER	BENT	1,890.70	1,890.70
1	EXHAUST PIPE	BENT	1,466.20	1,466.20
4	HEXAGON NUT	NECESSARY	3.20	3.20
4	(WB15) CLAMPING SLEEVE EXHAUST SYSTEM	NECESSARY	305.60	305.60
1	TAIL PIPE OUTER LH	BENT	202.60	202.60
1	TAIL PIPE	BENT	202.60	202.60
4	LENS-HEAD SCREW	NECESSARY	17.60	17.60
4	HEXAGON-HEAD BOLT	NECESSARY	4.00	4.00
	LESS 10% DISCOUNT		-780.94	-751.00
			7,028.46	6,759.00
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	NO PLATE (SN)	CUT	70.00	70.00
			170.00	120.00
<u>LABOUR</u>				
	TO REMOVE/REPLACE REAR DAMAGED BUMPER & OTHER AFFECTED BODY PARTS.INCLUDING PANEL BEAT/STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE.		2,800.00	2,100.00
	TO SPRAY PAINT REAR BUMPER.		1,400.00	1,200.00
	TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.		250.00	250.00

Report Ref No. CS/FCI17020691/Sgbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/REPLACE EXHAUST SYSTEM INCLUDE CHECK FOR LEAKAGE.		2,100.00	1,400.00
	TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES.		600.00	600.00
			7,150.00	5,550.00
GRAND TOTAL			14,348.46	12,429.00
RECOMMENDED COST OF REPAIRS				12,429.00

Report Ref No. CS/FCI17020691/Sgbn2

YEANG WAI KEEN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.