

CASE OWNER:

PW  
Ernest Tay

CC 4/AXA17020731

Gga3

LKK:

IDAC:

Surveyor:

Guo Qiang

DOI:

27/10/17

Date / Time:

30/10/17

Registered in Merimen:

20/10/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

895 212Y

Claim No.:

C0456026

Name of Insured:

DR WEI - WEI WEES - STEKLY

Policy No.:

P1677756

Insured Tel No.:

HP:

Make / Model:

BMW 520

Excess Sec II :S\$

D.O.A.:

05/10/17

Place of Accident:

IN FRONT OF 42 WATTEA VIEW

Is driver the owner?

( YES NO )

Nature of Accident:

If NO, Driver Name / Age: CHENG ING JOO

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Driver Tel No.:

821 1647

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

GU 2193 U



INSRS:

WSP: JHauto Trading

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

GU 2193 U - X ; 895 212Y - X

\*CHECK LIABILITY, OBTAIN INSURED DRIVER'S  
SG / FOREIGN DRIVING LICENCE COPY.03/11/17 (THU)  
THH)23/10 checked w pml - they don have old's  
DL.- BID holding - independent pass. In. Out  
Malaysia. they informed police that gun  
pand. do conduct.- checked w Lynn. OD claim handled by kitty.  
already settled.

3/3/2020 - file to Mei Kuan-tu-tu-ey

PRELIMINARY ADVICE Date/Time: 03/11/17 Sent By: Shirley

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow / Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT  
3/3/2020

250-10

REF: AXA

## ASSIGNMENT

From: \_\_\_\_\_ Date: 27-10-2017

Estimated Cost: \_\_\_\_\_

OO / FP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GU 2193U

at Workshop m/s JHauto Trading  
of Blk 14 Defulane 10 # DT-398

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Mr. Hui - 9771 8731

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: 6U2193U Yr Regn: 12 Feb 2001

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Grace cc 2476

Colour: Silver A/C Insured / Std / NI / NA

Sp. Reading: 37977 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMFGD27FP1K 483748

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185 R14

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HIFLY

Front

Rear

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A. D.O.I. 27-10-17

Survey held at W/S 6pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

US\$ 2550 (Red# 389.4K/ 574)

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) \$ + RS \$

) Photos

) Others

)

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/AXA17020731/Gua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 30-10-2017	
			Code : AXA2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGS 212Y	Veh. Inspected	GU 2193U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/10/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	05/10/2017	Inspection Date	27/10/2017	
Survey held at	JHAUTO TRADING 14 DEFU LANE 10 #01-398 DEFU INDUSTRIAL ESTATE SINGAPORE 539195			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

# JHAUTO TRADING

14 Defu Lane 10,  
Defu Industrial Estate.

#01-398

Singapore 539195

H/P: 9771 8731 / 9054 5425

Email: [gjh-wjh@hotmail.com](mailto:gjh-wjh@hotmail.com)

Business Registration : 53240776L

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from

**CASH SALE**

Invoice Date: 14/10/17

Acknowledged by Repairer

Signature:

Date:

Vehicle No: GU2193U

Make/Model: Hyundai H100

Chassis No:

Mileage:

To: 3<sup>rd</sup> Party Claim

S/N	QUANTITY	PARTICULARS	UNIT PRICE	AMOUNT (\$S)
01	01	Front Bumper — Cut	/	\$513.60
02	01	Right Side Door — bmc	/	\$620.60
03	02	Right Side Door Inner Plastic Window Support X Repair	\$123.05 X	\$246.10 X
04	01	Front Left Bumper Retainer X NN	X	\$90.95 X
05	01	Front Right Bumper Retainer — BT	48.5	\$90.95
06	01	Front Bumper Inner Panel — BT	280.6	\$428.00
07	01	Front Right Head Lamp — Cut	312.6	\$406.60
08	01	Front Right Signal Lamp — Self	102.6	\$299.60
09	01	Air Intake Hose — Cut	65	\$235.40
10	01	Right Side Door Outer Protector Sill — Self	/	\$107.00
11	01	Right Side Door Co. Sticker — Self	20(SN)	\$70.00
12	02	Right Side Door Hinges — BT 38.5	\$95.77	\$191.54
13	01	Right Side Door Inner Suspension — BT	30	\$139.10
14		Labour For Mount And Dismount Of Dash Board For Panel Adjusting	200	\$350
15		Panel Re-alignment & Panel Repair	500	\$900
		Labour For Above Spare Part Installation	80	\$400
16		Spray Painting for Accident Area ( Whole Right Hand Side)	700	\$850
			1480	
		<b>TOTAL:</b>		<b>\$5939.44</b>

7 Days. Guo Qiang - 82880282  
Lumpsum Repair / After paint photos.

Customer's Signature / Co. Stamp

For JHAUTO TRADING

27/10/17. 2119  
20%: 1695.2  
3195.2  
20%: 2550

3006.62  
10%: 2705.96  
4185.96  
20%: 3350

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ernest Tay

Date: 03 Nov 2017

**Preliminary Advice**

Insured Vehicle No	: SGS212Y	Accident Date	: 05/10/2017
TP Vehicle No	: GU2193U	Assignment Date	: 20/10/2017
Make	: HYUNDAI GRACE H100	Est. Duration of Repair	: 7 Days
Date of Inspection	: 27/10/2017		
Inspection At	: JHAUTO TRADING		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ....O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5939.44
Revised Amount	:S\$	3195.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3195.20

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : We have not authorized repairs.

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Business
Owner ID	0776L
Vehicle Details	
Vehicle No.	GU2193U
Vehicle to be Exported	No
Intended De-registration Date	30 Oct 2017
Vehicle Make	HYUNDAI
Vehicle Model	GRACE H100 M
Primary Colour	Green
Manufacturing Year	2000
Engine No.	D4BFY048635
Chassis No.	KMFGD27FP1K483748
Maximum Power Output	-
Open Market Value	\$18,048.00
Original Registration Date	12 Feb 2001
First Registration Date	12 Feb 2001
Transfer Count	4
Actual ARF Paid	\$903.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	31 Mar 2022
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	5
PQP Paid	\$24,394.00
COE Rebate Amount	\$21,561.00
<b>Total Rebate Amount</b>	<b>\$21,561.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Oct 2017

## ...CLAIM SUBFOLDER...(New Assignment)

Pending Driver License

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2017		20 Oct 2017 09:24 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS**

[ Created by insurer ]

Insured:	WEI-WEI, WEE-STEKLY, ID: S8081563H, Tel: +6581211647, Email: wcube@hotmail.com		
Main Claimant:	JHAUTO TRADING, Co. Reg. No.: 53240776L		
Vehicle Reg. No.:	GU2193U	Date of Loss:	05/10/2017 00:00 - :59
Claim Type:	TP / C0456026	Policy/Cover Note No.:	P1677756 (Comprehensive)
Vehicle Reg. No. (Insured):	SGS212Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Jhauto Trading (HQ) 4033 Ang Mo Kio Industrial Park 1, #01-62, 569640 Ang Mo Kio - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Ernest Tay - 6880 4835]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/10/2017]		
Driver/Custodian (Insured):	CHEN ING JOO (64 / Female), NRIC: G1712126Q, Tel: +6581211647		
Adj Asg. Remarks:	CHECK LIABILITY, OBTAIN INSURED DRIVER'S SG/ FOREIGN DRIVING LICENCE COPY.		

**ASSOCIATED MAIL RECEIVED**

View All | Compose Case Mail

- AXA\_SG (20/10/2017): WP / New TP Assignment - C0456026/P1677756

**ALL ASSOCIATED TASKS**

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

27.10.2017 @ 12.07pm veh in  
B1K4 Defu Lane 10 # 01-398 GQ  
Mr. Hui - 9771 8731

20.10.2017 - received assignment but no  
wksp contact number &  
detail. Try call Ernest ~~and~~ unable to  
get.

27.10.2017 - Mr. Hui informed veh in  
wksp two weeks already.  
Ernest ask him directly  
contact us. on 27.10.2017

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Tuesday, 12 February 2019 11:31 AM  
**To:** 'PBSP'; Inthiran Thurasamy  
**Cc:** Admin A; CS A Team  
**Subject:** RE: ACCIDENT INVOLVING SGS 212Y AND GU 2193U ALONG 42 WATTEN VIEW ON 05/10/2017 \*LKK REF: CC4/AXA17020731/Gpa3

Dear Sirs/Mdm.

Further to the below email.

Kindly advise whether you have forwarded a copy our insured CCTV Footage and Our Driver(Chen Ing Joo)'s Driving Licence to us.

Appreciate your early reply.

Thank you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Wednesday, 31 October 2018 1:14 AM  
**To:** Inthiran Thurasamy <inthiran.thurasamy@simedarby.com.sg>  
**Cc:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>  
**Subject:** Re: ACCIDENT INVOLVING SGS 212Y AND GU 2193U ALONG 42 WATTEN VIEW ON 05/10/2017

Dear Inthiran

AXA has received a claim from third-party against our customer. Please see email request from LKK below.

Please assist.



Thank you.

Regards,  
Caroline

---

**From:** Thin Thin (LKKAuto) <[thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)>

**Sent:** Tuesday, 30 October 2018 6:34:58 PM

**To:** PBSP

**Cc:** Hsiao Tong (LKKAuto); 甯珺 ©

**Subject:** ACCIDENT INVOLVING SGS 212Y AND GU 2193U ALONG 42 WATTEN VIEW ON 05/10/2017

Dear Caroline,

**ACCIDENT INVOLVING SGS 212Y AND GU 2193U ALONG 42 WATTEN VIEW ON 05/10/2017**

We are the loss adjuster appointed by **SGS 212Y** motor insurer, AXA Insurance Pte Ltd to deal with the third party claim.

We would like to request the CCTV Footage and Insured Driver Driving Licence for our necessary action.

Best Regards,

**Thin Thin Hlaing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2360 | email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Print Sent Message

This mail is associated with :

**\*GU2193U (C0456026)**

**[SGS212Y]**

TP

JHAUTO TRADING

Oct 5 2017 12:00AM

[WEI-WEI, WEE-STEKLY]

Jhauto Trading

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 23/10/2019 16:41 PM.  
**To** peter.wang@axa.com.sg  
**CC** AXA\_SG; chewht@lkkauto.com; admin-a@lkkauto.com  
**Subject** <Submit wp Report> C0456026

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that we have inspected third-party vehicle GU2193U on 05/10/2017, at JHAuto Trading. However, there is still no further action initiated by third-party repairer for their claim up-to-date.

In view of non-development from the third-party, we will proceed to temporarily close this outstanding claim file and submit our WP report to your good-office.

Thank you.

Hsiao Tong

## Hsiao Tong (LKKAuto)

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Monday, 2 March 2020 4:00 PM  
**To:** do-not-reply@merimen.com  
**Cc:** Hsiao Tong (LKKAuto); Admin A  
**Subject:** RE: <Submit wp Report> C0456026

This mail is associated with :

**\*GU2193U (C0456026)**

**[SGS212Y]**

TP

JHAUTO TRADING

Oct 5 2017 12:00AM

[WEI-WEI, WEE-STEKLY]

Jhauto Trading

Hi Team

Yellow tag removed.

Please upload your report.

Thank you!

Regards

Peter



<-- Original Message -->

From: LKK\_HQ  
To: peter.wang@axa.com.sg  
CC: AXA\_SG; chewht@lkkauto.com; admin-a@lkkauto.com  
Sent On: 06/01/2020 03:35 PM  
Subject: RE: C0456026

Dear Sirs/Mdm,

Kindly assist to remove yellow tag for our submission report in Merimen.

Thank you.

Hsiao Tong

<-- Original Message -->

From: LKK\_HQ  
To: peter.wang@axa.com.sg  
CC: AXA\_SG; chewht@lkkauto.com; admin-a@lkkauto.com

Sent On: 09/12/2019 09:54 AM  
Subject: RE: C0456026

Dear Sirs/Mdm,

Kindly assist to remove yellow tag for our submission report in Merimen.

Thank you.

Hsiao Tong

<-- Original Message -->

From: LKK\_HQ  
To: peter.wang@axa.com.sg  
CC: AXA\_SG; chewht@lkkauto.com; admin-a@lkkauto.com  
Sent On: 16/11/2019 11:23 AM  
Subject: RE: C0456026

Dear Sirs/Mdm,

Kindly assist to remove yellow tag for our submission report in Merimen.

Thank you.

Hsiao Tong

<-- Original Message -->

From: LKK\_HQ  
To: peter.wang@axa.com.sg  
CC: AXA\_SG; chewht@lkkauto.com; admin-a@lkkauto.com  
Sent On: 06/11/2019 04:33 PM  
Subject: RE: C0456026

Dear Sirs/Mdm,

Kindly assist to remove yellow tag for our submission report in Merimen.

Thank you.

Hsiao Tong

<-- Original Message -->

From: LKK\_HQ  
To: peter.wang@axa.com.sg  
CC: AXA\_SG; chewht@lkkauto.com; admin-a@lkkauto.com  
Sent On: 23/10/2019 04:41 PM  
Subject: C0456026

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that we have inspected third-party vehicle GU2193U on 05/10/2017, at JHAuto Trading. However, there is still no further action initiated by third-party repairer for their claim up-to-date.

In view of non-development from the third-party, we will proceed to temporarily close this outstanding claim file and submit our WP report to your good-office.

Thank you.

Hsiao Tong

This is an auto-generated email. Do not reply to this email.

Sent by : Peter Wang Xiao (AXA Insurance Pte Ltd)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2017		20 Oct 2017 09:24 <a href="#">Edit Adj Rpt</a>	<b>S\$2,550.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	WEI-WEI, WEE-STEKLY, ID: S8081563H, Tel: +6581211647, Email: wcube@hotmail.com		
Main Claimant:	JH AUTO defu lane, Co. Reg. No.: 53240776L		
Vehicle Reg. No.:	GU2193U	Date of Loss:	05/10/2017 00:00 - :59 [199 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0456026	Policy/Cover Note No.:	P1677756 (Comprehensive)
Vehicle Reg. No. (Insured):	SGS212Y	Policy No. (Claimant):	5071331975-02(TPFT)
		Excess:	S\$0.00
Repairer:	Jhauto Trading ( ) 14 DEFU LANE 10 #01-398, DEFU INDUSTRIAL ESTATE, 539195 Defu Lane - Tel:		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 ... [Handled by Peter Wang Xiao]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/10/2017]		
Driver/Custodian (Insured):	CHEN ING JOO (64 / Female), NRIC: G1712126Q, Tel: +6581211647 Email: WCUBE@HOTMAIL.COM		
Adj. Asp. Remarks:	CHECK LIABILITY, OBTAIN INSURED DRIVER'S SG/ FOREIGN DRIVING LICENCE COPY.		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA\_SG (02/03/2020): RE: <Submit wp Report> C0456026
- AXA\_SG (22/09/2018): Re: Direct Settlement - Accident Involving SGS212Y (OI : AXA - C0456026) and GU2...
- AXA\_SG (20/10/2017): WP / New TP Assignment - C0456026/P1677756

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GU2193U (C0456026)  
[SGS212Y]  
TP  
JH AUTO defu lane  
Oct 5 2017 12:00AM  
[WEI-WEI, WEE-STEKLY]  
Jhauto Trading

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/11/17 13:56	Adjuster Immediate Advice		Load HTM
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/11/17 12:09	LKK INSPECTION PHOTO		Load PDF
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/10/17 10:55	EMAIL_ABS		Load PDF
2	19/10/17 10:55	ESTIMATE_ABS		Load PDF
3	19/10/17 10:55	GIA SGS212Y INSD_ABS		Load PDF
4	19/10/17 10:56	GU2193U TP GIA RPT <small>From:OD - Reg. No: SGS212Y, Claimant: DR WEI-WEI WEE-STEKLY</small>		Load PDF
5	20/10/17 09:17	EDDIES - CHEN ING JOO - SGS212Y <small>INVALID</small>		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/17 18:50	\TP GIA REPORT		Load PDF
2	30/10/17 18:50	TP ESTIMATE- MARKED		Load PDF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17020731/GPA3Q2

Date: 04/03/2020

## REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No: P1677756

Claimant GU2193U

Insured Vehicle No : SGS212Y

Date of Loss: 05/10/2017

Nature of Claim: TP

Claim No: C0456026

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GU2193U

Make &amp; Model: HYUNDAI GRACE H100, 2.5 D (M)

Engine No: D4BFY048635

Reg. Date: 12/02/2001 (Man. Year: 2000)

Chassis No: KMFGD27FP1K483748

Colour: Silver

Odometer: 37977 km

Engine Capacity: 2476 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185 R14

Rear Tyre Size: 185 R14

Front Left Side: HIFLY 5 mm

Rear Left Side: HIFLY 5 mm

Front Right Side: HIFLY 5 mm

Rear Right Side: HIFLY 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,439.44	1,715.20	1,724.24	50.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,480.00	1,020.00	40.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,939.44	3,195.20	2,744.24	46.20
Approved Total (Overridden) (S\$)		2,550.00		
Nett Amount (S\$)	5,939.44	2,550.00	3,389.44	57.07
Global Sum Settlement (S\$)		0.00		

## INSPECTION

Date of Assignment: 20/10/2017

Date Inspected: 27/10/2017 Inspected At:

JHAUTO TRADING  
14 DEFU LANE 10 #01-398 DEFU  
INDUSTRIAL ESTATE  
SINGAPORE 539195

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	(Last Synchronised: 03 Mar 2020)	
<b>Parts:</b>	N/A	HYUNDAI GRACE H100 2.5 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GU2193U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (CONSISTENT)	Cut	513.60 F	*513.60 FL
2	1		*RIGHT SIDE DOOR (CONSISTENT)	Buckled	620.60 F	*620.60 FL
3	2		*RIGHT SIDE DOOR INNER PLASTIC WINDOW SUPPOT (CONSISTENT)	Repair	246.10 F	*- FL
4	1		*FRONT LEFT BUMPER RETAINER (CONSISTENT)	Not Necessary	90.95 F	*- FL
5	1		*FRONT RIGHT BUMPER RETAINER (CONSISTENT)	Bent	90.95 F	*48.50 FL
6	1		*FRONT BUMPER INNER PANEL (CONSISTENT)	Bent	428.00 F	*280.60 FL
7	1		*FRONT RIGHT HEAD LAMP (CONSISTENT)	Cut	406.60 F	*312.60 FL
8	1		*FRONT RIGHT SIGNAL LAMP (CONSISTENT)	Scratched	299.60 F	*102.60 FL
9	1		*AIR INTAKE HOSE (CONSISTENT)	Cut	235.40 F	*65.00 FL
10	1		*RIGHT SIDE DOOR OUTER PROTECTOR SILL (CONSISTENT)	Scratched	107.00 F	*107.00 FL
11	1		*RIGHT SIDE DOOR CO.STICKER (CONSISTENT)	Scratched	70.00 FS	*20.00 FS
12	2		*RIGHT SIDE DOOR HINGES (CONSISTENT)	Bent (1 PCS ONLY)	191.54 F	*38.50 FL
13	1		*RIGHT SIDE DOOR INNER SUSPENSION (CONSISTENT)	Bent	139.10 F	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	3,439.44	2,139.00
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	423.80

Total Parts (S\$)	3,439.44	1,715.20
-------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR MOUNT AND DISMOUNT OF DASH BOARD FOR PANEL ADJUSTING	New	350.00	200.00
2	PANEL RE-ALIGNMENT & PANEL REPAIR	New	900.00	500.00
3	LABOUR FOR ABOVE SPARE PART INSTALLATION	New	400.00	80.00
4	SPRAY PAINTING FOR ACCIDENT AREA (WHOLE RIGHT HAND SIDE)	New	850.00	700.00
Gross Labour Cost (\$\$)			2,500.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >