


Signature: *P. Amu*

REF: NS/2NC17020740/Riqber

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: SJL 47462  
 Policy No: 5088522084 140317 - 130818  
 Claims No: MT/0967034-002  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 12 days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: SHF 242S Yr Regn: 2012 Anh  
 Type: M.Car / M.Cycle / Bus / Van / Lorry /  Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: CHEVROLET EPICA cc: 1971  
 Colour: MARON A/C: Insured / Std / NI / NA  
 Sp. Reading: 671979 T.Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 Cr/No: KL1069R30B136854  
 Gen. Cond: Good /  Fair / Poor / Burnt  
 Steering:  Order / Jammed / Leaked / Burnt or  
 Brake:  Order / Jammed / Leaked / Burnt or  
 Modl: Nil / S/Rim /  STD A/Rim or  
 Tyre Size: F: 205/65R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or FALKEN  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 23/10/17 D.O.I. 30/10/17  
 Survey held at: SMP  
 Des. of Damages: Frt  Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision: \_\_\_\_\_

Date / Time	Action / Instruction	DAF	Other
	SHF 242S - C03 / CAL14007708 / Klwrm3k3	2104/14	10/17/2143
	SJL 47462 - X		N/A
	US \$14150, 12 days (Red \$15143.50, 52%)		SJL 47462

RECEIVED 12 DEC 2017  
 RECEIVED 20 DEC 2017

Date/Time: File Pass to?  Prel. Report  
 11/12/17 *Amu*  Final Report  
 Date/Time: File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format: TP  
 Lump Sum / I.B.N. (\$) 14150  
 Days Of Repair: 12  
 Resurvey No. of Trip: 1  
 Add Fee:  Site Insp (\$) \_\_\_\_\_  
 Interview (\$) \_\_\_\_\_  
 Tech. Inv. (\$) \_\_\_\_\_  
 Weekend (\$) \_\_\_\_\_  
 Survey Fee \_\_\_\_\_  
 Transportation \_\_\_\_\_  
 S + RS (\$) \_\_\_\_\_  
 Photo \_\_\_\_\_  
 Cost \_\_\_\_\_  
 TOTAL 195



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: NS/INC17020740/R1qb	
73 BRAS BASAH ROAD		Date: 31-10-2017	
#05-01 NTUC TRADE UNION HOUSESINGAPORE			
189556		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJL 4746Z	Veh. Inspected	SHF 242S
Policy No.	5088522084	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/10/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	23/10/2017	Inspection Date	30/10/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Survey Department Check List (Case Handler)

Reference No.: NS/NC/7020740/PLH/6  
 Policy Type: OD (TP) / TP RES / TL / EVA

SAF 2425  
 Typist

Admin ( Cath ): Case handler to make sure all information created by the assignment team are ACCURATE.

**(1) Office Assign Form**

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From				
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No				
C Insurance Authorisation (CA/REV/REP)				
C Report Type	✓			
C Weekend Charges				
N Survey held at/Repairer	✓			
C Excess				

Surveyor ( Ravi ): Case handler to make sure the surveyor completed all required information.

**(1) Assignment Form**

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

**(2) System - (Views/Merimen)**

C Damaged Vehicle Photographs Uploaded	✓		
--	---	--	--

**(3) Workshop Estimate/Assignment Form**

N ALL Parts condition	✓		
C Market Value for OD cases			
C Estimate Repair Cost for PRI (RSI, TMI, MSIG)			
C Days of repair	✓		
C Finalised Amount	✓		
C Re-inspection Cases to Finalize within 5 Days			

**(4) System - (Views/Merimen)**

C Resurvey photo Uploaded	✓		
---------------------------	---	--	--

Check By: [Signature] 08/12/17  
 Case Handler Date

TP Claims against NTUC Income: Follow-Through Survey

Date: 08/12/2017

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/0972139-002	COMFORT TRANSPORTATION PTE LTD	SH 8278X	SIC 8158T	03/12/2017	13:20	\$ 2,285.78	\$ 1,360.60
2	MT/0972594-002	COMFORT TRANSPORTATION PTE LTD	SHB 4355U	FBJ 730A	04/12/2017	17:30	\$ 1,559.40	\$ 750.00
3	MT/0967034-002	SMRT TAXI PTE LTD	SHF 242S	SIL 4746Z	23/10/2017	17:30	\$ 29,293.50	\$ 14,150.00
4	MT/0971684-002	COMFORT TRANSPORTATION PTE LTD	SHC 8443S	SHB 8982H	29/11/2017	2:30	\$ 1,327.04	\$ 560.00
5	MT/0972089-002	COMFORT TRANSPORTATION PTE LTD	SHC 1351U	SIP 319D	03/12/2017	1:45	\$ 3,507.04	\$ 900.00
6	MT/0973057-001	CITYCAB PTE LTD	SHD 8531R	SFM 1303E	04/12/2017	4:55	\$ 2,411.58	\$ 1,080.48

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)

[Change Password](#)

[Log Out](#)

**Policy Query**

Policy No.  Date of Accident   
Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5088522084	KONG LUAN	S8082091G	GPC	drive CLASSIC	SJL4746Z	SJL4746Z	14/03/2017	13/03/2018

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	26/10/2017 10:37
Date Of Accident	23/10/2017 17:30
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF242S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHOO THENG KOON
NRIC No	S7101003A
Date Of Birth	14/01/1971
Occupation	OUTDOOR
Date Of Driving Pass	23/06/1997
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name KAKI BUKIT NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 526 BEDOK NORTH STREET 3 #01-448 , POSTCODE: 460526  
 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-4429999 - FAX NO: 62444377  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO POLICE REPORT - T/20171024/2076 On 23/10/2017 at about 1730hrs, I was driving my vehicle SHF242S along PIE towards Changi when I met up with an accident involving another vehicle SJL4746Z after Eng Neo exit and before Stevens Exit just below the ERP gantry. I was driving on the second lane at that point of time and I passed through the ERP gantry, I heard the beep sound and after awhile, I felt an impact from the rear of my taxi. My car moved forward and as I wanted to avoid collision with the vehicle in front of me, I pressed my brake and as soon as I applied the brake, I felt another impact from the rear. After the collision, both of our cars stopped and both drivers came down to exchange particulars. The ambulance then came over and I was conveyed to Tan Tock Seng hospital because I felt pain on the back of my body. The rear bumper of my taxi was dented in.

**Attachment(s)**

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJL4746Z  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver KONG LUAN  
 NRIC/Passport Number S8082091G  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF INJURED PERSON 1**

Name

CHOO THENG KOON

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHF242S

Were seat belts worn?


Was injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A large rectangular area with horizontal lines for describing the accident circumstances.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

*Chris G...*  
26/10/17  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]*  
26/10/2017  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



*Chew Henry K.*

*[Signature]*  
26/10/2017

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*26/10/17.*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20171024.2076

1 of 3

Report No. T/20171024/2076

Police Station Of Origin:  
Kaki Bukit NPP  
526 Bedok North Street 3 #01-448  
SINGAPORE 460526  
Tel No: 1800-4429999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 24/10/2017 14:04	Vide Report No.:	Station Diary No.: 13
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: CHOO THENG KOON		Address: APT BLK 532 BEDOK NORTH STREET 3 #16-730 SINGAPORE 460532	
ID Type / ID No.: NRIC NO / S7101003A		Contact No.: Home/Office: Mobile: 97318210	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 46	Date of Birth: 14/01/1971	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3,4 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 23/10/2017 17:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY towards Changi Airport, after Eng Neo exit and before Stevens Exit just below the ERP				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHF242S	Car	CHEVROLET	EPICA	Maroon	Seriously Damaged	0
SJL4746Z	Car	HONDA	JAZZ	White		0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20171024/2076

Police Station Of Origin:  
Kaki Bukit NPP  
526 Bedok North Street 3 #01-448  
SINGAPORE 460526  
Tel No: 1800-4429999

2 of 3  
Report No. T/20171024/2076

CONTINUATION OF REPORT

Driver			
Name	CHOO THENG KOON	ID No.	S7101003A
Related Vehicle	SHF242S (Car)	Contact No.	97318210
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	23/10/2017	Date Discharge	23/10/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	KONG LUAN	ID No.	S8082091G
Related Vehicle	NIL	Contact No.	92205607
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 23/10/2017 at about 1730hrs, I was driving my vehicle SHF242S along PIE towards Changi when I met up with an accident involving another vehicle SJL4746Z after Eng Neo exit and before Stevens Exit just below the ERP gantry. I was driving on the second lane at that point of time and I passed through the ERP gantry, I heard the beep sound and after awhile, I felt an impact from the rear of my taxi. My car moved forward and as I wanted to avoid collision with the vehicle in front of me, I pressed my brake and as soon as I applied the brake, I felt another impact from the rear. After the collision, both of our cars stopped and both drivers came down to exchange particulars. The ambulance then came over and I was conveyed to Tan Tock Seng hospital because I felt pain on the back of my body. The rear bumper of my taxi was dented in.



SINGAPORE  
POLICE FORCE

Police Station Of Origin:  
Kaki Bukit NPP  
526 Bedok North Street 3 #01-448  
SINGAPORE 480526  
Tel No: 1800-4429999



T/20171024/2076

3 of 3

Report No: T/20171024/2076

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan


IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G/ SI SAW KIAN HOCK	
Signature Of Interpreter: Not applicable	
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt RAZIZ BIN TAHAR Contact.No.: 55476200	

Authentication Stamp  
NP168

Signature Of Informant: 
Date/Time: 24/10/2017 14:04
Classification Of Case:

## SMRT Accident Vehicle Repair Estimates



### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF242S  
Ref. No : TAX/10/17/2143  
Reg. Date : 08/08/2012  
Vehicle Type : TAXI  
Make : CHEVROLET EPICA 2.0 VCDI  
Model : EPICA-2.0  
Name of Driver : CHOO THENG KOON  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 23/10/2017 05:30:00 PM  
Accident Reported Date / Time : 26/10/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time : 23/10/2017  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024092739  
Special Instruction to ARC, if any :  
TOWED \$ 80/TOWED TO TP COMPOUND /S JL4746Z - NTUC IDAC (Resurvey after repair)  
Prepared Date : 26/10/2017 10:56:54 AM



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : KL1LA69RJBB136854

Mileage


0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	0.00
Total Spray Painting Charges	: 3,150.00	0.00
Total Material Charges	: 16,276.06	16,276.06
Other Charges	: 2,082.00	0.00
<b>TOTAL</b>	<b>: 23,367.06</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 23,350.00</b>	<b>0.00</b>
No. of Repair Days	: 12.00	0.00 <i>12 days - Lump sum</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 28/10/2017 09:40:27 AM	01/01/1900 12:00:00 AM



*Prepared*  
*30/10/17 09:30*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/10/2017 09:38:08 AM



**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : 0.00 Prepared Date : 10/28/2017 9:38:31 AM

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	0.00 1400
<b>Total Labour</b>	<b>1,859.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR BOOT LID	378.00	0.00 200
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00 100
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 80
TO RESPRAY REAR CHASSIS LH	180.00	0.00 100
TO RESPRAY REAR CHASSIS RH	180.00	0.00 100
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00 50
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESRAY REAR DOOR LH	378.00	0.00 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>3,150.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	112.00	0.00 X
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 160
TO REMOVE / REFIT SEAT	120.00	0.00 60
TO REMOVE & REFIT EXHAUST	120.00	0.00 60
TO ALIGN CHASSIS	350.00	0.00 200
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00 100
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 140
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 120
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
<b>Total Other Costs</b>	<b>2,082.00</b>	<b>0.00</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace <i>DE</i>	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace <i>DE</i>	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace <i>FA</i>	No
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace <i>DE</i>	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>NE</i>	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace <i>CRA</i>	No
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace <i>CRA</i>	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace <i>NE</i>	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace <i>NE</i>	No
96647117	COMMO N		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Replace ?	No
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace <i>FA</i>	No
96299719			EXHUAST HEAT SHIELD	1	159.00	10.00	143.10	Replace	Replace ?	No
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace <i>FA</i>	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace <i>FA</i>	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace <i>FA</i>	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace <i>CRA</i>	No
96474968	REAR		REAR BOOT SPRING GAS	2	144.00	10.00	259.20	Replace	Replace X	No
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace X	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace <i>BT</i>	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace <i>NE</i>	No
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace <i>at</i>	No
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace <i>NE</i>	No
96190751	REAR		LAMP LICENSE	2	56.00	10.00	100.80	Replace	Replace ?	No
	COMMO N		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace <i>DE</i>	No
	COMMO N		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>DE</i>	No
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace <i>CRA</i>	No
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace <i>sur</i>	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace <i>NE</i>	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace <i>NE</i>	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>NE</i>	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>NE</i>	No
96646491	COMMO N		W/HARNESS T / LID	1	83.52	10.00	75.17	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace <i>JA</i>	No
94503739			CLIP, TRIM	4	1.00	10.00	3.60	Replace	Replace <i>JA</i>	No
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace <i>JA</i>	No
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace <i>JA</i>	No
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace <i>JA</i>	No
96932979			COVER BAORD SPARE TYRE	1	661.00	10.00	594.90	Replace	Replace <i>JA</i>	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace <i>JA</i>	No
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace <i>JA</i>	No
			INSULATOR SHEET	1	41.48	10.00	37.33	Replace	Replace <i>JA</i>	No
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Replace <i>JA</i>	No
	BODY		CHASSIS MEMBER RR RH	1	525.38	10.00	472.84	Replace	Replace <i>JA</i>	No
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace <i>JA</i>	No
			JACK CARRIER	1	12.95	10.00	11.65	Replace	Replace <i>JA</i>	No
			JACK FOAM COVER	1	35.00	10.00	31.50	Replace	Replace <i>JA</i>	No
96632596	REAR		WHEELHOUSE A-RR LH	1	464.00	10.00	417.60	Replace	Replace <i>JA</i>	No
96632583			PANEL A-SIDE, INR, RR LH	1	830.00	10.00	747.00	Replace	Replace <i>JA</i>	No
96399775	COMMO N		W/HARNESS RR DEFOG	1	7.72	10.00	6.95	Replace	Replace <i>JA</i>	No
96646502	COMMO N		W/HARNESS TRK ROOM	1	51.74	10.00	46.57	Replace	Replace <i>JA</i>	No
	COMMO N		SPARE TYRE STUD	1	56.59	10.00	50.93	Replace	Replace <i>JA</i>	No
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace <i>JA</i>	No
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace <i>JA</i>	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>JA</i>	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>JA</i>	No
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace <i>JA</i>	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace <i>JA</i>	No
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace <i>JA</i>	No
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace <i>JA</i>	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>JA</i>	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>JA</i>	No
96633557	REAR	6504575	LINER LH REAR FENDER ( PROTECTOR )	1	201.00	10.00	180.90	Replace	Replace <i>JA</i>	No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace <i>JA</i>	No
	COMMO N		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96635655	DOOR	6504603	PANEL LH REAR DOOR	1	1,863.00	10.00	1,676.70	Replace	Replace <i>Repair</i>	No
	COMMON		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>new</i>	No
	DOOR		HINGE LOWER RR LH	1	30.00	10.00	27.00	Replace	Replace	No
	DOOR		HINGE UPPER RR LH	1	24.00	10.00	21.60	Replace	Replace	No
	COMMON		CHECK, LH REAR DOOR	1	30.00	0.00	30.00	Replace	Replace	No
96851984	DOOR		LATCH REAR DOOR LH	1	539.00	10.00	485.10	Replace	Replace	No
<b>TOTAL MATERIALS</b>								<b>20,345.07</b>	<b>20,345.07</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>16,276.06</b>	<b>16,276.06</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

*Chua*

*SHF 242S*  
*13-11-17 / 13:45*  
*14-11-17 / 08:45*


*31-10-17 / 08:45*

**SMRT Accident Vehicle Repair Estimates**

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SHF242S  
 Ref. No : TAX/10/17/2143  
 Reg. Date : 08/08/2012  
 Vehicle Type : TAXI  
 Make : CHEVROLET EPICA 2.0 VCDI  
 Model : EPICA-2.0  
 Name of Driver : CHOO THENG KOON  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 23/10/2017 05:30:00 PM  
 Accident Reported Date / Time : 26/10/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : *Rasul*  
 Vehicle is Towed Back? : *No Yes*  
 Towed Back Date/Time : 23/10/2017  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024092739  
 Special Instruction to ARC, if any :

*Save*



TOWED \$ 80/TOWED TO TP COMPOUND /S JL4746Z - NTUC IDAC *45*  
 Before paint photo , After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL  
 / HP : 9001 0068. email: rasul@lkkauto.com  
 LUMPSUM REPAIR  
 Prepared Date : 26/10/2017 10:56:54 AM


*97318210 Choo 1330 ✓*

*14/11/17 9:00 @C Reject spare Tyre stud missing*

*TRIM RR panel & LHR Boot RHR Boot crack*

Recording Camera    
 Radio Antenna    
 1<sup>st</sup> witness *R* Date *31-10-17*  
 2<sup>nd</sup> witness \_\_\_\_\_ Date \_\_\_\_\_

Vehicle to be Towed Date: *31/10*   
 Time In: *1330*  
 Toga Job No: *13667/10*  
 Date sent to SMRT Date: *13/11/17*  
 Time In: *1350* Driver: *[Signature]*  
 Received by (SMRT): *[Signature]*




Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB136854 Mileage : 0  
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	1,400.00
Total Spray Painting Charges	: 3,150.00	1,630.00
Total Material Charges	: 14,084.07	13,506.88
Other Charges	: 1,970.00	-2,386.88
<b>TOTAL</b>	<b>: 21,063.07</b>	<b>14,150.00</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 12.00	12.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sing Off Date	: 28/10/2017 09:40:27 AM	30/10/2017 04:35:47 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/10/2017 09:38:08 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1711-0360 Invoice No :  
Quotation Date : 15/11 Invoice Date :  
Invoice Amount : 0.00 Prepared Date : 10/28/2017 9:38:31 AM

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	1,400.00
<b>Total Labour</b>	<b>1,859.00</b>	<b>1,400.00</b> ✓

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY REAR BOOT LID	378.00	200.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00
TO RESPRAY REAR LH WHEEL HOUSE	180.00	100.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	80.00
TO RESPRAY REAR CHASSIS LH	180.00	100.00
TO RESPRAY REAR CHASSIS RH	180.00	100.00
TO RESPRAY REAR FENDER RH	378.00	200.00
TO RESPRAY TAIL LAMP PANEL LH	180.00	50.00
TO RESPRAY REAR FENDER LH	378.00	200.00
TO RESRAY REAR DOOR LH	378.00	200.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>3,150.00</b>	<b>1,630.00</b> ✓

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	160.00
TO REMOVE / REFIT SEAT	120.00	60.00
TO REMOVE & REFIT EXHAUST	120.00	60.00
TO ALIGN CHASSIS	350.00	200.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00
TO REMOVE AND REFIT WIRE HARDESS	200.00	100.00
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	140.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	120.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	40.00
Lump Sum Adjustment by Surveyor	0.00	-3,536.88
<b>Total Other Costs</b>	<b>1,970.00</b>	<b>-2,386.88</b>

1150

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No <i>OK</i>
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No <i>OK</i>
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No <i>BT</i>
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace	No <i>scr</i>
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>new</i>
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace	No <i>OK</i>
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace	No <i>OK</i>
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace	No <i>new</i>
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace	No <i>new</i>
96647117	COMMON		W/HARNES RR BPR	1	227.34	10.00	204.61	Replace	Check	No <i>Xscr</i>
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace	No <i>scr</i>
96299719			EXHUAUST HEAT SHIELD	1	159.00	10.00	143.10	Replace	Check	No <i>Xscr</i>
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace	No <i>BT</i>
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No <i>BT</i>
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace	No <i>BT</i>
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace	No <i>BT</i>
96474968	REAR		REAR BOOT SPRING GAS	0	144.00	10.00	0.00	Replace	Not given	No <i>CRK</i>
96636502	REAR		REAR BOOT HINGE	0	92.00	10.00	0.00	Replace	Not given	No <i>Xscr</i>
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace	No <i>Xscr</i>
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace	No <i>BT</i>
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace	No <i>new</i>
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No <i>scr</i>
96190751	REAR		LAMP LICENSE	2	56.00	10.00	100.80	Replace	Check	No <i>scr</i>
	COMMON		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <i>scr</i>
	COMMON		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No <i>scr</i>
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace	No <i>scr</i>
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace	No <i>scr</i>
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No <i>scr</i>
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No <i>new</i>
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>new</i>
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>new</i>
96646491	COMMON		W/HARNES T / LID	1	83.52	10.00	75.17	Replace	Check	No <i>Xscr</i>

7273.72

5873.06

Part Number	Location	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Total Price (\$)	Recommen d	Surveyor Approved	Photos Attached
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace	No <i>PA</i>
94503739			CLIP,TRIM	4	1.00	10.00	3.60	Replace	Replace	No <i>new</i>
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace	No <i>DE</i>
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace	No <i>DE</i>
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace	No <i>DE</i>
96932979			COVER BAORD SPARE TYRE	0	661.00	10.00	0.00	Replace	Not given	No <i>X SA</i>
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No <i>new</i>
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace	No <i>new</i>
			INSULATOR SHEET	1	41.48	10.00	37.33	Replace	Replace	No <i>new</i>
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Replace	No <i>PA</i>
	BODY		CHASSIS MEMBER RR RH	1	525.38	100.00	0.00	Replace	Repair	No <i>R</i>
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace	No <i>PA</i>
			JACK CARRIER	0	12.95	10.00	0.00	Replace	Not given	No <i>X SA</i>
			JACK FOAM COVER	0	35.00	10.00	0.00	Replace	Not given	No <i>X SA</i>
96632596	REAR		WHEELHOUSE A-RR LH	1	464.00	100.00	0.00	Replace	Repair	No <i>R</i>
96632583			PANEL A-SIDE, INR, RR LH	1	830.00	100.00	0.00	Replace	Repair	No <i>R</i>
96399775	COMMO N		W/HARNESS RR DEFOG	1	7.72	10.00	6.95	Replace	Check	No <i>X SA</i>
96646502	COMMO N		W/HARNESS TRK ROOM	1	51.74	10.00	46.57	Replace	Check	No <i>X SA</i>
	COMMO N		SPARE TYRE STUD	1	56.59	10.00	50.93	Replace	Replace	No <i>CRA</i>
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace	No <i>PA</i>
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	100.00	0.00	Replace	Repair	No <i>R</i>
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>new</i>
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>new</i>
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace	No <i>DE</i>
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace	No <i>CRA</i>
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace	No <i>PA</i>
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace	No <i>new</i>
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <i>new</i>
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>new</i>
96633557	REAR	6504575	LINER LH REAR FENDER ( PROTECTOR )	1	201.00	10.00	180.90	Replace	Replace	No <i>DE</i>
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace	No <i>new</i>
	COMMO N		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No <i>new</i>

Number				Qty	List Price (\$)	Discount (%)	Final Price (\$)	Recommen d	Surveyor Approved	Notes Attached	
96635655	DOOR	6504603	PANEL LH REAR DOOR	1	1,863.00	100.00	0.00	X	Replace	Repair	No <i>R</i>
	COMMO N		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00		Replace	Replace	No <i>Re</i>
	DOOR		HINGE LOWER RR LH	0	30.00	10.00	0.00	X	Replace	Not given	No <i>X8u</i>
	DOOR		HINGE UPPER RR LH	0	24.00	10.00	0.00	X	Replace	Not given	No <i>X8u</i>
	COMMO N		CHECK, LH REAR DOOR	0	30.00	0.00	0.00	X	Replace	Not given	No <i>X8u</i>
96851984	DOOR		LATCH REAR DOOR LH	0	539.00	10.00	0.00	X	Replace	Not given	No <i>X8u</i>
TOTAL MATERIALS								14,084.07	13,506.88		
TOTAL MATERIALS(Discounted)								14,084.07	13,506.88		

Added Spare Parts / Material Usage After Surveyor Signed off

*6233156*

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

*14,519.14*  
*13,506.88*  
*1400.00*  
*2780.00*  


---

*17,686.88*  
*20%*  
*14,149.50*  


---

*41.14,150*  


---

*12 days*

*29293.50*



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17020740/R1qbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 09-01-2018



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJL 4746Z	Veh. Inspected	SHF 242S
Policy No.	5088522084	Coverage (\$)	0.00
Claim No.	MT/0967034-002	Excess (\$)	0.00
Assign From		Assign Date	30/10/2017

### 2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB136854	Colour	MAROON
Odometer	671979	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R15	FALKEN	5 mm
L/H Front Tyre	205/65 R15	FALKEN	5 mm
R/H Rear Tyre	205/65 R15	FALKEN	5 mm
L/H Rear Tyre	205/65 R15	FALKEN	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	23/10/2017	Inspection Date	30/10/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 242S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER RR (DISC 10%)	DEFORMED	1,238.00	1,114.20
1	ABSORBER ENGY RR BUMPER (DISC 10%)	DEFORMED	70.00	63.00
1	BEAM RR BUMPER IMPACT (DISC 10%)	BENT	1,221.00	1,098.90
1	COVER TOWING EYE RR (DISC 10%)	SCRATCHED	21.00	18.90
1	REFLECTOR REFLEX RR LH (DISC 10%)	CRACKED	264.00	237.60
1	REFLECTOR REFLEX RR RH (DISC 10%)	CRACKED	264.00	237.60
1	BRACKET RR BUMPER SIDE LH (DISC 10%)	NECESSARY	49.00	44.10
1	BRACKET RR BUMPER SIDE RH (DISC 10%)	NECESSARY	49.00	44.10
2	EXHAUST PIPE MOUNTING, REAR @\$4.40 (DISC 10%)	DISTORTED	8.80	7.92
1	MUFFLER A-EXH, RR (DISC 10%)	BENT	2,909.00	2,618.10
1	REAR BOOT LID (DISC 10%)	BENT	974.00	876.60
1	REAR BOOT LOCK (DISC 10%)	BENT	77.00	69.30
1	REAR BOOT REFLECTOR (DISC 10%)	CRACKED	165.00	148.50
1	REAR BOOT STRIKER (DISC 10%)	BENT	15.00	13.50
1	REAR BOOT WEATHERSTRIP (DISC 10%)	NECESSARY	49.00	44.10
1	TRIM TAIL LID (DISC 10%)	CUT	71.00	63.90
1	EMBLEM REAR (DISC 10%)	NECESSARY	44.00	39.60
1	LAMP BACK UP LH (DISC 10%)	SCRATCHED	151.00	135.90
1	LAMP BACK UP RH (DISC 10%)	SCRATCHED	122.00	109.80
1	LETTERING:"CHEVROLET" (DISC 10%)	NECESSARY	29.00	26.10
1	LETTERING:"EPICALT" (DISC 10%)	NECESSARY	28.00	25.20
1	PANEL END REAR (DISC 10%)	BENT	255.00	229.50
4	CLIP, TRIM @\$1.00 (DISC 10%)	NECESSARY	4.00	3.60
1	TRIM REAR END PANEL (DISC 10%)	DEFORMED	114.00	102.60
1	TRIM REAR BOOT, LH (DISC 10%)	DEFORMED	125.00	112.50
1	TRIM REAR BOOT, RH (DISC 10%)	DEFORMED	125.00	112.50
1	PANEL SPARE TYRE (DISC 10%)	BUCKLED	2,299.00	2,069.10
1	INSULATOR SHEET (DISC 10%)	NECESSARY	41.48	37.33
1	CHASSIS MEMBER RR LH (DISC 10%)	BENT	525.38	472.84
1	PNL SIDE LH SPARE TYRE (DISC 10%)	BENT	650.00	585.00

Report Ref No. NS/INC17020740/R1qbe2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE STUD (DISC 10%)	CRACKED	56.59	50.93
1	LAMP RR COMBINATION RH (DISC 10%)	BROKEN	415.00	373.50
1	LINER RH REAR FENDER (PROTECTOR) (DISC 10%)	DEFORMED	65.00	58.50
1	LAMP RR COMBINATION LH (DISC 10%)	CRACKED	415.00	373.50
1	PANEL TAIL LAMP, LH (DISC 10%)	BENT	143.40	129.06
1	FENDER LH REAR (DISC 10%)	BUCKLED	1,191.00	1,071.90
1	LINER LH REAR FENDER (PROTECTOR) (DISC 10%)	DEFORMED	201.00	180.90
1	MOLDING WINDSCREEN REAR (DISC 10%)	NECESSARY	45.00	40.50
1	SENSOR REVERSE (SN)	NOT WORKING	180.00	180.00
1	NUMBER PLATE (SN)	SCRATCHED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	SCRATCHED	12.00	12.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	74.00	74.00
1	STICKER DECAL 6555 8888 (DOOR) (SN)	NECESSARY	60.00	60.00
1	W/HARNESS RR BPR	SERVICEABLE	227.34	-
1	EXHAUST HEAT SHIELD	SERVICEABLE	159.00	-
1	REAR BOOT SPRING GAS	SERVICEABLE	144.00	-
1	REAR BOOT HINGE	SERVICEABLE	92.00	-
2	LAMP LICENSE @\$56.00	SERVICEABLE	112.00	-
1	W/HARNESS T / LID	SERVICEABLE	83.52	-
1	COVER BOARD SPARE TYRE	SERVICEABLE	661.00	-
1	JACK CARRIER	SERVICEABLE	12.95	-
1	JACK FOAM COVER	SERVICEABLE	35.00	-
1	W/HARNESS RR DEFOG	SERVICEABLE	7.72	-
1	W/HARNESS TRK ROOM	SERVICEABLE	51.74	-
1	HINGE LOWER RR LH	SERVICEABLE	30.00	-
1	HINGE UPPER RR LH	SERVICEABLE	24.00	-

Report Ref No. NS/INC17020740/R1qbe2



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CHECK, LH REAR DOOR	SERVICEABLE	30.00	-
1	LATCH REAR DOOR LH	SERVICEABLE	539.00	-
1	CHASSIS MEMBER RR RH	TO REPAIR	525.38	-
1	WHEELHOUSE A-RR LH	TO REPAIR	464.00	-
1	PANEL A-SIDE, INR, RR LH	TO REPAIR	830.00	-
1	FENDER RH REAR	TO REPAIR	1,467.00	-
1	PANEL LH REAR DOOR	TO REPAIR	1,863.00	-
			22,314.50	13,506.88
	<b>LABOUR</b>			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		3,469.00	2,330.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		3,350.00	1,790.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.		60.00	40.00
			6,979.00	4,180.00
	<b>GRAND TOTAL</b>		<b>29,293.50</b>	<b>17,686.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>14,150.00</b>

Report Ref No. NS/INC17020740/R1qbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.