

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 06 Dec 2017

Preliminary Advice

Insured Vehicle No : GBG1209Z

TP Vehicle No : YH98E

Make : TOYOTA DYNA 150

Date of Inspection : 04/12/2017

Inspection At : CHENG HOE MOTOR PTE LTD (YISHUN)
BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A
SINGAPORE 768761

Accident Date : 26/10/2017

Assignment Date : 01/11/2017

Est. Duration of Repair : 3.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,412.43
Revised Amount	:S\$	1,732.43
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,732.43

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.