

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 27/03/2017 13:50
Date Of Accident 25/03/2017 13:45
Exact Location Of Accident SECOND LINK TOWARDS MALAYSIA, BEF. MALAYSIA CUSTOM
Country/State of Loss Malaysia/Johor Darul Takzim

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKT5148P
Insured/Policyholder
Name Of Registered Owner FOONG TZE KANG (FENG ZHIGANG)
NRIC No S7811253J
Email Address lawrence.foong@promatrix.sg
Mobile Phone No (LOCAL) +65-91992589
Alternative Phone No Office-91992589
Vehicle Particulars
Manufacturer HONDA
Model HRV 1.5 LX CVT
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? No
If No, Please state action to be taken Third Party
Vehicle Category Private Car
Insurance Company
Name of Insurance Company Liberty Insurance Pte Ltd
Type Of Coverage Comprehensive
Fleet Policy No
Policy Number SI16V06030/VPC/R01 (COMP)
Cover Note Number
Driver
Name of Driver FOONG TZE KANG (FENG ZHIGANG)
NRIC No S7811253J
Date Of Birth 24/04/1978
Occupation Indoor
Date Of Driving Pass 23/07/1996
Driving Experience 20 Years And 8 Months
Gender Male
Mobile Number (Local) +65-91992589
Fax Number
Contact Number Office-91992589
EMail Address lawrence.foong@promatrix.sg

Address	BLK 391 BUKIT BATOK WEST AVE 5 #15-426
Postcode	650391
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Owner
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WPR2378
Vehicle Make/Model/Colour	PERODUA MYVI

Details Of Properties

Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKH6627E
Vehicle Make/Model/Colour	AUDI Q3

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address



POLIS DIRAJA MALAYSIA REPOt POLIS

(A)

Balai : TRAFIK ISKANDAR PUTERI
Daerah : ISKANDAR PUTERI
Kontinjen : JOHOR
No Repot : TRAFIK IPUTERI/002657/17
Tarikh : 25/03/2017
Waktu : 1533 PM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R190317

Butir-butir Penerima Repot

Nama : AHMAD FIKRI BIN SAMSUDIN

No Personel : R196927

Pangkat : KONST/P

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Pasport : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : FOONG TZE KANG

No K/P (Baru) : ---

No Polis/Tentera : ---

No Pasport : E4374243B

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 24/04/1973

Umur : 38 tahun 11 bulan

Keturunan : Cina

Warganegara : Singapore

Pekerjaan : MANAGER

Alamat Tempat Tinggal : BLK 391 BUKIT BATOK WEST AVE 5 #15-426 SINGAPORE 650391, 650391

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 6591992589

Emel : ---

Pengadu Menyatakan:-

PADA 25/03/2017 JAM LEBIH KURANG 1344 PETANG, SAYA MEMANDU MOTOKAR JENIS HONDA HRV NOMBOR SKT5148P DARI SINGAPORE MAHU MENUJU KE TUN AMINAH. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KOMPLEKS SULTAN ABU BAKAR KASTAM, SEMASA SAYA MEMBERHENTIKAN M/KAR SAYA UNTUK MENUNGGU PEMERIKSAAN DARI PIHAK KASTAM. TIBA-TIBA SEBUAH MOTOKAR JENIS PERODUA MYVI NOMBOR WPR2378 DARI ARAH BELAKANG TELAH MELANGGAR BELAKANG M/KAR SAYA LALU M/KAR SAYA MENGEKUNCI KE DEPAN DAN MELANGGAR SEBUAH M/KAR JENIS AUDI Q3 NOMBOR SKH6627E YANG BERADA DI HADAPAN SAYA. SAYA TIDAK MENGALAMI APA-APA KECEDERAAN. KEROSAKAN M/KAR DI BAHAGIAN BELAKANG BUMPER, BONET, SENSOR, BAHAGIAN DEPAN BUMPER, NO PLAT DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN REPOt SAYA

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada) :

Tandatangan Penerima Repot:

Id Pencetak : Tarikh @ Masa Cetak : R196927 | 25/03/2017 03:50:17 PM



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK ISKANDAR PUTERI
 Daerah : ISKANDAR PUTERI
 Kontinjen : JOHOR
 No Repot : TRAFIK IPUTERI/002657/17
 Tarikh : 25/03/2017
 Waktu : 1533 PM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R190317

Butir-butir Penerima Repot

Nama : AHMAD FIKRI BIN SAMSUDIN

No Personel : R196927

Pangkat : KONST/P

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : FOONG TZE KANG

No K/P (Baru) : ---

No Polis/Tentera : ---

No Paspot : E4374243B

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 24/04/1978

Umur : 38 tahun 11 bulan

Keturunan : Cina

Warganegara : Singapore

Pekerjaan : MANAGER

Alamat Tempat Tinggal : BLK 391 BUKIT BATOK WEST AVE 5 #15-426 SINGAPORE 650391, 650391

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 6591992589

Emel : ---

Pengadu Menyatakan:-

PADA 25/03/2017 JAM LEBIH KURANG 1344 PETANG, SAYA MEMANDU MOTOKAR JENIS HONDA HRV NOMBOR SKT5148P DARI SINGAPORE MAHU MENUJU KE TUN AMINAH. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KOMPLEKS SULTAN ABU BAKAR KASTAM, SEMASA SAYA MEMBERHENTIKAN M/KAR SAYA UNTUK MENUNGGU PEMERIKSAAN DARI PIHAK KASTAM. TIBA-TIBA SEBUAH MOTOKAR JENIS PERODUA MYVI NOMBOR WPR2378 DARI ARAH BELAKANG TELAH MELANGGAR BELAKANG M/KAR SAYA LALU M/KAR SAYA MENGELUNSUR KE DEPAN DAN MELANGGAR SEBUAH M/KAR JENIS AUDI Q3 NOMBOR SKH6627E YANG BERADA DI HADAPAN SAYA. SAYA TIDAK MENGALAMI APA-APA KECEDERAAN. KEROSAKAN M/KAR DI BAHAGIAN BELAKANG BUMPER, BONET, SENSOR, BAHAGIAN DEPAN BUMPER, NO PLAT DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI. SEKIAN REPOT SAYA

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

PEJ. SALINAN REPOT
 TRAFIK IPD ISKANDAR PUTERI
 SALINAN YANG DICAHKAN BENAR
 (HANYA UNTUK TUNJUKAN SIVIL)



POLIS DIRAJA MALAYSIA

REPOT POLIS

(5)

Balai : TRAFIK ISKANDAR PUTERI
 Daerah : ISKANDAR PUTERI
 Kontinjen : JOHOR
 No Repot : TRAFIK IPUTERI/002662/17
 Tarikh : 25/03/2017
 Waktu : 1905 PM
 Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R190317
 No Repot Bersangkut : TRAFIK
 IPUTERI/002657/17

Butir-butir Penerima Repot

Nama : AHMAD FIKRI BIN SAMSUDIN

No Personel : R196927

Pangkat : KONST/P

Butir-butir Jurubahasa (Jika Ada)

Nama : ---

No K/P (Baru) : ---

No Polis/Tentera : ---

No Pasport : ---

Bahasa Asal : ---

Alamat : ---

Butir-butir Pengadu

Nama : PUNG CHE FOH

No K/P (Baru) : 890405125539

No Polis/Tentera : ---

No Pasport : ---

No Sijil Beranak : ---

Jantina : Lelaki

Tarikh Lahir : 05/04/1989

Umur : 27 tahun 11 bulan

Keturunan : Cina

Warganegara : Malaysia

Pekerjaan : SWASTA

Alamat Tempat Tinggal : C-09-06 BISTARI IMPIAN, JALAN SERANTAU TAMAN DATO ONN, 80350, JOHOR

Alamat Ibu/Bapa : ---

Alamat Pejabat : ---

No Tel (Rumah) : ---

No Tel (Pejabat) : ---

No Tel (HP) : 0168480538

Pengadu Menyatakan:-

PADA 25/03/2017 JAM LEBIH KURANG 1344 PETANG, SAYA MEMANDU M/KAR JENIS PERODUA MYVI NOMBOR WPR2378 DARI SINGAPORE MAHU BALIK KE RUMAH DI TAMAN DATO ONN. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KOMPLEKS SULTAN ABU BAKAR KASTAM, SEMASA SAYA MEMBERHENTIKAN M/KAR TIBA-TIBA M/KAR SAYA TELAH MENGELUNSUR KE DEPAN DAN MELANGGAR SEBUAH MOTOKAR JENIS HONDA BRV NOMBOR SKT5148P YANG BERADA DI HADAPAN SAYA. DALAM KEJADIAN ITU, SAYA TIDAK MENGALAMI APA-APA KECEDEeraan.KEROSAKAN M/KAR DI BAHAGIAN DEPAN BUMPER, BONET, SET LAMPU DAN LAIN-LAIN KEROSAKAN BELUM PASTI LAGI.SEKIAN REPOT SAYA

Tandatangan Pengadu:

Tandatangan Jurubahasa(Jika ada) :

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

: A6028672 | 29/03/2017 02:39:47 PM

REJ. SALINAN REPOT
 TRAFIK IPD ISKANDAR PUTERI
 SALINAN YANG DIBERIKAN BENAR
 (HANYA UNTUK TUGAS TILIAH SIVIL)

KETUA TRAFIK IPD ISKANDAR PUTERI
 TIDAK BOLEH DISALAHKAN DALAM PERBICARAAN



POLIS DIRAJA MALAYSIA

REPOT POLIS

Balai : TRAFIK ISKANDAR PUTERI
Daerah : ISKANDAR PUTERI
Kontinjen : JOHOR
No Repot : TRAFIK IPUTERI/002791/17
Tarikh : 29/03/2017
Waktu : 1120 AM
Bahasa Diterima : B. Malaysia

Pegawai Penyiasat : R190317
No Repot Bersangkut : TRAFIK
IPUTERI/002657/17

Butir-butir Penerima Repot

Nama : WAN ZAROL IKRAM BIN WAN MOHAMED
Butir-butir Jurubahasa (Jika Ada)
Nama : ---
No Paspot : ---
Alamat : ---

No Personel : R197035
Pangkat : KONST/P
No K/P (Baru) : ---
No Polis/Tentera : ---
Bahasa Asal : ---

Butir-butir Pengadu

Nama : CHEW HAN CHEE (ZHOU HANYI)
No K/P (Baru) : ---
No Sijil Beranak : ---
Jantina : Lelaki
Keturunan : Cina
Pekerjaan : SWASTA
Alamat Tempat Tinggal : 4 BEDOK RESERVOIR VIEW #03-12 THE CLEARWATER SINGAPORE, 479233
Alamat Ibu/Bapa : ---
Alamat Pejabat : ---
No Tel (Rumah) : ---
Emel : ---

No Polis/Tentera : ---
No Paspot : S7815194C
Tarikh Lahir : 01/06/1978
Umur : 38 tahun 9 bulan
Warganegara : Malaysia
No Tel (Pejabat) : ---
No Tel (HP) : 94898908

Pengadu Menyatakan:-

PADA 25/03/2017 JAM LEBIH KURANG 1344 PETANG, SAYA MEMANDU MOTOKAR NOMBOR SKH6627E DARI DARI SINGAPURA HENDAK KE MALAYSIA. PADA KETIKA ITU, APABILA SAYA SAMPAI DI KOMPLEKS SULTAN ABU BAKAR, SEDANG MENUNGGU PEMERIKSAAN KASTAM. PADA MASA YANG SAMA, SAYA DENGAR BUNYI YANG KUAT DARI ARAH BELAKANG. SAYA TURUN DAN DAPATI SEBUAH MOTOKAR NOMBOR SKT5148P TELAH MELANGGAR KENDERAAN SAYA. DALAM KEJADIAN ITU, SAYA TIDAK MENGALAMI APA-APA KECEDERAAN. KEROSAKAN MOTOKAR SAYA IALAH KEROSAKAN DI BAHAGIAN BELAKANG FOG LIGHT, BUMPER DAN LAIN-LAIN KEROSAKAN BELUM KENAL PASTI. SEKIAN REPOT SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

PEJ. SALINAN REPOT
TRAFIK IPUTERI ISKANDAR PUTERI
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK PERALIHAN SIVIL)

ID Pencetak | Tarikh @ Masa Cetak

: A6028672 | 29/03/2017 02:39:47 PM


RAJAH KASAR KEMALANGAN JALANRAYA

IPTR NO: 02657/17, TARIKH 25/03/2017

LOKASI: KOMPLEKS SULTAN ABU BAKAR

ISKANDAR PUTERI, JOHOR.

(Ukuran Tidak Mengikut Scale)



KENDERAAN TERLIBAT TIADA DI TEMPAT KEJADIAN SEMASA PEMERIKSAAN DIJALANKAN

Tanda Pengenalan :-

- A - -Tepi Sebelah Kiri Jalan
- A1 - -Garis Putih Putus-Putus Pembahagi Lorong,
- A2 - -Garis Putih Putus-Putus Pembahagi Lorong
- A3 - -Pembahagi Jalan
- B - -Arah Ke Malaysia
- C - -Arah Ke Singapore

Ukuran :-

- A ke A1 - 3.4 Meter,
- A1 ke A2 - 3.4 Meter,
- A2 ke A3 - 3.4 Meter,

PEJ. C
 TRAFIK IPD
 SALINAN YANG
 (HANYA UNTUK)

ISKANDAR PUTERI
 JOHOR
 (HANYA UNTUK)

(MOHD JURAHAKIM B. JUMART) SJN 190317
 PEN. PEG. PENYIASAT (TRAFIK)
 IPD NUSAJAYA
 JOHOR

PEJ. C
 TRAFIK IPD
 SALINAN YANG
 (HANYA UNTUK)



KETUA POLIS ISKANDAR PUTERI
IBU PEJABAT POLIS DAERAH ISKANDAR PUTERI
81300 SKUDAI
JOHOR

Tel : 075114222 Samb :

Ruj :
Tkh : 26/03/2017

FOONG TZE KANG No KP :
BLK 391 BUKIT BATOK WEST AVE 5 #15-426 SINGAPORE 650391
650391 - Motokar SKT5148P

KEPUTUSAN PENYIASATAN KES

No. Pengaduan Polis : TRAFIK IPUTERI/002657/17
Tkh/Masa Rpt : 25/03/2017 15:33 HRS
Kesalahan : R10 LN166/59
Tkh/Masa Kemalangan : 25/03/2017 13:44 HRS
Tempat Kemalangan : LEBUHRAYA LINK KEDUA

Dengan hormatnya saya merujuk kepada pengaduan yang dibuat sepertimana dinyatakan di atas.

2. Untuk makluman, pihak yang bertanggungjawab melakukan kesalahan di atas telah disaman polis (RM 300) pada 26/03/2017 (CARS170052530).

3. Butir-butir pihak yang disalahkan adalah seperti berikut :-
PUNG CHE FOH KP : 890405125539
C-09-06 BISTARI IMPIAN, JALAN SERANTAU TAMAN DATO ONN
80350
WPR2378 PEMANDU Motokar

"BERHATI-HATI DI JALAN RAYA"

KETUA TRAFIK DAERAH
ISKANDAR PUTERI, JOHOR

(R190317 - MOHD JURA HAKIM BIN JUMAAT)
AIO TRAFIK
81300 SKUDAI

s . k KST No :
[Notis ini hanya sebagai makluman anda sahaja]



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0029/17	Date of Report	: 5 April 17
To : Foong Tze Kang (Feng Zhigang)	Date of Request	: 27 March 17
	Report requested by	: Foong Tze Kang (Feng Zhigang)
Block 391, #15-426	Date of Accident	: 25 March 17
Bukit Batok West Avenue 5	Date of Inspection	: 27 March 17
Singapore 650391	Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SKT 5148 P	Odometer Reading	: 33,550 km
Make	: Honda	Carrying Capacity	: 4
Model	: HRV (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2015	Air-Conditioner	: Yes
Colour	: Metallic Black	Wing Mirror	: Yes
Engine Capacity	: 1,497 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: MRHRU1830FP000141	Others	: Nil

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Dunlop	Make	: Dunlop
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Dunlop	Make	: Dunlop
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: No
--------------	----------	------------	------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	23,140.00	16,225.60
Labour Charges :	3,660.00	2,670.00
Paint Work :	2,800.00	2,400.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	29,600.00	21,295.60

Reduction (S \$) : 8,304.40

Recommended Reserve (S \$) : 21,295.60

Estimated Normal Period of Repairs : 10 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at MG Solution Pte Ltd, 23, Kaki Bukit Avenue 4, (South Wing) #02-03, Singapore 415933.

Follow-up inspection has been conducted.

Point of Impact

At the front and rear portion.

Damages

Front portion: The front bumper, front bumper reinforcement, front grille, headlamps assembly, support panel, etc.

Rear portion: The tailgate, rear bumper, end panel, exhaust silencer, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$21,295.60

Conclusion

The repairer has agreed to undertake repairs at our adjusted amount of \$21,295.60 corresponding to labour charges, spray painting and replacement of parts.

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser



LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SKT 5148 P Honda HRV (A)
Workshop : MG Solution Pte Ltd

TP/0029/17

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
To Supply :					
1pc. Front bumper	Dented	1,140.00		1,140.00	20
1pc. Front bumper RH side retainer	Necessary	34.00		34.00	20
1pc. Front bumper LH side retainer	Necessary	34.00		34.00	20
1pc. Front bumper lower grille	Refit	201.00		--	20
1pc. Front bumper reinforcement	Dented	472.00		472.00	20
1pc. Front grille	Cracked	405.00		405.00	20
1pc. Front grille emblem	Necessary	75.00		75.00	20
1pc. RH headlamp	Cracked	2,550.00		2,550.00	20
1pc. RH headlamp lower bracket	Cracked	108.00		108.00	20
1pc. LH headlamp	Cracked	2,550.00		2,550.00	20
1pc. LH headlamp lower bracket	Cracked	108.00		108.00	20
1pc. A/C condenser	Dented	1,445.00		1,445.00	20
1pc. Radiator	Refit	1,843.00		--	20
1pc. Tailgate	Dented	1,760.00		1,760.00	20
1pc. Tailgate 'HR-V' emblem	Necessary	56.00		56.00	20
1pc. Tailgate centre emblem	Not Necessary	70.00		--	20
1pc. Tailgate RH lamp	Cracked	433.00		433.00	20
1pc. Tailgate LH lamp	Defaced / Cracked	433.00		433.00	20
1pc. Tailgate lock	Bent	281.00		281.00	20
1pc. Tailgate lock catch	Bent	34.00		34.00	20
1pc. Tailgate weatherstrip	Bent	167.00		167.00	20
1pc. Tailgate inner trim board	Cracked	455.00		455.00	20
2pcs. Tailgate hinges	Serviceable	231.00		--	20
1pc. Rear bumper	Dented	903.00		903.00	20
1pc. Rear RH bumper	Dented / Cracked	433.00		433.00	20
1pc. Rear RH bumper side retainer	Necessary	82.00		82.00	20
1pc. Rear LH bumper	Dented / Cracked	433.00		433.00	20
1pc. Rear LH bumper side retainer	Necessary	82.00		82.00	20
1pc. End panel	Dented	783.00		783.00	20
1pc. End panel inner garnish	Deformed	155.00		155.00	20
1pc. Rear LH fender arch moulding	Refit	288.00		--	20
1pc. Rear RH fender arch moulding	Deformed	288.00		288.00	20
1pc. Exhaust silencer	Dented / Bent	1,118.00		1,118.00	20
1pc. Driver seat frame	Damaged	2,540.00		2,540.00	20
Sub-Total :-		21,990.00		19,357.00	
Total Discount :-		--		3,871.40	
		21,990.00		15,485.60	
Special Nett Items :-					
1set. Front bumper clips	Necessary	70.00		40.00	
1pc. Front number plate	Dented	80.00		35.00	
1set. Front grille clips	Necessary	70.00		30.00	
1btl. Radiator coolant	Necessary	50.00		25.00	

Vehicle No : SKT 5148 P Honda HRV (A)

TP/0029/17

Workshop : MG Solution Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
1pc. Tailgate windscreen glass inner seal	Necessary	70.00		20.00	
1tube. Tailgate windscreen glass sealant	Necessary	70.00		40.00	
1set. Tailgate inner trim board clips	Necessary	70.00		30.00	
1set. Rear bumper reverse sensor	Dented / Malfunction	450.00		300.00	200
1pc. Exhaust silencer chrome finisher	Dented	220.00		220.00	150
Total For Parts :-		23,140.00		16,225.60	
Labour Charges :					
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, reposition & re-align, replacement of parts to the original position including adjustment.		2,200.00		1,800.00 1,140.00	
Apply rust coating on the replaced & repaired panels.		200.00		90 120.00	
Check wiring & lighting system.		100.00		60.00	
Remove & replace A/C condenser & pipes to assist repairs.		180.00		100.00	
Remove & re-install radiator, hoses & fan assembly to assist repairs.		180.00		80.00	
Remove & re-install tailgate windscreen glass to assist repairs.		200.00		120.00	
Transfer & replace tailgate mechanism to new tailgate.		100.00		70.00	
Remove, re-install & replace rear inner trims, garnishes & boards to assist repairs.		280.00		90 180.00	
Remove & replace exhaust silencer & chrome finisher.		120.00		80.00	
Remove & replace rear bumper reverse sensor.		100.00		60.00	
Spray Painting :					
To putty & spray repaired & replaced body panels.		2,800.00		1,600 2,400.00	
Grand Total :-		29,600.00		21,295.60	

9 days

Vehicle No : SKT 5148 P Honda HRV (A)

TP/0029/17

Workshop : MG Solution Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist.%	Our Recommendation (S \$)	Dist.%
----------------------	-----------	----------------------------------	--------	---------------------------------	--------

Surveyed By : Lawrence Ng