

ASSIGNED BY

REF CS/MSG17020873/Sqber

Sebastian
Merimen
From (Person) Irene Tan

ASSIGNMENT (Office)

MSIG

Date/Time 1/11/2017 @ 1.51pm

Estimated Cost

Bill to

OD / TP / WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLR 8292J

Insured

GBF 782X

at Workshop no

World Auto

Tel

97588347

of No. 1 Kranji Loop, 739 535

Policy No

A28979241MKC

Claim No

534 973

Sum Insured

Excess

Make of Vch

(Client's Record)

D.O.A

30/10/2017

CA / REV / REP. / REV 24 HRS

'wp'

02/11/17

H.O.D. Endorsement

Date/Time 2.55pm @ 1/11/17

Person Contacted

Mr. Sim

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 8292J - X
	GBF 782X - X
07/11/17 @ 3.40pm	revised to Irene Tan via Merimen.
	Final fig 65557.88, 6 days (red \$2730.36, 33%)

REF: MSIG

ASSIGNMENT

From: _____ Date: 2/11/2017

Estimated Cost: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLR 8292Jat Workshop n/s World Autoof No. 1 Kranji loop, 739535

Insured

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1 wpr

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Veh No: SLR 8292J Yr Reg: 29/8/2017Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or: _____

Make: Honda Shuttle cc 1496Colour: White A/C ☐ Insured / Std / NI / NASp Reading: 11527 T/Radio: ☐ Insured / Std / NI / NA

Eng No: _____

O/No: GP71046156Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ N / ☐ S / ☐ Rim / ☐ STD A/Rim orTyre Size: F: 185/60R15R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mmL/Bal: 6 mm L/Bal: 6 mmD.O.A: 20/10/2017 D.O.A: 2/11/2017Survey held at: World AutoDes. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Data/Time File Pass to?



Preli. Report



Final Report

Data/Time File Return to?

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation

Add Fee:



Site Insp \$



Interview \$



Tech Insp \$



Weekend \$

Report Format:

Lump Sum / I.B.I. \$

MER-7P5557.28

Fuels

Other

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17020873/Sqb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 01-11-2017



Code : MSG

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 782X	Veh. Inspected	SLR 8292J
Policy No.	A28979241MKC	Coverage (\$)	0.00
Claim No.	534973	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	01/11/2017

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--

5.

General Information

Accident Date	30/10/2017	Inspection Date
Survey held at	WORLD AUTO PTE LTD 47 JALAN PEMIMPIN #01-02/03 HALCYON 2 BLDG SINGAPORE 577200	

5a.

Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No.: CS/MS/617020873/Sq/b
 Policy Type: OD / TP / TP RES / TL / EVA

SLR 8292J

Case Handler

Typist

Admin (Center): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Sebastian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

28/11/17
 Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2017		01 Nov 2017 13:51 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JK TECHNOLOGY PTE LTD, Co. Reg. No.: 199000721C		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLR8292J	Date of Loss:	30/10/2017 14:00 - :59
Claim Type:	TP / 534973	Policy/Cover Note No.:	A28979241MKC (Comprehensive) Coverage: 17/06/2017 - 16/06/2018
Vehicle Reg. No. (Insured):	GBF782X	Policy No. (Claimant):	
		Excess:	
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/11/2017]		
Driver/Custodian (Insured):	MUHAMMAD ISKANDAR BIN (), NRIC: S9333421C		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Nur Amirah Binte Mohamed Yunos

From: Tan Jin Hao
Sent: Wednesday, November 01, 2017 11:11 AM
To: Nur Amirah Binte Mohamed Yunos
Subject: FW: 3rd party survey for SLR 8292J

Follow Up Flag: Follow up
Flag Status: Flagged

A Member of **MS&AD** INSURANCE GROUP

From: Koh Lay Hoon
Sent: Wednesday, November 01, 2017 10:58 AM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msiga-asia.com>
Subject: FW: 3rd party survey for SLR 8292J

From: Sim [<mailto:sim@worldauto.com.sg>]
Sent: Wednesday, November 01, 2017 10:57 AM
To: Claims <claims@sg.msiga-asia.com>
Subject: Re: 3rd party survey for SLR 8292J

Dear sir
Please arrange a 3rd party surveyor to survey the following car
Our client: SLR 8292J
Your Insured: GBF 782X
Date of accident: 30/10/17
Regards

S.T.Sim
Claims Manager
97588347
World Auto Pte Ltd
No 1 Kranji Loop
Singapore 739535

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 03 Nov 2017

Preliminary Advice

Insured Vehicle No	: GBF782X	Accident Date	: 30/10/2017
TP Vehicle No	: SLR8292J	Assignment Date	: 01/11/2017
Make	: HONDA SHUTTLE HYBRID	Est. Duration of Repair	: 6.00
Date of Inspection	: 02/11/2017		
Inspection At	: WORLD AUTO PTE LTD - KRANJI (HQ) NO 1 KRANJI LOOP SINGAPORE 739535		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,287.64
Revised Amount	:S\$	6,947.84
Check Items (Estimated)	:S\$	78.40
Total	:S\$	7,026.24

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MS16

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/10/2017 17:21
Date Of Accident	30/10/2017 14:15
Exact Location Of Accident	EU TONG SEN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8292J
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	CHEW LAM YONG
NRIC No	S1631252E
Date Of Birth	13/09/1964
Occupation	OUTDOOR
Date Of Driving Pass	12/01/1982
Driving Experience	35 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PAID DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF782X
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF INJURED PERSON 1

Name CHEW LAM YONG
 Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLR8292J

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time
30-10-17 1630pm

Witnessed by Reporting Centre Personnel

Sketch Plan




Sketch Plan #2

Describe Circumstances of the Accident

ON DATE 30-10-2017 AT ABOUT 14.15 PM I WAS TRAVELING ON ELA YONG SEN STREET. AND THE WEATHER WAS CLEAR AND THE ROAD WAS DRY. THE TRAFFIC WAS MOVING SLOW. OUT OF SUDEN I HEAR A SHARP SOUND FROM BEHIND AND ONE A NISSAN VAN HIT DIRECT AT MY VEHICAL BACK. THE NISSAN VAN NO/PLATE IS GBT 782 X MY VEHICAL NO PLATE IS SLR 8292 J HONDA SHUTTLE. AFTER THE ACCIDENT, I FILL MY BACK AND NECK WAS PAIN.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

30-10-17 1630 PM

Witnessed by Reporting Centre Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES005207

Attention : Motor Claim Department

Date : 30/10/2017
 Vehicle Num. : SLR 8292J
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 30/10/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE (SHUTTLE) ✓ DT	1200	1,850.00
2.	1	REAR TAILGATE HYBRID EMBLEM (SHUTTLE) ✓ NEC	88.40	50.80
3.	1	REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE) ✓ NEC	88.40	50.80
4.	1	REAR TAILGATE WEATHERSTRIP (SHUTTLE) ✓ Defor	380.00	250
5.	1	REAR WINDSCREEN MOULDING (SHUTTLE) ✓ NEC	195.00	138
6.	1	REAR TAILGATE LOCK CATCH (SHUTTLE) X NEC NEC	158.00	60
7.	1	REAR TAILGATE LOCK (SHUTTLE) ✓ JM	550.00	200
8.	1	REAR END PANEL TOP GARNISH (SHUTTLE) ✓ Defor	260.00	187
9.	1	REAR END PANEL (SHUTTLE) ✓ DT	950.00	660
10.	1	REAR BUMPER (SHUTTLE) ✓ DT	1,350.00	1200
List Total S\$:			3996.60	
20.00% Discount S\$:			-20%	
			1) 3197.28	
				5,869.80
				1,173.96
				4,695.84
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR ✓ NEC. garant ✓ NEC	260.00	200
2.	1	REAR WINDSCREEN MOULDING (SHUTTLE) X garant	-195.00	40
3.	8	REAR BUMPER CLIP ✓ NEC	9.80	78.40
4.	8	REAR END PANEL TOP GARNISH CLIPS (SHUTTLE)	9.80	78.40
Special Nett Total S\$:				611.80
LABOUR :				
TRANSFER TAILGATE MECHANISM (SHUTTLE)				160.90

1) Parts : \$ 3197.28

2) S/Nett : \$ 300.00

3) Labour : \$ 2060.00

\$ 5557.28 @ 6 days

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES005207

Attention : Motor Claim Department

Date : 30/10/2017
 Vehicle Num. : SLR 8292J
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 30/10/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)		160.00
		To labour charge for removing rear tailgate, rear bumper, end panel out to facilitate repairs and replacement of damaged parts		1,000.00
		To respray rear tailgate, rear bumper, end panel		700
		To deactivate and activate high voltage hybrid battery as a requirement for safety precautions		240
		To conduct a standard of operating procedure post repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs		240
		Labour Total S\$:		2,980.00

3/2060

E. & O.E.

Total S\$: 8,287.64
 =====

for WORLD AUTO PTE LTD

Sebastian
 2/11/2017

- Part big paid repair
 - Photo Before Paint
 900 36121

sebastianyeang@lkkauto.com

6 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES005207

Attention : Motor Claim Department

Date : 30/10/2017

Vehicle Num. : SLR 8292J

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 30/10/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR TAILGATE (SHUTTLE) ✓ DT		1,850.00
2.	1	REAR TAILGATE HYBRID EMBLEM (SHUTTLE) ✓ NEC		88.40
3.	1	REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE) ✓ NEC		88.40
4.	1	REAR TAILGATE WEATHERSTRIP (SHUTTLE) ✓ Defom		380.00
5.	1	REAR WINDSCREEN MOULDING (SHUTTLE) ✓ NEC		195.00
6.	1	REAR TAILGATE LOCK CATCH (SHUTTLE) X		158.00 <i>hn</i>
7.	1	REAR TAILGATE LOCK (SHUTTLE) ✓ JM		550.00
8.	1	REAR END PANEL TOP GARNISH (SHUTTLE) ✓ Defom		260.00
9.	1	REAR END PANEL (SHUTTLE) ✓ DT		950.00
10.	1	REAR BUMPER (SHUTTLE) ✓ DT		1,350.00

List TotalS\$:

20.00% Discount S\$:

Supplty
Left tailgate panel

5,869.80

1,173.96

4,695.84

SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR ✓ DMG. Sealant ✓ NEC		260.00 <i>200</i>
2.	1	REAR WINDSCREEN MOULDING (SHUTTLE) X <i>Replaced</i>		-195.00 <i>40</i>
3.	8	REAR BUMPER CLIP ✓ NEC	9.80	78.40 <i>30</i>
4.	8	REAR END PANEL TOP GARNISH CLIPS (SHUTTLE)	9.80	78.40 <i>30 NEC</i>

Special Nett Total S\$:

611.80

LABOUR :

TRANSFER TAILGATE MECHANISM (SHUTTLE)

160.00 *60*

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Attention : Motor Claim Department

Estimate : ES005207

Date : 30/10/2017

Vehicle Num. : SLR 8292J

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 30/10/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)		160.00
		To labour charge for removing rear tailgate, rear bumper, end panel out to facilitate repairs and replacement of damaged parts		1,000.00
		To respray rear tailgate, rear bumper, end panel		700
		To deactivate and activate high voltage hybrid battery as a requirement for safety precautions		700
		To conduct a standard of operating procedure post repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs		240
				240
		Labour Total S\$:		8,287.64

E. & O.E.**Total S\$: 8,287.64**

=====

for WORLD AUTO PTE LTD

Sebastian
2/11/2017

- Part by part repair

- Photo Before Paint

900 36121

sebastianyeang@lkkauto.com



6 days.

LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2017		01 Nov 2017 13:51 Edit Adj Rpt	S\$5,557.28 Edit Estimates	S\$5,557.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		JK TECHNOLOGY PTE LTD, Co. Reg. No.: 199000721C							
Main Claimant:		LCRF PTE LTD, Co. Reg. No.: 201624597K							
Vehicle Reg. No.:		SLR8292J	Date of Loss:	30/10/2017 14:00 - :59					
Claim Type:		TP / 534973	Policy/Cover Note No.:	A28979241MKC (Comprehensive) Coverage: 17/06/2017 - 16/06/2018					
Vehicle Reg. No. (Insured):		GBF782X	Policy No. (Claimant):						
		Excess:							
Repairer:		World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 01/12/2017]							
Driver/Custodian (Insured):		MUHAMMAD ISKANDAR BIN (), NRIC: S9333421C							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR8292J (534973)
[GBF782X]
TP
LCRF PTE LTD
Oct 30 2017 2:00PM
[JK TECHNOLOGY PTE LTD]
World Auto Pte Ltd - Kranji

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer	
Assessment Reports						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	03/11/17 15:40	Adjuster Immediate Advice				Load HTM	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	24/11/17 10:09	General View				Load JPG	☒
2	24/11/17 10:09	General View				Load JPG	☒
3	24/11/17 10:09	General View				Load JPG	☒
4	24/11/17 10:09	General View				Load JPG	☒
5	24/11/17 10:09	General View				Load JPG	☒
6	24/11/17 10:09	General View				Load JPG	☒
7	24/11/17 10:09	General View				Load JPG	☒
8	24/11/17 10:09	General View				Load JPG	☒
9	24/11/17 10:09	General View				Load JPG	☒
10	24/11/17 10:09	General View				Load JPG	☒
11	24/11/17 10:09	General View				Load JPG	☒
12	24/11/17 10:09	General View				Load JPG	☒
13	24/11/17 10:09	General View				Load JPG	☒
14	24/11/17 10:09	General View				Load JPG	☒
15	24/11/17 10:09	General View				Load JPG	☒
16	24/11/17 10:09	General View				Load JPG	☒
17	24/11/17 10:09	General View				Load JPG	☒
18	24/11/17 10:09	General View				Load JPG	☒
19	24/11/17 10:09	General View				Load JPG	☒
20	24/11/17 10:09	General View				Load JPG	☒
21	24/11/17 10:09	General View				Load JPG	☒
22	24/11/17 10:09	General View				Load JPG	☒
23	24/11/17 10:09	General View				Load JPG	☒
24	24/11/17 10:09	General View				Load JPG	☒
25	24/11/17 10:09	General View				Load JPG	☒
26	24/11/17 10:09	General View				Load JPG	☒
27	24/11/17 10:09	General View				Load JPG	☒
28	24/11/17 10:09	General View				Load JPG	☒
29	24/11/17 10:09	General View				Load JPG	☒
30	24/11/17 10:09	General View				Load JPG	☒
31	24/11/17 10:09	General View				Load JPG	☒
32	24/11/17 10:09	PHOTO BEFORE PAINT				Load JPG	☒
33	24/11/17 10:09	PHOTO BEFORE PAINT				Load JPG	☒
34	24/11/17 10:09	PHOTO BEFORE PAINT				Load JPG	☒
35	24/11/17 10:09	PHOTO BEFORE PAINT				Load JPG	☒

36	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
37	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
38	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
39	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
40	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
41	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
42	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
43	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
44	24/11/17 10:09	PHOTO BEFORE PAINT		Load JPG	☒
Documentation					
				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	01/11/17 11:46	Email from Third Party		Load PDF	
2	01/11/17 11:48	OI GIA Rep - GBF 782X		Load PDF	
3	01/11/17 11:48	TP GIA Rep - SLR 8292J		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020873/SQBE2

Date: 07/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28979241MKC
Claimant Vehicle No :	SLR8292J	Insured Vehicle No :	GBF782X
Date of Loss:	30/10/2017	Nature of Claim:	TP
		Claim No:	534973

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8292J	Engine No:	LEB4266408
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71046136
Reg. Date:	29/08/2017 (Man. Year: 2016)	Odometer:	11527 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,307.64	3,497.28	1,810.36	34.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	2,060.00	920.00	30.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,287.64	5,557.28	2,730.36	32.94
+ GST 7.00/7.00% (S\$)	580.13	389.01	191.12	32.94
Nett Amount (S\$)	8,867.77	5,946.29	2,921.48	32.94

INSPECTION

Date of Assignment:	01/11/2017		
Date Inspected:	02/11/2017	Inspected At:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop Singapore 739535

Estimated Period of Repair: 6.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Dec 2017)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8292J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE (SHUTTLE)	Dented	1,850.00 FL	*1,200.00 FL
2	1	*REAR TAILGATE HYBRID EMBLEM (SHUTTLE)	Necessary	88.40 FL	*50.80 FL
3	1	*REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE)	Necessary	88.40 FL	*50.80 FL
4	1	*REAR TAILGATE WEATHERSTRIP (SHUTTLE)	Deformed	380.00 FL	*250.00 FL
5	1	*REAR WINDSCREEN MOULDING (SHUTTLE)	Necessary	195.00 FL	*138.00 FL
6	1	*REAR TAILGATE LOCK CATCH (SHUTTLE)	Necessary	158.00 FL	*60.00 FL
7	1	*REAR TAILGATE LOCK (SHUTTLE)	Jammed	550.00 FL	*200.00 FL
8	1	*REAR END PANEL TOP GARNISH (SHUTTLE)	Deformed	260.00 FL	*187.00 FL
9	1	*REAR END PANEL (SHUTTLE)	Dented	950.00 FL	*660.00 FL
10	1	*REAR BUMPER (SHUTTLE)	Dented	1,350.00 FL	*1,200.00 FL
11	1	*REVERSE SENSOR	Damaged	260.00 FS	*200.00 FS
12	1	*REAR WINDSCREEN SEALANT (SHUTTLE)	Necessary	195.00 FS	*40.00 FS
13	8	*REAR BUMPER CLIPS	Necessary	78.40 FS	*30.00 FS
14	8	*REAR END PANEL TOP GARNISH CLIPS (SHUTTLE)	Necessary	78.40 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,481.60	4,296.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,173.96	799.32
Total Parts (\$\$)	5,307.64	3,497.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSFER TAILGATE MECHANISM (SHUTTLE)	New	160.00	60.00
2	REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)	New	160.00	120.00
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR BUMPER, END PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,000.00	700.00
4	TO RESPRAY REAR TAILGATE, REAR BUMPER, END PANEL	New	900.00	700.00
5	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	380.00	240.00
6	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	380.00	240.00

Gross Labour Cost (\$\$)	2,980.00	2,060.00
--------------------------	----------	----------

Report was unsubmitted during this print-out.

< END OF ESTIMATES >