

REF:

CC3 / ALG17020876 / Agb02

Bureau:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Segn: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

\* 07/11/17

days

Res: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SKG 2886E.

Yr Regn: \_\_\_\_\_

2012 / May

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Audi A8

C.C.

2995

Colour \_\_\_\_\_

Black

A/C:

Insured / Std / NI / NA

Sp. Reading \_\_\_\_\_

55809.

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

WAU222 4H

\* 4CN016577

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: \_\_\_\_\_

F:

255/45R19.

R:

255/45R19

BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

06

mm

R/Bal. \_\_\_\_\_

06

mm

L/Bal. \_\_\_\_\_

06

mm

L/Bal. \_\_\_\_\_

06

mm

D.O.A. \_\_\_\_\_

D.O.I. \_\_\_\_\_

01/11/17.

Survey held at \_\_\_\_\_

Premium.

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ALG.

SKG 2886E - X

02/11/17 @ 3.14pm revert to Victor via messenger.

02/11/17 @ 4.46pm Victor informed c/a via messenger.

02/11/17 @ 10.50am informed Jeffrey c/a \$ EX: \$ 1400 by email.

27/12/17 @ 1.57pm confirmed with Mr Bos final AG \$ 9473.44, 7 days.  
Cred \$ 21427.56, 69%.

RECEIVED 19 JAN 2018

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

7

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: \_\_\_\_\_



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photos

Others

TOTAL

200

10

210

Report Format: \_\_\_\_\_

MER-0D

Lump Sum / I.B.I. (\$) \_\_\_\_\_

9473.44



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17020876/Aqb

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 01-11-2017



Code : AIG

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SKG 2886E
Policy No. 2100342352	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	01/11/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date 30/10/2017	Inspection Date 01/11/2017
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699	

## 5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

# Survey Department Check List (Case Handler)

Reference No.: CC3/ALG/1700876/ARB  
Policy Type: OD / TP / TP RES / TL / EVA

SKG 2886E

Case Handler

Typist

Admin (Cath): Case handler to make sure all Information created by the assignment team are ACCURATE.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

  
Case Handler Date

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 27 December, 2017 1:57 PM  
**To:** 'Boo seng yak'; SUR; Carrine Leong; Chang Chee Sing  
**Subject:** RE: FINAL REVISION SKG2886E - OD IG - SURVEYED 1 NOV 17

Dear Mr Boo,

Confirm final fig \$9,473.44 before excess \$1,400.00 & GST and 7 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

*Wishes you a Happy New Year 2018*

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Boo seng yak [mailto:boojohnny@gmail.com]

**Sent:** Monday, 11 December, 2017 9:04 AM

**To:** Adrian Ling (LKKAUTO) <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>; Shiau Chan (LKKAUTO) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Carrine Leong <[carrine.leong@premiumauto.com.sg](mailto:carrine.leong@premiumauto.com.sg)>; Chang Chee Sing <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>

**Subject:** FINAL REVISION SKG2886E - OD IG - SURVEYED 1 NOV 17

Hi Adrian and all

Revised estimate attached.

Please confirm repair cost of \$9473.44 @ 8 days of repairs.

Your early closure is well appreciated.

Best regards - jb

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Friday, 3 November, 2017 10:50 AM  
**To:** 'Claims Dept'; SUR  
**Subject:** RE: SKG 2886 E Own Damage Claims

Dear Jeffrey,

As instructed by our client **AIG Insurance**, please proceed to repair the insured vehicle **SKG 2886E (Excess \$1,400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims Dept [mailto:claims@premiumauto.com.sg]  
**Sent:** Thursday, 2 November, 2017 11:57 AM  
**To:** SUR <sur@lkkauto.com>  
**Cc:** claims@premiumauto.com.sg  
**Subject:** RE: SKG 2886 E Own Damage Claims

Dear all,

Any update on the this case?

Please advise on the approval urgently.

Many thanks!

Best regards,  
**Jeffery Tan**

**Premium Automobiles Pte Ltd** (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg) w. [www.audi.com.sg](http://www.audi.com.sg)

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	30 Oct 2017 19:15	Clim Veh Model Changed	Reg No: SKG2886E. Policy No: 2100342352-04000. Acct Date: 2017/10/30. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA117143486	[ ] Merimen Administrator
2	30 Oct 2017 19:15	Clim Created		[I] Merimen Administrator
3	01 Nov 2017 15:54	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[ ] CATHERINE CHONG KAI LING
4	01 Nov 2017 15:54	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[ ] CATHERINE CHONG KAI LING
5	01 Nov 2017 15:54	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	01 Nov 2017 15:54	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/10	[A] CATHERINE CHONG KAI LING
7	01 Nov 2017 15:54	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	01 Nov 2017 15:54	Clim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	01 Nov 2017 15:54	Clim Veh Model Changed	(205049) AUDI A8 L 3.0 TFSI QU (A).	[A] CATHERINE CHONG KAI LING
10	01 Nov 2017 15:55	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	02 Nov 2017 11:29	Adj Rpt Initiated		[A] SHIAU CHAN
12	02 Nov 2017 11:29	Clim Details Notified		[A] SHIAU CHAN
13	02 Nov 2017 14:18	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 1400.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
14	02 Nov 2017 14:18	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
15	02 Nov 2017 15:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/11/10	[A] SHIAU CHAN
16	02 Nov 2017 15:14	Adj Mandate Request	Cur.Req:11623.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	02 Nov 2017 16:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/11/10. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
18	02 Nov 2017 16:46	Adj Mandate Set	Approved:10374.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1627801	02/11/2017 11:29	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKG2886E		10.70

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Loo, Tong Shing

Date: 02 Nov 2017

**Preliminary Advice**

Vehicle No	: SKG2886E	Accident Date	: 30/10/2017
Make	: AUDI A8 L	Policy No.	: 2100342352-04000
Assignment Date	: 01/11/2017	Excess	: S\$0.00
Date of Inspection	: 01/11/2017	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,901.00
Revised Amount	:S\$	10,374.00
Check Items (Estimated)	:S\$	1,249.00
Total	:S\$	11,623.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	99,169.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,831.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Company
Owner ID	0257K
<b>Vehicle Details</b>	
Vehicle No.	SKG2886E
Vehicle to be Exported	No
Intended De-registration Date	02 Nov 2017
Vehicle Make	AUDI
Vehicle Model	A8L 3.0 TFSI QU (SR+HID)
Primary Colour	Black
Manufacturing Year	2011
Engine No.	CGW027281
Chassis No.	WAUZZZ4H4CN016577
Maximum Power Output	213.0 kW (285 bhp)
Open Market Value	\$84,054.00
Original Registration Date	15 May 2012
First Registration Date	15 May 2012
Transfer Count	0
Actual ARF Paid	\$84,054.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	14 May 2022
PARF Rebate Amount	\$58,837.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	14 May 2022
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$88,990.00
COE Rebate Amount	\$40,332.00
<b>Total Rebate Amount</b>	<b>\$99,169.00</b>

The information contained herein is correct as at 02 Nov 2017

OK

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S74728041



Name

NG SOI YEEN

Race

CHINESE

Date of Birth

24-03-1974

Sex

M

Country of Birth

MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENCE


Licence Number: S74728041

Name:

NG SOI YEEN

Birth Date: 24 Mar 1974

Issue Date: 02 Oct 2008



001669255E



8370537

NRIC No: S74728041



Nationality

MALAYSIAN

Blood Group

A+

Date of issue

06-09-2000

APT BLK 272D JURONG WEST STREET 24 #12-18  
SINGAPORE 644272

NRIC No: S74728041

Date: 21-06-2003

No: 4564705

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

PASS DATE


Class 2B MOTORCYCLES NOT EXCEEDING 246 CC  
Class 2A MOTORCYCLES BETWEEN 241 CC AND 499 CC  
Class 3A MOTOR CARS AND MOTOR TRACTORS WITHOUT  
CLUTCH PEDALS THE WEIGHT OF WHICH UNLADEN  
DOES NOT EXCEED 3500 KILOGRAMS

01 Apr 2011  
06 Jul 2015  
02 Oct 2068

S / No. 9000227392

S74728041

NP 428A



Licence No: S74728041



HOTLINE TEL: (65) 8419 3000  
FAX: (65) 6415-3723

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.4

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100342352-04000

OWN DAMAGE EXCESS S\$1400.00 (1)

WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value

INSURING WITH COE/PARF Yes

SKG2886E

SINOPEC LUBRICANT (SINGAPORE) PTE LTD

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT  
OF INSURANCE FOR THE PURPOSES OF THE ACT

15 May 2017

4) DATE OF EXPIRY OF INSURANCE

14 May 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE \*  
SUBJECT TO AGE CONDITION :All Age Condition

Any person who is driving on the Insured's order or with their permission.  
This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.  
A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the  
Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said  
Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or  
has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf  
from driving the Motor Vehicle.

6) LIMITATION AS TO USE \*

Use only for social, domestic and pleasure purposes and for the Insured's business.  
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing  
the carriage of goods other than samples in connection with any trade or business or use for any purpose in  
connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 6 Bk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY NA  
/ EMPLOYER'S LOAN

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and  
Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-  
Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 26 Apr 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200  
PREMIUM LEASING - AP  
281 ALEXANDRA ROAD  
AUDI CUSTOMER SERVICE CENTRE  
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSCNFY

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/1076/2017/JT  
Date : 1-Nov-17

Vehicle IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Sinopec Lubricants (Singapore) Pte Ltd  
Address : 150 Tuas South Ave 5

Singapore 637363  
Telephone : HP +65 9844 4280 Mr Ng  
Type of Claim : Own Damage Claim  
Policy No. : 2100342352-04000  
Vehicle No : **SKG 2886 E**  
Model Code : Audi A8L D4 3.0 TFSI qu  
Model / Year : May-12  
Engine No : CGW 027281  
Chassis No : WAUZZZ4H4CN016577  
Mileage : -  
Date In : 31-Oct-17  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 30-Oct-17  
Place of Accident : Entrance of Summerdale Condo

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKE 2886 E.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To set up and place vehicle in aluminium repair facility.	S/N \$	1,200.00	X
2	To remove and transfer LHS rear door multi lock system, power window devices and door soft closure assy.	S/N \$	480.00	//
3	To remove and reinstall rear seat, back rest, hat trays, ABCD pillar trims, luggage compartment trims, and seat belts. Disengage curtain airbags.	S/N \$	1,800.00	X
4	To dismantle LHS rear door and LHS side member trims. Cut out and weld LHS rear fender lower section. Renew LHS side member trims and LHS rear door, align to position. Re-organize rear crash management components. Reinstall all parts removed.	\$	<del>4,800.00</del>	1500/-
5	To carry out aluminium primer works, stone chip treatment and joint sealer works. Respray LHS rear door, door handle LHS rear fender, LHS sill panel, door entrance and LHS side member trim.	\$	<del>4,200.00</del>	2000/-
6	To carry out diagnostic checks.	S/N \$	192.00	//
TOTAL LABOUR CHARGES		:	<u>\$ 12,672.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKG 2886 E.

		<u>Damage Parts &amp; Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR DOOR - LHS <i>Distorted</i>	\$ 5,040.00	✓ 4032
2	REAR DOOR ATTACHMENT PARTS - LHS <i>Not New</i>	\$ 95.00	? X
3	REAR DOOR OUTER SEAL - LHS <i>new</i>	\$ 224.00	✓ 178.80
4	BONDING AGENT <i>Not New</i>	\$ 42.00	? X
5	REAR DOOR CATCH - LHS <i>new</i>	\$ 123.00	X
6	REAR DOOR SEAL - LHS <i>Not New</i>	\$ 194.00	? X
7	REAR DOOR HANDLE - LHS <i>Ryrie</i>	\$ 377.00	X
8	REAR DOOR MOUNTING BAR - LHS <i>new</i>	\$ 115.00	X
9	SIDE MEMBER TRIM LOWER SECTION - RHS <i>Ryrie</i>	\$ 964.00	X
10	SILL PANEL COVER - RHS <i>Delud</i>	\$ 938.00	✓ 750
11	SILL PANEL ATTACHMENT PARTS - RHS <i>new</i>	\$ 418.00	? 334.40 ✓
12	REAR SECTIONAL PIECE - RHS <i>Ryrie</i>	\$ 5,563.00	X
13	2-PACK EPOXY AHHESIVE 2	\$ 98.00	X
14	ALUMINIUM POWDER	\$ 500.00	+
15	HARDENER	\$ 184.00	X
16	POP RIVETS & DRILLS	\$ 94.00	+
17	ACRYLIC SEALER	S/N \$ 180.00	X
18	CAVITY WAX	S/N \$ 140.00	X
19	STONE CHIP	S/N \$ 180.00	X
20	SUNDRIES <i>new</i>	\$ 500.00	? 6.74 ✓
<b>GRAND TOTAL SPARE PARTS</b>		:	<b>\$ 15,969.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 14,932.00</b>
<b>GRAND TOTAL</b>		:	<b>\$ 30,901.00</b>

28641

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian Lj  
Surveyed Date : 01/11/17.  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorized, OS Reps.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/1076/2017/JT  
Date : 1-Nov-17

Vehicle IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

*Hi Adrian*

*You recommended 5 days*

*We took 8 days exclude 1 Sunday*

*Jb- 11 Dec*

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Sinopec Lubricants (Singapore) Pte Ltd  
Address : 150 Tuas South Ave 5

Singapore 637363  
Telephone : HP +65 9844 4280 Mr Ng  
Type of Claim : Own Damage Claim  
Policy No. : 2100342352-04000  
Vehicle No : **SKG 2886 E**  
Model Code : Audi A8L D4 3.0 TFSI qu  
Model / Year : May-12  
Engine No : CGW 027281  
Chassis No : WAUZZZ4H4CN016577  
Mileage : -  
Date In : 31-Oct-17  
Liability : -  
Excess Cost : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 30-Oct-17  
Place of Accident : Entrance of Summerdale Condo

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKE 2886 E.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To set up and place vehicle in aluminium repair facility.	S/N \$ 1,200.00	
2	To remove and transfer LHS rear door multi lock system, power window devices and door soft closure assy.	S/N \$ 480.00	\$ 480.00
3	To remove and reinstall rear seat, back rest, hat trays, ABCD pillar trims, luggage compartment trims, and seat belts. Disengage curtain airbags.	S/N \$ 1,800.00	
4	To dismantle LHS rear door and LHS side member trims. Cut out and weld LHS rear fender lower section. Renew LHS side member trims and LHS rear door, align to position. Re-organize rear crash management components. Reinstall all parts removed.	\$ 4,800.00	\$ 1,500.00
5	To carry out aluminium primer works, stone chip treatment and joint sealer works. Respray LHS rear door, door handle LHS rear fender, LHS sill panel, door entrance and LHS side member trim.	\$ 4,200.00	\$ 2,000.00
6	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 12,672.00	\$ 4,172.00

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKG 2886 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR DOOR - LHS	\$ 5,040.00	\$ 4,032.00
2	REAR DOOR ATTACHMENT PARTS - LHS	\$ 95.00	
3	REAR DOOR OUTER SEAL - LHS	\$ 224.00	\$ 178.80
4	BONDING AGENT	\$ 42.00	
5	REAR DOOR CATCH - LHS	\$ 123.00	
6	REAR DOOR SEAL - LHS	\$ 194.00	
7	REAR DOOR HANDLE - LHS	\$ 377.00	
8	REAR DOOR MOUNTING BAR - LHS	\$ 115.00	
9	SIDE MEMBER TRIM LOWER SECTION - RHS	\$ 964.00	
10	SILL PANEL COVER - RHS	\$ 938.00	\$ 750.00
11	SILL PANEL ATTACHMENT PARTS - RHS - <b>NEC</b>	\$ 418.00	\$ 334.40
12	REAR SECTIONAL PIECE - RHS	\$ 5,563.00	
13	2-PACK EPOXY ADHESIVE	\$ 98.00	
14	ALUMINIUM POWDER	\$ 500.00	
15	HARDENER	\$ 184.00	
16	POP RIVETS & DRILLS	\$ 94.00	
17	ACRYLIC SEALER	S/N \$ 180.00	
18	CAVITY WAX	S/N \$ 140.00	
19	STONE CHIP	S/N \$ 180.00	
20	SUNDRIES	\$ 500.00	\$ 6.24
<b>GRAND TOTAL SPARE PARTS</b>		<b>\$ 15,969.00</b>	<b>\$ 5,301.44</b>
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 14,932.00</b>	<b>\$ 4,172.00</b>
<b>GRAND TOTAL</b>		<b>\$ 30,901.00</b>	<b>\$ 9,473.44</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SKG 2886 E**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/1076/2017/MAS

27 Oct 2017

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

Dear Sir,

**RE: INSURANCE CLAIM FOR SKG 2886 E, Audi A8L D4 3.0 TFSI QU**

With reference to the above-mentioned vehicle, no. **SKG 2886 E**, claimant, **Sinopec Lubricant (Singapore) Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85012006 – S\$8,638.58
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encls

AIG – SKG 2886 E

total pages

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	02 Nov 2017 11:29		01 Nov 2017 15:54 <a href="#">Edit Adj Rpt</a>	<b>S\$9,473.44</b> <a href="#">Edit Estimates</a>	<b>S\$9,473.44</b> <a href="#">View Rpt</a>	
						<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
<b>Insured:</b>	SINOPEC LUBRICANT (SINGAPORE) PTE LTD, Co. Reg. No.: 201010257K								
<b>Vehicle Reg. No.:</b>	SKG2886E	<b>Date of Loss:</b>	30/10/2017 13:00 - :59						
<b>Claim Type:</b>	OD / 9385625906SG	<b>Policy/Cover Note No.:</b>	2100342352-04000 (Comprehensive)						
		<b>Excess:</b>	S\$1,400.00						
<b>Repairer:</b>	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
<b>Handling Insurer:</b>	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/11/2017]								
<b>Driver/Custodian:</b>	NG SOI YEEN (43 / Male), NRIC: S7472804I, Tel: +6598444280								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (02/11/2017): Alert - Adj Mandate Approved (S\$10374.00) - SKG2886E - Claim Handler: Loo, Tong ...</li> <li>AIG_SG (02/11/2017): SKG2886E / OD / 30/10/2017 / Coverage &amp; Excess update</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

\*SKG2886E (9385625906SG)  
 OD  
 Oct 30 2017 1:40PM  
 [SINOPEC LUBRICANT (SINGAPORE) PTE LTD]  
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		Use Viewer	
Assessment Reports										1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	02/11/17 15:13	Adjuster Immediate Advice								1 Load HTM			
										3 per page		<input checked="" type="checkbox"/>	
Photos/Images													
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
2	02/11/17 11:26	Chassis Number								1 Load JPG	<input checked="" type="checkbox"/>		
3	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
4	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
5	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
6	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
7	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
8	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
9	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
10	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
11	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
12	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
13	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
14	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
15	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
16	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
17	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
18	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
19	02/11/17 11:26	General View								1 Load JPG	<input checked="" type="checkbox"/>		
										1 per page		<input checked="" type="checkbox"/>	
Documentation													
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print		
1	02/11/17 11:26	Singapore Accident Statement								1 Load PDF			
2	02/11/17 11:26	Certificate of Insurance								1 Load PDF			
3	02/11/17 11:26	Drivers Driving License								1 Load PDF			
4	02/11/17 11:26	WORKSHOP ESTIMATE								1 Load PDF			
5	19/01/18 12:45	WORKSHOP INVOICE								1 Load PDF			
6	19/01/18 12:45	DISCHARGE VOUCHER								1 Load PDF			

## Linked Accident Report Documents

			View	Use Viewer
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	30/10/17 19:15	Accident Statement	1 Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	30/10/17 19:13	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
2	30/10/17 19:13	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
3	30/10/17 19:13	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>

4	30/10/17 19:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	30/10/17 19:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	30/10/17 19:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	30/10/17 19:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	30/10/17 19:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	30/10/17 19:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	30/10/17 19:13	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		<b>Thumbnail</b>	<b>Print</b>
1	30/10/17 19:05	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	30/10/17 19:05	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

Our File No: CC3/AIG17020876/AQBN2

Date: 19/01/2018

## REFERENCE

Insured/Claimant: SINOPEC LUBRICANT (SINGAPORE) PTE LTD

Policy No: 2100342352-04000

Date of Loss: 30/10/2017

Nature of Claim:

OD

Claim No: 9385625906SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKG2886E

Make &amp; Model: AUDI A8 L, 3.0 TFSI QU (A)

Engine No: CGW027281

Reg. Date: 15/05/2012 (Man. Year: 2011)

Chassis No: WAUZZZ4H4CN016577

Colour: Black

Odometer: 55809 km

Engine Capacity: 2995 cc

Market Value/New Car Price: S\$120,000.00

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 255/45 R19

Rear Tyre Size: 255/45 R19

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,969.00	5,301.44	10,667.56	66.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,672.00	4,172.00	8,500.00	67.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,641.00</b>	<b>9,473.44</b>	<b>19,167.56</b>	<b>66.92</b>
<b>- Excess (S\$)</b>	<b>1,400.00</b>	<b>1,400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>27,241.00</b>	<b>8,073.44</b>	<b>19,167.56</b>	<b>70.36</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,906.87</b>	<b>565.14</b>	<b>1,341.73</b>	<b>70.36</b>
<b>Nett Amount (S\$)</b>	<b>29,147.87</b>	<b>8,638.58</b>	<b>20,509.29</b>	<b>70.36</b>

## INSPECTION

Date of Assignment: 01/11/2017

Date Inspected: 01/11/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LHS	Distorted	5,040.00 FS	*4,032.00 FS
2	1		*REAR DOOR ATTACHMENT PARTS-LHS	Not Necessary	95.00 FS	*- FS
3	1		*REAR DOOR OUTER SEAL-LHS	Necessary	224.00 FS	*178.80 FS
4	1		*BONDING AGENT	Not Necessary	42.00 FS	*- FS
5	1		*REAR DOOR CATCH-LHS	Not Necessary	123.00 FS	*- FS
6	1		*REAR DOOR SEAL-LHS	Not Necessary	194.00 FS	*- FS
7	1		*REAR DOOR HANDLE-LHS	Repair	377.00 FS	*- FS
8	1		*REAR DOOR MOUNTING BAR-LHS	Not Necessary	115.00 FS	*- FS
9	1		*SIDE MEMBER TRIM LOWER SECTION-RHS	Repair	964.00 FS	*- FS
10	1		*SILL PANEL COVER-RHS	Deformed	938.00 FS	*750.00 FS
11	1		*SILL PANEL ATTACHMENT PARTS-RHS	Necessary	418.00 FS	*334.40 FS
12	1		*REAR SECTIONAL PIECE-RHS	Repair	5,563.00 FS	*- FS
13	1		*2-PACK EPOXY ADHESIVE	Not Necessary	98.00 FS	*- FS
14	1		*ALUMINIUM POWDER	Not Necessary	500.00 FS	*- FS
15	1		*HARDENER	Not Necessary	184.00 FS	*- FS
16	1		*POP RIVETS & DRILLS	Not Necessary	94.00 FS	*- FS
17	1		*ACRYLIC SEALER	Not Necessary	180.00 FS	*- FS
18	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
19	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
20	1		*SUNDRIES	Necessary	500.00 FS	*6.24 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **15,969.00**    **5,301.44**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO SET UP AND PLACE VEHICLE IN ALUMINIUM REPAIR FACILITY	New	1,200.00	-
2	TO REMOVE AND TRANSFER LHS REAR DOOR MULTI LOCK SYSTEM,POWER WINDOW DEVICES AND DOOR SOFT CLOSURE ASSY	New	480.00	480.00
3	TO REMOVE AND REINSTALL REAR SEAT,BACK REST,HAT TRAYS,ABCD PILLAR TRIMS,LUGGUAGE COMPARTMENT TRIMS,AND SEAT BELTS,DISENGAGE CURTAIN AIRBAGS	New	1,800.00	-
4	TO DISMANTLE LHS REAR DOOR AND LHS SIDE MEMBER TRIMS.CUT OUT AND WELD LHS REAR FENDER LOWER SECTION.RENEW LHS SIDE MEMBER TRIMS AND LHS REAR DOOR,ALIGN TO POSITION.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	4,800.00	1,500.00
5	TO CARRY OUT ALUMINIUM PRIMER WORKS,STONE CHIP TREATMENT AND JOINT SEALER WORKS.RESPRAY LHS REAR DOOR,DOOR HANDLE,LHS REAR FENDER,LHS SILL PANEL,DOOR ENTRANCE AND LHS SIDE MEMBER TRIM	New	4,200.00	2,000.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			12,672.00	4,172.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;