

ASSIGNED BY

REF CS/SM017020882/Agbnz

Version 1.0

Date/Time

Adrian

ASSIGNMENT (Official)

Printed Person

Sheng Wong

SMO

Date/Time

1/11/17 @ 3.38pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SLA 605H

Insured

CB 78955

at Workshop no

Hua feng Automotive

Tel

9271 2214

or

Blk 1 Kaki Bukit Ave 6 # 01-107 Autobay 117883

Policy No

Claim No

CMTD1703867 / GPL

Sum Insured

Excess

Make of Veh

D.O.A

31/10/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp'

H.O.D. Endorsement

Date/Time

3.47pm @ 1/11/17

Person Contacted

Chris

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 605H - X

CB 78955 - X

REF: SMO

ASSIGNMENT

From:

Date: 01-11-2017

Veh No:

SLA 605H

Yr Regn: 19/2/2016

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA 605H

at Workshop m/s

Hua Feng Automotive

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

cc 1496

Colour:

silver.

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Ru11106372

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60 R16

R:

215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

01/11/17

Survey held at

Hua Feng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/11/17 TP Sengoo.
email to Shery - pending est from wksp.
4s \$ 6200 Cfed: 8587.60, 587.7.

RECEIVED 20 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: \$ 6200

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17020882/Agb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 01-11-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7895S	Veh. Inspected	SLA 605H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703867	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	01/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/10/2017	Inspection Date	01/11/2017
Survey held at	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Thursday, 2 November, 2017 4:35 PM
To: 'Wong, Shi Yi Shery'
Cc: 'Henry, Irene James'; 'Gnoh, Pau Loong'; SUR
Subject: RE: SLA605H &CB7895S DOA 31/10/17

Dear Shery,

Please be informed that we have inspected the vehicle SLA 605H on 01-11-2017.
We are pending estimate from repairer.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 1 November, 2017 3:49 PM
To: 'Wong, Shi Yi Shery' <Shery.Wong@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SLA605H &CB7895S DOA 31/10/17

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Shi Yi Shery [<mailto:Shery.Wong@sompo.com.sg>]
Sent: Wednesday, 1 November, 2017 3:38 PM
To: assignments
Cc: Catherine Chong (LKK Auto); Henry, Irene James; Gnoh, Pau Loong; chris_chanbebe@hotmail.com
Subject: FW: SLA605H &CB7895S DOA 31/10/17

Our Reference: CMTD1703867/GPL

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SLA605H).

Nivitha (LKK Auto)

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Wednesday, 1 November, 2017 3:38 PM
To: assignments
Cc: Catherine Chong (LKK Auto); Henry, Irene James; Gnoh, Pau Loong; chris_chanbebe@hotmail.com
Subject: FW: SLA605H &CB7895S DOA 31/10/17

Our Reference: CMTD1703867/GPL

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SLA605H).

Please refer to the email correspondence below.

Thank you.

Best Regards

Shery Wong

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]
Sent: Wednesday, November 01, 2017 3:33 PM
To: Wong, Shi Yi Shery
Subject: Re: SLA605H &CB7895S DOA 31/10/17

Blk 1 Kaki bukit ave 6#01-107 Autobay @ KB (S)417883

Regards,
Chris Chan Pick Yuen

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Wednesday, November 1, 2017 2:25:58 PM
To: chan pick yuen
Subject: RE: SLA605H &CB7895S DOA 31/10/17

Hi Chris,

Kindly let us have the location of your workshop in order for me to arrange for survey.

Thank you.

Best Regards

Shery Wong

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Wednesday, November 01, 2017 2:16 PM

To: Wong, Shi Yi Shery

Subject: Re: SLA605H & CB7895S DOA 31/10/17

LKK Auto CONSULTANT pte Ltd.

Please let me have your confirmation.Thanks

Regards,

Chris Chan Pick Yuen

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>

Sent: Wednesday, November 1, 2017 2:04:21 PM

To: chris_chanbebe@hotmail.com

Cc: Henry, Irene James; Gnoh, Pau Loong

Subject: RE: SLA605H & CB7895S DOA 31/10/17

Our Reference: CMTD1703867/GPL

Your Reference: SLA605H

Date: 01ST November 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S HUA FENG AUTOMOTIVE

Accident involving SLA605H and CB7895S on 31/10/2017

Dear Sir

We refer to your Notice of Accident via email dated 01/11/2017.

Please be informed that Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Shery Wong

Claims Division

D: 6329 5339 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: chan pick yuen [mailto:chris_chanbebe@hotmail.com]

Sent: Wednesday, November 01, 2017 12:35 PM

To: Motor Survey

Subject: SLA605H &CB7895S DOA 31/10/17

Dear Sir ,

Enclosed is scene photo.

Please let us have your 10 name list surveyor to survey our client's car no: SLA605H .

Regards,

Chris Chan Pick Yuen

Hua Feng Automotive Engineering & Reconstruction

Hp:92712214

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/11/2017 15:12
Date Of Accident	31/10/2017 19:15
Exact Location Of Accident	TAMPINES AVE 10.
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA605H
Insured/Policyholder	
Name Of Registered Owner	LOW TEIK HANG
NRIC No	S7582249I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81254603
Alternative Phone No	OFFICE-81254603

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01002067
Cover Note Number	

Driver

Name of Driver	CHAN WAI LENG
NRIC No	S8072950B
Date Of Birth	02/09/1980
Occupation	INDOOR
Date Of Driving Pass	18/03/2002
Driving Experience	15 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91469043
Fax Number	
Contact Number	
Email Address	IRENE2980@YAHOO.COM

Address	BLK 717 TAMPINES ST 72 #07-63
Postcode	520717
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES N.P.C
Police Station Address	ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY VEHICLE WAS STATIONARY, VEHICLE B SUDDENLY HIT ONTO MY VEHICLE REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB7895S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLA605H

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Accident Sketch Plan Pg. 1


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my vehicle was stationary, vehicle B sudden hit onto my
vehicle rear

irene2980@yahoo.com

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Page 6 of 22

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171101/2115

1 of 3

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

Report No: T/20171101/2115

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/11/2017 15:30		Vide Report No.:		Station Diary No.: 95	
Informant's Particulars					
Name of Informant: CHAN WAI LENG			Address: APT BLK 717 TAMPINES STREET 72 #07-63 SINGAPORE 520717		
ID Type / ID No.: NRIC NO / S8072950B			Contact No.: Home/Office: Mobile: 91469043		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 37	Date of Birth: 02/09/1980	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Accounts executive			Driving Licence Information: Class: 2B,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 31/10/2017 19:15	Type of Location: Straight Road
Location: Along Road 1 TAMPINES AVENUE 10				
After Bartley Flyover				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CB7895S	Bus/Coach/Minibus					0
SLA605H	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171101/2115

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

2 of 3

Report No. T/20171101/2115

CONTINUATION OF REPORT

Driver			
Name	KOH HOO HAI	ID No.	S1727931G
Related Vehicle	CB7895S (Bus/Coach/Minibus)	Contact No.	91905859
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHAN WAI LENG	ID No.	S8072950B
Related Vehicle	SLA605H (Car)	Contact No.	91469043
Hospital/Clinic	HEALTHWAY TAMPINES CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	01/11/2017	Date Discharge	01/11/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 31/10/2017 at around 1915hrs, I was travelling along Bartley Flyover going towards Tampines Ave 10. It was a 3 lanes road and I am on the most left lane. One vehicle CB7895S was behind my vehicle. It was red light and therefore I had already stopped my vehicle and it was stationary. So suddenly, the minibus collided onto the rear of my vehicle. I then went down of the vehicle and the driver of the mini bus also came down of the vehicle. We then exchange particulars.

Due to the impact of the incident, I felt some pain on the left side of my neck. Today 01/11/2017, I woke up and felt that the pain was getting worse and therefore I went to see a doctor at Healthway Tampines clinic and the doctor informed me that I have sprained my neck and I was then given 3 days of medical leave from 01/11/2017 to 03/11/2017.

My vehicle also suffered dents at the rear and the damage of the cost would be around \$4000-\$5000.

There was no in-car camera in front and behind of my vehicle and thus did not capture the incident.



**SINGAPORE
POLICE FORCE**



T/20171101/2115

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529682
Tel No: 1800-5871999

3 of 3

Report No. T/20171101/2115

CONTINUATION OF REPORT


Sketch Plan


Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 1 LAM XUE TING	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 01/11/2017 15:30
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case:
Authentication Stamp NP168	

OWNER





Accident Sketch Plan Pg. 1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8072950B



 Name
CHAN WAI LENG
曾慧玲

Place
CHINESE

 Date of birth
02-09-1980

Sex
F

Country/Place of birth
MALAYSIA

S8072950B


5447392



NRIC No. S8072950B

 Date of issue
01-04-2015

Address
APT BLK 717 TAMPINES STREET 72
#07-63
SINGAPORE 520717



HUA FENG AUTOMOTIVE

ENGINEERING & RECONSTRUCTION

BLOCK 1 KAKI BUKIT AVENUE 6 #01-107 AUTOBAY @ KB (S) 417883

Tel: (65) 69664526 HP: 92712214 Fax: (65) 67476918

BLOCK 1 KAKI BUKIT AVE 6
#01-107 AUTOBAY @ KB
Singapore 417883

01st NOV 2017

TP Sompoo
Ai Phing

Accident date: 31st OCT 2017

Estimated repair cost for vehicle no: SLA605H HONDA VEZEL

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Distorted		\$1,195.00
2	2	Rear Boot Lid damper Not New	\$180.00	\$360.00
3	2	rear Boot Lid hinges Not New	\$168.00	\$336.00
4	1	Rear boot lid emblem logo Not New		\$55.00
5	1	Rear boot lid VEZEL logo New		\$38.10
6	1	rear boot lid Emblem logo Not New		\$38.10
7	2	Rear Boot Lid side reflector RH and L	\$402.20	\$804.40
8	1	Rear boot lid inner rubber bit		\$237.00
9	1	Rear Boot Lid Inner Lock Damaged		\$284.20
10	1	Rear Boot Lid Number Plate Not New		\$50.00
11	1	rear Boot Lid number Plate top garnish Not New		\$110.00
12	2	Rear Boot Lid Number Plate Lamp Not New	\$61.10	\$122.20
13	1	Rear Boot Lid center moulding Not New		\$320.80
14	10	Rear Boot Lid Inner Trim board clips	\$5.00	\$50.00
15	1	Rear Boot Lid Inner Trim board Deformed		\$354.00
16	2	Rear tail lamp RH and L	\$380.00	\$760.00
17	1	Rear end panel Dented		\$420.00
18	1	Rear End Panel Top Garnish Deformed		\$168.00
19	1	Rear Bumper Deformed		\$745.30
20	1	Rear bumper top garnish Best		\$226.20
21	2	Rear Bumper Side Bracket New	\$48.00	\$96.00
22	1	Rear Bumper reverse sensor Damaged		\$400.00
23	2	Rear side Bumper RH and L	\$125.00	\$250.00
24	8	Rear bumper clips New	\$5.00	\$40.00
25	2	Rear Bumper Side Reflector Corroded	\$88.00	\$176.00

26	1	Rear Exhaust	Best		\$708.50	✓
27	1	Rear Exhaust aluminium cover	new		\$64.00	+
28	2	Rear Fender Inner Trim Board	del'd	\$285.00	\$570.00	✓
29	4	Rear Fender Inner Trim Board Clips	✓	\$32.00	\$128.00	50
30	1	Rear windscreen moulding	new		\$158.00	✓
31	1	Rear spare tire panel	new		\$1,045.30	+
32	1	rear spare tyre top board	del'd		\$299.50	✓
33	1	Rear spare tire panel lower cover	2		\$428.00	+
34	2	Rear spare tire panel insulation	new		\$150.00	+
35	1	Rear spare tire panel sealant			\$180.00	+

Rear Bumper Lower Spoiler Del'd

65658 SN 570
525268

Subtotal :-

\$11,367.60

Labour charges

To Remove & refix cushion

\$150.00 60

To Remove & refix rear windscreen

\$120.00 100

Gum (SN) nec

\$50.00 ✓

To Remove & refix rear exhaust

\$280.00 80

To Remove & refix reverse Sensor

\$120.00 50

Tuff kote

2020

\$120.00 50

Towing charges

\$100.00 +

To Check Wiring System

\$80.00 30

Panel beating

\$1,200.00 80

Spray painting

\$1,200.00 80

Subtotal :-

\$3,420.00

Total:-

\$14,787.60

15437.60

total 7000 640
4/5 6.2K

07 Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17020882/Agbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 02-01-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7895S	Veh. Inspected	SLA 605H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703867/GPL	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	01/11/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11106372	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/10/2017	Inspection Date	01/11/2017
Survey held at	HUA FENG AUTOMOTIVE ENGINEERING & RECONSTRUCTION BLK 1 KAKI BUKIT AVE 6 #01-107 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 605H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	DISTORTED	1,195.00	1,195.00
2	REAR BOOT LID DAMPER @\$180.00	NOT NECESSARY	360.00	-
2	REAR BOOT LID HINGES @168.00	NOT NECESSARY	336.00	-
1	REAR BOOT LID EMBLEM LOGO	NOT NECESSARY	55.00	-
2	REAR BOOT LID SIDE REFLECTOR @\$402.20	N/S CRACKED	804.40	285.00
1	REAR BOOT LID VEZEL LOGO	NECESSARY	38.10	38.10
1	REAR BOOT LID EMBLE LOGO	NOT NECESSARY	38.10	-
1	REAR BOOT LID INNER RUBBER	CUT	237.00	237.00
1	REAR BOOT LID INNER LOCK	DAMAGED	284.20	284.20
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID NUMBER PLATE TOP GARNISH	NOT NECESSARY	110.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$61.10	NOT NECESSARY	122.20	-
1	REAR BOOT LID CENTER MOULDING	NOT NECESSARY	320.80	-
10	REAR BOOT LID INNER TRIM BOARD CLIPS @\$5.00	NECESSARY	50.00	30.00
1	REAR BOOT LID INNER TRIM BOARD	DEFORMED	354.00	354.00
2	REAR TAIL LAMP @\$380.00	O/S CRACKED	760.00	380.00
1	REAR END PANEL	DENTED	420.00	420.00
1	REAR END PANEL TOP GARNISH	DEFORMED	168.00	168.00
1	REAR BUMPER	DEFORMED	745.30	745.30
1	REAR BUMPER TOP GARNISH	BENT	226.20	226.20
2	REAR BUMPER SIDE BRACKET @\$48.00	NECESSARY	96.00	96.00
2	REAR SIDE BUMPER @\$125.00	O/S DEFORMED	250.00	125.00
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	40.00
2	REAR BUMPER SIDE REFLECTOR @\$88.00	CRACKED	176.00	176.00
1	REAR EXHAUST	BENT	708.50	708.50
1	REAR EXHAUST ALUMINIUM COVER	NOT NECESSARY	64.00	-
2	REAR FENDER INNER TRIM BOARD @\$285.00	DEFORMED	570.00	570.00
4	REAR FENDER INNER TRIM BOARD CLIPS @\$32.00	NECESSARY	128.00	30.00
1	REAR WINDSCREEN MOULDING	NECESSARY	158.00	158.00
1	REAR SPARE TIRE PANEL	TO REPAIR SEE LABOUR	1,045.30	-
1	REAR SPARE TYRE TOP BOARD	DEFORMED	299.50	299.50
1	REAR SPARE TIRE PANEL LOWER COVER	NOT NECESSARY	428.00	-
1	REAR SPARE TIRE PANEL INSULATION	NOT NECESSARY	150.00	-

Report Ref No. CS/SMO17020882/Agbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPARE TIRE PANEL SEALANT	NOT NECESSARY	180.00	-
	LESS 20% DISCOUNT		-	-1,313.16
			10,967.60	5,252.64
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER LOWER SPOILERS (SN)	DEFORMED	650.00	350.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	400.00	220.00
1	GUM (SN)	NECESSARY	50.00	50.00
			1,100.00	620.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX CUSHION.		150.00	60.00
	TO REMOVE & REFIX REAR WINDSCREEN.		120.00	100.00
	TO REMOVE & REFIX REVERSE SENSOR.		120.00	50.00
	TUFF KOTE.		120.00	50.00
	TOWING CHARGES.	NOT NECESSARY	100.00	-
	TO CHECK WIRING SYSTEM.		80.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR SPARE TIRE PANEL.		1,200.00	800.00
	SPRAY PAINTING.		1,200.00	800.00
	TO REMOVE & REFIX REAR EXHAUST.		280.00	80.00
			3,370.00	1,970.00
	GRAND TOTAL		15,437.60	7,842.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO IT'S PRE-ACCIDENT CONDITION)			6,200.00

Report Ref No. CS/SMO17020882/Agbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.