

REF: CS3/m8(117020937/Wrb⁰²

From (Person): Limel Tan of mslh Date/Time: 02/02/2018
Estimated Cost: _____ Bill to: _____

Special Instruction:

48: \$5150.00

Third Parties:

Claimant:

Surveyor: Prominent Approvals

Workshop: Rev Solutions

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: STL 7627P Insured: GV 7231E
at Workshop m/s REV Solutions Tel: 9339 1185
of 11 Kaki Bukit Rd 1 #01-02
Policy No:

Policy No: _____ Claim No: 535001

Sum Insured: _____ Claim No: 535001

Make of Veh: _____ Excess: _____
(Client's Record) _____ D.O.A. 30-10-2012

Make of Veh: _____ Excess: _____
(Client's Record) _____ D.O.A. 30-10-2012

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____
 Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____ %; Original _____ days)
 Date/Time: 25/1/18 Submit Final Fig 83350, 6 days (Red \$ 1800 / 34 %; Original 8 days)
 Date/Time _____ Action/Instruction _____

H.O.D. Enborsement/Date:

Date/Time	Action/Instruction
-----------	--------------------

RECEIVED 29 JAN 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)
--

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add	
Transport	
Photos	
Others	
Total	

Date: _____

1) Date/Time _____ File Pass to _____
 3) Date/Time _____ File Pass to _____
 5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____
 4) Date/Time _____ File Return to _____
 6) Date/Time _____ File Return to _____

ASSIGNED BY

REF CS3/MSG17020937/Wb

range

To/From

Wilson

ASSIGNMENT (Office)

Merimen

From (Person)

Lionel Tan

MSG

Date/Time 1/11/17 @ 5.30pm

Estimated Cost

Bill to

OD (H) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJL 7627P

Insured

GV 7231 E

at Workshop in

Rev Solutions

Tel

9339.1185

at 11 kaki Bukit Road 1, # 01-02 Eunus Technotink, 415939

Policy No

A29017653 TMV

Claim No

535001

Sum Insured

Excess

Make of Veh

D.O.A 30/10/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time 2/11/17

Person Contacted

Ronald

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJL 7627P - NBA / TM17020804/y - D.O.A: 30/10/2017

GV 7231 E - NBA / TM17020804/y - D.O.A: 30/10/2017

25-11-17 445pm Email to Lionel Tan thru Merimen.

Summit

PRG Wilson

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV:
 To inspect Vehicle No: **SJL 7627 P**
 at Workshop m/s: **Reo Solution**
 of: **11, Kaka: Buk-t Rel 1 #01**
 Insured:
 Policy No:
 Claims No:
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ \$ 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: **SJL 7627 P** yr Regn: **2008 Dec 11**
 Type: **(M.Car)** M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Toyota** cc: **1447**
 Colour: **Red.** AC Insured / Std / NI / NA
 Sp. Reading: **189104** T. Ratio: Insured / Std / NI / NA
 Eng. No:
 C/No: **MR0531HY930301115**
 Gen. Cond: **(Good)** / Fair / Poor / Burnt
 Steering: **(Inorder)** / Jammed / Leaked / Burnt or
 Brake: **(Inorder)** / Jammed / Leaked / Burnt or
 Mod: **(Nil)** / S/Rim / STD A/Rim or
 Tyre Size: F: **195/55 R15**
 R: **195/55 R15**
 BS / DUN / EXNOVA / GY / FS / LIZ / **(MIC)** / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: **4** mm R. Bal: **3** mm
 L. Bal: **4** mm L. Bal: **3** mm
 D.O.A.: _____ D.O.I: **21/11/2017C**
 Survey held at: **As Above** **3:46pm**
 Des. of Damages: Frt **(Rear)** O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time: File Pass to: ☐ : Preli. Report
☐ : Final Report

Date/Time: File Return to:

Days Of Repair:
 Resurvey No. of Trip:

Survey Fee
 Transceptor

Add Fee: ☐ Site Insp. \$
☐ Interview \$
☐ Techn. Insp. \$
☐ Weekend \$

Report Format:
 Lump Sum / I.B.I. (\$) _____

1. 1-10-10

2. 1-10-10

3. 1-10-10

4. 1-10-10

5. 1-10-10

Survey Department Check List (Case Handler)

Reference No.: 031M61702095710b
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Wilson): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By:

Celine 25/1/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG17020937/Wb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-11-2017



Code : MSG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GV 7231E	Veh. Inspected	SJL 7627P
Policy No.	A29017653TMV	Coverage (\$)	0.00
Claim No.	535001	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	02/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/10/2017	Inspection Date	02/11/2017
Survey held at	REV SOLUTIONS - 11 KAKI BUKIT RD 1 #01-02		
Repairer	-		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2017		01 Nov 2017 17:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIN HONG SEAFOOD, Co. Reg. No.: 53240837C, Tel: +6597313032		
Main Claimant:	SIM DING WEI LEONARD, ID: S8629697G		
Vehicle Reg. No.:	SJL7627P	Date of Loss:	30/10/2017 18:00 - :59
Claim Type:	TP / 535001	Policy/Cover Note No.:	A29017653TMV (Third Party Only) Coverage: 03/10/2017 - 02/10/2018
Vehicle Reg. No. (Insured):	GV7231E	Policy No. (Claimant):	
		Excess:	
Repairer:	Rev Solutions Pte Ltd (HQ) 11 KAKI BUKIT ROAD 1, #01-02 EUNOS TECHNOLINK, 415939 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/11/2017]		
Driver/Custodian (Insured):	SOH GUAN SENG (45 / Male), NRIC: S0235888C, Tel: +6597548232		
Adj Asg. Remarks:	Please ask the surveyor in charge to direct liaise with the repairer. Our client's vehicle will be ready on 02/11/17 onwards.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Sent: Wednesday, 3 January, 2018 9:26 AM
To: assignments
Subject: FW: TP Survey - SJL7627P Our Ref: 535001

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lionel Tan [mailto:lionel_tan@sg.msig-asia.com]
Sent: Tuesday, January 02, 2018 1:20 PM
To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: TP Survey - SJL7627P Our Ref: 535001

Happy New Year!

Need you to do the following:

1. Upload PRI report
2. Prepare paper re-survey report

Best Regards,

Lionel Tan
Executive, Claims Services (Motor)
Direct line +65 6643 1307 | Direct fax +65 6225 7402 | lionel_tan@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us

on    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

* To counter club

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		D.O.A → 30/10/2017	
Owner ID Type:	Singapore NRIC		
Owner ID:	9697G		
Vehicle Details			
Vehicle No.:	SJL7627P	10 ³⁰	12 ¹ 2018
Vehicle to be Exported:	No	30	10 2017
Intended De-registration Date:	22 Jan 2018	10	1
Vehicle Make:	TOYOTA (Bal: 0.3 month)		
Vehicle Model:	VIOS G AUTO		
Primary Colour:	Red	Bal → 1.1 - 1.3 month	
Manufacturing Year:	2008	13.3 month	
Engine No.:	1NZX836349		
Chassis No.:	MR053HY9305091115	Average Depreciation	
Maximum Power Output:	80.0 kW (107 bhp)	→ #11520 / 4 yrs	
Open Market Value:	\$13,245.00	→ \$960	
Original Registration Date:	11 Dec 2008		
First Registration Date:	11 Dec 2008		
Transfer Count:	1		
Actual ARF Paid:	\$13,245.00 x 50% = 6622		
Intended PARF Rebate Details			
PARF Eligibility:	Yes	13.3 month x \$960 / month	
PARF Eligibility Expiry Date:	10 Dec 2018	→ \$12768 + \$6622	
PARF Rebate Amount:	\$6,622.00	= \$19390	
Intended COE Rebate Details			
COE Expiry Date:	10 Dec 2018	#19000 - \$7303	
COE Category:	A - Car (1600cc & below)	= \$11697	
COE Period(Years):	10		
QP Paid:	\$7,721.00		
COE Rebate Amount:	\$681.00		
Total Rebate Amount:	\$7,303.00		

The information contained herein is correct as at 22 Jan 2018

* M.V. → OK → \$19000

** Net Value → \$11,697

http://www.sgcar mart.com/used_cars/listing.php?ORD=RGD_DESC&MOD=toyota vi... 22/1/2018

SINGAPORE ACCIDENT STATEMENT

SJL 7627 P
Accident
Report

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2017 16:25
Date Of Accident	30/10/2017 18:00
Exact Location Of Accident	NO.6 UPPER THOMSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL7627P
Insured/Policyholder	
Name Of Registered Owner	SIM DING WEI LEONARD
NRIC No	S8629697G
Email Address	YVONECHEW87@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92205690
Alternative Phone No	OTHERS-94870175

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MV011809
Cover Note Number	

Driver

Name of Driver	CHEW AN BAO, YVONNE (ZHOU ANBAO)
NRIC No	S8727339C
Date Of Birth	02/09/1987
Occupation	INDOOR
Date Of Driving Pass	09/02/2007
Driving Experience	10 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94870175
Fax Number	
Contact Number	OTHERS-92205690
Email Address	YVONECHEW87@GMAIL.COM

Address	BLK 2 KITCHENER ROAD #11-85
Postcode	200002
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV7231E
Vehicle Make/Model/Colour	TOYOTA DYNA (LORRY)
Details Of Properties	
Name of Driver	SOH GUAN SENG
NRIC/Passport Number	S0235888C
Contact Number	97548232
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

N10 & UPPER HOWSON ROAD



A) SL 7427P
B) GV 7331E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

was stationary waiting in line for traffic light to turn green when lorry traveling at high speed was attempting to switch lane to the left. But mis-calculated and hit the rear of my vehicle with a hard impact.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time 31/10/17
4:25pm

Reporting Centre Personnel's Signature
Name: Paul H. Waters
NIC/TIN No.

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 31/10/17
4:30pm

Reporting Centre Personnel's Signature
Name: ROSE VATHAS
NRIC/FIN No:

Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



View Sent Message

This mail is associated with :

***SJL7627P (535001)**
[GV7231E]TP
SIM DING WEI LEONARD
Oct 30 2017 6:00PM
[SIN HONG SEAFOOD]
Rev Solutions Pte Ltd

Resend

View Recipients

Print Message

Delete Message

Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 25/11/2017 16:49 PM.
To MSIG_LTTP
Subject Pre-repair Inspection

Dear Lionel,

Refer to your assignment on 01.11.2017 at 5.30PM.

Please be informed that we have inspected the vehicle SJL 7627P on 02.11.2017 at 3.46PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

INVOICE

Mr Sim Ding Wei Leonard
Blk 2 Kitchener Road
#11-85
Singapore 200002

Invoice No. : HA/1711-40

Date : 30/11/2017

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 468.00
SGD Dollar : Four Hundred Sixty Eight Dollars Only.	
Our Reference : PAS/TP/0061117	
Vehicle No. : SJL7627P	
Make & Model : Toyota Vios (A) G	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".
Please indicate our "INVOICE NO." on the reverse side of the cheque.
Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 8722 8508 Email: pasvos@hotmail.com

Business Reg 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0061117

Date of Report : 30/11/2017

To : Mr Sim Ding Wei Leonard
Blk 2 Kitchener Road
#11-85
Singapore 200002

Date of Assignment : 01/11/2017
Report requested by : Mr Sim Ding Wei Leonard
Date of Accident : 30/10/2017
Date of Inspection : 01/11/2017
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SJL7627P
Make & Model : Toyota Vios (A) G
Date of Registration : 11/12/2008
Colour : Met. Red

Engine Capacity (cc) : 1497cc
Mileage (km) : 189104km
Chassis / Frame No. : MR053HY9305091115
Engine No. : 1NZX836349

TYRE CONDITION

Front LH : 6 mm
Make : Michelin

Front RH : 6 mm
Make : Michelin

Rear LH : 6 mm
Make : Michelin

Rear RH : 6 mm
Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. REV Solutions Pte Ltd
74, Sungei Kadut Loop, Singapore 729513

ASSESSMENT

Repairer's Estimate : \$ 8,222.50
Revised Amount : \$ 6,427.53
Less Excess : \$ -
Recommended Reserve : \$ 5,150.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Report No.: PAS/TP/0061117

Vehicle No: SJL7627P

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. REV Solutions Pte Ltd, 11, Kaki Bukit Road 1, #01-02, Eunos Technolink, Singapore 415939.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear LH portion.

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, LHR chassis member, rear fenders, LH taillamp, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$6,427.53.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$5,150.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No.: SJL7627P

Report No.: PAS/TP/0061117

APPRAISEMENT SCHEDULE

S/No	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$)	Our Assessment (\$)
1	1 pc	Boot lid	Dented ✓ DD	\$ 556.20	\$ 556.20 ✓
2	2 pcs	Boot lid hinge R/L	Bent/Repair X NN \$ 57.00	\$ 114.00	\$ - X
3	1 pc	Boot lid emblem (logo)	Necessary ✓ NEC	\$ 50.80	\$ 50.80 ✓
4	1 pc	Boot lid emblem (G)	Necessary ✓ NEC	\$ 36.60	\$ 36.60 ✓
5	1 pc	Boot lid emblem (VIOS)	Necessary ✓ NEC	\$ 47.00	\$ 47.00 ✓
6	1 pc	Boot lid no.plate lamp garnish	Dented/Cracked ✓ CRA	\$ 137.20	\$ 137.20 ✓
7	2 pcs	Boot no.plate lamp R/L	Refit X NN \$ 62.40	\$ 124.80	\$ - X
8	1 pc	Boot lid lock	Bent/Jammed ✓ BT/JM	\$ 102.00	\$ 102.00 ✓
9	1 pc	Boot lid lock striker	Bent	\$ 10.10	\$ 10.10 ✓
10	1 pc	Boot lid lock weatherstrip	Torn/Necessary X NEC	\$ 186.50	\$ 186.50 ✓
11	1 pc	Taillamp LH	Cracked ✓ CRA	\$ 409.90	\$ 409.90 ✓
12	1 pc	Taillamp panel LH	Dented/Distorted X R	\$ 134.20	\$ 134.20 X
13	1 pc	Rr windscreen top moulding	Necessary X NN	\$ 79.30	\$ 79.30 X
14	1 pc	Rr windscreen lower moulding	Necessary X NN	\$ 41.20	\$ 41.20 X
15	1 pc	Rr fender panel LH	Dented/Distorted X R	\$ 899.60	\$ 899.60 X
16	1 pc	Rr fender inner trim LH	Torn/Deformed X NN	\$ 237.90	\$ 237.90 X
17	6 pcs	Rr fender inner trim clip LH	Necessary X NN \$ 2.80	\$ 16.80	\$ 16.80 X
18	1 pc	Rr bumper	Dented ✓ DD	\$ 431.90	\$ 431.90 ✓
19	4 pcs	Rr bumper clip	Necessary ✓ NEC \$ 3.50	\$ 14.00	\$ 14.00 ✓
20	2 pcs	Rr bumper support R/L	Necessary X NN \$ 33.20	\$ 66.40	\$ 66.40 X
21	2 pcs	Rr bumper retainer R/L	Necessary ✓ NEC \$ 98.50	\$ 197.00	\$ 197.00 65
22	1 pc	Rr bumper reflector LH	Dented/Cracked ✓ CHRP	\$ 87.70	\$ 87.70 ✓
23	1 pc	Rr end panel	Dented ✓ DD	\$ 608.10	\$ 608.10 ✓
24	1 pc	Rr end panel garnish	Dented/Deformed ✓ DD	\$ 213.50	\$ 213.50 ✓
25	2 pcs	Rr end panel garnish clip	Necessary ✓ NEC \$ 2.80	\$ 5.60	\$ 5.60 ✓
26	1 pc	Rr compartment trim	Serviceable X NN	\$ 292.10	\$ - X
27	1 pc	Rr compartment cover	Refit X NN	\$ 121.60	\$ - X
28	2 pcs	Rr compartment sponge R/L	LH Dented/Deformed X NN \$ 227.20	\$ 454.40	\$ 227.20 X
29	1 pc	Rr floor panel	Dented/Repair X NN	\$ 673.60	\$ - X
				\$ 6,350.00	\$ 4,796.70
Less Discount : 25%				\$ 1,587.50	\$ 1,199.18
List Parts Sub-Total :				\$ 4,762.50	\$ 3,597.53
1	1 pc	Rr windscreen sealant	Necessary X NN S/N	\$ 50.00	\$ 40.00 X
2	1 pc	Rr fender panel sealant LH	Necessary X NN S/N	\$ 50.00	\$ 40.00 X
3	1 pc	Rr end panel sealant	Necessary ✓ NEC S/N	\$ 50.00	\$ 40.00 ✓
4	1 pc	Rr floor panel sealant	Not necessary X NN S/N	\$ 50.00	\$ - X
5	1 set	Rr reverse sensor	Dented/Damaged ✓ DD S/N	\$ 260.00	\$ 250.00 200
Special Nett Sub-Total :				\$ 460.00	\$ 370.00 240
Parts Total :				\$ 5,222.50	\$ 3,967.53



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJL7627P

Report No. : PAS/TP/0061117

S/No	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 50.00	\$ 30.00 ✓
2	To transfer boot component parts to new boot.	\$ 100.00	\$ 70.00 45
3	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	\$ 150.00	\$ 120.00 60
4	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 80.00	\$ 50.00 ✓
5	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,300.00	\$ 1,100.00 800
6	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	\$ 1,000.00 800
7	To spray anti-rust coating on new and affected panels. X NN	\$ 120.00	\$ 90.00 X
Labour Total :		\$ 3,000.00	\$ 2,460.00
Total (Parts & Labour) :		\$ 8,222.50	\$ 6,427.53 1735

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 5,150.00

Under normal circumstances, the repairs should be completed within a reasonable period of 8 Working Days.

68 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Parts (List)	\$ 2962.10
Discount 25%	- \$ 740.53
	\$ 2221.57
Parts (Special Net)	\$ 240.00
	\$ 2461.57
Labour	\$ 1735.00
	\$ 4196.57
Discount 20% (Lump Sum)	- \$ 839.31
	\$ 3357.26

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.

* Lump Sum Repair \$ 3350
Repair Day → 6 Days

...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Oct 2017		01 Nov 2017 17:31 Edit Adj Rpt	S\$3,350.00 Edit Estimates	S\$3,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: **SIN HONG SEAFOOD**, Co. Reg. No.: 53240837C, Tel: +6597313032

Main Claimant: **SIM DING WEI LEONARD**, ID: S8629697G

Vehicle Reg. No.: **SJL7627P** Date of Loss: 30/10/2017 18:00 - :59

Claim Type: **TP / 535001** Policy/Cover Note No.: A29017653TMV (Third Party Only)

Vehicle Reg. No. (Insured): **GV7231E** Coverage: 03/10/2017 - 02/10/2018

Policy No. (Claimant):

Excess:

Repairer: **Rev Solutions Pte Ltd (HQ)** 11 KAKI BUKIT ROAD 1, #01-02 EUNOS TECHNOLINK, 415939 Kaki Bukit - Tel: +65 6827 7888 ... [Handled by **Lionel Tan Tian Pei** - 6643 1307]

Handling Insurer: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: +65 6827 7888 ... [Handled by **Teo Cheng Ming Wilson** - 6643 1307]

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **Teo Cheng Ming Wilson** - 6643 1307]

Driver/Custodian (Insured): **SOH GUAN SENG (45 / Male)**, NRIC: S0235888C, Tel: +6597548232

Adj Asg. Remarks: Please ask the surveyor in charge to direct liaise with the repairer. Our client's vehicle will be ready on 02/11/17 onwards.

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- MSIG_SG (19/12/2017): Upload PRI report

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL7627P (535001)
[GV7231E]

TP

SIM DING WEI LEONARD
Oct 30 2017 6:00PM
[SIN HONG SEAFOOD]
Rev Solutions Pte Ltd

View View in Browser

Upload Documents
Upload Photos
Compose New Letter

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)
1	01/11/17 17:28	Accident Statement From: SC - Reg. No: GV7231E, Claimant: SIN HONG SEAFOOD

1 per page 1 ☒

Thumbnail	Print
Load HTM	☐

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	25/01/18 16:19	General View
2	25/01/18 16:19	General View
3	25/01/18 16:19	General View
4	25/01/18 16:19	General View
5	25/01/18 16:19	General View
6	25/01/18 16:19	General View
7	25/01/18 16:19	General View
8	25/01/18 16:19	General View
9	25/01/18 16:19	General View
10	25/01/18 16:19	General View
11	25/01/18 16:19	General View
12	25/01/18 16:19	General View
13	25/01/18 16:19	General View
14	25/01/18 16:19	General View
15	25/01/18 16:19	General View
16	25/01/18 16:19	General View
17	25/01/18 16:19	General View
18	25/01/18 16:19	General View
19	25/01/18 16:19	General View
20	25/01/18 16:19	General View
21	25/01/18 16:19	General View
22	25/01/18 16:19	General View
23	25/01/18 16:19	General View
24	25/01/18 16:19	General View
25	25/01/18 16:19	General View
26	25/01/18 16:19	General View
27	25/01/18 16:19	General View
28	25/01/18 16:19	General View
29	25/01/18 16:19	General View
30	25/01/18 16:19	General View
31	25/01/18 16:19	General View

3 per page 3 ☒

Thumbnail	Print
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒
Load JPG	☒

32	25/01/18 16:19	General View	1	Load JPG	☒
33	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
34	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
35	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
36	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
37	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
38	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
39	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
40	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
41	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
42	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
43	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
44	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
45	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
46	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
47	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
48	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
49	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
50	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
51	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
52	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
53	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
54	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
55	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
56	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
57	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
58	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
59	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
60	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
61	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
62	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
63	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
64	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
65	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
66	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
67	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
68	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
69	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
70	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
71	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
72	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
73	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
74	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
75	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
76	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
77	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
78	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
79	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
80	25/01/18 16:33	Photographs of Damaged Parts	1	Load JPG	☒
81	25/01/18 16:34	Photo After Spray	1	Load JPG	☒

Merimen e-Claims

82	25/01/18 16:34	Photo After Spray	1	Load JPG	☒
83	25/01/18 16:34	Photo After Spray	1	Load JPG	☒
84	25/01/18 16:34	Photo After Spray	1	Load JPG	☒
			1 per page	☐	☒
Documentation				Thumbnail	Print
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1	Load PDF	
1	01/11/17 17:29	TPD SJL7627P GIA REPORT From: SC - Reg. No: GV7231E, Claimant: SIN HONG SEAFOOD	1	Load PDF	
2	29/12/17 16:52	TP Survey Report	1	Load PDF	
3	11/01/18 18:16	Repairers Bill		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load PDF	
1	30/01/18 08:25	PHOTO			

Documents Checklist

		Reset	Save	Print
DOCUMENTS CHECKLIST				
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17020937/WBE2
Date: 30/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29017653TMV
Claimant Vehicle No: SJL7627P Insured Vehicle No: GV7231E
Date of Loss: 30/10/2017 Nature of Claim: TP Claim No: 535001

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJL7627P**
Make & Model: TOYOTA VIOS, 1.5 G (A) Engine No: 1NZX836349
Reg. Date: 11/12/2008 (Man. Year: 2008) Chassis No: MR053HY9305091115
Colour: Red Odometer: 189104 km
Engine Capacity: 1497 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 3 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,222.50	2,408.10	2,814.40	53.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,785.00	1,215.00	40.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,222.50	4,193.10	4,029.40	49.00
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	8,222.50	3,350.00	4,872.50	59.26
+ GST 7.00/7.00% (S\$)	575.58	234.50	341.08	59.26
Nett Amount (S\$)	8,798.08	3,584.50	5,213.58	59.26

INSPECTION

Date of Assignment: 01/11/2017
Date Inspected: 02/11/2017 Inspected At: Rev Solutions Pte Ltd (HQ)
11 KAKI BUKIT ROAD 1, #01-02 EUNOS
TECHNOLINK
Singapore 415939
Estimated Period of Repair: 6.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2018)
Parts: 143	TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJL7627P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	556.20 FL	*495.00 FL
2	2		*BOOT LID HINGE R/L	Not Necessary	114.00 FL	*- FL
3	1		*BOOT LID EMBLEM (LOGO)	Necessary	50.80 FL	*50.80 FL
4	1		*BOOT LID EMBLEM (G)	Necessary	36.60 FL	*36.60 FL
5	1		*BOOT LID EMBLEM (VIOS)	Necessary	47.00 FL	*47.00 FL
6	1		*BOOT LID NO. PLATE LAMP GARNISH	Cracked	137.20 FL	*137.20 FL
7	2		*BOOT NO. PLATE LAMP R/L	Not Necessary	124.80 FL	*- FL
8	1		*BOOT LID LOCK	Bent / Jammed	102.00 FL	*102.00 FL
9	1		*BOOT LID LOCK STRIKER	Not Necessary	10.10 FL	*- FL
10	1		*BOOT LID LOCK WEATHERSTRIP	Necessary	186.50 FL	*186.50 FL
11	1		*TAILLAMP LH	Cracked	409.90 FL	*409.90 FL
12	1		*TAILLAMP PANEL LH	Repair	134.20 FL	*- FL
13	1		*RR WINDSCREEN TOP MOULDING	Not Necessary	79.30 FL	*- FL
14	1		*RR WINDSCREEN LOWER MOULDING	Not Necessary	41.20 FL	*- FL
15	1		*RR FENDER PANEL LH	Repair	899.60 FL	*- FL
16	6		*RR FENDER INNER TRIM CLIP LH	Not Necessary	16.80 FL	*- FL
17	1		*RR BUMPER	Dented	431.90 FL	*431.90 FL
18	4		*RR BUMPER CLIP	Necessary	14.00 FL	*14.00 FL
19	2		*RR BUMPER SUPPORT R/L	Not Necessary	66.40 FL	*- FL
20	1		*RR BUMPER REFLECTOR LH	Chipped	87.70 FL	*87.70 FL
21	1		*RR END PANEL	Dented	608.10 FL	*608.10 FL
22	1		*RR END PANEL GARNISH	Dented	213.50 FL	*213.50 FL
23	2		*RR END PANEL GARNISH CLIP	Necessary	5.60 FL	*5.60 FL
24	1		*RR COMPARTMENT TRIM	Not Necessary	292.10 FL	*- FL
25	1		*RR COMPARTMENT COVER	Not Necessary	121.60 FL	*- FL
26	2		*RR COMPARTMENT SPONGE R/L	Not Necessary	454.40 FL	*- FL
27	1		*RR FLOOR PANEL	Repair	673.60 FL	*- FL
28	1		*RR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
29	1		*RR FENDER PANEL SEALANT LH	Not Necessary	50.00 FS	*- FS
30	1		*RR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS
31	1		*RR FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS
32	1		*SET RR REVERSE SENSOR	Dented	260.00 FS	*200.00 FS
33	1		*RR FENDER INNER TRIM LH	Not Necessary	237.90 FL	*- FL
34	1		*RR BUMPER RETAINER R/L	Necessary - 1pc only	197.00 FL	*65.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,810.00	3,130.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,587.50	722.70
Total Parts (\$\$)	5,222.50	2,408.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	50.00	30.00
2	TO TRANSFER BOOT COMPONENT PARTS TO NEW BOOT	New	100.00	45.00
3	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS	New	150.00	60.00
4	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	New	80.00	50.00
5	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,300.00	800.00
6	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA	New	1,200.00	800.00
7	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	120.00	0.00
Gross Labour Cost (S\$)			3,000.00	1,785.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >