

Minimen Adrian

ASSIGNMENT (Office)

From (Person)

Monica Chung

MSIG

1/11/17 @ 5:37pm

Estimated Cost

Bill to

OD (1) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJF 824P

Insured

FU 4348 P

at Workshop no

Dynamic Autowork

Tel

9856 4815

of 8 kaki Bukit Ave 4 #08-09 Premier, 415875

Policy No MSD/VMT/16-978129

Claim No

MSC/V/17-001694

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A. 31/10/2017

CA / REV / REP. / REV 24 HRS

'wp'

R.O.D. Endorsement

Date/Time

9:45am @ 2/11/17

Person Contacted

Michelle

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF824P - X
	FU4348P - X
	Sent preli through minimen
	Confirm LIs \$5.5K, 8 days
	Red: \$7,766.08, 59%.

Surrey

ASSIGNMENT

17/05/08

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SJF824P

Yr Regn: _____

2008 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Honda Civic

C.C 1799

Colour: _____

Silves

A/C: Insured / Std / NI / NA

Sp. Reading: _____

221432

T/Radio: Insured / Std / NI / NA

Eng/No: _____

JHMF D16308S215337

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

205/55R16

R: _____

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.I. _____

02/11/17

Survey held at: _____

Dynamic

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP msig

MV: 17.5K

PV: 12K

Nett: 5.5K

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

300

10

310

Report Format: TP

Lump Sum / B.I. (\$) 5.5K




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17020939/Arb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 02-11-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FU 4348P	Veh. Inspected	SJF 824P
Policy No.	MSD/VMT/16-978129	Coverage (\$)	0.00
Claim No.	MSC/V/17-001694	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	02/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/10/2017	Inspection Date	02/11/2017
Survey held at	DYNAMIC AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		02 Nov 2017 10:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	MUHAMMAD FADLY BIN SALIM, ID: S8903054D								
Main Claimant:	SAID NASIR B SAID ABDULRAB TALIB, ID: S0084444F								
Vehicle Reg. No.:	SJF824P	Date of Loss:	31/10/2017 00:00 - :59						
Claim Type:	TP / MSC/V/17-001694	Policy/Cover Note No.:	MSD/VMT/16-978129 (Third Party Only) Coverage: 26/11/2016 - 25/11/2017						
Vehicle Reg. No. (Insured):	FU4348P	Policy No. (Claimant):							
Repairer:	Dynamic Autowork Pte. Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/11/2017]								
Adj Asg. Remarks:	PRI SURVEY								
				View All	Compose Case Mail				
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Sent: Wednesday, 1 November, 2017 5:37 PM
To: 'Dynamic Autowork'; 'Catherine Chong (LKK Auto)'
Cc: Monica Chung; Rashitha Binte Shahuthuman
Subject: RE: FW: SJF824P (Pre-inspection)
Attachments: 01112017135949.pdf

Dear LKK





Please survey SJF824P. Thank you.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: Dynamic Autowork [mailto:dynamicautowork@gmail.com]
Sent: Wednesday, 1 November, 2017 5:23 PM
To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>
Subject: Re: FW: SJF824P (Pre-inspection)

Dear All,

Thanks for your reply.

Please arrange **LKK Auto Consultants Pte Ltd** to survey the above vehicle

--

Thank You.

Yours Sincerely,

Michelle
HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit
Singapore (415875)
Tel : 6341 6789
Fax : 6341 6778

On Wed, Nov 1, 2017 at 2:47 PM, Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msg-asia.com> wrote:

OUR REF - FU4348P

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email .

Our insured have not report accident to us. We are unable to revert on liability.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua

- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.





Thank you.

Rashitha

Senior Admin Officer

Direct line [+65 6594 2582](tel:+6565942582) | Direct fax [+65 6225 7402](tel:+6562257402) | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel [+65 6220 9644](tel:+6562209644) | Fax [+65 6225 6371](tel:+6562256371) | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: Dynamic Autowork [<mailto:dynamicautowork@gmail.com>]

Sent: Wednesday, November 01, 2017 2:02 PM

To: Claims <claims@sg.msig-asia.com>

Subject: SJF824P (Pre-inspection)

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

--

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit

Singapore (415875)

Tel : 6341 6789

Fax : 6341 6778

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

DYNAMIC AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No. : 201436361C

Date: 01/11/17

By Fax & Email

To: MSIG

Attn : Motor Claims Department

Re: Accident involving motor vehicle Nos. SJF 824P and FU 4348P
along PIE towards Jurong (Before Paya Lebar Exit) on 31/10/2017


We refer to the above matter.

We are instructed by Said Nasir Bin Said Abdulrahman Talib to notify you of a road traffic accident
on 31/10/2017 at about 14:20 at PIE towards Jurong (Before Paya Lebar Exit)
involving our client's/customer's vehicle registration number SJF 824P and vehicle
registration number FU 4348P driven by you at the material time.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our
client/we proceed to repair the damaged vehicle, please let us know within 2 working days of
your receipt of this notice whether you or your insurer would like to conduct a pre-repair
survey of the vehicle. If we do not receive any reply from you within the stipulated timeline,
our client/we shall proceed to repair the vehicle without further reference to you.

Thank You

Yours faithfully



Abby

Hp : 9856 4815

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/11/2017 13:13
Date Of Accident	31/10/2017 14:20
Exact Location Of Accident	PIE TOWARDS JURONG (BEFORE PAYA LEBAR EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF824P
Insured/Policyholder	
Name Of Registered Owner	SAID NASIR B SAID ABDULRAB TALIB
NRIC No	S0084444F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96778728
Alternative Phone No	OFFICE-96778728

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.8L A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5071189597-02 CLASSIC
Cover Note Number	

Driver

Name of Driver	SAID NASIR B SAID ABDULRAB TALIB
NRIC No	S0084444F
Date Of Birth	13/04/1954
Occupation	INDOOR
Date Of Driving Pass	27/06/1975
Driving Experience	42 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96778728
Fax Number	
Contact Number	OFFICE-96778728
Email Address	NOEMAIL

Address	BLK 717 #04-4544 BEDOK RESERVOIR ROAD
Postcode	470717
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAKI BUKIT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 526 BEDOK NORTH STREET 3 #01-448 , POSTCODE: 460526 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4429999 - FAX NO: 62444377
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FU4348P
Vehicle Make/Model/Colour	YAMAHA RXZ
Details Of Properties	
Name of Driver	MUHAMMAD FADLY BIN SALIM
NRIC/Passport Number	S8903054D
Contact Number	84520094
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	

Email Address

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD FADLY BIN SALIM
Approximate Age	
Injuries Sustain	BLEEDING ON NOSE & FOREHEAD
Injured person in which vehicle?	FU4346P
Were seat belts worn?	
Was injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Policyholder's Signature:

Date & Time:

- 1 NOV 2017



Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg


Reporting Centre Personnel's Signature:

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Report NO: T/20171031/2151

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: - 11 DV 2 11

[Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Individual Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171031/2151

1 of 3

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

Report No. T/20171031/2151

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/10/2017 19:13	Vide Report No.:	Station Diary No.: 24
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: SAID NASIR BIN SAID ABDULRAB TALIB		Address: APT BLK 717 BEDOK RESERVOIR ROAD #04-4544 SINGAPORE 470717	
ID Type / ID No.: NRIC NO / S0084444F		Contact No.: Home/Office: Mobile: 96778728	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 63	Date of Birth: 13/04/1954	Type of Informant: Driver
Race: Arab		Language: English	Institution / School Name:
Occupation: Retiree		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 31/10/2017 14:20	Type of Location: Straight Road
Location: Along Road 1 PAN-ISLAND EXPRESSWAY				
PAN-ISLAND EXPRESSWAY (PIE) towards Jurong, before Paya Lebar Exit.				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FU4348P	Motorcycle	YAMAHA	RXZ	Purple	Slightly Damaged	1
SJF824P	Car	HONDA	CIVIC 1.8L A	Silver	Seriously Damaged	2

Details of Vehicle Insurance					
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date	
SJF824P	NTUC Income Insurance Co-Operative Limited	5071189597-02	17/05/2017	16/05/2018	

Individual Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171031/2151

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

2 of 3

Report No. T/20171031/2151

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	Muhammad Fadly Bin Salim	ID No.	S8903054D
Related Vehicle	FU4348P (Motorcycle)	Contact No.	84520094
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	SAID NASIR BIN SAID ABDULRAB TALIB	ID No.	S0084444F
Related Vehicle	SJF824P (Car)	Contact No.	96778728
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 31st October 2017 at about 14:20hrs, while I was driving my car (SJF824P) along PIE towards Jurong before Paya Lebar Exit on the extreme right lane with my daughter as a front seat passenger, I noticed the traffic ahead was congested and hence, I applied gentle braking to slow down my vehicle.

Suddenly, I heard a loud sound at the rear of my car and later confirmed that a motorcyclist (FU4348P) had hit the rear of my vehicle. The rider fell onto the road and I immediately stopped my car. It was fortunate that the rider was not seriously injured, but I called the ambulance so that the medical officer can assess his injuries. The rider sustained some bleeding at his nose and forehead. He was then subsequently conveyed to the hospital.

The rear bumper of my car is badly damaged.

I wish to state that my daughter and I are not injured in the accident. That's all.

Individual Statement Pg. 1



SINGAPORE
POLICE FORCE



T/20171031/2151

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

3 of 3

Report No. T/20171031/2151

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 NUR 'ASRI BIN AGUS

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

31/10/2017 19:13

Officer In Charge Of Case:

TP / GIT /

Sgt 3 RASHIDAH BINTE AZMAN

Contact No.: 65476216

Classification Of Case:

Authentication Stamp

NP168

Signature



Username / Email Add

password



Connect

» Sign Up New Account

» Forgot Password

Honda Civic

Price Range

Depreciation

2008

Vehicle Type

Advanced
Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Honda Civic 1.8A VTI-S

Honda Civic 1.8A VTI-S

Honda Civic 1.8A VTI-S

Honda Civic 1.8A VTI-S



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

CAR DETAILS

Price	\$19,888	\$19,800	\$17,600	\$16,988
Instalment	\$2,355	\$2,344	\$1,791	\$2,408
Registration Date	15-May-2008	26-May-2008	06-Jun-2008	14-Apr-2008
Manufactured	2008	2008	2008	2008
Mileage	128,925 km	-	110,000 km	170,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,799 cc	1,799 cc	1,799 cc	1,799 cc
Road Tax	\$978 /yr	\$978 /yr	\$978 /yr	\$978 /yr
Power	-	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)
Curb Weight	0 kg	1,219 kg	0 kg	0 kg
Features	-	Responsive And Reliable 1.8L I-Vtec Engine Mated With Smooth Auto Transmission With Paddleshift, Multi Fuction Steering, ABS, Dual Airbags.	4-cylinder In-line 16-valve SOHC I-VTEC Engine, 5-speed Automatic Transmission, Airbags, ABS.	ABS, SRS Airbags.
Accessories	-	Leather, Original Built In Audio Player With 6 Disc Changer, Reverse Sensors, Solar Film, Fog Lamp, Sports Rims.	Sports Rims, Reverse Sensors, Leather Seats, CD Player,	Leather Seats, Rev And Back Video Re
Description	Suspension, Engine Mounting And Alternator Replace In Feb 2016. Overall Working Fine, Very Good For COE Renewal. Suitable For Short Term Usage As Well. SMS Only.	Well Maintained, Excellent Choice. Only \$1,980 Down Payment. Up To 90% Flexible Loan.We Provide Lowest Interest Rate In Town. Flexible Loan And High Trade In Are Available. Package With Unrivaed Warranty Complete With Certificate And Test Report. Check Out Our New Offer Now. Meet Our Friendly Consultant For An Non Obligation Advise.	2 Month Warranty (Engine And Auto Transmission), In Very Good Condition.	2 Careful Owners, PARF Rebate, Regi Agent, Price Negot Arrange A Test Driv
COE	\$16,898	\$19,001	\$17,113	\$19,001
OMV	\$20,467	\$21,092	\$21,092	\$22,417
ARF	\$20,467	\$21,092	\$21,092	\$22,417
Depreciation	\$18,260 /yr	\$16,560 /yr	\$11,980 /yr	-
No. of Owners	1	3	3	2
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	PARF Car, Direct Owner Sale	PARF Car	PARF Car, Direct Owner Sale	PARF Car, Direct O
Availability	Available	Available	Available	Available

SELLER INFORMATION

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	4444F

Vehicle Details

Vehicle No.	SJF824P
Vehicle to be Exported	No
Intended De-registration Date	01 Nov 2017
Vehicle Make	HONDA
Vehicle Model	CIVIC 1.8L A
Primary Colour	Silver
Manufacturing Year	2008
Engine No.	R18A13033738
Chassis No.	JHMF16308S215337
Maximum Power Output	103.0 kW (138 bhp)
Open Market Value	\$22,158.00
Original Registration Date	17 May 2008
First Registration Date	17 May 2008
Transfer Count	1
Actual ARF Paid	\$22,158.00

15/05/2008

\$ 7 7 5 6 . 0 0

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	16 May 2018
PARF Rebate Amount	\$11,079.00

Intended COE Rebate Details

COE Expiry Date	16 May 2018
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$19,501.00
COE Rebate Amount	\$1,053.00
Total Rebate Amount	\$12,132.00

The information contained herein is correct as at 01 Nov 2017

OK

26	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 127.80	\$ 127.80	-
27	REAR FLOOR PANEL <i>Distorted</i>	1	\$ 984.50	\$ 984.50	-
28	REAR FLOOR PANEL TOP BOARD <i>Deland</i>	1	\$ 316.00	\$ 316.00	-
29	REAR SPARE TYRE BOLT <i>new</i>	1	\$ 29.20	\$ 29.20	+
30	REAR TOOLS SPONGE TRAY <i>3M</i>	1	\$ 84.50	\$ 84.50	+
31	REAR EXHAUST PIPE <i>3M</i>	1	\$ 695.30	\$ 695.30	+

5247.10

415768

TOTAL PRICE	\$ 8,332.60
LESS 20%	\$ 1,666.52
SUB TOTAL PRICE	\$ 6,666.08

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	-
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
3	BOOTLID INSULATOR CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	BOOTLID NUMBER PLATE LAMP COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 20.00	\$ 20.00	10
5	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
6	REAR WINDSCREEN SEALANT <i>3M</i>	1	\$ 80.00	\$ 80.00	+
7	REAR WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	+
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	10
9	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
10	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	+
11	TRIANGLE BREAKDOWN SIGN <i>3M</i>	1	\$ 180.00	\$ 180.00	80
12	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	440

TOTAL \$ 1,320.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	1200.
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	800.
3	TUFF COAT	\$ 250.00	80
4	WIRING CHECK	\$ 180.00	30.
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 280.00	80.
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 250.00	x
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	x
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x

Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 01.11.2017

TO : **MSIG** MOTOR CLAIMS DEPTS

VEHICLE NO : **SJF824P**

MODEL : **HONDA CIVIC**

DATE OF ACCIDENT : 31.10.17

TIME OF ACCIDENT : 14:20HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 695.70	\$ 695.70
2	BOOTLID REFLECTOR <i>Crack</i>	2	\$ 199.80	\$ 399.60
3	BOOTLID INSULATOR <i>new</i>	1	\$ 187.60	\$ 187.60
4	BOOTLID NUMBER PLATE COVER GARNISH <i>Crack</i>	1	\$ 197.60	\$ 197.60
5	BOOTLID INNER STOPPER <i>new</i>	2	\$ 18.00	\$ 36.00
6	BOOTLID HINGE <i>new</i>	2	\$ 48.00	\$ 96.00
7	BOOTLID KEY LOCK <i>new</i>	1	\$ 214.30	\$ 214.30
8	BOOTLID TOP LOCK <i>new</i>	1	\$ 194.90	\$ 194.90
9	BOOTLID LOWER LOCK <i>new</i>	1	\$ 15.00	\$ 15.00
10	BOOTLID LOGO <i>?</i>	1	\$ 25.70	\$ 25.70
11	BOOTLID EMBLEM '1.8'	1	\$ 17.00	\$ 17.00
12	BOOTLID EMBLEM 'V-TECH'	1	\$ 37.10	\$ 37.10
13	BOOTLID EMBLEM 'CIVIC'	1	\$ 29.10	\$ 29.10
14	BOOTLID WEATHER STRIP <i>lot</i>	1	\$ 154.00	\$ 154.00
15	REAR FENDER LH <i>Repair</i>	1	\$ 976.40	\$ 976.40
16	REAR FENDER INNER TRIM <i>LH Behind</i>	2	\$ 249.90	\$ 499.80
17	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 155.60	\$ 155.60
18	REAR NUMBER PLATE LAMP <i>LH cracked</i>	2	\$ 54.30	\$ 108.60
19	REAR BUMPER <i>Distorted</i>	1	\$ 698.60	\$ 698.60
20	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 39.40	\$ 78.80
21	REAR BUMPER EXHAUST GARNISH <i>new</i>	1	\$ 38.90	\$ 38.90
22	TAILLAMP <i>lot</i>	2	\$ 299.60	\$ 599.20
23	TAILLAMP LOWER BRACKET <i>new</i>	2	\$ 29.10	\$ 58.20
24	TAILLAMP PANEL LH <i>Repair</i>	1	\$ 194.30	\$ 194.30
25	REAR END PANEL <i>Distorted</i>	1	\$ 387.30	\$ 387.30

249.90

54.30

10	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	X
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,280.00

2240

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,986.08
TOTAL LABOUR COST : \$ 5,280.00
TOTAL REPAIR COST : \$ 13,266.08

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian King
L/S 02/11/17.

08 Days.

total: 6877.68
L/S: S.S.K.

L/S S.S.K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17020939/ARBN2

Date: 06/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/16-978129
Claimant Vehicle No :	SJF824P	Insured Vehicle No :	FU4348P
Date of Loss:	31/10/2017	Nature of Claim:	TP
		Claim No:	MSCN/17-001694

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF824P	Engine No:	R18A13033738
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMF16308S215337
Reg. Date:	17/05/2008 (Man. Year: 2008)	Odometer:	221432 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,986.08	4,687.68	3,298.40	41.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,280.00	2,240.00	3,040.00	57.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,266.08	6,927.68	6,338.40	47.78
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	13,266.08	5,500.00	7,766.08	58.54
+ GST 7.00/7.00% (S\$)	928.63	385.00	543.63	58.54
Nett Amount (S\$)	14,194.71	5,885.00	8,309.71	58.54

INSPECTION

Date of Assignment: 02/11/2017

Date Inspected: 02/11/2017 Inspected At:

Dynamic Autowork Pte. Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2017)
Parts: 143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF824P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	695.70 FL	*695.70 FL
2	2		*BOOTLID REFLECTOR	Cracked	399.60 FL	*399.60 FL
3	1		*BOOTLID INSULATOR	Not Necessary	187.60 FL	*- FL
4	1		*BOOTLID NUMBER PLATE COVER GARNISH	Cracked	197.60 FL	*197.60 FL
5	2		*BOOTLID INNER STOPPER	Not Necessary	36.00 FL	*- FL
6	2		*BOOTLID HINGE	Not Necessary	96.00 FL	*- FL
7	1		*BOOTLID KEY LOCK	Not Necessary	214.30 FL	*- FL
8	1		*BOOTLID TOP LOCK	Damaged	194.90 FL	*194.90 FL
9	1		*BOOTLID LOWER LOCK	Not Necessary	15.00 FL	*- FL
10	1		*BOOTLID LOGO	Necessary	25.70 FL	*25.70 FL
11	1		*BOOTLID EMBLEM 1.8	Necessary	17.00 FL	*17.00 FL
12	1		*BOOTLID EMBLEM V-TECH	Necessary	37.10 FL	*37.10 FL
13	1		*BOOTLID EMBLEM CIVIC	Necessary	29.10 FL	*29.10 FL
14	1		*BOOTLID WEATHER STRIP	Cut	154.00 FL	*154.00 FL
15	1		*REAR FENDER LH	Repair	976.40 FL	*- FL
16	1		*REAR FENDER INNER TRIM	N/s Deformed	499.80 FL	*249.90 FL
17	1		*REAR WINDSCREEN MOULDING	Not Necessary	155.60 FL	*- FL
18	1		*REAR NUMBER PLATE LAMP	N/s Cracked	108.60 FL	*54.30 FL
19	1		*REAR BUMPER	Distorted	698.60 FL	*698.60 FL
20	2		*REAR BUMPER SIDE RETAINER	Necessary	78.80 FL	*78.80 FL
21	1		*REAR BUMPER EXHAUST GARNISH	Not Necessary	38.90 FL	*- FL
22	2		*TAILLAMP	Cut	599.20 FL	*599.20 FL
23	2		*TAILLAMP LOWER BRACKET	Not Necessary	58.20 FL	*- FL
24	1		*TAILLAMP PANEL LH	Repair	194.30 FL	*- FL
25	1		*REAR END PANEL	Distorted	387.30 FL	*387.30 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	127.80 FL	*127.80 FL
27	1		*REAR FLOOR PANEL	Distorted	984.50 FL	*984.50 FL
28	1		*REAR FLOOR PANEL TOP BOARD	Deformed	316.00 FL	*316.00 FL
29	1		*REAR SPARE TYRE BOLT	Not Necessary	29.20 FL	*- FL
30	1		*REAR TOOLS SPONGE TRAY	Not Necessary	84.50 FL	*- FL
31	1		*REAR EXHAUST PIPE	Not Necessary	695.30 FL	*- FL
32	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
33	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
34	1		*SET BOOTLID INSULATOR CLIP	Not	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Necessary		
35	1		*SET BOOTLID NUMBER PLATE LAMP COVER GARNISH CLIP	Necessary	20.00 FS	*10.00 FS
36	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
39	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
40	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
41	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
42	1		*TRIANGLE BREAKDOWN SIGN	Cracked	180.00 FS	*80.00 FS
43	1		*REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	9,652.60	5,737.10
				- List Item Discount on L Items 20.00/20.00% (\$\$)	1,666.52	1,049.42
				Total Parts (\$\$)	7,986.08	4,687.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,800.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	80.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	280.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REAR CHASSIS ALIGNMENT	New	250.00	-
8	TRANFER BOOTLID MECHANISM	New	80.00	-
9	CONDUCT WATER LEAKAGE TEST	New	80.00	-
10	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	-
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	-
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	-
Gross Labour Cost (S\$)			5,280.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >