

ASS. REC. BY:

REF:

C9/EG17020948/RLrb<sup>7</sup>

Special Instruction:

Supervisor:

Rasul

ASSIGNMENT (Office)

From (Person):

Siti

of

EGL

Date/Time:

01-11-2017 5:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGV 4205B

Insured:

GZ 27748

at Workshop m/s

Xinya Auto

Tel:

6273 3810

of

Blk 1002 Bukit Merah Lane 3 #01-75

Policy No:

Claim No:

DSMCM1702540/SE/SA

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21-10-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

08.11.2017 @ 1pm owner waiting

H.O.D. Endorsement:

Date/Time:

02.11.2017 1:06pm

Person Contacted:

Calvin

Vehicle IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SGV 4205B - CA / ALH 11000034/r
	GZ 27748 - x

DLA: 211210

STANDARD

REF: EGI

## ASSIGNMENT

COG XPIRY: 2022/Jan

From: \_\_\_\_\_ Date: 8/11/17

Estimated Cost: \_\_\_\_\_

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SGV 4205B

at Workshop m/s Xinya Auto

of Blk 1002 Blk Merah Lane 3#01-75

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

1pm @ owner waiting

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 1 up

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGV 4205B Yr Regn: 2007 Jan

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA AXO 1.5XA 1496

Colour: WHITE A/C Insured / Std / NI / NA

So Reading: 265090 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: N2E 1416034180

Gen. Cond: Good (P) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 24/10/17 D.O.I. 08/11/17

Survey held at XINYA AUTO

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

o/s Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/11/17 email to SIK - pending est from wksp.

15/8/2.34pm Confirmed LE \$1250/- with May. (Red. 1660.30, 57%)

RECEIVED 16 AUG 2018 pass back to handle

RECEIVED 06 SEP 2018 review file from handle

Date/Time: File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 1

Survey Fee

Transportation

) 3 - 25 5)

Phone

Other

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

250

Report Format: TP

Lump Sum / I.B.I: \$1250/-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17020948/R1gb

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 02-11-2017



Code : EGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 2774S	Veh. Inspected	SGV 4205B
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1702540/SE/sa	Excess (\$)	0.00
Assign From	SITI	Assign Date	01/11/2017

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	21/10/2017	Inspection Date
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719	

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Celine Fong (LKKAUTO)

---

**From:** Xinya Auto Services <xinyaauto@singnet.com.sg>  
**Sent:** Wednesday, 15 August 2018 2:34 PM  
**To:** Celine Fong (LKKAUTO)  
**Subject:** RE: VEHICLE NO. SGV 4205B DOA: 21.10.2017

Hi Ms Fong

Agreeable pls proceed to raise report.

Thk you

Regds.  
May

---

**From:** Celine Fong (LKKAUTO) [mailto:celinefong@lkkauto.com]  
**Sent:** Wednesday, August 8, 2018 12:30 PM  
**To:** xinyaauto@singnet.com.sg  
**Subject:** VEHICLE NO. SGV 4205B DOA: 21.10.2017

Dear May/Kelvin,

Can we confirm the repair cost LS \$1,250.00 and 4 days.

Best Regards,

**Celine Fong**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [celinefong@lkkauto.com](mailto:celinefong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Virus-free. [www.avg.com](http://www.avg.com)

# Survey Department Check List (Case Handler)

Reference No. : CS/EG117020948/Rib

Policy Type: OD / TP / RES / TL / EVA

Case Handler

Typist

**Admin** ( Catherine ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor** ( Rasul ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

Catherine  
Case Handler

Date

\*C: Critical \*N: Non-Critical

21/05/2014

## Ai Phing (LKKAuto)

---

**From:** Ai Phing (LKKAuto)  
**Sent:** Friday, 10 November, 2017 3:13 PM  
**To:** Survey Report (ERGO Insurance Pte. Ltd.)  
**Cc:** SUR  
**Subject:** RE: GZ 2774S | TP: SGV 4205B | DOA: 21.10.2017 - PRS | OUR REF:DSMCV1702540/SE/sa

Dear Siti,

Please be informed that we have inspected the vehicle SGV 4205B on 8-11-2017.  
We are pending estimate from repairer.

Best Regards,

**Ai Phing** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 2 November, 2017 1:07 PM  
**To:** 'Siti A Thikah AB Rahman' <[siti.rahman@ergo.com.sg](mailto:siti.rahman@ergo.com.sg)>  
**Cc:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: GZ 2774S | TP: SGV 4205B | DOA: 21.10.2017 - PRS | OUR REF:DSMCV1702540/SE/sa

Dear Siti,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Siti A Thikah AB Rahman [<mailto:siti.rahman@ergo.com.sg>]  
**Sent:** Wednesday, 1 November, 2017 5:17 PM  
**To:** Catherine Chong (LKK Auto) ([admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** Survey Report (ERGO Insurance Pte. Ltd.) <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>  
**Subject:** GZ 2774S | TP: SGV 4205B | DOA: 21.10.2017 - PRS | OUR REF:DSMCV1702540/SE/sa

Catherine,

## Catherine Chong (LKK Auto)

---

**From:** Siti A Thikah AB Rahman <siti.rahman@ergo.com.sg>  
**Sent:** Wednesday, 1 November, 2017 5:17 PM  
**To:** Catherine Chong (LKK Auto) (admin-d@lkkauto.com)  
**Cc:** Survey Report (ERGO Insurance Pte. Ltd.)  
**Subject:** GZ 2774S | TP: SGV 4205B | DOA: 21.10.2017 - PRS | OUR REF:DSMCV1702540/SE/sa  
**Attachments:** PRS FORM.pdf; 01112017155640-0001.pdf; GZ2774S - report for surveyor.pdf; SGV4205B - report for surveyor.pdf

Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK Auto Consultants Pte Ltd** to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and to try finalise with the repairer on the repairs.  
(Note: No repair estimate was provided to us)

Please fill up the necessary on ERGO PRS Form and return to us together on your update of the survey status.

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

**NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.**

Thank you.

Warmest regards

**Siti A'thikah**

Claims Department  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9170  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

---

**From:** Xinya Auto Services [mailto:xinyaauto@singnet.com.sg]  
**Sent:** Wednesday, 1 November, 2017 4:22 PM  
**To:** Siti A Thikah AB Rahman  
**Subject:** RE: GZ 2774S | TP: SGV 4205B | DOA: 21.10.2017 - PRS | OUR REF:DSMCV1702540/SE/sa

Hi, Siti

Kindly arrange LKK to inspect the vehicle.

Thank you  
Regards

**From:** Siti A Thikah AB Rahman [<mailto:siti.rahman@ergo.com.sg>]

**Sent:** Wednesday, November 1, 2017 4:11 PM

**To:** [xinyaaauto@singnet.com.sg](mailto:xinyaaauto@singnet.com.sg)

**Subject:** OI: GZ 2774S | TP: SGV 4205B | DOA: 21.10.2017 - PRS | OUR REF:DSMCV1702540/SE/sa

WITHOUT PREJUDICE

Dear Sir,

We refer to your email below.

Attached our template for your input.

Kindly let us have your reply.

Thank you.

Warmest regards

**Siti A'thikah**

Claims Department

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

Tel.: 65 6829 9170

Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

**EMAIL DISCLAIMER**

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Virus-free. [www.avg.com](http://www.avg.com)



# ERGO

Date: 01.11.2017  
Our Reference: DSMCV1702540/SE  
Your Reference: SGV4205B

Sent via Fax

or

Email

xinyaauto@singnet.com.sg

To: XINYA AUTO SERVICES PTE LTD

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SGV 4205B  
Insured's Vehicle: SGZ 2774S  
Date Of Accident: 21.10.2017


We acknowledge receipt of your request for PRS on: 01.11.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us today.
<input type="checkbox"/>	Others: _____

Prepared by:		Siti	6829 9170	<u>claims@ergo.com.sg</u>
Signature:				<b>FAX : 6829 9247</b>

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

## Enquire Transfer Fee

### Vehicle Details

Vehicle No.	SGV4205B
Vehicle Type	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	TOYOTA
Vehicle Model	COROLLA AXIO 1.5X A
Chassis No.	NZE1416034180
Propellant	Petrol
Engine No.	1NZC603798
Engine Capacity	1496 cc
Maximum Power Output	81.0 kW ( 108 bhp )
Maximum Laden Weight	1405 kg
Unladen Weight	1130 kg
Year Of Manufacture	2007
Original Registration Date	14 Jun 2007
Lifespan Expiry Date	-
COE Category	A - Car (1600cc & below)
PQP Paid	\$25,313.00
COE Expiry Date	13 Jun 2022
Road Tax Expiry Date	13 Dec 2017
Inspection Due Date	13 Jun 2018
Intended Transfer Date	10 Nov 2017
CO2 Emission	-

The current road tax expiry is 13 Dec 2017. You may renew the road tax from 14 Sep 2017 with all pre-requisite(s) fulfilled. If the road tax is renewed after 13 Dec 2017, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

### Amount Payable (From 14 Dec 2017 to 13 Jun 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00
<b>Sub Total</b>			<b>11.00</b>

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	2030X
<b>Vehicle Details</b>	
Vehicle No.:	SGV4205B
Vehicle to be Exported:	No
Intended De-registration Date:	08 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	1NZC603798
Chassis No.:	NZE1416034180
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,574.00
Original Registration Date:	14 Jun 2007
First Registration Date:	14 Jun 2007
Transfer Count:	1
Actual ARF Paid:	\$12,732.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Jun 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,313.00
COE Rebate Amount:	\$19,476.00
<b>Total Rebate Amount:</b>	<b>\$19,476.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Aug 2018

OK

Address : SMOOTH DRIVE  
BLK 681A JURONG WEST CENTRAL 1  
# 14-96  
SINGAPORE 641681

Reference : TP 1134/10/17  
Vehicle No : SGV4205B  
Make/Model : TOYOTA AXIO  
Insurance Co. : NTUC

RE : QUOTATION REPAIRS TO SGV 4205BT FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>
1) FRONT BUMPER	1	\$ 425.80 <i>Scr</i>
2) FRONT BUMPER RETAINER	1	\$ 53.60 <i>Me</i>
3) FENDER	1	\$ 475.00 <i>BT</i>
4) HEADLAMP RH	1	\$ 646.00 <i>X SVC</i>
LIST PRICE TOTAL		\$ 1,600.40 <i>957.40</i>
LESS DISCOUNT 25%		\$ 400.10 <i>25%</i>
LIST PRICE TOTAL AFTER LESS		\$ 1,200.30 <i>715.80</i>
NETT PRICE TOTAL		\$0.00

TOTAL PARTS COST

**\$1,200.30**

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP AND TO PANEL BEAT & ADJUST.	\$ 800.00 <i>400</i> (4 days)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER, FENDER AND PART OF BONNET.	\$ 600.00 <i>400</i> (3 PANEL) <i>840</i>
3)	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP	\$ 80.00 <i>X</i>
4)	TUFF KOTE	\$ 230.00 <i>40</i>
LABOUR TOTAL		<b>\$ 1,710.00</b>

TOTAL ESTIMATED REPAIR COST

**\$ 2,910.30**

*715.80*  
*840.00*  
*1555.80*

*20%*  
*1244.64*

*45-1,250*

*Pass*

*Hp 90010068*

*4 days*

*4/3*

*08/11/2017 @ 1310*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref.: CS/EGI17020948/R1rbn2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date: 06-09-2018		
		Code: EGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GZ 2774S	Veh. Inspected	SGV 4205B	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMCV1702540/SE/sa	Excess (\$)	0.00	
Assign From	SITI	Assign Date	01/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COROLLA AXIO 1.5XA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	NZE1416034180	Colour	WHITE	
Odometer	265090	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MICHELIN	5 mm	
L/H Front Tyre	195/60 R15	MICHELIN	5 mm	
R/H Rear Tyre	195/60 R15	MICHELIN	5 mm	
L/H Rear Tyre	195/60 R15	MICHELIN	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/10/2017	Inspection Date	08/11/2017	
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 4205B**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	SCRATCHED	425.80	425.80
1	FRONT BUMPER RETAINER	NECESSARY	53.60	53.60
1	FENDER	BENT	475.00	475.00
1	HEADLAMP RH	SERVICEABLE	646.00	-
	LESS 25% DISCOUNT		-400.10	-238.60
			1,200.30	715.80
	<b><u>LABOUR</u></b>			
	TO REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP AND TO PANEL BEAT & ADJUST.		800.00	400.00
	TO PUTTY & SPRAY PAINT FRONT BUMPER, FENDER AND PART OF BONNET.		600.00	400.00
	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.	NOT NECESSARY	80.00	-
	TUFF KOTE.		230.00	40.00
			1,710.00	840.00
	<b>GRAND TOTAL</b>		<b>2,910.30</b>	<b>1,555.80</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,250.00</b>

Report Ref No. CS/EGI17020948/R1rbn2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING****B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.