				- 24		
ASS. REC. BY:		REF: CS/MSG 1702	.0964 Albr	)2_ Special is	nstruction:	· ·
Surveyor :	Rosul	ASSIGNM	ENT (Office)			
MUML() From (Person):	Ikhu Tan	of	msuh	Date	Time: 12.11.17	1-43pm
Estimated Cost:			Bill to:			
O		ES / EVA / INV / MV /	CS		CIC has	20
To Inspect Vehi	cle No:	SCP ZUL			SJG 4537	<u> </u>
at Workshop m	/s	ferfumano.		Tel:	6319 0174	
of		303 Alexandra	RU			
	80435	195amx	Claim No:			
Sum Insured:			Excess: _			
Make of Veh:				D.0	FIDE-11-10 A.C	
(Client's Record)		1	F104-11-80			
CA / REV /	REP. / REV 24	HRS WP	70 11 20	F	I.O.D. Endorsement:	
Date/Time:	D2.11.2017 1.50	Person Contacted	(con)in	Vehi	cle IN/OUT	
-						
Date/Time	Action/Instruction	on ( V ) Estimat	te Han			
	SCP24L	->	Managaran			
	81G 4530 0	-NA/TMI/30052	24/02-D.C	0-A:18/0	3/2013	
	19973320	-NH 11/11/15/00/02	-11/29			
6 <del>1</del>	re I mel IL			-10/00/07/19:51		
	Sent preli th	n menmen				
1	1					

			and the same of	
1. 2	3 7 10 7	10.7	1 1 1	S 1
2433	153:	4	13.44	7 1
4 18 14 70	-		Complete Andrews	

From: Date 8/11/2017	Veh No: SCP 24L YARega 2010 MAL
Estimated Cost.	Type M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SCP 24 L	Make: B.M.W 3182 2.0A as 1995
at Workshop m/s Performance	Colour GREY A/O Insured / Std / NI / NA
303 Alexandra Road	Sp Reading /380(o T.Radio: Insured / Std / NI / NA
Insured	Eng/No:
Policy No.	CINO: WB4PF72070A793596
Claims No.	Gen. Cond: Good (Fa) / Poor / Burnt
Sum Insured: Excess	Steering: Prorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder/ Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil SRPn / STD A/Rim or
	Tyre Size: F: 235/35 R19
(Policy Condition)	R: 4 (
Remark: The veh had commenced its N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Ball or Market Value:	Eront Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm
Est. Repairs: days Res: Yes or No	D.O.A 61/11/17
Lum Sum: % 3 Val.: Yes or No	Survey held at PERFORMANCE
CA / REV / REP. / 24 HRS WP	Des. of Damages : Frt   O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT  Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The Old / Chassis Halle / Body Structure and the same
Confirm \$ 3863.95, 3 days	
•	
RECEIVED 0 % FE3 2018	
Date/Time: File Pass to? : Preli. Report	Days Of Repair: 3
Data/Time File Return to?	Resurvey No. of Trip: — Survey Fee.
2 Add Fe	e: Site Insp (\$ 1-55_5 200
281	Interview (\$ 1 Facial
Report Format:	Tech invs (\$ ten
Lump-Sum / I.B.I: (\$ 386395	Westend (\$
	210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

red Veh. by No. m No. gn From e & Model ine No. ssis No.	SJG 4532A 80435195QMX MERIMEN (IRENE TAN)	Ref: CS/MSG1702  Date: 02-11-2017  Code: MSG  :- THIRD PARTY CLA  Veh. Inspected  Coverage (\$)  Excess (\$)  Assign Date  culars & Condition  c.c			
red Veh. cy No. m No. gn From e & Model ine No. ssis No.	Policy Particulars SJG 4532A 80435195QMX  MERIMEN (IRENE TAN)  Vehicle Particulars	Code: MSG :- THIRD PARTY CLA Veh. Inspected Coverage (\$) Excess (\$) Assign Date culars & Condition c.c	SCP 24L 0.00 0.00 02/11/2017		
gn From e & Model ine No. ssis No.	SJG 4532A 80435195QMX MERIMEN (IRENE TAN) Vehicle Partic	Veh. Inspected Coverage (\$) Excess (\$) Assign Date culars & Condition c.c	SCP 24L 0.00 0.00 02/11/2017		
gn From e & Model ine No. ssis No.	MERIMEN (IRENE TAN)  Vehicle Partic	Coverage (\$) Excess (\$) Assign Date culars & Condition c.c	0.00 0.00 02/11/2017		
m No. gn From e & Model ine No. sssis No.	MERIMEN (IRENE TAN)  Vehicle Partic	Excess (\$) Assign Date culars & Condition c.c	0.00		
gn From e & Model ine No. ssis No.	Vehicle Partie	Assign Date culars & Condition c.c	02/11/2017		
e & Model ine No. ssis No.	Vehicle Partie	culars & Condition			
ne No. ssis No.		c.c	0		
ne No. ssis No.	HIDDEN		0		
ssis No.	HIDDEN				
		Year of Reg.			
Locrosc a merce		Colour			
meter		Steering			
es		Modification			
eral					
	Conditi	ions of Tyres	the content of the same of the		
	Size	Make	Balance		
Front Tyre			mm		
Front Tyre			mm		
Rear Tyre			mm		
Rear Tyre			mm		
TOTAL THOM	Descripti	on of Damages			
	Genera	I Information			
ident Date	01/11/2017	Inspection Date			
ey held at	PERFORMANCE MOTORS LTI	D			
The second secon	303 ALEXANDRA ROAD SINGAPORE 159941				
	R	emarks			
_	ey held at	dent Date 01/11/2017  ey held at PERFORMANCE MOTORS LTI 303 ALEXANDRA ROAD SINGAPORE 159941  R E INSPECTION WAS CONDUCTED ON A"WI	ey held at PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD		

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte, Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date:

08 Feb 2018

## Preliminary Advice

Insured Vehicle No : SJG4532A

: SCP24L

Accident Date

: 01/11/2017

TP Vehicle No

Assignment Date

: 02/11/2017

Make

: BMW 318I

Date of Inspection

: 08/11/2017

Est. Duration of Repair

: 3.00

Inspection At

: PERFORMANCE MOTORS LIMITED (ALEXANDRA)

303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE

SINGAPORE 159941

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,066.45
Revised Amount	:S\$	3,863.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,863.95

Lump Sum Repair

:S\$

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

- The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rut	Adj Sulamitte	d Ins Aut	n'ed	Status		
Main	01 Nov 2017		02 Nov 2017 13:43 Assign					New Ass Cancel C	ignment ase	
	Main	Refere	nce	Claim Det	ails	Docume	ents	] [	Show All	
CLAIM S	JBFOLDER DETA	ILS				[Cre	ated by in	surer]		
Insured:		MUHD HAMZ	AH BIN MALIK	, ID: S8025781	C					
Main Clain	nant:	LIM WEE CH	EE, ID: S7146	779A		48				
Vehicle Re	g. No.:	SCP24L		Date of	Loss:	01/11	/2017 11:0	00 - :59	59	
Claim Type	2:	TP		Policy/0	over Note No.:		80435195QMX (Comprehensive) Coverage: 30/06/2017 - 29/06/201			
Vehicle Re	g. No. (Insured):	SJG4532A		Policy N	o. (Claimant):					
				Excess						
Repairer:			Motors Limite el: 63190172/63	<b>d (Alexandra)</b> 190174	03 Alexandra R	oad, Sime Dari	by Perform	ance Centr	e, 159941	
Handling I	nsurer:	MSIG Insura 6594 2541]	nce (Singapore	e) Pte. Ltd. (HQ	) - Tel: +65 682	7 7888 [Ha	ndled by I	rene Tan	Gek Ing -	
Adjuster:		LKK Auto Co	nsultants Pte L	td (HQ) - Tel: 6	256-3561 [ <b>I</b> t	nm.Advice	due 03/1	1/2017]		
ASSOCIA	TED MAIL RECE	IVED					View All	Compose	Case Mail	
There are	no mail for this cas	se.								
ALL ASS	OCIATED TASKS	8			View All	Search Tasks	Create N	New Task	Complete	
Due Dat	e Priority Ty	ype Task Gro	up Subject	Handler A	ssigned By	Completed	F) F-	eated On	Done	

### Celine Fong (LKKAuto)

From:

- 45.

PBSP <pml-pbsp@simedarby.com.sg>

Sent:

Friday, 22 December 2017 10:55 AM

To:

Rasul (LKKAuto); SUR

Subject:

FINAL REPORT / SCP24L

Attachments:

Final Report SCP24L.pdf

Dear Rasul

We refer to the above and attached Final Report.

#### Please confirm COR as follows:

Total Labour :	2,567.00
Total Parts :	1,296.95
Total Labour & Parts :	3,863.95

#### Thank you.

Regards, Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- Any false reporting may be referred to the Police for investigation.
   This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.

#### **ACCIDENT STATEMENT**

01/11/2017 14:28 Date Of Report 01/11/2017 11:50 Date Of Accident

ALG UPP CHANGI RD TOWARDS EXPO BEF TURNING PIE Exact Location Of Accident

SINGAPORE Country/State of Loss

#### DETAILS OF OWN VEHICLE

SCP24L Vehicle Registration Number

Insured/Policyholder

LIM WEE CHEE Name Of Registered Owner S7146779A NRIC No

WEECHEELIM@GMAIL.COM Email Address

(LOCAL) +65-96199991 Mobile Phone No OFFICE-96199991 Alternative Phone No

Vehicle Particulars

BMW Manufacturer 3181 Model

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

THIRD PARTY If No, Please state action to be taken PRIVATE CAR Vehicle Category

Insurance Company

AVIVA LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

Fleet Policy NO 10572997 Policy Number N.A

Cover Note Number

Driver

LIM WEE CHEE Name of Driver S7146779A NRIC No 24/12/1971 Date Of Birth INDOOR Occupation 11/10/1989 Date Of Driving Pass

28 YEARS AND 0 MONTHS Driving Experience

MALE Gender

(LOCAL) +65-96199991 Mobile Number

Fax Number

OFFICE-96199991 Contact Number

WEECHEELIM@GMAIL.COM **EMail Address** 

Address

Postcode

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

4

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG UPPER CHANGI ROAD BEFORE TURNING TO PIE (TUAS). THE TRAFFIC WAS STOP AND GO THEN SUDDENLY THIRD PARTY COLLIDED ONTO THE REAR OF MY VEHICLE, ONLY TWO VEHICLES WERE INVOLVED WITHOUT ANY INJURIES.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJG4532A

Vehicle Make/Model/Colour

MITSUBISHI LANCER 1.5 / RED

Details Of Properties

Name of Driver

MUHAMMAD HAMZAH B MALIK

NRIC/Passport Number

S8025781C

Contact Number

Address

Postcode

MSIG.

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


40

Details of Witness

Name

Phone Number

Email Address



#### Common Statement Pg. 1

TUAS). THE TRAFFIC WAS STOP AN COLLIDED ONTO THE REAR OF MY	CHANGI ROAD BEFORE TURNING TO PIE ID GO THEN SUDDENLY THIRD PARTY VEHICLE. ONLY TWO VEHICLES WERE
NVOLVED WITHOUT ANY INJURIES.	
Taxi Voucher No.:	
ECLABATION	
	nded above are true in every aspect
We declare that the above particulars & information prov	rided above are true in every aspect
We declare that the above particulars & information prov	rided above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER -	nded above are true in every aspect
We declare that the above particulars & information prov VERIFIED BY AJAX MARS REPORTING OFFICER -	inded above are true in every aspect
Ne declare that the above particulars & information prov	nded above are true in every aspect
We declare that the above particulars & information prov	Registered Owner or Driver's Signature

Wed OFfII a Islam 8 & R

SCP 24L

BMW Dealer"

# Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401558W GST Reg. No M2-0020881-X

Sime Darby Performance Centre Singapore 159941

Tel. 83190100 (Sales a Admin) 63190111 (AfterBales) FMX. 64747770

280, Hampong Arang Road Bast Coast Centre Singapore 438185 Tel. 63190888 (AfterSales) Fax. 63445773

315, Alexandra Road Sime Darby Business Centre Singapore 159544 Tel 63190528 (AfterSales) 63190533/530 (Motocrad) Fax. 64796601 (AfterSales) 6496624 (Motocrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

0 2 NOV 2017

(50) 177.00

80.00

Page No. : 1 of 2 Estimate No. 44685 : b1 : 02/11/2017 Date Estimated Prepared By : Han Kwan Yong - ACCOUNT -40000 - ESTIMATE REPAIR FOR -Cash Sales - Service Lim Wee Chee (Lin Weizhi)

Singapore

#03-505 Singapore 530838

838 Hougang Central

MILEAGE REGN. NO. REGN. DATE MODEL CHASSIS NO. 0 SCP24L A793596 30/03/2010 318i/4(A)

VALUE DESCRIPTION 850 1,275.00 To replace rear bumper & attac hments including to knock out dented area caused by the accident 1337 1,486.00 To respray rear bumper and rear bumper lower apron cover 150 177.00 To remove old PDC assembly, replace damaged parts and

reconnect to new bumper including conduct checks for proper function.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

Total Labour 1: 3,195.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING NUT	4	0.60	C 2 2.40
# REAR BUMPER SET MOUNTING PAR	1	33.15	33.15
RR BUMPER CARRIER	1	413.90	15-C) \$ 413.90
RR BUMPER CTR GUIDE	1	30.85	7 30.85
RR BUMPER CTR BOTTOM GUIDE	. 1	61.20	61.20
RR BUMPER INSERT (M)	1	154.60	154.60
RR BUMPER COVER (M)	1	79.70	79.70
# RR BUMPER TOW HOOK COVER (M)	1	19.70	x s/c/ 7 19.70
# RR BUMPER (M)	1	1,217.25	DE - 1,217.25
UNDERFLOOR COATING ACTIV.CHARCOAL	1	69.65	69.65
DECOUPLING RING PDC TORQUE CONVERTE	2	4.95	ورا ) ع 9.90
PDC sensor	2	363.05	726.10
(DG) ADHESIVE SET K6	1	53.05	53.05
	Tot	tal Parts	: 2,871.45

BMW Dealer

## Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-5030081-X

\* 303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438280

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190537/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

#### ESTIMATE

Estimate No. Date Estimated

44685 : b1

: 02/11/2017

CHASSIS NO.

Prepared By

: Han Kwan Yong

MODEL

MILEAGE

SCP24L

REGN. NO.

A793596

REGN. DATE 30/03/2010

N 5.8 6

318i/4(A)

0

Page No. : 2 of 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured	losses / Dire	ct Settlement
Regn No.	Claim No.	
Dato&Time 08 11 17 @1145	Excess S\$	
Data&Time DE (1   17 @ 1145 Surveyor's Name RASML		
Surveyor's Tel goowolf	Authorised	Yes / No
Authorised Date	Time	
RESURVEY PARTS PHOTO BY SURVE		
Surveyor's E-mail		
No. of Working Days Recommend	days	

6066.45

Labour 1	:	3,195.00
Parts	:	2,871.45
Labour 2	:	0.00
Excess		0.00
Total GST @ 7%		424.65
Grand Total	: -	6,491.10

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# **Performance Motors Limited**

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



#### FINAL REPORT

Estimate No.

b1 44685

Date Estimated

02/11/2017

Prepared By

Han Kwan Yong

REPAIR FOR -

- ACCOUNT -

66

Page No. :

Lim Wee Chee (Lin Weizhi)

.

MSIG Insurance (S) Pte Ltd

838 Hougang Central

4 Shenton Way

#03-505

#21-01 SGX Centre 2 Singapore 068807

Singapore 530838

M LEAGE MODEL REGN. DATE CHASSIS NO. REGN NO. n 318i/4(A) 30/03/2010 A793596 SCP24L NETT DISC. % ORIGINAL PRICE DESCRIPTION 850.00 To replace rear bumper and attachments include knocking 850.00 out dented areas caused by the accident 1,337.00 1337.00 To respray rear bumper and lower apron cover 150.00 150.00 To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function. 150.00 150.00 To check electrical wiring systems and lightings at the rear section for proper function. 80.00 80.00 Sundries. DISC. % NETT QTY UNIT PRICE DESCRIPTION 79.70 1.00 79.70 RR BUMPER COVER (M) 1,217.25 1.00 1,217.25 RR BUMPER (M) # SUPPLEMENTARY ITEMS 2.567.00 Total Labour: 1,296.95 Total Parts: 3,863.95 Total Labour & Parts: Deduction for Excess: 3,863.95 Total Repair Costs less Excess: 270.48 GST @7%: 4,134.43 Grand Total:

#### LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG17020964/R1RBN2

Date:

09/02/2018

REFERENCE

Vehicle No:

Handling

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A80435195QMX

Insurer: Claimant

SCP24L

Insured Vehicle No: SJG4532A

Date of Loss:

01/11/2017

Nature of Claim:

TP

Claim No: 535256

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SCP24L

Make & Model:

BMW 318I, 2.0 L (A) 30/03/2010 (Man. Year: 2009) Engine No: Chassis No: Odometer:

B339I623N46B20BZ WBAPF72070A793596

138010 km

Req. Date: Colour:

Grey

**Engine Capacity:** Market Value/New Car Price: 1995 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

235/35R19

Rear Tyre Size: Rear Left Side:

235/35R19 Pirelli 6 mm

Front Right Side:

Pirelli 6 mm Pirelli 6 mm Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 2,951.45	Adjuster's 1,376.95	Difference 1,574.50	Diff % 53.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,115.00	2,487.00	628.00	20.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,066.45	3,863.95	2,202.50	36.31
+ GST 7.00/7.00% (S\$)	424.65	270.48	154.17	36.31
Nett Amount (S\$)	6.491.10	4,134.43	2,356.67	36.31

INSPECTION

Date of Assignment:

02/11/2017

Nett Amount (S\$)

Date Inspected:

08/11/2017 Inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 09 Feb 2018)

Parts:

143

BMW 318I 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCP24L)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

#### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*EXPANDING NUT	Serviceable	2.40 FS	*- FS
2	1		*REAR BUMPER SET MOUNTING PAR	Serviceable	33.15 FS	*-FS
3	1		*RR BUMPER CARRIER	Serviceable	413.90 FS	*-FS
4	1		*RR BUMPER CTR GUIDE	Serviceable	30.85 FS	*-FS
5	1		*RR BUMPER CTR BOTTOM GUIDE	Serviceable	61.20 FS	*-FS
6	1		*RR BUMPER INSERT (M)	Serviceable	154.60 FS	*-FS
7	1		*RR BUMPER COVER (M)	Deformed	79.70 FS	*79.70 FS
8	1		*RR BUMPER TOW HOOK COVER (M)	Serviceable	19.70 FS	*-FS
9	1		*RR BUMPER (M)	Deformed	1,217.25 FS	*1,217.25 FS
10	1		*UNDERFLOOR COATING ACTIV CHARCOAL	Serviceable	69.65 FS	*-FS
11	2		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	9.90 FS	*-FS
12	2		*PDC SENSOR	Serviceable	726.10 FS	*-FS
13	1		*(DG) ADHESIVE SET K6	Serviceable	53.05 FS	*-FS
14	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
F=Fr	anchise	part. S=Spcl	Nett.			
				Total Parts (S\$)	2,951.45	1,376.95

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER AND REAR BUMPER LOWER APRON COVER	New	1,486.00	1,337.00
3	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
	Gross Labou	3,115.00	2,487.00	
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >