

ASS. REC BY

REF CS/FCI17020979/Ktbnz

Customer

Kenneth

ASSIGNMENT (Office)

CWS

Name (Person)

Sithara

FCI

Date/Time 3.24pm @ 2/11/17

Estimated Cost

RM

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No

SJM 82015

Insured

SHC 0763X

at Workshop m/s

Motor Image

Tel

90903323

of 19 Lurong 8 Toa Payoh

Policy No

Claim No

D17010220MFSH

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

31/10/17

CA / REV / REP. / REV 24 HRS

wpi

27.11.2017 @ after 10am

H.O.D. Endorsement

Date/Time

3.30pm @ 2.21pm

Person Contacted

Fazli

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJM 82015 - X

SHC 0763X - X

Part By Part \$1152 (Red: 1202.24; 51%)

REF: FCI

ASSIGNMENT

From _____ Date: 27/11/2017

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJN82015

at Workshop mis Motor Image
of 19 Toyota 8 Ton pyoh

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 10 am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAO Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP: / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SJN 82015 Regn: 09 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lhan A Forster Wagon 1995

Colour:

M.P. White A/D Insured / Std / NI / NA

So. Reading:

4886 T/Radio Insured / Std / NI / NA

Eng No:

C.No:

JF1SJSK C3JG 099288

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SiRim / STD / R/Rim or

Tyre Size:

F:

R:

225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

9 mm

R/Bal:

9 mm

L/Bal:

9 mm

L/Bal:

9 mm

D.O.A:

31/10/17

D.O.A:

27/11/17

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/11 File pass to Customer

RECEIVED 06 FEB 2018

Date/Time File Pass to:

6/2 Typist

Date/Time File Return to:



Preli. Report



Final Report

Days Of Repair: 2

Resurvey No. of Trip: -

Survey Fee

Transporter

Fuel & PG

Food

Other

Add Fee:



Site Insp / \$



Inter. exp / \$



Tech. Insp / \$



Wash and / \$

Report Format:

Lump Sum / (E) 3

TP

1152

110
50

11

111



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17020979/Ktb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 0763X	Veh. Inspected	SJN 8201S
Policy No.		Coverage (\$)	0.00
Claim No.	D17010220MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	02/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/10/2017	Inspection Date
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	01-11-2017	Our Ref No. D17010220MFSH
Accident Date	31-10-2017	Claim Type. Third Party
Insured Vehicle	SHC0763X	Third Party Vehicle. SJN8201S
Survey Location	19 LORONG 8 TOA PAYOH	
Contact Person.	MOHAMAD FAZLI BIN BACHOK	
Contact No.	67038101/ 90903323	Fax No. 62535535
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MOTOR IMAGE ENTERPRISES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229741)



PRI Documents



Close



PRI Header Details

Claim No	D17010220MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & MOTOR IM
Workshop Name	MOTOR IMAGE ENTERPRISES PTE LTD (Contact Person : MOHAMAD FAZLI BIN BACHOK)	Survey Location & Contact Details	19 LORONG 8 TOA PAYOH Mobile: 90903323 , Phone: 67038101 , Fax: 6253553! EmailId: FAZLIBACHOK@MOTORIMAGE.NET		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM 1		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0763X	TP Vehicle No	SJN8201S
PRI Recieved Date	01-11-2017 09:18:16 PM	Surveyor Appointed Date	02-11-2017 03:23:33 PM	Surveyor Accept Date	02-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	02-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0462/2017
DATE : 31-OCT-2017

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : ONG SU KIT
ADDRESS : APT BLK 605 JURONG WEST STREET 62
#12-221
S(640605)
TELEPHONE NO : 9680 2552

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700058869
VEHICLE NO : SJN8201S
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YB23220
CHASSIS NO : JF1SJ5KCSJG099288
MILEAGE : 1 KM
DATE IN : 31/10/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MOHAMAD FAZLI BIN BACHOK**
ACCIDENT DATE : 31/10/2017

Print Date : 01/11/2017
Print Time : 12:31:59

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 19255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJNB201S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SHC763X (FIRST CAPITAL)		
2	ZZ/001	ACCIDENT DATE:31/10/2017 TIME:0700HRS LOCATION:JUNCTION JURONG WEST AVE 4 & PIONEER RD		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER & REAR BUMPER BEAM	1120.00	280x
4	ZZ/003	RESPRAY REAR BUMPER	420.00	✓
5	ZZ/004	SUNDRIES	nee 100.00	20x
TOTAL LABOUR CHARGES			1640.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN82018

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
1	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	✓	
2	BRKT CORNER R RH	57707SG060	18.00	X	
3	BRKT CORNER R LH	57707SG070	18.00	X	
4	BRKT SD R RH	(1) 57707SG080	14.40	X	
5	BRKT SD R LH	57707SG090	14.40	X	
6	BEAM COMPL R EU	57711SG0219P	288.00	X	
SUB TOTAL			892.80	0.00	0.00
LESS DISCOUNT (NETT-20 %)			178.56	0.00	0.00
GRAND TOTAL			714.24	0.00	0.00
OVERALL TOTAL			714.24		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJN82015

TOTAL LABOUR CHARGES	1640.00
TOTAL SPARE PARTS CHARGES	714.24
GRAND TOTAL	2354.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Authored
Running B4 paint
2 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dent(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

-Email to Kenneth to final
amend (5/2/18)

Ht

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0462/2017
DATE : 31-OCT-2017

FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

Wu - 2 days

OWNER'S NAME : ONG SU KIT
ADDRESS : APT BLK 605 JURONG WEST STREET 62
#12-221
S(640605)
TELEPHONE NO : 9680 2552

TYPE OF CLAIM : THIRD PARTY CLAIM /
POLICY NO : 1700058869
VEHICLE NO : SJNS2018
MODEL CODE : 6J5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : F820YB23220
CHASSIS NO : JF18J5KC5JG099288
MILEAGE : 1 KM
DATE IN : 31/10/2017
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MOHAMAD FAZLI BIN BACHOK**
ACCIDENT DATE : 31/10/2017

Print Date : 01/02/2018
Print Time : 19:25:41

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJN8201S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SHC763X (FIRST CAPITAL)		
2	22/001	ACCIDENT DATE:31/10/2017 TIME:0700HRS LOCATION:JUNCTION JURONG WEST AVE 4 & PIONEER RD		
3	22/002	REPAIR/REPLACE REAR BUMPER & REAR BUMPER BEAM	1120.00	280.00 ✓
4	22/003	RESPRAY REAR BUMPER	420.00	420.00 ✓
5	22/004	SUNDRIES	100.00	20.00 ✓
TOTAL LABOUR CHARGES			1640.00	720.00

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJN82015

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
			NETT	LIST	S/NETT		
1 BUMPER FACE REAR FORESTER IL		57704SG012	540.00 ✓				OK
2 BRKT CORNER R RH		57707SG060	18.00				X
3 BRKT CORNER R LH		57707SG070	18.00				X
4 BRKT SD R RH	(1)	57707SG080	14.40				X
5 BRKT SD R LH		57707SG090	14.40				X
6 BEAM COMPL R EU		57711SG0219P	286.00				X
SUB TOTAL			540.00	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			108.00	0.00	0.00	0.00	
GRAND TOTAL			432.00	0.00	0.00	0.00	
OVERALL TOTAL			432.00				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SJK82015

NETT ITEM	540.00
LESS 20 %	-108.00 ✓
NETT AMOUNT	432.00

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	720.00
----------------------	--------

TOTAL SPARE PARTS CHARGES	432.00
---------------------------	--------

TOTAL CHARGES	1152.00
---------------	---------

ADD 7 % GST	80.64
-------------	-------

GRAND TOTAL	1232.64
-------------	---------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17020979/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 763X	Veh. Inspected	SJN 8201S	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17010220MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	02/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU FORESTER (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1SJ5KC5JG099288	Colour	METALLIC PEARL WHITE	
Odometer	4866	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	TOYO	9 mm	
L/H Front Tyre	225/60 R17	TOYO	9 mm	
R/H Rear Tyre	225/60 R17	TOYO	9 mm	
L/H Rear Tyre	225/60 R17	TOYO	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/10/2017	Inspection Date	27/11/2017	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 8201S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER FACE REAR FORESTER IL (N)	BENT	540.00	540.00
1	BRKT CORNER R RH (N)	SERVICEABLE	18.00	-
1	BRKT CORNER R LH (N)	SERVICEABLE	18.00	-
1	BRKT SD R RH (N)	TO REPAIR SEE LABOUR	14.40	-
1	BRKT SD R LH (N)	SERVICEABLE	14.40	-
1	BEAM COMPL R EU (N)	TO REPAIR SEE LABOUR	288.00	-
	LESS 20% DISCOUNT		-178.56	-108.00
			714.24	432.00
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
LABOUR				
	REPAIR/REPLACE REAR BUMPER & REAR BUMPER BEAM.INCLUSIVE OF THE REPAIR OF BRKT SD R RH AND BEAM COMPL R EU.		1,120.00	280.00
	RESPRAY REAR BUMPER.		420.00	420.00
			1,540.00	700.00
GRAND TOTAL			2,354.24	1,152.00
RECOMMENDED COST OF REPAIRS				1,152.00

Report Ref No. CS/FCI17020979/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.