










C

n

ONS

ı

SUUSE



















FormTeam Consultancy Pte Ltd

Vehicle No: SJJ 56698

Workshop: Twincar Automotive Pte Ltd

Your Reference: CMTD1400364/THE

Our Reference: RRE14-102800/PRI/FP

Accident Date: 18 October 2014

Date of Inspection: 20 October 2014

No. 33 Ubi Ave 3 #02-15 Vertex Singapore 408868

Tel: (65) 6509 1788 Fax: (65) 6509 6221

Email: motorsurvey@fta.com.sg www.fta.com.sg

Co. Reg No: 200819280D

GST Reg. No: 200819280D



FormTeam Consultancy Pte Ltd

PAGE: 6

Our Reference: RRE14-102800/PRI/FP/ADJ/FP/cg

Your Reference: CMTD1400364

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)	\$22,200.00	\$12,100.00

REMARKS:

ur recommended Lump Sum Repair Cost is \$12,100.00 (instead of the submitted repair cost of \$22,200.00 .In normal circumstances, repairs to the vehicle would take approximately 08 days to complete. Please find enclosed our note of charges for your kind attention.

Remarks:

Market Value:

28,000.00

Salvage Value:

18,000.00

Nett Loss:

\$

10,000.00

In our opinion, it is not economical to repair if the repair cost exceeds \$10,000.00.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by FormTeam. Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FormTeam Consultancy Pte Ltd

Frankie Pang

AMSAE(AUST), AMIRTE, AMSOE,

MASPACI, MSAAA

Licensed Appraiser