

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/12/2017 12:13
Date Of Accident	10/12/2017 18:05
Exact Location Of Accident	PIE TWDS CHANGI B4 EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK277T
Insured/Policyholder	
Name Of Registered Owner	HASINAH BINTE MOHAMED AMIN
NRIC No	S9215459I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96329079
Alternative Phone No	OTHERS-96329079

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100494692-01
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ZAKWAN BIN MOHD RIDZWAN
NRIC No	S8851590J
Date Of Birth	23/12/1988
Occupation	INDOOR
Date Of Driving Pass	22/08/2012
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Celine Fong (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Wednesday, 20 December, 2017 10:26 AM
To: Sarjeet Singh; SUR
Subject: RE: Appointment of Mr Chua Kang Seng of LKK Auto Consultants as SJE in MC Suit No. 11700/2016 Alan Shankar & Lim LLC Ref: SS/10170/716 Vision Law Ref: AKN-atv-INS-T140-93433-14

Dear Sarjeet,

Thank you for the email.

Dear Veron,

FYNA - CS1/LAW17020997/Uvb

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Sarjeet Singh [mailto:sarjeet@asllaw.com.sg]
Sent: Wednesday, 20 December, 2017 10:20 AM
To: Ai Phing (LKKAuto) <aiphing@lkkauto.com>
Subject: Appointment of Mr Chua Kang Seng of LKK Auto Consultants as SJE in MC Suit No. 11700/2016 Alan Shankar & Lim LLC Ref: SS/10170/716 Vision Law Ref: AKN-atv-INS-T140-93433-14

Dear Ai Phing,

We spoke last Friday on this matter. As spoken, we had sent our letter of 15 September 2018 to LKK informing that Mr Chua has been appointed as the SJE and we furnished the supporting documents.

We then sent an email on 9 November informing of Mr Chua's appointment after overlooking the fact that we had already done so on 15 September 2017.

The court has directed that the SJE report be provided by 12 January 2017 failing which the SJE is to provide reasons for the delay.

We hope to have the same by then. Many thanks.

Best regards,

Sarjeet Singh
Alan Shankar & Lim LLC









GARLINK



CONSULANCY















































FRONT RH FENDER INNER SHIELD CLIPS - SET	1	1	NECESSARY	ner	30.00	30.00
FRONT RH FENDER INSULATOR	1	1	NECESSARY	ner	350.00	350.00
SOUND MAT	1	1	NECESSARY	ner	40.00	40.00
FRONT RH HEADLAMP 'HIGH' BEAM BULB	1	1	FAULTY	faulty	10.00	10.00
FRONT RH HEADLAMP 'PARKING' BULB	1	1	FAULTY	faulty	12.00	12.00
FRONT RH HEADLAMP 'SIGNAL' BULB	1	1	FAULTY	faulty	80.00	80.00
RADIATOR COOLANT	1	1	NECESSARY	NN		
Subtotal before discount					SS 1,467.00	SS 1,467.00
Sub-total					SS 1,467.00	SS 1,467.00
Parts-total					SS 26,622.57	SS 22,338.2

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	100	150.00
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	180.00	30	60.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	580.00	200	250.00
To road test driving, check and resetting wheel alignments system.	180.00	100	100.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,250.00	1000	1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,750.00	1000	1,600.00
To mount vehicle on to Car 'O' Liner.	400.00	100	280.00
To apply anti-rust chemical on repaired and replaced panel.	120.00	100	100.00
Labour Total	SS 4,640.00		SS 3,740.00
Parts & Labour Total	SS 31,262.57		SS 26,078.21

Results of inspection of the accident vehicle are as shown above,

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 22,200.00
and the recommended number of working days for the repairs is within 8 day(s).


AUTOMOTIVE APPRAISER

3412
14464.54
11571