

ASS. SEC. BY:

REF:

CS/CTU7021005 / Amber

Adnan will join

Special Instruction:

Surveyor : Adnan
malimen

ASSIGNMENT (Office)

From (Person): Juwyn Tay

of at

Date/Time: 02.11.2017 5:48pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 6533E

Insured:

GX 84403

at Workshop m/s

mt Solution

Tel:

6243 1373

of

23 Kaki Bukit Ave 4 #02-18B

Policy No:

DMCVSN3071771700

Claim No:

SNM7D06323C02/C

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30.10.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement

Date/Time:

02.11.2017

Person Contacted:

Xiao Hui

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GEB FB33E - X
	GX 3AUCB - NO / CTHPUDCSH / L4
	SIN = 301017

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G8B6533E Regn: 2009 OctType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen Berlingo C.C. 1560Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 183969 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF7789HTC9J095873Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 01/11/17Survey held at MG SolutionDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China29/3/18 L/S \$11,500 (\$46,880.19, 0.80%) Repair 18 days.

RECEIVED 29 MAR 2018

Date/Time. File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) S + RS. SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 11,500)250250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17021005/Agb		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-11-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GX 8440B	Veh. Inspected	GBB 6533E	
Policy No.	DMCVSN3071271700	Coverage (\$)	0.00	
Claim No.	SNM17D06323C02/0	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	02/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/10/2017	Inspection Date	03/11/2017	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No. : CS/CTI17021005/Anb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler Rita Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(..) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			
/			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

--	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Rita 29/3/18
Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Actioned	Status
Main	01 Nov 2017		02 Nov 2017 17:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S JUZ INTERIOR PTE LTD, Co. Reg. No.: -								
Main Claimant:	J CONCEPTERS PTE LTD								
Vehicle Reg. No.:	GBB6533E		Date of Loss:	30/10/2017 15:00 - :59					
Claim Type:	TP / SNM17D06323C02/0		Policy/Cover Note No.:	DMCVSN3071271700 (TP, Fire & Theft)					
Vehicle Reg. No. (Insured):	GX8440B		Policy No. (Claimant):						
			Excess:	S\$0.00					
Repalrer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 13/11/2017]								
Adj. Apg. Remarks:	NO ESTIMATES LKK SELECTED AS SJE FOR WP PRS								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2017 15:36
Date Of Accident	30/10/2017 15:05
Exact Location Of Accident	PUNGGOL EAST TOWARDS TPE BEFORE PUNGGOL FIELD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB6533E
Insured/Policyholder	
Name Of Registered Owner	J CONCEPTERS PTE LTD
Co Reg No	201512889H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88888888
Vehicle Particulars	
Manufacturer	CITROEN
Model	BERLINGO-1.6 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ17-001774
Cover Note Number	
Driver	
Name of Driver	TAN JUN KIANG (CHEN JUN QIANG)
NRIC No	S8132340B
Date Of Birth	01/10/1981
Occupation	OUTDOOR
Date Of Driving Pass	19/03/2009
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88081683
Fax Number	
Contact Number	
Email Address	TAN.JACKY@LIVE.COM

Address , BLK 619C PUNGGOL DRIVE
#11-753
Postcode 823619
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON 30/10/2017 AT ABOUT 1505HRS AT ALONG PUNGGOL EAST ROAD TOWARDS TPE BEFORE JUNCTION OF PUNGGOL FIELD. I WAS TRAVELLING ON THE CENTRE LANE OF PUNGGOL EAST ROAD AND WHEN COMING TOWARDS THE ABOVE MENTIONED JUNCTION, MY FRONT VEHICLE (D) SLOW DOWN AND STOP DUE TO THE RED TRAFFIC LIGHT HENCE I FOLLOW SUIT. SUDDENLY I HEARD A LOUD BANG FROM BEHIND AND THE GREAT IMPACT FORCED MY VEHICLE (A) FORWARD TO HIT ONTO THE REAR PORTION OF VEHICLE (D). WHEN I ALIGHTED, I REALISED THAT IT WAS VEHICLE (B) WHO HIT ONTO MY REAR LEFT PORTION OF MY VEHICLE (A1) AND AGAIN WAS HIT BY VEHICLE (C2) ONTO THE REAR PORTION OF MY VEHICLE (A2) CAUSING DAMAGES TO MY VEHICLE. I HAVE ONE PASSEGER INSIDE MY VEHICLE. TOTAL 4 VEHICLES INVOLVED IN THIS ACCIDENT. (A) GBB6533E (B) GX 8440B (C) SBS 6410L (D) YK 78Y

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GX8440B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SBS6410L

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number YK78Y

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name DRIVER AND PASSENGER

Approximate Age

Injuries Sustain

Injured person in which vehicle? GBB6533E

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the date of the accident referred to in the sketch plan.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to supply of the report being made available to interested parties.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, on knowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may use personal data, e.g., name, address and/or process my Personal Information for the purpose of the above Purposes; and
 - (c) my Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party law firm, arbitrator or expert including their lawyers/law firms, which may include outside of Singapore, for use or more of the above Purposes;
 - (d) my Personal Information may have collected and/or disclosed to the claims handler, their insurers, staff of their department, subject to their management to present and all future claims;
 - (e) my Personal Information may/are used, by the Insurers and/or GIA, to:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


J CONCEPTERS PTE LTD
201512889H

Policyholder's print name
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/10/2017 at about 1505 hrs at along Punggol East Road towards TPE before junction of Punggol Field. I was travelling on the centre lane of Punggol East Road and when coming towards the above mentioned junction, my front Vehicle (D) slow down and stop due to the Red Traffic light hence I follow suit. Suddenly I heard a loud bang from behind and the great impact forced my Vehicle (A) forward to hit onto the Rear Portion of Vehicle (D). When I alighted, I realised that it was Vehicle (B) who hit onto my Rear Left Portion of my Vehicle (A1) and again was hit by Vehicle (C2) onto the Rear Portion of my Vehicle (A2) causing damages to my vehicle. I have one passenger inside my vehicle. Total 4 vehicles involved in this accident.

(A) GBB 6S33E

(B) GX 8440 B

(C) SBS 6410 L

(D) YK 78 Y

DECLARATION

We declare that the above particulars are true in every respect.

J CONCEPTERS PTE LTD
201512889H

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	2889H

Vehicle Details

Vehicle No.	GBB6533E
Vehicle to be Exported	Yes
Intended De-registration Date	01 Nov 2017
Vehicle Make	CITROEN
Vehicle Model	BERLINGO 1.6L M/T AB 2WD 6DR FGL 1N1 TC
Primary Colour	Silver
Manufacturing Year	2009
Engine No.	10JBCB0032478
Chassis No.	VF77B9HTC9J095873
Maximum Power Output	-
Open Market Value	\$20,850.00
Original Registration Date	27 Oct 2009
First Registration Date	27 Oct 2009
Transfer Count	2
Actual ARF Paid	\$1,043.00

Intended PARF Rebate Details

PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	26 Oct 2019
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$18,189.00
COE Rebate Amount	\$4,073.00
Total Rebate Amount	\$4,073.00

The information contained herein is correct as at 01 Nov 2017

OK

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: CHINA TAIPING INSURANCE (SINGAPC	DATE	: 31/10/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: GBB6533E		
MODEL	: CITROEN BERLINGO 1.6L		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 30-Oct-17
		TIME	: 15:05HRS
THIRD PARTY REQUESTOR / CONTACT	:	MS HONG / SHARON	

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT WINDSCREEN <i>cracked</i>	1	\$ 930.00	\$ 930.00	-
2	FRONT WINDSCREEN MOULDING <i>new</i>	1	\$ 110.00	\$ 110.00	-
3	FRONT WINDSCREEN PILLAR <i>2 p/s</i>	2	\$ 903.80	\$ 1,807.60	x
4	FRONT WIPER BLADE <i>2</i>	1	\$ 103.00	\$ 103.00	x
5	FRONT WIPER BLADE ARM <i>2 not new</i>	2	\$ 75.00	\$ 150.00	x
6	FRONT WIPER BLADE MOTOR	2	\$ 250.00	\$ 500.00	x
7	FRONT WIPER GARNISH <i>2</i>	1	\$ 340.00	\$ 340.00	x
8	FRONT WIPER SIDE GARNISH <i>2 not new</i>	2	\$ 55.00	\$ 110.00	x
9	FRONT WIPER SIDE SPONGE	2	\$ 35.00	\$ 70.00	x
10	BONNET <i>Distorted.</i>	1	\$ 750.00	\$ 750.00	-
11	BONNET LOCK <i>Jammed</i>	1	\$ 65.00	\$ 65.00	-
12	BONNET HINGE <i>Bent</i>	2	\$ 65.00	\$ 130.00	-
13	BONNET STOPPER <i>new</i>	2	\$ 30.00	\$ 60.00	-
14	FRONT BUMPER <i>deformed</i>	1	\$ 670.00	\$ 670.00	-
15	FRONT BUMPER (UPPER) RH <i>2 not new</i>	1	\$ 160.00	\$ 160.00	x
16	FRONT BUMPER (UPPER) LH	1	\$ 160.00	\$ 160.00	x
17	FRONT BUMPER LOWER GRILLE <i>2 not new</i>	1	\$ 103.00	\$ 103.00	x
18	FRONT BUMPER REINFORCEMENT	1	\$ 310.00	\$ 310.00	x

19	FRONT BUMPER REINFORCEMENT COVER GARNISH ^{new}	1	\$ 180.00	\$ 180.00	X
20	HORN ^{new}	1	\$ 60.00	\$ 60.00	X
21	HEADLAMP ^{2H smashed}	2	\$ 410.00	\$ 820.00	4.0
22	HEADLAMP PANEL ^{new}	2	\$ 210.00	\$ 420.00	X
23	FRONT GRILLE WITH CHROME ^{crushed.}	1	\$ 322.20	\$ 322.20	/
24	FRONT FENDER ^{LH Distorted}	2	\$ 522.20	\$ 1,044.40	522.20.
25	FRONT FENDER SIGNAL LAMP ^{new}	2	\$ 42.00	\$ 84.00	X
26	FRONT FENDER INNER COWLING ^{LH rebound}	2	\$ 130.00	\$ 260.00	130
27	FRONT WHEEL HOUSE PANEL LH ^{Ryrie}	1	\$ 730.00	\$ 730.00	X.
28	FRONT SUPPORT PANEL ^{Distorted}	1	\$ 810.00	\$ 810.00	/
29	RADIATOR ^{Distorted.}	1	\$ 750.00	\$ 750.00	/
30	RADIATOR FAN MOTOR WITH COWLING (COMPLETE) ^{Distorted}	1	\$ 310.00	\$ 310.00	/
31	RADIATOR TOP HOSE ^{twisted}	1	\$ 50.00	\$ 50.00	/
32	RADIATOR BOTTOM HOSE ^{new}	1	\$ 55.00	\$ 55.00	X.
33	RADIATOR RESERVIOR HOSE ^{Distorted.}	1	\$ 80.00	\$ 80.00	/
34	AIR CONDENSOR ^{Distorted.}	1	\$ 810.00	\$ 810.00	/
35	AIR CON SUCTION PIPE ^{3 new}	1	\$ 320.00	\$ 320.00	X
36	AIR CON PRESSURE PIPE ^{new}	1	\$ 180.00	\$ 180.00	X.
37	AIR CLEANER DUCT ^{Distorted}	1	\$ 90.00	\$ 90.00	/
38	AIR FLEXIBLE DUCT	1	\$ 150.00	\$ 150.00	/
39	ENGINE MOUNTING (SET) ^{new}	1	\$ 820.10	\$ 820.10	X.
40	FRONT WIRE HARNESS ^{new}	1	\$ 3,390.00	\$ 3,390.00	X
41	ALTERNATOR ^{3 new}	1	\$ 890.00	\$ 890.00	+
42	AIR COOLER	1	\$ 420.00	\$ 420.00	+
43	AIR AIR COOLER HOSE ³	1	\$ 80.00	\$ 80.00	+
44	TURBO ASSY ^{new}	1	\$ 3,600.00	\$ 3,600.00	X
45	EXHAUST DOWN PIPE (CATALYTIC CONVERTERS)	1	\$ 440.00	\$ 440.00	X
46	FRONT EXHAUST MANIFOLD ^{Damaged}	1	\$ 740.00	\$ 740.00	/
47	FRONT EXHAUST MANIFOLD INSULATOR ^{torn}	2	\$ 80.00	\$ 160.00	/
48	FRONT EXHAUST O2 SENSOR ^{3 new}	1	\$ 460.00	\$ 460.00	+
49	FUSE AND RELAY BOX ^{new}	1	\$ 350.00	\$ 350.00	X.
50	SAFETY BELT ³	2	\$ 1,055.30	\$ 2,110.60	X
51	AIR BAG SENSOR ^{new}	1	\$ 310.00	\$ 310.00	X
52	AIR BAG CONTROL UNIT	1	\$ 980.00	\$ 980.00	X.
53	FRONT DOOR LH ^{Ryrie}	1	\$ 1,380.00	\$ 1,380.00	+
54	SLIDING DOOR ^{Ryrie}	1	\$ 1,830.00	\$ 1,830.00	X.
55	REAR DOOR ^{Distorted.}	2	\$ 1,020.60	\$ 2,041.20	/
56	REAR DOOR EMBLEM 'CITROEN' ^{3 new}	1	\$ 65.00	\$ 65.00	/
57	REAR DOOR EMBLEM 'C&C'	1	\$ 62.00	\$ 62.00	/

58	REAR DOOR EMBLEM'BERLINGO' <i>NEC</i>	1	\$ 60.00	\$ 60.00	/
59	REAR DOOR HINGE(UPPER) <i>3 New</i>	2	\$ 120.00	\$ 240.00	x
60	REAR DOOR HINGE(LOWER) <i>New</i>	2	\$ 120.00	\$ 240.00	x
61	REAR DOOR WEATHERSTRIPE <i>ut</i>	1	\$ 240.00	\$ 240.00	/
62	REAR DOOR TOP LOCK <i>3 New</i>	1	\$ 230.00	\$ 230.00	/
63	REAR DOOR LOWER LOCK	1	\$ 320.00	\$ 320.00	/
64	REAR DOOR WINDSCREEN GLASS <i>Shattered</i>	2	\$ 980.00	\$ 1,960.00	/
65	REAR DOOR WINDSCREEN GLASS MOULDING <i>new</i>	2	\$ 520.00	\$ 1,040.00	220.
66	REAR DOOR WIPER ARM <i>Missing</i>	1	\$ 70.00	\$ 70.00	/
67	REAR DOOR WIPER ARM BLADE <i>Missing.</i>	1	\$ 53.00	\$ 53.00	/
68	REAR DOOR WIPER ARM MOTOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	/
69	REAR DOOR OUTER HANDLE <i>Deformed.</i>	1	\$ 263.00	\$ 263.00	/
70	REAR DOOR INNER TRIM <i>LH Deformed</i>	2	\$ 203.50	\$ 407.00	203.50.
71	REAR DOOR INNER LOCK <i>Turned</i>	1	\$ 260.00	\$ 260.00	/
72	NUMBER PLATE LAMP <i>new</i>	2	\$ 55.30	\$ 110.60	x
73	REAR BUMPER <i>Distorted</i>	1	\$ 710.30	\$ 710.30	/
74	REAR BUMPER SIDE RETAINER <i>new</i>	1	\$ 52.00	\$ 52.00	/
75	REAR BUMPER REINFORCEMENT <i>Bent.</i>	1	\$ 472.50	\$ 472.50	/
76	REAR BUMPER TOWING COVER <i>Deformed.</i>	1	\$ 50.00	\$ 50.00	/
77	TAILLAMP <i>LH cracked</i>	2	\$ 270.00	\$ 540.00	270
78	TAILLAMP PANEL LH <i>Distorted</i>	1	\$ 233.00	\$ 233.00	/
79	REAR FENDER <i>Distorted.</i>	1	\$ 1,550.30	\$ 1,550.30	/
80	REAR FENDER RAILWAY <i>Not NEC</i>	1	\$ 184.00	\$ 184.00	x
81	REAR FENDER INNER BOARD <i>Deformed</i>	1	\$ 255.60	\$ 255.60	/
82	REAR FENDER INNER COWLING <i>new</i>	1	\$ 103.20	\$ 103.20	x
83	REAR FUEL TANK COVER <i>Deformed</i>	1	\$ 205.30	\$ 205.30	/
84	REAR END PANEL (OUTER) <i>3 Distorted.</i>	1	\$ 580.00	\$ 580.00	/
85	REAR END PANEL (INNER)	1	\$ 665.30	\$ 665.30	/
86	FLOOR PANEL <i>Rps</i>	1	\$ 3,655.20	\$ 3,655.20	x
87	FLOOR PANEL TOP BOARD <i>cracked.</i>	1	\$ 887.20	\$ 887.20	250(s.w).
88	EXHAUST PIPE <i>3 New</i>	1	\$ 877.20	\$ 877.20	x
89	SPARE TYRE BRACKET	1	\$ 211.30	\$ 211.30	x.

193614 /
17425.26 S.W. 250

TOTAL PRICE \$ 51,129.10
LESS 10% \$ 5,112.91
SUB TOTAL PRICE \$ 46,016.19

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	x
2	FRONT WINDSCREEN SEALANT <i>new</i>	1	\$ 100.00	\$ 100.00	60.

3	FRONT WINDSCREEN INNER SEAL <i>Nu</i>	1	\$ 120.00	\$ 120.00	30
4	FRONT GRILLE CLIPS(SET) <i>Nu</i>	1	\$ 25.00	\$ 25.00	10
5	FRONT BUMPER CLIPS(SET) <i>Nu</i>	1	\$ 25.00	\$ 25.00	✓
6	FRONT BUMPER CENTRE GRILLE CLIPS(SET) <i>2</i>	1	\$ 25.00	\$ 25.00	x
7	FRONT BUMPER LOWER GRILLE CLIPS(SET) <i>not Nu</i>	1	\$ 22.00	\$ 22.00	x
8	FRONT BUMPER LOWER COVER CLIPS(SET)	1	\$ 20.00	\$ 20.00	x.
9	HEADLAMP CLIPS(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00	x
10	FRONT RADIATOR TOP COVER CLIPS(SET) <i>2</i>	1	\$ 25.00	\$ 25.00	x
11	FRONT SUPPORT PANEL CLIPS(SET)	1	\$ 20.00	\$ 20.00	x
12	RADIATOR COOLANT <i>Nu</i>	1	\$ 80.00	\$ 80.00	40.
13	TURBO OIL COOLER HOSE BOLT <i>3</i>	1	\$ 30.00	\$ 30.00	x
14	EXHAUSE INNER SEAL BOLT	1	\$ 30.00	\$ 30.00	x.
15	REAR NUMBER PLATE <i>crackd</i>	1	\$ 50.00	\$ 50.00	✓
16	REAR DOOR INNER TRIM CLIP (SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00	✓
17	REAR DOOR WINDSCREEN SEALANT <i>3</i>	2	\$ 100.00	\$ 200.00	60
18	REAR DOOR WINDSCREEN INNER SEAL	2	\$ 120.00	\$ 240.00	60.
19	REAR DOOR 70KM/H STICKER <i>3</i>	1	\$ 50.00	\$ 50.00	15
20	REAR DOOR 6PAX STICKER	1	\$ 50.00	\$ 50.00	15
21	REAR BUMPER CLIP (SET) <i>Nu</i>	1	\$ 22.00	\$ 22.00	✓
22	TAIL LAMP CLIP (SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00	x
23	REAR FENDER SEALANT(SET) <i>Nu</i>	1	\$ 100.00	\$ 100.00	x
24	REAR FENDER INNER COWLING CLIPS(SET) <i>Nu</i>	1	\$ 20.00	\$ 20.00	✓
25	REAR END PANEL INSULATION SEAL <i>Nu</i>	1	\$ 150.00	\$ 150.00	60
26	REAR FLOOR PANEL INSULATION SEAL <i>Nu</i>	1	\$ 150.00	\$ 150.00	x
27	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200.
687			TOTAL	\$ 1,884.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,800.00	1200	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,600.00	800.	
3	Tuff Coat	\$150.00	30	
4	WIRING CHECK	\$80.00	30	
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$120.00	60	
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$80.00	60	

7	REMOVE AND REFIX FRONT WINDSCREEN	\$120.00	/	
8	REMOVE AND REFIX AIR BAG & SAFETY BELT	\$450.00	X.	
9	REMOVE AND REFIX FRONT DOOR	\$180.00	X.	

TOTAL

\$4,580.00

2300

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$2,500.00	1600.	
2	SPRAY PAINTING TO AFFECTED AREA	\$2,000.00	12400.	
3	TUFF COAT	\$200.00	60	
4	WIRING CHECK	\$200.00	30.	
5	REMOVE & REFIX REVERSE SENSOR	\$120.00	50	
6	REMOVE & REFIX REAR EXHAUST PIPE	\$220.00	X	
7	CONDUCT WATER LEAKAGE TEST	\$150.00	X	
8	TRANSFER & REFIX TAILGATE	\$100.00	80.	
9	TRANSFER & REFIX FUEL TANK COVER	\$120.00	80.	
10	TRANSFER & REFIX TAILGATE WINDSCREEN	\$280.00	120.	

TOTAL

\$5,900.00

3420

total: 24082.26

H/S: 115K

18 Days

11.5K

18 Days

ESTIMATE REPORT

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before after spray painting
- To display estimate for 14 days
- Parts prices are subject to change
- Third party survey, if required
- No illegal modifications are allowed
- Supplementary items are subject to final survey

APPROVED DETAILS

SURVEYOR

Acknowledged by Repairer

Signature:

Date:

CONTACT NO

FAX

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Nov 2017		02 Nov 2017 17:09 Edit Adj Rpt	S\$11,500.00 Edit Estimates	S\$11,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	M/S JUZ INTERIOR PTE LTD, Co. Reg. No.: -					
Main Claimant:	J CONCEPTERS PTE LTD					
Vehicle Reg. No.:	GBB6533E	Date of Loss:	30/10/2017 15:00 - :59			
Claim Type:	TP / SNM17D06323C02/0	Policy/Cover Note No.:	DMCVSN3071271700 (TP, Fire & Theft)			
Vehicle Reg. No. (Insured):	GX8440B	Policy No. (Claimant):				
		Excess:	S\$0.00			
Repairer:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre, 415933 Kaki Bukit - Tel: 91886931					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 13/11/2017]					
Adj Asg. Remarks:	NO ESTIMATES LKK SELECTED AS SJE FOR WP PRS					

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBB6533E (SNM17D06323C02/0)**
[GX8440B]

TP
J CONCEPTERS PTE LTD
Oct 30 2017 3:00PM
[M/S JUZ INTERIOR PTE LTD]
MG Solution Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser ▼	
Assessment Reports				1 per page ▼	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	01/11/17 10:44	Accident Statement	1	Load HTM	
Photos/Images				3 per page ▼	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
5	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
8	01/11/17 10:39	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
9	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
10	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
11	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
12	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
13	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
14	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
15	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
16	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
17	01/11/17 10:40	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
18	01/11/17 10:43	Police Report [Linked Accident Report Documents]	1	Load JPG	☒
19	01/11/17 10:43	Police Report [Linked Accident Report Documents]	1	Load JPG	☒
20	01/11/17 10:43	Police Report [Linked Accident Report Documents]	1	Load JPG	☒
21	01/11/17 10:43	Police Report [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/11/17 10:34	General View	1	Load JPG	☒
2	03/11/17 10:34	General View	1	Load JPG	☒
3	03/11/17 10:34	General View	1	Load JPG	

					☒
4	03/11/17 10:34	General View	1	Load JPG	☒
5	03/11/17 10:34	General View	1	Load JPG	☒
6	03/11/17 10:34	General View	1	Load JPG	☒
7	03/11/17 10:34	General View	1	Load JPG	☒
8	03/11/17 10:34	General View	1	Load JPG	☒
9	03/11/17 10:34	General View	1	Load JPG	☒
10	03/11/17 10:34	General View	1	Load JPG	☒
11	03/11/17 10:34	General View	1	Load JPG	☒
12	03/11/17 10:34	General View	1	Load JPG	☒
13	03/11/17 10:34	General View	1	Load JPG	☒
14	03/11/17 10:34	General View	1	Load JPG	☒
15	03/11/17 10:34	General View	1	Load JPG	☒
16	03/11/17 10:34	General View	1	Load JPG	☒
17	03/11/17 10:34	General View	1	Load JPG	☒
18	03/11/17 10:34	General View	1	Load JPG	☒
19	03/11/17 10:34	General View	1	Load JPG	☒
20	03/11/17 10:34	General View	1	Load JPG	☒
21	03/11/17 10:34	General View	1	Load JPG	☒
22	03/11/17 10:34	General View	1	Load JPG	☒
23	03/11/17 10:34	General View	1	Load JPG	☒
24	03/11/17 10:34	General View	1	Load JPG	☒
25	03/11/17 10:34	General View	1	Load JPG	☒
26	03/11/17 10:34	General View	1	Load JPG	☒
27	03/11/17 10:34	General View	1	Load JPG	☒
28	03/11/17 10:34	General View	1	Load JPG	☒
29	03/11/17 10:34	General View	1	Load JPG	☒
30	03/11/17 10:34	General View	1	Load JPG	☒
31	03/11/17 10:34	General View	1	Load JPG	☒
32	03/11/17 10:34	General View	1	Load JPG	☒
33	03/11/17 10:34	General View	1	Load JPG	☒
34	03/11/17 10:34	General View	1	Load JPG	☒
35	03/11/17 10:34	General View	1	Load JPG	☒
36	03/11/17 10:34	General View	1	Load JPG	☒
37	03/11/17 10:34	General View	1	Load JPG	☒
38	03/11/17 10:34	General View	1	Load JPG	☒
39	03/11/17 10:34	General View	1	Load JPG	☒
40	03/11/17 10:34	General View	1	Load JPG	☒
41	03/11/17 10:34	General View	1	Load JPG	☒
42	03/11/17 10:34	General View	1	Load JPG	☒
43	03/11/17 10:34	General View	1	Load JPG	☒
44	03/11/17 10:34	General View	1	Load JPG	☒
45	03/11/17 10:34	General View	1	Load JPG	☒
46	03/11/17 10:34	General View	1	Load JPG	☒
47	03/11/17 10:34	General View	1	Load JPG	☒
48	03/11/17 10:34	General View	1	Load JPG	☒
49	03/11/17 10:34	General View	1	Load JPG	☒
50	03/11/17 10:34	General View	1	Load JPG	☒
51	03/11/17 10:34	General View	1	Load JPG	☒
52	03/11/17 10:34	General View	1	Load JPG	☒

53	03/11/17 10:34	General View	1	Load JPG	☒
54	03/11/17 10:34	General View	1	Load JPG	☒
55	03/11/17 10:34	General View	1	Load JPG	☒
56	03/11/17 10:34	General View	1	Load JPG	☒
57	03/11/17 10:34	General View	1	Load JPG	☒
58	03/11/17 10:34	General View	1	Load JPG	☒
59	03/11/17 10:34	General View	1	Load JPG	☒
60	03/11/17 10:34	General View	1	Load JPG	☒
61	03/11/17 10:34	General View	1	Load JPG	☒
62	03/11/17 10:34	General View	1	Load JPG	☒
63	03/11/17 10:34	General View	1	Load JPG	☒
64	03/11/17 10:34	General View	1	Load JPG	☒
65	03/11/17 10:34	General View	1	Load JPG	☒
66	03/11/17 10:34	General View	1	Load JPG	☒
67	03/11/17 10:34	General View	1	Load JPG	☒
68	03/11/17 10:34	General View	1	Load JPG	☒
69	03/11/17 10:34	General View	1	Load JPG	☒
70	03/11/17 10:34	General View	1	Load JPG	☒
71	03/11/17 10:34	General View	1	Load JPG	☒
72	03/11/17 10:34	General View	1	Load JPG	☒
73	03/11/17 10:34	General View	1	Load JPG	☒
74	03/11/17 10:34	General View	1	Load JPG	☒
75	03/11/17 10:34	General View	1	Load JPG	☒
76	03/11/17 10:34	General View	1	Load JPG	☒
77	03/11/17 10:34	General View	1	Load JPG	☒
78	03/11/17 10:34	General View	1	Load JPG	☒
79	03/11/17 10:34	General View	1	Load JPG	☒
80	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
81	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
82	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
83	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
84	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
85	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
86	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
87	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
88	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
89	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
90	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
91	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
92	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
93	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
94	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
95	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
96	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
97	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
98	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
99	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
100	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
101	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
102	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒

103	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
104	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
105	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
106	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
107	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
108	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
109	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
110	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
111	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
112	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
113	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
114	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
115	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
116	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
117	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
118	28/03/18 18:26	Reinspection Photo	1	Load JPG	☒
Documentation					
			1 per page	☒	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/11/17 17:10	ASSIGNMENT	1	Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	01/11/17 10:38	Sketch Plan [Linked Accident Report Documents]	1	Load JPG	☒
2	01/11/17 10:38	Sketch Plan #2 [Linked Accident Report Documents]	1	Load JPG	☒
3	01/11/17 10:38	Sketch Plan #3 [Linked Accident Report Documents]	1	Load JPG	☒
4	01/11/17 10:38	Sketch Plan #4 [Linked Accident Report Documents]	1	Load JPG	☒
5	01/11/17 10:38	Sketch Plan #5 [Linked Accident Report Documents]	1	Load JPG	☒

Linked Accident Report Documents

			View	View in Browser	
Assessment Reports					
			1 per page	☒	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	01/11/17 10:44	Accident Statement	1	Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	01/11/17 10:39	Accident Photo	1	Load JPG	☒
2	01/11/17 10:39	Accident Photo	1	Load JPG	☒
3	01/11/17 10:39	Accident Photo	1	Load JPG	☒
4	01/11/17 10:39	Accident Photo	1	Load JPG	☒
5	01/11/17 10:39	Accident Photo	1	Load JPG	☒
6	01/11/17 10:39	Accident Photo	1	Load JPG	☒
7	01/11/17 10:39	Accident Photo	1	Load JPG	☒
8	01/11/17 10:39	Accident Photo	1	Load JPG	☒
9	01/11/17 10:40	Accident Photo	1	Load JPG	☒
10	01/11/17 10:40	Accident Photo	1	Load JPG	☒
11	01/11/17 10:40	Accident Photo	1	Load JPG	☒
12	01/11/17 10:40	Accident Photo	1	Load JPG	☒
13	01/11/17 10:40	Accident Photo	1	Load JPG	☒
14	01/11/17 10:40	Accident Photo	1	Load JPG	☒

					☒
15	01/11/17 10:40	Accident Photo		Load JPG	☒
16	01/11/17 10:40	Accident Photo		Load JPG	☒
17	01/11/17 10:40	Accident Photo		Load JPG	☒
18	01/11/17 10:43	Police Report		Load JPG	☒
19	01/11/17 10:43	Police Report		Load JPG	☒
20	01/11/17 10:43	Police Report		Load JPG	☒
21	01/11/17 10:43	Police Report		Load JPG	☒
Documentation					
				1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	01/11/17 10:38	Sketch Plan		Load JPG	☒
2	01/11/17 10:38	Sketch Plan #2		Load JPG	☒
3	01/11/17 10:38	Sketch Plan #3		Load JPG	☒
4	01/11/17 10:38	Sketch Plan #4		Load JPG	☒
5	01/11/17 10:38	Sketch Plan #5		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17021005/ANBE2

Date: 29/03/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3071271700

Claimant Vehicle
No: GBB6533EInsured Vehicle
No: GX8440B

Date of Loss: 30/10/2017

Nature of Claim: TP

Claim
No: SNM17D06323C02/0

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB6533E		
Make & Model:	CITROEN BERLINGO, 1.6 D (M)	Engine No:	10JBCB0032478
Reg. Date:	27/10/2009 (Man. Year: 2009)	Chassis No:	VF77B9HTC9J095873
Colour:	Silver	Odometer:	183969 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,900.19	18,362.26	29,537.93	61.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,480.00	5,720.00	4,760.00	45.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	58,380.19	24,082.26	34,297.93	58.75
Approved Total (Overridden) (S\$)		11,500.00		
(S\$)	58,380.19	11,500.00	46,880.19	80.30
+ GST 7.00/7.00% (S\$)	4,086.61	805.00	3,281.61	80.30
Nett Amount (S\$)	62,466.80	12,305.00	50,161.80	80.30

INSPECTION

Date of Assignment: 02/11/2017

Date Inspected: 01/11/2017 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B, VICOM
Inspection Centre
Singapore 415933

Estimated Period of Repair: 18.0 days

Adjuster: ADRIAN LING**Manager:** LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 29 Mar 2018)

Parts: N/A CITROEN BERLINGO 1.6 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBB6533E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT WINDSCREEN	Cracked	930.00 FL	*930.00 FL
2	1	*FRONT WINDSCREEN MOULDING	Necessary	110.00 FL	*110.00 FL
3	2	*FRONT WINDSCREEN PILLAR	Repair	1,807.60 FL	*- FL
4	1	*FRONT WIPER BLADE	Not Necessary	103.00 FL	*- FL
5	2	*FRONT WIPER BLADE ARM	Not Necessary	150.00 FL	*- FL
6	2	*FRONT WIPER BLADE MOTOR	Not Necessary	500.00 FL	*- FL
7	1	*FRONT WIPER GARNISH	Not Necessary	340.00 FL	*- FL
8	2	*FRONT WIPER SIDE GARNISH	Not Necessary	110.00 FL	*- FL
9	2	*FRONT WIPER SIDE SPONGE	Not Necessary	70.00 FL	*- FL
10	1	*BONNET	Distorted	750.00 FL	*750.00 FL
11	1	*BONNET LOCK	Jammed	65.00 FL	*65.00 FL
12	2	*BONNET HINGE	Bent	130.00 FL	*130.00 FL
13	2	*BONNET STOPPER	Necessary	60.00 FL	*60.00 FL
14	1	*FRONT BUMPER	Deformed	670.00 FL	*670.00 FL
15	1	*FRONT BUMPER (UPPER) RH	Not Necessary	160.00 FL	*- FL
16	1	*FRONT BUMPER (UPPER) LH	Not Necessary	160.00 FL	*- FL
17	1	*FRONT BUMPER LOWER GRILLE	Not Necessary	103.00 FL	*- FL
18	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	310.00 FL	*- FL
19	1	*FRONT BUMPER REINFORCEMENT COVER GARNISH	Not Necessary	180.00 FL	*- FL
20	1	*HORN	Not Necessary	60.00 FL	*- FL
21	1	*HEADLAMP	N/S Smashed	820.00 FL	*410.00 FL
22	2	*HEADLAMP PANEL	Not Necessary	420.00 FL	*- FL
23	1	*FRONT GRILLE WITH CHROME	Cracked	322.20 FL	*322.20 FL
24	1	*FRONT FENDER	N/S Distorted	1,044.40 FL	*522.20 FL
25	2	*FRONT FENDER SIGNAL LAMP	Not Necessary	84.00 FL	*- FL
26	1	*FRONT FENDER INNER COWLING	N/S Deformed	260.00 FL	*130.00 FL
27	1	*FRONT WHEEL HOUSE PANEL LH	Repair	730.00 FL	*- FL
28	1	*FRONT SUPPORT PANEL	Distorted	810.00 FL	*810.00 FL
29	1	*RADIATOR	Distorted	750.00 FL	*750.00 FL
30	1	*RADIATOR FAN MOTOR WITH COWLING (COMPLETE)	Distorted	310.00 FL	*310.00 FL
31	1	*RADIATOR TOP HOSE	Twisted	50.00 FL	*50.00 FL
32	1	*RADIATOR BOTTOM HOSE	Not Necessary	55.00 FL	*- FL
33	1	*RADIATOR RESERVIOR HOSE	Distorted	80.00 FL	*80.00 FL
34	1	*AIR CONDENSOR	Distorted	810.00 FL	*810.00 FL
35	1	*AIR CON SUCTION PIPE	Not Necessary	320.00 FL	*- FL
36	1	*AIR CON PRESSURE PIPE	Not Necessary	180.00 FL	*- FL
37	1	*AIR CLEANER DUCT	Distorted	90.00 FL	*90.00 FL
38	1	*AIR FLEXIBLE DUCT	Distorted	150.00 FL	*150.00 FL
39	1	*SET ENGINE MOUNTING	Not Necessary	820.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
40	1	*FRONT WIRE HARNESS	Not Necessary	3,390.00 FL	*- FL
41	1	*ALTERNATOR	Not Necessary	890.00 FL	*- FL
42	1	*AIR COOLER	Not Necessary	420.00 FL	*- FL
43	1	*AIR COOLER HOSE	Not Necessary	80.00 FL	*- FL
44	1	*TURBO ASSY	Not Necessary	3,600.00 FL	*- FL
45	1	*EXHAUST DOWN PIPE (CATALYTIC CONVERTERS)	Not Necessary	440.00 FL	*- FL
46	1	*FRONT EXHAUST MANIFOLD	Damaged	740.00 FL	*740.00 FL
47	2	*FRONT EXHAUST MANIFOLD INSULATOR	Torn	160.00 FL	*160.00 FL
48	1	*FRONT EXHAUST O2 SENSOR	Not Necessary	460.00 FL	*- FL
49	1	*FUSE AND RELAY BOX	Not Necessary	350.00 FL	*- FL
50	2	*SAFETY BELT	Not Necessary	2,110.60 FL	*- FL
51	1	*AIR BAG SENSOR	Not Necessary	310.00 FL	*- FL
52	1	*AIR BAG CONTROL UNIT	Not Necessary	980.00 FL	*- FL
53	1	*FRONT DOOR LH	Repair	1,380.00 FL	*- FL
54	1	*SLIDING DOOR	Repair	1,830.00 FL	*- FL
55	2	*REAR DOOR	Distorted	2,041.20 FL	*2,041.20 FL
56	1	*REAR DOOR EMBLEM CITROEN	Necessary	65.00 FL	*65.00 FL
57	1	*REAR DOOR EMBLEM C&C	Necessary	62.00 FL	*62.00 FL
58	1	*REAR DOOR EMBLEM BERLINGO	Necessary	60.00 FL	*60.00 FL
59	2	*REAR DOOR HINGE (UPPER)	Not Necessary	240.00 FL	*- FL
60	2	*REAR DOOR HINGE (LOWER)	Not Necessary	240.00 FL	*- FL
61	1	*REAR DOOR WEATHERSTRIPE	Cut	240.00 FL	*240.00 FL
62	1	*REAR DOOR TOP LOCK	Damaged	230.00 FL	*230.00 FL
63	1	*REAR DOOR LOWER LOCK	Damaged	320.00 FL	*320.00 FL
64	2	*REAR DOOR WINDSCREEN GLASS	Shattered	1,960.00 FL	*1,960.00 FL
65	2	*REAR DOOR WINDSCREEN GLASS MOUDLING	Necessary	1,040.00 FL	*220.00 FL
66	1	*REAR DOOR WIPER ARM	Missing	70.00 FL	*70.00 FL
67	1	*REAR DOOR WIPER ARM BLADE	Missing	53.00 FL	*53.00 FL
68	1	*REAR DOOR WIPER ARM MOTOR	Damaged	220.00 FL	*220.00 FL
69	1	*REAR DOOR OUTER HANDLE	Deformed	263.00 FL	*263.00 FL
70	1	*REAR DOOR INNER TRIM	N/S Deformed	407.00 FL	*203.50 FL
71	1	*REAR DOOR INNER LOCK	Jammed	260.00 FL	*260.00 FL
72	2	*NUMBER PLATE LAMP	Not Necessary	110.60 FL	*- FL
73	1	*REAR BUMPER	Distorted	710.30 FL	*710.30 FL
74	1	*REAR BUMPER SIDE RETAINER	Necessary	52.00 FL	*52.00 FL
75	1	*REAR BUMPER REINFORCEMENT	Bent	472.50 FL	*472.50 FL
76	1	*REAR BUMPER TOWING COVER	Deformed	50.00 FL	*50.00 FL
77	1	*TAILLAMP	N/S Cracked	540.00 FL	*270.00 FL
78	1	*TAILLAMP PANEL LH	Distorted	233.00 FL	*233.00 FL
79	1	*REAR FENDER	Distorted	1,550.30 FL	*1,550.30 FL
80	1	*REAR FENDER RAILWAY	Not Necessary	184.00 FL	*- FL
81	1	*REAR FENDER INNER BOARD	Deformed	255.60 FL	*255.60 FL
82	1	*REAR FENDER INNER COWLING	Not Necessary	103.20 FL	*- FL
83	1	*REAR FUEL TANK COVER	Deformed	205.30 FL	*205.30 FL
84	1	*REAR END PANEL (OUTER)	Distorted	580.00 FL	*580.00 FL
85	1	*REAR END PANEL (INNER)	Distorted	665.30 FL	*665.30 FL
86	1	*FLOOR PANEL	Repair	3,655.20 FL	*- FL
87	1	*FLOOR PANEL TOP BOARD	Cracked	798.48 FS	*250.00 FS
88	1	*EXHAUST PIPE	Not Necessary	877.20 FL	*- FL
89	1	*SPARE TYRE BRACKET	Not Necessary	211.30 FL	*- FL
90	1	*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
91	1	*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*60.00 FS
92	1	*FRONT WINDSCREEN INNER SEAL	Necessary	240.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*SET FRONT GRILLE CLIPS	Necessary	25.00 FS	*10.00 FS
94	1		*SET FRONT BUMPER CLIPS	Necessary	25.00 FS	*25.00 FS
95	1		*SET FRONT BUMPER CENTRE GRILLE CLIPS	Not Necessary	25.00 FS	*- FS
96	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	22.00 FS	*- FS
97	1		*SET FRONT BUMPER LOWER COVER CLIPS	Not Necessary	20.00 FS	*- FS
98	1		*SET HEADLAMP CLIPS	Not Necessary	20.00 FS	*- FS
99	1		*SET FRONT RADIATOR TOP COVER CLIPS	Not Necessary	25.00 FS	*- FS
100	1		*SET FRONT SUPPORT PANEL CLIPS	Not Necessary	20.00 FS	*- FS
101	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
102	1		*TURBO OIL COOLER HOSE BOLT	Not Necessary	30.00 FS	*- FS
103	1		*EXHAUST INNER SEAL BOLT	Not Necessary	30.00 FS	*- FS
104	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
105	1		*SET REAR DOOR INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
106	2		*REAR DOOR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
107	2		*REAR DOOR WINDSCREEN INNER SEAL	Necessary	120.00 FS	*60.00 FS
108	1		*REAR DOOR 70KM/H STICKER	Necessary	50.00 FS	*15.00 FS
109	1		*REAR DOOR 6 PAX STICKER	Necessary	50.00 FS	*15.00 FS
110	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
111	1		*SET TAIL LAMP CLIP	Not Necessary	20.00 FS	*- FS
112	1		*SET REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
113	1		*SET REAR FENDER INNER COWLING CLIPS	Necessary	20.00 FS	*20.00 FS
114	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
115	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
116	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	52,924.38	20,298.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	5,024.19	1,936.14
Total Parts (\$\$)	47,900.19	18,362.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,800.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	150.00	30.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
7	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	120.00
8	REMOVE AND REFIX AIR BAG & SAFETY BELT	New	450.00	0.00
9	REMOVE AND REFIX FRONT DOOR	New	180.00	0.00
10	PANEL BEATING, REMOVING AND REPLACING PARTS	New	2,500.00	1,600.00
11	SPRAY PAINTING TO AFFECTED AREA	New	2,000.00	1,400.00
12	TUFF COAT	New	200.00	60.00
13	WIRING CHECK	New	200.00	30.00
14	REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
15	REMOVE & REFIX REAR EXHAUST PIPE	New	220.00	0.00
16	CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
17	TRANSFER & REFIX TAILGATE	New	100.00	80.00
18	TRANSFER & REFIX FUEL TANK COVER	New	130.00	80.00
19	TRANSFER & REFIX TAILGATE WINDSCREEN	New	280.00	120.00
Gross Labour Cost (\$\$)			10,480.00	5,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >