



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AM-INS-T22-96907-15-jt(tjw)

Date: 15<sup>th</sup> January 2018

Our Ref: CS1/LAW17021025/Dqbs2

**M/s Vision Law LLC**

133 New Bridge Road #18-01/02

Chinatown Point

Singapore 059413

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:**

**SKQ 796S**

**INSURED VEHICLE: SGD 5657T**

**ACCIDENT DATE: 24/09/2015**

We thank you for your instruction on 02/11/2017.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKQ 796S from M/s Constant Appraiser Services.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Final Repair Bill of SKQ 796S from M/s Toh Painting & Services Pte Ltd.
- d) Singapore Accident Statement of Vehicles SKQ 796S, SGD 5657T and GV 7493R.
- e) Colour damaged vehicle photographs of SKQ 796S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SKQ 796S
Make & Model	: Mercedes Benz S350L
Year of Registration	: 2008
Chassis Number	: WDD2211562A242455
Engine Capacity	: 3498 cc

2. We recommend that the repairs of the entire damage require about 16 (Sixteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.