


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1342S  
 Ref. No : BUS/10/17/7028  
 Reg. Date : 01/01/1900  
 Vehicle Type : BUS -12M  
 Make : MAN  
 Model : MAN  
 Name of Driver : Mohammad Al Rahman Bin Kamarulizam  
 Type of Accident :  
 Date / Time of Accident : 24/10/2017 05:57:00 PM  
 Accident Reported Date / Time : 25/10/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : EQ Ins Co Ltd  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC,if any :  
 SMB1342S - RIGHT REAR PORTION  
 YP7703D (TP) - INSURED WITH EQ.  
 Prepared Date : 02/11/2017 02:31:30 PM



*Sebastian.  
 2/11/2017.  
 - Lump Sum Repair.  
 - Photo After Paint.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:


**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0

Work Shop : Internal Repair Completed Date / Time :

**Summary of Repair Estimates**

|                                | <b>Quotation from ARC</b> | <b>Adjusted by Surveyor, if applicable</b> |
|--------------------------------|---------------------------|--|
| Total Labour Charges :         | 795.00                    | 530.00                                     |
| Total Spray Painting Charges : | 446.00                    | 300.00                                     |
| Total Material Charges :       | 288.11                    | 293.99                                     |
| Other Charges :                | 0.00                      | 0.00                                       |
| <b>TOTAL :</b>                 | <b>1,529.11</b>           | <b>1,123.99</b>                            |
| <b>Lum Sum Total :</b>         | <b>0.00</b>               | <b>0.00</b>                                |
| No. of Repair Days :           | 3.00                      | 2.00                                       |
| Prepared / Adjusted By :       |                           |  |
| Arc / Surveyor Sing Off Date : | 02/11/2017 02:33:07 PM    | 02/11/2017 02:37:34 PM                     |




Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/11/2017 02:33:07 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
 Quotation Date : Invoice Date :  
 Invoice Amount : Prepared Date :

LKK Auto Consulting  
 the Repairer of the Vehicle  
 • To review the repair estimate  
 • To display damaged parts  
 • Parts prices are subject to  
 • Third party survey report  
 • No illegal modification  
 • Supplemental parts  
 as subject to the repair  
 Acknowledged by Repairer  
 Signature:  
 Date:

**Part 4 - Spare Parts / Material Usage**

| Part Number                        | Portion | Stock No | Part Name        | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|------------------------------------|---------|----------|------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 4001B05-LAM141                     |         | 6010303  | SIDE SIGNAL LAMP | 1   | 186.10          | 10.00        | 167.49           | Replace            | Replace           | No <i>✓ CRK</i> |
|                                    | COMMO N | 4005299  | SMRT STICKER(B)  | 1   | 200.00          | 0.00         | 200.00           | Replace            | Replace           | No <i>✓ CRK</i> |
| <b>TOTAL MATERIALS</b>             |         |          |                  |     |                 |              |                  | <b>367.49</b>      | <b>367.49</b>     |                 |
| <b>TOTAL MATERIALS(Discounted)</b> |         |          |                  |     |                 |              |                  | <b>288.11</b>      | <b>293.99</b>     |                 |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number                          | Portion | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check | LT Check |
|--------------------------------------|---------|-----------|-----|-----------------|--------------|------------------|-----------|----------------|----------|
| <b>TOTAL SUPPLEMENTARY MATERIALS</b> |         |           |     |                 |              |                  |           |                |          |

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | 795.00             | 530.00                              |
| <b>Total Labour</b>   | <b>795.00</b>      | <b>530.00</b>                       |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope   | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | 446.00             | 300.00                              |
| <b>Total Spray Painting &amp; Panel Beating</b>                     | <b>446.00</b>      | <b>300.00</b>                       |

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

| Job Scope                | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------|--------------------|-------------------------------------|
| <b>Total Other Costs</b> |                    |                                     |