

REF:

FCI

ASSIGNMENT

From:

Date:

27/11/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To: Inspect Vehicle No:

SKB 76145

at Workshop/mis

K Kim Hin

at:

S/m

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

after 10 am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAO Accident Report: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Sum. Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: Person Contacted:

Veh No:

SKB 76145

Veh Reg:

07 of

Type: ☒ Car / ☐ M Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

1796

Make:

M E200

CC:

1770

Colour:

M. Black

AC:

Insured / Std / Nil / NA

Sp. Reading:

16896P

T. Radio:

Insured / Std / Nil / NA

Eng No:

C No:

WDB 211 0412B 325400

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

R:

235/45 ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

1 Hankook

Front:

Rear:

R. Bal:

mm

R. Bal:

9

mm

L. Bal:

mm

L. Bal:

9

mm

D.O.A:

1/11/17

D.O.A:

27/11/17

Survey held at:

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/O / Rooftop or

The U/O / Chassis frame / Body Structure affected due to collision

Date/Time Action/Instruction

28/11 File sent to Customer.

RECEIVED 16 MAY 2018

Date/Time File Passed:



Prelim. Report

Final Report

Date/Time File Returned:

2

Days Of Repair:

2

Resurvey No. of Trip:

2

Survey Fee:

Transporter:

L. & F. Fee:

Focus:

Covers:

Tools:

Total:

130

50

50+50

19

299

Report Format:

Lump Sum / 1B / 1C

7P
3104.70

Add Fee:

Site Insp: \$

Interp: \$

Tech. Insp: \$

Total Fee: \$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021112/Krb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8700A	Veh. Inspected	SKB 7614S
Policy No.		Coverage (\$)	0.00
Claim No.	D17010291MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	06/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/11/2017	Inspection Date
Survey held at	160 SIN MING DRIVE # 02-20,575722	
Repairer	K KIM HIN AUTOMOTIVE PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	03-11-2017	Our Ref No. D17010291MFSH
Accident Date	01-11-2017	Claim Type. Third Party
Insured Vehicle	SHC8700A	Third Party Vehicle. SKB7614S
Survey Location	160 Sin Ming Drive #02-20SIN MING AUTOCITY	
Contact Person.	SHUMAN	
Contact No.	64527018/ 96222116	Fax No. 64583895
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	K. KIM HIN AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229819)



PRI Documents



Close



PRI Header Details

Claim No	D17010291MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & K. KIM HIN
Workshop Name	K. KIM HIN AUTO PTE LTD (Contact Person : SHUMAN)	Survey Location & Contact Details	160 Sin Ming Drive #02-20SIN MING AUTOCITY Mobile: 96222116 , Phone: 64527018 , Fax: 64583895 EmailId: ADMIN1@KKIMHIN.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM T		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8700A	TP Vehicle No	SKB7614S
PRI Recieved Date	03-11-2017 06:51:09 PM	Surveyor Appointed Date	06-11-2017 08:34:00 AM	Surveyor Accept Date	06-11-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	8755D
Vehicle Details	
Vehicle No.	SKB7614S
Vehicle to be Exported	No
Intended De-registration Date	02 Nov 2017
Vehicle Make	MERCEDES BENZ
Vehicle Model	E200K
Primary Colour	Black
Manufacturing Year	2008
Engine No.	27195631040929
Chassis No.	WDB2110412B325400
Maximum Power Output	135.0 kW (181 bhp)
Open Market Value	\$51,260.00
Original Registration Date	28 Jul 2008
First Registration Date	28 Jul 2008
Transfer Count	2
Actual ARF Paid	\$51,260.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	27 Jul 2018
PARF Rebate Amount	\$25,630.00
Intended COE Rebate Details	
COE Expiry Date	27 Jul 2018
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$15,661.00
COE Rebate Amount	\$1,137.00
Total Rebate Amount	\$26,767.00

The information contained herein is correct as at 02 Nov 2017

OK

Kr



CO. REG. NO: 19770
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

No. : 29274

Vehicle Insured : SHC 8700 A
Accident Date : 01-Nov-2017

Date : 03-Nov-2017

Our Ref : 170799 *FIRST* SHUMAN

PAGE : 1

ANG SIEW LIAN JOYCE (MDM)
Singapore

Not Authorized
11 Sep 87
Recovery After Repair *2 days*

ESTIMATED COST OF REPAIR FOR MERCEDES BENZ E200K (2008) SKB7614S

- 1 pc bootlid "E200" emblem
- 1 pc bootlid logo
- 1 pc bootlid "KOMPRESSOR" emblem
- 1 pc rear bumper
- 1 pc rear bumper reinforcement
- 1 pc rear bumper chrome moulding -centre
- 2 pcs rear bumper chrome moulding (LH/RH)

un 75.00 X
un 46.00 X
un 105.00 X
Bu 1,350.00 ✓
un 570.00 ✓
un 185.00 ✓

@ S\$130.00 *un* 260.00 ✓

2,591.00
Less 10% : -259.10

2,331.90

- 1 pc reverse sensor

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

To remove and refit reverse sensor
assy.

To putty and respray on affected
portions.

2365.00
+ 218.00

2583.00
-10%

2324.70 *5/Part*
220.00 *sn*
+ 560.00 *Labour*

Total : S\$ 3,581.90

\$3104.70 *✓ 0%*

3178.10

Share 220.00 sn ✓
450.00 25cl
80.00 6cl
500.00 25cl

Singapore Dollars Three Thousand Five Hundred
and Eighty One and Cents Ninety Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

Supplementary Item
1pc Rear Bumper Centre Bracket *\$248.00* *✓*



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PARTS LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhinh.com.sg

Vehicle Insured : SHC 8700 A
Accident Date : 01-Nov-2017

Date : 27-Nov-2017

Our Ref : 170799 (FIRST) / SIMON

ANG SIEW LIAN JOYCE (MDM)
Singapore

SUPPLEMENTARY ITEMS FOR MERCEDES BENZ E200 SKB 7614S

1 pc Rear Bumper Centre Bracket

CMA \$ 218.00 ✓

\$ 218.00

Less 10%: - \$ 21.80

Total: \$ 196.20

Note: Amount quoted above is subjected to prevailing GST at time of tax invoice.

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SHC 8700 A
Accident Date : 01-Nov-2017

Our Ref : 170799 *FIRST* SHUMAN

ANG SIEW LIAN JOYCE (MDM)
Singapore

No. : 29274

Date : 03-Nov-2017

PAGE : 1

ESTIMATED COST OF REPAIR FOR MERCEDES BENZ E200K (2008) SKB7614S

- 1 pc bootlid "E200" emblem
- 1 pc bootlid logo
- 1 pc bootlid "KOMPRESSOR" emblem
- 1 pc rear bumper
- 1 pc rear bumper reinforcement
- 1 pc rear bumper chrome moulding -centre
- 2 pcs rear bumper chrome moulding (LH/RH)

@ S\$130.00

nn 75.00 X
nn 46.00 X
nn 105.00 X
Br 1,350.00 ✓
BT 570.00 ✓
nn 185.00 ✓

nn 260.00 ✓

2,591.00

Less 10% :

-259.10

2,331.90

- 1 pc reverse sensor

Shaw 220.00 sn ✓

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

450.00 *25cl*

To remove and refit reverse sensor
assy.

80.00 *6cl*

To putty and respray on affected
portions.

500.00 *25cl*

Total : S\$ 3,581.90

Singapore Dollars Three Thousand Five Hundred
and Eighty One and Cents Ninety Only

Note: Amount quoted above is subject to prevailing GST at

LKK Auto Consultants hence notify
time of tax invoice.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17021112/Krbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-05-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8700A	Veh. Inspected	SKB 7614S
Policy No.	D-15072701MFSH	Coverage (\$)	0.00
Claim No.	D17010291MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	06/11/2017

2. Vehicle Particulars & Condition

Make & Model	MERCEDES E200 (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WDB2110412B325400	Colour	METALLIC BLACK
Odometer	168969	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 ZR17	HANKOOK	8 mm
L/H Front Tyre	235/45 ZR17	HANKOOK	8 mm
R/H Rear Tyre	235/45 ZR17	HANKOOK	9 mm
L/H Rear Tyre	235/45 ZR17	HANKOOK	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/11/2017	Inspection Date	27/11/2017
Survey held at	160 SIN MING DRIVE # 02-20,575722		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 7614S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID "E200" EMBLEM	NOT NECESSARY	75.00	-
1	BOOTLID LOGO	NOT NECESSARY	46.00	-
1	BOOTLID "KOMPRESSOR" EMBLEM	NOT NECESSARY	105.00	-
1	REAR BUMPER	BUCKLED	1,350.00	1,350.00
1	REAR BUMPER REINFORCEMENT	BENT	570.00	570.00
1	REAR BUMPER CHROME MOULDING-CENTRE	DENTED	185.00	185.00
2	REAR BUMPER CHROME MOULDING-(LH/RH) @\$130.00	NECESSARY	260.00	260.00
	REAR BUMPER CENTRE BRACKET (ADDITIONAL)	CRACKED	218.00	218.00
	LESS 10% DISCOUNT		-280.90	-258.30
			2,528.10	2,324.70
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SHORTED	220.00	220.00
			220.00	220.00
LABOUR				
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.		450.00	250.00
	TO REMOVE AND REFIT REVERSE SENSOR ASSY.		80.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		500.00	250.00
			1,030.00	560.00
GRAND TOTAL			3,778.10	3,104.70
RECOMMENDED COST OF REPAIRS				3,104.70

Report Ref No. CS/FCI17021112/Krbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.