

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD 356H -

AAD1711-026

Not Authored

Resony B4 point

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 356H - CANDY
 VF1ABL15AUC282675
 RENAULT
 LATITUDE
 01.11.2017
AA

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>Per</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
4	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
6	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.22 X
7	1	BUMPER RETAINER FRT RH	\$	<i>D.V</i> 151.41 ✓
8	1	BUMPER BRACKET FRT RH	\$	<i>R</i> 181.75 X
9	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43 X
10	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
11	1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83 —
12	1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84 X
13	1	FENDER BRACKET FRT RH	\$	<i>R</i> 34.14 X
14	1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84 X
15	1	WHEEL HOUSING PANEL FRT RH L70Y	\$	<i>R</i> 4,682.09 X
16	1	LOWER ARM FRT RH	\$	685.76 ?
17	1	KUNCKLE ARM FRT RH	\$	846.98 ?
18	1	ABSORBER FRT RH	\$	360.54 ?
19	1	RADAITOR GRILLE	\$	<i>SL</i> 1,707.78 X
20	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 173.36 X
21	1	RADAITOR GRILLE FRAME	\$	<i>SL</i> 1,353.75 X
22	1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90 X
23	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X
24	1	BONNET	\$	<i>R</i> 1,941.63 X
25	1	DOOR MIRROR RH	\$	<i>SL</i> 1,483.40 X
26	1	DOOR MIRROR GLASS RH	\$	<i>SL</i> 242.33 X
27	1	DOOR MIRROR BACK COVER RH	\$	<i>SL</i> 218.46 X
28	1	DOOR PANEL FRT RH	\$	<i>B</i> 2,844.66 X
29	1	DOOR CHECK FRT RH	\$	<i>SL</i> 194.77 X
30	1	DOOR FINISHER FRT RH	\$	<i>SL</i> 515.06 X
31	1	DOOR MOULDING FRT RH	\$	<i>SL</i> 176.82 X
32	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50 X
33	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55 X
34	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 987.49 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-026

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 356H -

35	1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66 <i>X</i>
----	---	--------------------	----	----------------------------

TOTAL	\$	<u>28,661.62</u>
--------------	----	------------------

10%	\$	<u>2,866.16</u>
------------	----	-----------------

	\$	<u>25,795.46</u>
--	----	------------------

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	<i>nn</i> 66.00 <i>X</i>
2	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 <i>✓</i>
3	1	RIM RH FRT	\$	<i>nn</i> 385.00 <i>X</i>
4	1	TYRE RH FRT	\$	<i>nn</i> 330.00 <i>X</i>
5	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 <i>601n</i>
6	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 <i>15nn</i>
7	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 <i>601n</i>

TOTAL	\$	<u>1,037.00</u>
--------------	----	-----------------

TOTAL PARTS	\$	<u>26,832.46</u>
--------------------	----	------------------

To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
---	----	-------------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00 <i>5001</i>
---	----	----------------------

Putty and spray painting of the affected portion.	\$	3,000.00 <i>11001</i>
---	----	-----------------------

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>
---	----	---------------------------

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 <i>X</i>
--	----	---------------------------

To check steering geometry and computer wheel alignment	\$	220.00 <i>601</i>
---	----	-------------------

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 <i>X</i>
---	----	---------------------------

To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>601</i>
--	----	-------------------

Towing fees	\$	<i>nn</i> 120.00 <i>X</i>
-------------	----	---------------------------

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-026

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 356H -To rust-proofing of the affected areas. \$ 170.00 *602*To dismantle and refit front end suspension,
undercarriage parts, final checking and testing. \$ 380.00 *?*

TOTAL	\$	7,540.00
Over All Total	\$	34,372.46

(PARTS BY PARTS) Repair Days**10 Days***4 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: