

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 356H -

AAD1711-026

*Not Notified**Presony B4 party*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 356H - CANDY

VF1ABL15AUC282675

RENAULT

LATITUDE

01.11.2017

*ACA***PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Br</i>	1,259.42	✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i>	394.68	X
3	1	BUMPER BEAM FRT	\$	<i>R</i>	914.08	X
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i>	181.75	X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i>	266.80	X
6	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i>	207.22	X
7	1	BUMPER RETAINER FRT RH	\$	<i>Div</i>	151.41	✓
8	1	BUMPER BRACKET FRT RH	\$	<i>R</i>	181.75	X
9	1	HEADLAMP RH	\$	<i>Sn</i>	1,184.43	X
10	1	HEADLAMP PANEL FRT RH	\$	<i>R</i>	152.15	X
11	1	FENDER PANEL FRT RH	\$	<i>Br</i>	783.83	✓
12	1	FENDER INSULATOR RH	\$	<i>Sn</i>	130.84	X
13	1	FENDER BRACKET FRT RH	\$	<i>R</i>	34.14	X
14	1	WHEELARCH FRT RH	\$	<i>Sn</i>	278.84	X
15	1	WHEEL HOUSING PANEL FRT RH L70Y	\$	<i>R</i>	4,682.09	X
16	1	LOWER ARM FRT RH	\$		685.76	X <i>MM</i>
17	1	KUNCKLE ARM FRT RH	\$		846.98	X <i>MM</i>
18	1	ABSORBER FRT RH	\$		360.54	X <i>MM</i>
19	1	RADAITOR GRILLE	\$	<i>Sn</i>	1,707.78	X
20	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i>	173.36	X
21	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i>	1,353.75	X
22	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i>	615.90	X
23	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	X
24	1	BONNET	\$	<i>R</i>	1,941.63	X
25	1	DOOR MIRROR RH	\$	<i>Sn</i>	1,483.40	X
26	1	DOOR MIRROR GLASS RH	\$	<i>Sn</i>	242.33	X
27	1	DOOR MIRROR BACK COVER RH	\$	<i>Sn</i>	218.46	X
28	1	DOOR PANEL FRT RH	\$	<i>R</i> → X <i>Br</i>	2,844.66	X <i>X</i>
29	1	DOOR CHECK FRT RH	\$	<i>Sn</i>	194.77	X
30	1	DOOR FINISHER FRT RH	\$	<i>Sn</i>	515.06	X
31	1	DOOR MOULDING FRT RH	\$	<i>Sn</i>	176.82	X
32	1	DOOR HINGE UPPER RH	\$	<i>R</i>	274.50	X
33	1	DOOR HINGE LOWER RH	\$	<i>R</i>	300.55	X
34	1	ROCKER PANEL OUTER RH	\$	<i>R</i>	987.49	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-026

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 356H -

35 1 DOOR PANEL REAR RH

\$

R 2,844.66 X

TOTAL \$ 28,661.62**10%** \$ 2,866.16

\$ 25,795.46

Specical Nett

1 1SET WHEELARCH CLIP FRT RH

\$

nr 66.00 X

2 1SET FRONT BUMPER CLIP

\$

nr 66.00 ✓

3 1 RIM RH FRT

\$

Rn 385.00 X

4 1 TYRE RH FRT

\$

Sn 330.00 X

5 1 DOOR STICKER "Trans-cab"

\$

nr 80.00 60sn

6 1 DOOR STICKER "Classic"

\$

nr 30.00 15sn

7 1 DOOR STICKER "6555-3333"

\$

nr 80.00 60sn

TOTAL \$ 1,037.00**TOTAL PARTS** \$ 26,832.46

To Check Electrical Lighting Concerned.

\$

170.00 201

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$

2,800.00 5001

Putty and spray painting of the affected portion.

\$

3,000.00 11001

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$

nr 170.00 X

To transfer of tire, rim and on wheel balancing.

\$

nr 170.00 X

To check steering geometry and computer wheel
alignment

\$

220.00 601

To Remove And Refit Front W/Screen Glass To
Facilitate Bodywork Repair.

\$

nr 170.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$

170.00 601

Towing fees

\$

nr 120.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-026

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 356H -

To rust-proofing of the affected areas. \$ 170.00 *602*

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing. \$ 380.00 *7 NM*

TOTAL	\$	7,540.00
Over All Total	\$	34,372.46

(PARTS BY PARTS) Repair Days**10 Days***4 day,*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: