

22/09/2001

ASS. REC. BY:

REF: CS/FCI17021177/11/16/12

Special Instruction:

Subject:

R0511

ASSIGNMENT (Office)

AWS

From (Person):

Sorene Ler

of

FCI

Date/Time: 5:17pm @ 6/11/17

Estimated Cost:

Bill to:

OD: ~~HP~~ WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 9970X

Insured:

SHD 4929D

at Workshop m/s

AMA Automotive

Tel:

87783636

of

36 Toh Guan Rd # 01-36

Policy No:

Claim No:

D17010324 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3/11/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

Lup

7/11/17

H.O.D. Endorsement:

Date/Time:

5:23pm @ 6/11/17

Person Contacted:

Melvin

Vehicle: ~~IN~~ OUT

Date/Time

Action/Instruction (✓) Estimate

GBD 9970X-X

SHD 4929D - CS/FCI17018342/11/16/12 - D.O.A: 17/9/17

Lump Sum \$45007, 7days (Red: 5434.97, 54%)

REF: FCI

C
72972

ASSIGNMENT

From: _____ Date: 7/11/17

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD 9970X

at Workshop m/s AMA Automotive

of 36 Yoh Guan Rd #01-36

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

'wp'

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBD 9970X Yr Reg: 2015 AMH

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HILUX 3.0 D4M cc 2982

Colour: WHITE A/C Insured / Std / NI / NA

Sp Reading: 91863 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KQH 201 6159888

Gen. Cond: Good ☒ Fair ☐ Poor / BurntSteering: Inorder ☒ Jammed / Leaked / Burnt orBrake: Inorder ☒ Jammed / Leaked / Burnt orMod: Nil ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MK / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 63/11/17

Survey held at AMA

Des. of Damages: Fr ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 02 JUL 2018

Date/Time: File Pass to?



: Preli. Report

2/7 Typist



: Final Report

Date/Time: File Return to?

2:

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee

Transportation

) 3-4-5-6-7-8-9-10-11-12-13-14-15-16-17-18-19-20-21-22-23-24-25-26-27-28-29-30-31-32-33-34-35-36-37-38-39-40-41-42-43-44-45-46-47-48-49-50-51-52-53-54-55-56-57-58-59-60-61-62-63-64-65-66-67-68-69-70-71-72-73-74-75-76-77-78-79-80-81-82-83-84-85-86-87-88-89-90-91-92-93-94-95-96-97-98-99-100-101-102-103-104-105-106-107-108-109-110-111-112-113-114-115-116-117-118-119-120-121-122-123-124-125-126-127-128-129-130-131-132-133-134-135-136-137-138-139-140-141-142-143-144-145-146-147-148-149-150-151-152-153-154-155-156-157-158-159-160-161-162-163-164-165-166-167-168-169-170-171-172-173-174-175-176-177-178-179-180-181-182-183-184-185-186-187-188-189-190-191-192-193-194-195-196-197-198-199-200-201-202-203-204-205-206-207-208-209-210-211-212-213-214-215-216-217-218-219-220-221-222-223-224-225-226-227-228-229-230-231-232-233-234-235-236-237-238-239-240-241-242-243-244-245-246-247-248-249-250-251-252-253-254-255-256-257-258-259-260-261-262-263-264-265-266-267-268-269-270-271-272-273-274-275-276-277-278-279-280-281-282-283-284-285-286-287-288-289-290-291-292-293-294-295-296-297-298-299-300-301-302-303-304-305-306-307-308-309-310-311-312-313-314-315-316-317-318-319-320-321-322-323-324-325-326-327-328-329-330-331-332-333-334-335-336-337-338-339-340-341-342-343-344-345-346-347-348-349-350-351-352-353-354-355-356-357-358-359-360-361-362-363-364-365-366-367-368-369-370-371-372-373-374-375-376-377-378-379-380-381-382-383-384-385-386-387-388-389-390-391-392-393-394-395-396-397-398-399-400-401-402-403-404-405-406-407-408-409-410-411-412-413-414-415-416-417-418-419-420-421-422-423-424-425-426-427-428-429-430-431-432-433-434-435-436-437-438-439-440-441-442-443-444-445-446-447-448-449-450-451-452-453-454-455-456-457-458-459-460-461-462-463-464-465-466-467-468-469-470-471-472-473-474-475-476-477-478-479-480-481-482-483-484-485-486-487-488-489-490-491-492-493-494-495-496-497-498-499-500-501-502-503-504-505-506-507-508-509-510-511-512-513-514-515-516-517-518-519-520-521-522-523-524-525-526-527-528-529-530-531-532-533-534-535-536-537-538-539-540-541-542-543-544-545-546-547-548-549-550-551-552-553-554-555-556-557-558-559-560-561-562-563-564-565-566-567-568-569-570-571-572-573-574-575-576-577-578-579-580-581-582-583-584-585-586-587-588-589-590-591-592-593-594-595-596-597-598-599-600-601-602-603-604-605-606-607-608-609-610-611-612-613-614-615-616-617-618-619-620-621-622-623-624-625-626-627-628-629-630-631-632-633-634-635-636-637-638-639-640-641-642-643-644-645-646-647-648-649-650-651-652-653-654-655-656-657-658-659-660-661-662-663-664-665-666-667-668-669-670-671-672-673-674-675-676-677-678-679-680-681-682-683-684-685-686-687-688-689-690-691-692-693-694-695-696-697-698-699-700-701-702-703-704-705-706-707-708-709-710-711-712-713-714-715-716-717-718-719-720-721-722-723-724-725-726-727-728-729-730-731-732-733-734-735-736-737-738-739-740-741-742-743-744-745-746-747-748-749-750-751-752-753-754-755-756-757-758-759-760-761-762-763-764-765-766-767-768-769-770-771-772-773-774-775-776-777-778-779-780-781-782-783-784-785-786-787-788-789-790-791-792-793-794-795-796-797-798-799-800-801-802-803-804-805-806-807-808-809-810-811-812-813-814-815-816-817-818-819-820-821-822-823-824-825-826-827-828-829-830-831-832-833-834-835-836-837-838-839-840-841-842-843-844-845-846-847-848-849-850-851-852-853-854-855-856-857-858-859-860-861-862-863-864-865-866-867-868-869-870-871-872-873-874-875-876-877-878-879-880-881-882-883-884-885-886-887-888-889-890-891-892-893-894-895-896-897-898-899-900-901-902-903-904-905-906-907-908-909-910-911-912-913-914-915-916-917-918-919-920-921-922-923-924-925-926-927-928-929-930-931-932-933-934-935-936-937-938-939-940-941-942-943-944-945-946-947-948-949-950-951-952-953-954-955-956-957-958-959-960-961-962-963-964-965-966-967-968-969-970-971-972-973-974-975-976-977-978-979-980-981-982-983-984-985-986-987-988-989-990-991-992-993-994-995-996-997-998-999-1000-1001-1002-1003-1004-1005-1006-1007-1008-1009-1010-1011-1012-1013-1014-1015-1016-1017-1018-1019-1020-1021-1022-1023-1024-1025-1026-1027-1028-1029-1030-1031-1032-1033-1034-1035-1036-1037-1038-1039-1040-1041-1042-1043-1044-1045-1046-1047-1048-1049-1050-1051-1052-1053-1054-1055-1056-1057-1058-1059-1060-1061-1062-1063-1064-1065-1066-1067-1068-1069-1070-1071-1072-1073-1074-1075-1076-1077-1078-1079-1080-1081-1082-1083-1084-1085-1086-1087-1088-1089-1090-1091-1092-1093-1094-1095-1096-1097-1098-1099-1100-1101-1102-1103-1104-1105-1106-1107-1108-1109-1110-1111-1112-1113-1114-1115-1116-1117-1118-1119-1120-1121-1122-1123-1124-1125-1126-1127-1128-1129-1130-1131-1132-1133-1134-1135-1136-1137-1138-1139-1140-1141-1142-1143-1144-1145-1146-1147-1148-1149-1150-1151-1152-1153-1154-1155-1156-1157-1158-1159-1160-1161-1162-1163-1164-1165-1166-1167-1168-1169-1170-1171-1172-1173-1174-1175-1176-1177-1178-1179-1180-1181-1182-1183-1184-1185-1186-1187-1188-1189-1190-1191-1192-1193-1194-1195-1196-1197-1198-1199-1200-1201-1202-1203-1204-1205-1206-1207-1208-1209-1210-1211-1212-1213-1214-1215-1216-1217-1218-1219-1220-1221-1222-1223-1224-1225-1226-1227-1228-1229-1230-1231-1232-1233-1234-1235-1236-1237-1238-1239-1240-1241-1242-1243-1244-1245-1246-1247-1248-1249-1250-1251-1252-1253-1254-1255-1256-1257-1258-1259-1260-1261-1262-1263-1264-1265-1266-1267-1268-1269-1270-1271-1272-1273-1274-1275-1276-1277-1278-1279-1280-1281-1282-1283-1284-1285-1286-1287-1288-1289-1290-1291-1292-1293-1294-1295-1296-1297-1298-1299-1300-1301-1302-1303-1304-1305-1306-1307-1308-1309-1310-1311-1312-1313-1314-1315-1316-1317-1318-1319-1320-1321-1322-1323-1324-1325-1326-1327-1328-1329-1330-1331-1332-1333-1334-1335-1336-1337-1338-1339-1340-1341-1342-1343-1344-1345-1346-1347-1348-1349-1350-1351-1352-1353-1354-1355-1356-1357-1358-1359-1360-1361-1362-1363-1364-1365-1366-1367-1368-1369-1370-1371-1372-1373-1374-1375-1376-1377-1378-1379-1380-1381-1382-1383-1384-1385-1386-1387-1388-1389-1390-1391-1392-1393-1394-1395-1396-1397-1398-1399-1400-1401-1402-1403-1404-1405-1406-1407-1408-1409-1410-1411-1412-1413-1414-1415-1416-1417-1418-1419-1420-1421-1422-1423-1424-1425-1426-1427-1428-1429-1430-1431-1432-1433-1434-1435-1436-1437-1438-1439-1440-1441-1442-1443-1444-1445-1446-1447-1448-1449-1450-1451-1452-1453-1454-1455-1456-1457-1458-1459-1460-1461-1462-1463-1464-1465-1466-1467-1468-1469-1470-1471-1472-1473-1474-1475-1476-1477-1478-1479-1480-1481-1482-1483-1484-1485-1486-1487-1488-1489-1490-1491-1492-1493-1494-1495-1496-1497-1498-1499-1500-1501-1502-1503-1504-1505-1506-1507-1508-1509-1510-1511-1512-1513-1514-1515-1516-1517-1518-1519-1520-1521-1522-1523-1524-1525-1526-1527-1528-1529-1530-1531-1532-1533-1534-1535-1536-1537-1538-1539-1540-1541-1542-1543-1544-1545-1546-1547-1548-1549-1550-1551-1552-1553-1554-1555-1556-1557-1558-1559-1560-1561-1562-1563-1564-1565-1566-1567-1568-1569-1570-1571-1572-1573-1574-1575-1576-1577-1578-1579-1580-1581-1582-1583-1584-1585-1586-1587-1588-1589-1590-1591-1592-1593-1594-1595-1596-1597-1598-1599-1600-1601-1602-1603-1604-1605-1606-1607-1608-1609-1610-1611-1612-1613-1614-1615-1616-1617-1618-1619-1620-1621-1622-1623-1624-1625-1626-1627-1628-1629-1630-1631-1632-1633-1634-1635-1636-1637-1638-1639-1640-1641-1642-1643-1644-1645-1646-1647-1648-1649-1650-1651-1652-1653-1654-1655-1656-1657-1658-1659-1660-1661-1662-1663-1664-1665-1666-1667-1668-1669-1670-1671-1672-1673-1674-1675-1676-1677-1678-1679-1680-1681-1682-1683-1684-1685-1686-1687-1688-1689-1690-1691-1692-1693-1694-1695-1696-1697-1698-1699-1700-1701-1702-1703-1704-1705-1706-1707-1708-1709-1710-1711-1712-1713-1714-1715-1716-1717-1718-1719-1720-1721-1722-1723-1724-1725-1726-1727-1728-1729-1730-1731-1732-1733-1734-1735-1736-1737-1738-1739-1740-1741-1742-1743-1744-1745-1746-1747-1748-1749-1750-1751-1752-1753-1754-1755-1756-1757-1758-1759-1760-1761-1762-1763-1764-1765-1766-1767-1768-1769-1770-1771-1772-1773-1774-1775-1776-1777-1778-1779-1780-1781-1782-1783-1784-1785-1786-1787-1788-1789-1790-1791-1792-1793-1794-1795-1796-1797-1798-1799-1800-1801-1802-1803-1804-1805-1806-1807-1808-1809-1810-1811-1812-1813-1814-1815-1816-1817-1818-1819-1820-1821-1822-1823-1824-1825-1826-1827-1828-1829-1830-1831-1832-1833-1834-1835-1836-1837-1838-1839-1840-1841-1842-1843-1844-1845-1846-1847-1848-1849-1850-1851-1852-1853-1854-1855-1856-1857-1858-1859-1860-1861-1862-1863-1864-1865-1866-1867-1868-1869-1870-1871-1872-1873-1874-1875-1876-1877-1878-1879-1880-1881-1882-1883-1884-1885-1886-1887-1888-1889-1890-1891-1892-1893-1894-1895-1896-1897-1898-1899-1900-1901-1902-1903-1904-1905-1906-1907-1908-1909-1910-1911-1912-1913-1914-1915-1916-1917-1918-1919-1920-1921-1922-1923-1924-1925-1926-1927-1928-1929-1930-1931-1932-1933-1934-1935-1936-1937-1938-1939-1940-1941-1942-1943-1944-1945-1946-1947-1948-1949-1950-1951-1952-1953-1954-1955-1956-1957-1958-1959-1960-1961-1962-1963-1964-1965-1966-1967-1968-1969-1970-1971-1972-1973-1974-1975-1976-1977-1978-1979-1980-1981-1982-1983-1984-1985-1986-1987-1988-1989-1990-1991-1992-1993-1994-1995-1996-1997-1998-1999-2000-2001-2002-2003-2004-2005-2006-2007-2008-2009-2010-2011-2012-2013-2014-2015-2016-2017-2018-2019-2020-2021-2022-2023-2024-2025-2026-2027-2028-2029-2030-2031-2032-2033-2034-2035-2036-2037-2038-2039-2040-2041-2042-2043-2044-2045-2046-2047-2048-2049-2050-2051-2052-2053-2054-2055-2056-2057-2058-2059-2060-2061-2062-2063-2064-2065-2066-2067-2068-2069-2070-2071-2072-2073-2074-2075-2076-2077-2078-2079-2080-2081-2082-2083-2084-2085-2086-2087-2088-2089-2090-2091-2092-2093-2094-2095-2096-2097-2098-2099-2100-2101-2102-2103-2104-2105-2106-2107-2108-2109-2110-2111-2112-2113-2114-2115-2116-2117-2118-2119-2120-2121-2122-2123-2124-2125-2126-2127-2128-2129-2130-2131-2132-2133-2134-2135-2136-2137-2138-2139-2140-2141-2142-2143-2144-2145-2146-2147-2148-2149-2150-2151-2152-2153-2154-2155-2156-2157-2158-2159-2160-2161-2162-2163-2164-2165-2166-2167-2168-21



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021177/R1tb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4929D	Veh. Inspected	GBD 9970X
Policy No.		Coverage (\$)	0.00
Claim No.	D17010324MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	06/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/11/2017	Inspection Date	
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINGAPORE 608580		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-11-2017	Our Ref No. D17010324MFSH
Accident Date	03-11-2017	Claim Type. Third Party
Insured Vehicle	SHD4929D	Third Party Vehicle. GBD9970X
Survey Location	36 Toh Guan Road #01-36	
Contact Person.	MR MELVIN	
Contact No.	87783636/ 87783636	Fax No. 0
Survey Type	WITHOUT PREJUDICE: NO EST. COR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AMA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229865)



PRI Documents



Close



PRI Header Details

Claim No	D17010324MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & AMA AUTC
Workshop Name	AMA AUTOMOTIVE PTE LTD (Contact Person : MR MELVIN)	Survey Location & Contact Details	36 Toh Guan Road #01-36 Mobile: 87783636 , Phone: 87783636 , Fax: 0 EmailId: AMA.CLAIM@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST. COR		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4929D	TP Vehicle No	GBD9970X
PRI Recieved Date	06-11-2017 06:03:14 PM	Surveyor Appointed Date	06-11-2017 05:16:33 PM	Surveyor Accept Date	06-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-11-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action


Surveyor Job Remarks

Remarks

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





AMA Automotive Pte Ltd
Enterprise Hub
36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636
Co Reg no. 201627681R

Page No. 1

Vehicle No. GBD 9970X

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)
	<u>PARTS (LIST ITEMS)</u>		
1	Tailgate	DISTORTED	PA 1858.45
1	Tailgate Centre Garnish	DEFORMED	SVC X 231.10
1	Tailgate Toyota Logo (Badge)	NECESSARY	new 82.40
1	Tailgate Lock	DAMAGED	SA 387.40
1	Tailgate Lock catch	DAMAGED	PA 142.00
2	Tailgate Dampers @ 322.70	STIFFENED	SVC X 645.40
1	Tailgate windscreen moulding	NECESSARY	new 182.00
2	Tail Lamp RH & LH @ 792.00	CRACK	SVC X 1584.00
2	Tail Lamp Lower Panel RH & LH @ 181.60	DEFORMED	SVC X 363.20
1	Tailgate inner trim board	DEFORMED	SVC X 372.00
1	Rear Bumper	DEFORMED	DE 1122.00
1	Rear Bumper inner frame	DEFORMED	SVC X 378.00
1	Rear Bumper top step mat	DEFORMED	SVC X 245.00
1	Rear End Panel	DISTORTED	PA 587.00
			8179.95
			25% 2044.98
			6134.97
	<u>SPECIAL NETT ITEMS</u>		
1	Toyota sticker	NECESSARY	new 60.00 40
1	Hiace Sticker	NECESSARY	new 60.00 40
1	70km/hr Sticker	NECESSARY	new 60.00 15
1	8pax sticker	NECESSARY	new 60.00 15
1 set	Rear bumper Clips	NECESSARY	new 40.00
1	Reverse Parking Sensors	DAMAGED	new 280.00 220
1	Rear Windscreen Sealant	NECESSARY	new 100.00 60
1	Rear Licence Plate	DAMAGED	SVC X 50.00
		TOTAL PARTS	6844.97

4361.25
25%
3270.93

430



AMA Automotive Pte Ltd
Enterprise Hub
36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636
Co Reg no. 201627681R

Page No. 2

Vehicle No. GBD 9970X

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
	LABOUR	
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1200.00 750
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1200.00 750
3	To remove, refix wiring system at accident damaged areas and check for proper function	150.00 60 60
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	150.00 80
5	To remove and refix rear windscreen	140.00 (20)
6	To remove and replace reverse sensors and test for proper function	100.00 60
7	To perform anti-rust treatment on affected areas	150.00 80
	Labour Total :	3090.00
	TOTAL (PARTS & LABOUR):	9934.97

Yours Faithfully,



Melvin Wee
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
HP 90010068
7 days
4/5
07/11/17 @ 1600
Resurvey after repair



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17021177/R1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4929D	Veh. Inspected	GBD 9970X	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010324MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	06/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE 3.0 DX M	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KDH2010159888	Colour	WHITE	
Odometer	91863	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	MICHELIN	6 mm	
L/H Front Tyre	195 R15C	MICHELIN	6 mm	
R/H Rear Tyre	195 R15C	MICHELIN	6 mm	
L/H Rear Tyre	195 R15C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/11/2017	Inspection Date	07/11/2017	
Survey held at	AMA AUTOMOTIVE PTE. LTD. 36 TOH GUAN ROAD EAST #03-36 SINAGPORE 608580			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE MARKET VALUE IS S\$74,000.00 (EST. AVERAGE) C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 9970X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	BENT	1,858.45	1,858.45
1	TAILGATE CENTRE GARNISH	SERVICEABLE	231.10	-
1	TAILGATE TOYOTA LOGO (BADGE)	NECESSARY	82.40	82.40
1	TAILGATE LOCK	JAMMED	387.40	387.40
1	TAILGATE LOCK CATCH	BENT	142.00	142.00
2	TAILGATE DAMPERS @\$322.70	SERVICEABLE	645.40	-
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	182.00	182.00
2	TAIL LAMP RH & LH @\$792.00	SERVICEABLE	1,584.00	-
2	TAIL LAMP LOWER PANEL RH & LH @\$181.60	SERVICEABLE	363.20	-
1	TAILGATE INNER TRIM BOARD	SERVICEABLE	372.00	-
1	REAR BUMPER	DEFORMED	1,122.00	1,122.00
1	REAR BUMPER INNER FRAME	SERVICEABLE	378.00	-
1	REAR BUMPER TOP STEP MAT	SERVICEABLE	245.00	-
1	REAR END PANEL	BENT	587.00	587.00
	LESS 25% DISCOUNT		-2,044.98	-1,090.31
			6,134.97	3,270.94
SPECIAL NETT ITEMS				
1	TOYOTA STICKER (SN)	NECESSARY	60.00	40.00
1	HIACE STICKER (SN)	NECESSARY	60.00	40.00
1	70KM/HR STICKER (SN)	NECESSARY	60.00	15.00
1	8PAX STICKER (SN)	NECESSARY	60.00	15.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	40.00	40.00
1	REVERSE PARKING SENSORS (SN)	NOT WORKING	280.00	220.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
1	REAR LICENCE PLATE (SN)	SERVICEABLE	50.00	-
			710.00	430.00
LABOUR				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS: PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.		1,200.00	750.00

Report Ref No. CS/FCI17021177/R1tbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		1,200.00	750.00
	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION.		150.00	60.00
	TO REMOVE/REFIX INNER TRIMS,FITTINGS,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR.		150.00	80.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		140.00	120.00
	TO REMOVE AND REPLACE REVERSE SENSORS AND TEST FOR PROPER FUNCTION.		100.00	60.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		150.00	80.00
			3,090.00	1,900.00
	GRAND TOTAL		9,934.97	5,600.94
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,500.00

Report Ref No. CS/FCI17021177/R1tbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.