



AMA Automotive Pte Ltd
Enterprise Hub
36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636
Co Reg no. 201627681R

Page No. 1

Vehicle No. GBD 9970X

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)
	<u>PARTS (LIST ITEMS)</u>		
1	Tailgate	DISTORTED	7st / 1858.45
1	Tailgate Centre Garnish	DEFORMED	X / 231.10
1	Tailgate Toyota Logo (Badge)	NECESSARY	neu / 82.40
1	Tailgate Lock	DAMAGED	8st / 387.40
1	Tailgate Lock catch	DAMAGED	7A / 142.00
2	Tailgate Dampers @ 322.70	STIFFENED	X / 645.40
1	Tailgate windscreen moulding	NECESSARY	neu / 182.00
2	Tail Lamp RH & LH @ 792.00	CRACK	X / 1584.00
2	Tail Lamp Lower Panel RH & LH @ 181.60	DEFORMED	X / 363.20
1	Tailgate inner trim board	DEFORMED	X / 372.00
1	Rear Bumper	DEFORMED	DE / 1122.00
1	Rear Bumper inner frame	DEFORMED	X / 378.00
1	Rear Bumper top step mat	DEFORMED	X / 245.00
1	Rear End Panel	DISTORTED	7A / 587.00
			8179.95
			25% 2044.98
			6134.97
	<u>SPECIAL NETT ITEMS</u>		
1	Toyota sticker	NECESSARY	neu / 60.00 40
1	Hiace Sticker	NECESSARY	neu / 60.00 40
1	70km/hr Sticker	NECESSARY	neu / 60.00 15
1	8pax sticker	NECESSARY	neu / 60.00 15
1 set	Rear bumper Clips	NECESSARY	neu / 40.00
1	Reverse Parking Sensors	DAMAGED	neu / 280.00 220
1	Rear Windscreen Sealant	NECESSARY	neu / 100.00 60
1	Rear Licence Plate	DAMAGED	X / 50.00
		TOTAL PARTS	6844.97

4361.25

25%

3270.93

430