

Account

ASS. REC. BY

REF CS/FCI17021179 / Alrb2

Surveyor

Rusul

ASSIGNMENT (Office)

M/S

Person

Ang Yin Min

FCI

5:17pm @ 6/11/17

Estimated Cost

Bill to

OD / TH / WS / TI / RES / OD RES / EVA / INV / MV / CE

To Inspect Vehicle No:

SLK 184C

Insured

SHA 9865L

at Workshop no:

Hong seh Motors

Tel:

62661555

of 10 Fourth Lok yang Rd

Policy No:

Claim No:

D17010311MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/10/17

CA / REV / REP. / REV 24 HRS

WPI

15.11.2017 @ 11am

H.O.D. Estimated:

Date/Time

5:26pm @ 6/11/17

Person Contacted:

Scam

Vehicle IN/OUT

OUT

Date/Time

Action/Instructions (✓) Estimate

SLK 184C - x

SHA 9865L

Confirm \$38,626.79, @12 days

Red: \$17,026.50 31/.

Surveyor *J. P. [Signature]*

REF:

4768A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 184C

at Workshop m/s Hong Sen Motor

of 10, Fourth Lukyanov Rd

Insured: FCI/TP

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

11am



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLK 184C Yr Regn: 2016 / Kc

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MASERATI QUATTROPORTE cc 4691

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 35740 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZAM JK 39C 000056012

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or _____

Brake: Order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 285/35ZR19

R: 2+

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/10/17 D.O.I. 15/11/17

Survey held at Hong Sen

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No LS repair, 2/11/17
	RECEIVED 11 SEP 2018 Extend in

Date/Time. File Pass to? : Prel. Report

1) typist : Final Report

Date/Time. File Return to?

2) _____

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee:		
<input type="checkbox"/>	Site Insp (\$)	S + RS \$1
<input type="checkbox"/>	Interview (\$)	Photo
<input type="checkbox"/>	Tech. Invs (\$)	Others
<input type="checkbox"/>	Weekend (\$)	

Report Format: TP
Lump Sum / I.B.I: (\$ 38,626.79)

Survey Fee:	
	<u>1201.675</u>
Transportation	<u>50</u>
S + RS \$1	<u>50</u>
Photo	<u>85</u>
Others	
TOTAL	1336.675

TP
8/9/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021179/R1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-11-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9865L	Veh. Inspected	SLK 184C
Policy No.		Coverage (\$)	0.00
Claim No.	D170106311MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	06/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/10/2017	Inspection Date	
Survey held at	HONG SEH MOTORS PTE LTD 10 FOURTH LOK YANG ROAD JURONG TOWN SINGAPORE 628631		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	06-11-2017	Our Ref No. D17010311MFSH
Accident Date	30-10-2017	Claim Type. Third Party
Insured Vehicle	SHA9865L	Third Party Vehicle. SLK184C
Survey Location	10 FOURTH LOK YANG ROAD	
Contact Person.	SAM TAN	
Contact No.	62661555/ 0	Fax No. 62659595
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

Samtan@hongseh.com
39.

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HONG SEH MOTORS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/229850)

PRI Documents

Close X

PRI Header Details

Claim No	D17010311MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & HONG SEH
Workshop Name	HONG SEH MOTORS PTE LTD (Contact Person : SAM TAN)	Survey Location & Contact Details	10 FOURTH LOK YANG ROAD Mobile: 0 , Phone: 62661555 , Fax: 62659595 EmailId: SAMTAN@HONGSEH.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9865L	TP Vehicle No	SLK184C
PRI Recieved Date	06-11-2017 04:27:17 PM	Surveyor Appointed Date	06-11-2017 05:16:47 PM	Surveyor Accept Date	06-11-2017 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	06-11-2017	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/10/2017 19:44
Date Of Accident	30/10/2017 17:35
Exact Location Of Accident	CAPITAL SQUARE CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK184C
Insured/Policyholder	
Name Of Registered Owner	ALEXANDER SIU WAH NAM
NRIC No	S2594768A
Email Address	HENRYSIUKL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97533970
Alternative Phone No	OFFICE-97533970

Vehicle Particulars

Manufacturer	MASERATI
Model	QUATTROPORTE S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V11826
Cover Note Number	NA

Driver

Name of Driver	HENRY SIU KAI LOK
NRIC No	S8470787B
Date Of Birth	20/12/1984
Occupation	INDOOR
Date Of Driving Pass	13/02/2004
Driving Experience	13 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97533970
Fax Number	
Contact Number	
Email Address	HENRYSIUKL@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured CHILDREN
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name CENTRAL POLICE DIVISIONAL HQ (A DIVISION)
Police Station Address ROAD: 391 NEW BRIDGE ROAD #03-112 POLICE CANTONMENT COMPLEX BLOCK A , POSTCODE: 088762 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-2240000 - FAX NO: 62200877
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO THE ATTACHMENT OF THE POLICE REPORT : I was exiting from Capital Square car park when a ComfortDelgro taxi (vehicle no. SHA 9865, driver name Mohammad Bin Abdul Rahman of NRIC S0272378F) reversed into my car. His taxi was at the taxi bay when he reversed and hit into the front of my car, even though I had tried to sound the horn to warn him. He tried to drive away and wave me off, but I stopped my car in front of his and asked for him to alight from the taxi and give me his particulars. Upon inspection of my car, there were damaged on the front bumper including a dent and scratches. There was an eye witness (Kenny Ong, contact 96489734) in the car behind me that was also exiting the car park, who can confirm my claim. I have called the management office (fire commend centre, contact: 65359110) at Capital Square to retrieve the CON footage of the accident, however, they will only release the video to the police. The video is only stored for 30 days.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA9865L
Vehicle Make/Model/Colour HYUNDAI / I40 1.7L CRDI A
Details Of Properties NA
Name of Driver MOHAMMAD BIN ABDUL RAHMAN
NRIC/Passport Number S0272378F
Contact Number
Address
Postcode
Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

KENNY ONG

Phone Number

98489734

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in the accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Handwritten Signature]

31/10/17 11:15 am


VERIFIED BY AJAX MARS
REPORTING OFFICER
EUGENE KOH

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



CAPITAL SQUARE
CAR PARK.

- A) SLK 184C
- B) SHA 9865 L
- W) WITNESS
(KENNY ONG)

POLICE REPORT



**SINGAPORE
POLICE FORCE**



A/2017 1030/7025

1 of 3

POLICE REPORT (NP299)

Report No. A/20171030/7025

Police Station Of Origin
Central Police Divisional HQ
A 391 New Bridge Road #03-112 Police
Cantonment Complex SINGAPORE 088762
Tel No:1800-2240000

Date/Time Report Made 30/10/2017 18:39	Vide Report No.	Station Diary No.
Name Of Informant HENRY SIU KAI LOK	Address 169C JOO CHIAT TERRACE SINGAPORE 427316	
ID Type / ID No. NRIC NO / S8470787B	Contact No. Home/Office:	Mobile: 97533970
Nationality SINGAPORE CITIZEN	Email Address hennysiukl@gmail.com	
Occupation Company director	Sex Male	Age 32
Institution/School Name	Date of Birth 20/12/1984	Race Chinese
Date/Time Of Incident 30/10/2017 17:35	Location Of Incident 23 CHURCH STREET CAPITAL SQUARE SINGAPORE 049481	

Brief details.

I was exiting from Capital Square car park when a ComfortDelgro taxi (vehicle no. SHA 9865, driver name Mohammad Bin Abdul Rahman of NRIC S0272378F) reversed into my car. His taxi was at the taxi bay when he reversed and hit into the front of my car, even though I had tried to sound the horn to warn him. He tried to drive away and wave me off, but I stopped my car in front of his and asked for him to alight from the taxi and give me his particulars. Upon inspection of my car, there were damaged on the front bumper including a dent and scratches. There was an eye witness (Kenny Ong, contact 98489734) in the car behind me that was also exiting the car park, who can confirm my claim. I have called the

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 30/10/2017 18:39
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

POLICE REPORT


**SINGAPORE
POLICE FORCE**


A/20171030/7025

2 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. A/20171030/7025

management office (fire command centre, contact: 65359110) at Capital Square to retrieve the CCTV footage of the accident, however, they will only release the video to the police. The video is only stored for 30 days.

Subjects Involved				
Suspect				
Person Name	Mohammed Bin Abdul Rahman			
ID Type	NRIC NO	ID No	S0272378F	
Gender	Male	Age	67	
Race	Malay	Language	English	
Occupation	Taxi driver	Address Type	HDB / HUDC	
Address	APT BLK 420 Serangoon Central #11-414 SINGAPORE 550420			
Victim				
Person Name	HENRY SIU KAI LOK			
ID Type	NRIC NO	ID No	S8470787B	
Gender	Male	Age	32	
Race	Chinese	Language	English	
Occupation	Company director	Address Type		
Address	169C JOO CHIAT TERRACE SINGAPORE 427316		Mobile No	97533970
Is Informant A Victim?	Yes			

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

30/10/2017 18:39

Classification Of Case:

POLICE REPORT



SINGAPORE
POLICE FORCE



A/20171030/7025

3 of 3

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. A/20171030/7025

Person Name	HENRY SIU KAI LOK (Informant)
-------------	-------------------------------

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 30/10/2017 18:39
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





First Captial Insurance Ltd
 6 Raffles Quay
 #21-00
 Singapore 048580

motor_claims@first-insurance.com.sg

03 November 2017

Dear Sir / Madam

RE: Masarati Quattroporte S , Vehicle Reg.No: SLK184C , Chassis No.ZAMJK39C000056012

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

A) <u>Labour Description</u>	<u>Part Cost</u>	<u>Labour Cost</u>
1 Remove, install & renew :- Front bumper, front grill, both headlamp washer system piping, front bumper air conveyor, both headlamp, indicator lamp and engine under tray.		\$ 5,800.00 4650
2 Reshape left & right headlamp support bracket.		\$ 850 1,050.00
3 Remove & Renew front bonnet include alignment.		XMS \$ 1,200.00 750
4 Reset all system with computer tester and reset headlight aiming .		\$ 1,500.00 1200
5 Reset all wheel alignment		MS \$? 650.00
6 Respray premier & paint: Front front bumper, front bonnet, parking sensor and bull bar		\$ 5,400.00 2800

B) <u>Parts</u>	<u>Qty</u>	<u>Total Price (\$\$)</u>
1 Complete Frt Bumper MQP	1	\$ 8,456.80 DE
2 Air Conveyor Gasket	1	\$ 75.00 ? nee
3 Screw	5	\$ 19.50 ? nee
4 Washer	5	\$ 17.50 ? nee
5 Tow Hook Plug (MY2009)	1	\$ 10.00 ? nee
6 Bracket	4	\$ 48.00 ? nee
7 Complete Calendar Chrome	1	\$ 1,656.60 ? CAP
8 Screw For Frt Grille	4	\$ 33.00 ? nee
9 Front Bumper Cpl Net Kit	1	\$ 1,570.14 ? Cpl
10 RH Fog Headlight Plate	1	\$ 527.35 ? nee
11 Lh Fog Headlight Plate	1	\$ 527.35 ? nee
12 FRONT BUMPER CABLE	1	\$ 2,818.00 ? X
13 Grill Park Sensor Support LH	1	\$ 18.00 ? nee

14	Grill Park Sensor Support RH	1	\$	18.00	? ne /
15	P Sensor Gasket Dark Paint	2	\$	7.60	? ne /
16	Innner Parking Sensor	2	\$	790.00	? x su
17	Front Parking Sensor Sleeve	2	\$	99.00	? ne /
18	RING Valid for cars with light paint	2	\$	70.00	? x su
19	Outer Parking Sensor	2	\$	1,530.00	? x su
20	Oval Emblem, Mgs	1	\$	65.00	? ne /
21	Frnt Hood Bonnet - Mqp	1	\$	6,845.00	R
22	Button	24	\$	108.00	? } x su
23	Gasket	1	\$	352.00	? } x su
24	RH Front LED Headlight	1	\$	6,250.00	? ch /
25	LH Front LED Headlight	1	\$	6,250.00	? ch /
26	RH Headlight Washer Plate	1	\$	93.95	? ne /
27	LH Headlight Washer Plate	1	\$	93.95	? ne /
28	Under Body Flor Shield	1	\$	380.00	x su
29	Bracket	3	\$	7.50	? ka n
30	Cap - Mqp (nut)	7	\$	315.00	? complete ne /
31	Screw	1	\$	2.20	? ne /
32	Screw	3	\$	12.00	? ne /
33	Screw -Mgs	11	\$	31.35	? ne /
34	Bracket	11	\$	71.50	? ne /
35	Screw	6	\$	12.00	? ne /
36	RH TELESCOPIC HEADLIGHT WASHER	1	\$	792.00	? x su
37	REG PLATE NO.	1	\$	80.00	78 ne /

RASUL

Hp 90010068
7 days
P/P
15/11/17 @ 1100
Resurvey by part

\$	40,053.29	\$	15,600.00
Total Labour	:	\$	15,600.00
Total Parts	:	\$	40,053.29
Plus 7% GST	:	\$	3,895.73
Grand Total	:	\$	59,549.02

Should this repair job require any additional parts, we will inform you and bill you accordingly. Please confirm your acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

Yours sincerely,

I agree and accept the above quotation.

Workshop Department

Signature & Company stamp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Chassis No. 0056012

Customer

Number Plate:

Model

Engine Type:

Assembly No.

Gearbox Type

Life Start Date 2010-12-03T00:00:00

Faults**01/11/2017 3:32:00 PM**

Chassis No.	0056012		
Days to next service check	408	Km to next service check	11783
Number of check executed	4	Dealer code	61326
ECU Identification Code	NFA HEADLIGHT MASTER	Acceptance	AUTOMATIC
Km:	35284		
Maintenance Program active		Warranty Start Date	0001-01- 01T00:00:00
Warranty End Date	0001-01- 01T00:00:00	Warranty Type	
Service Entries active			

Identification Parameters

DRAW N.:	215137	HW N.:	1307329127
HW VER.:	01	SW N.:	1037373659
SW VER.:	0000	ISO CODE	C107020423
PRODUCTION DATE:	03/11/2009		

Faults

**1 MALFUNZIONAMENTO MOTORE PASSO-PASSO DELL AVAC /
B1040
NO SYMPTOM AVAILABLE**

DTC: 0x9040 FMI: 0x0 Status: PRES.

Environmental Conditions

INFO 1 DIAGNOSIS COMPLETED

INFO 2 ERROR PRESENT

INFO 3 WARNING LAMP ON

INFO 4 NO INFORMATION AVAILABLE

Hong Seh Motors Pte Ltd
 10 Fourth Lok Yang Road
 Singapore, 629707

Phone No. 6266 1555
 Fax No. 6265 9595
 E-Mail

Hong Seh Motors Pte Ltd, 10 Fourth Lok Yang Road, Singapore, 629707

Siu Wah Nam Alexander
 127 Lorong K Telok Kurau
 #02-05
 , 425768

VAT Registrat/ M2-0055566-0

Service Preview

Customer No. CUST2383
 Order No. SO18010010-R
 ReceivingDate 10/01/16 13:26
 Pickup Appt.
 Order Limit
 Page 1

Phone: Mobile 97533970

Make	Model Description	Mileage	Service Technician
MASERATI	Quattroporte S (4.7)	36,540	Cheah Yen Hwa
License No.	VIN	Initial Registration	Sales Advisor
SLK184C	ZAMJK39C000056012	03/12/10	
Engine Code	Labor Type	Engine No.	Model Code
M139R		166409	M139/BBR

No.	Bill-to Customer N	Description	Qty.	UoM	Unit Price	Amount
10000		Accident repair works, front bumper , headlamp - Accident Claim Rep				
EXTSVC0023	CUST1120	Repair/Respray Frt Bonnet/Fender/All Rims/	1	Unit	4,600.00	4,600.00 ✓
TAW0000208	CUST1120	Reshape Lh & Rh Headlamp Support Brack	1	Hour	850.00	850.00 ✓
TAW0000208	CUST1120	Reset All System & Headlamp Aiming With	1	Hour	1,200.00	1,200.00 ✓
TAW0000208	CUST1120	Respray Front Bumper, Bonnet & Bull Bar.	1	Hour	2,800.00	2,800.00 ✓
TAW0000208	CUST1120	3rd Party Insurance Company Enqulry Fee.	1	Hour	5.00	5.00
		Sum Labor				9,455.00
	CUST1120	1) Complete Frt Bumper MQP' with parking sensor	1	Piece	8,456.80	8,456.80
	CUST1120	2) Air Conveyor Gasket	1	Piece	75.00	75.00
	CUST1120	3) Screw	5	Piece	3.90	19.50
	CUST1120	4) Washer	5	Piece	3.50	17.50
	CUST1120	5) Tow Hook Plug	1	Piece	10.00	10.00
	CUST1120	6) Clip	4	Piece	12.00	48.00
	CUST1120	7) Complete Calendar Chrome Std	1	Piece	1,656.60	1,656.60
	CUST1120	8) Screw For Frt Grille	4	Pieca	8.25	33.00
	CUST1120	9) Front Bumper Cpl Net Kit	1	Piece	1,570.14	1,570.14
	CUST1120	10) RH Fog Headlight Plate	1	Piece	527.35	527.35
	CUST1120	11) Lh Fog Headlight Plate	1	Piece	527.35	527.35
	CUST1120	13) Grill Park Sensor Support LH	1	Piece	18.00	18.00
	CUST1120	14) Grill Park Sensor Support RH	1	Piece	18.00	18.00

Sum carried forward 22,439.84

Hong Seh Motors Pte Ltd
 10 Fourth Lok Yang Road
 Singapore, 629707

Phone No. 6266 1555
 Fax No. 6265 9595
 E-Mail

Hong Seh Motors Pte Ltd, 10 Fourth Lok Yang Road, Singapore, 629707

Siu Wah Nam Alexander
 127 Lorong K Telok Kurau
 #02-05
 , 425766

VAT Registrati M2-0055566-0

Service Preview

Customer No. CUST2383
 Order No. SO18010010-R
 ReceivingDate 10/01/18 13:28
 Pickup Appt.
 Order Limit
 Page 2

Phone: Mobile 97533970

Make	Model Description	Mileage	Service Technician
MASERATI	Quattroporte S (4.7)	36,540	Cheah Yen Hwa
License No.	VIN	Initial Registration	Sales Advisor
SLK184C	ZAMJK39C000056012	03/12/10	
Engine Code	Labor Type	Engine No.	Model Code
M139R		166409	M139/BBR

				Continued	22,439.84
CUST1120	15) P Sensor Gasket Dark Paint	2 Piece	3.80	7.60	
CUST1120	17) Front Parking Sensor Sleeve	2 Piece	49.50	99.00	
CUST1120	20) Oval Emblem, Mgs A2J3	1 Piece	65.00	65.00	
CUST1120	24) RH Front Headlight MQPGTS	1 Piece	6,250.00	6,250.00	
CUST1120	25) LH Front Headlight MQPGTS	1 Piece	6,250.00	6,250.00	
CUST1120	26) RH Headlight Washer Plate	1 Piece	93.95	93.95	
CUST1120	27) LH Headlight Washer Plate	1 Piece	93.95	93.95	
CUST1120	30) Cap - Mqp	7 Piece	45.00	315.00	
CUST1120	31) Screw	1 Piece	2.20	2.20	
CUST1120	32) Screw	3 Piece	4.00	12.00	
CUST1120	33) Screw -Mgs	11 Piece	2.85	31.35	
CUST1120	34) Bracket	11 Piece	6.50	71.50	
CUST1120	35) Screw	6 Piece	2.00	12.00	
CUST1120	12) Front Bumper Wiring	1 Piece	2,818.00	2,818.00	
CUST1120	Front Reg Plate. A1C2	1 Piece	78.00	78.00	
Sum Item					29,176.79
Sum Service Job No. 10000					38,631.79
Total SGD					38,631.79
7% GST					2,704.23
Total SGD Incl. VAT					41,336.02

Chassis No. 0056012
Customer
Number Plate:
Model
Engine Type:
Assembly No.
Gearbox Type
Life Start Date 2010-12-03T00:00:00

Faults

01/11/2017 3:32:00 PM

Chassis No.	0056012		
Days to next service check	408	Km to next service check	11783
Number of check executed	4	Dealer code	61326
ECU Identification Code	NFA HEADLIGHT MASTER	Acceptance	AUTOMATIC
Km:	35284		
Maintenance Program active		Warranty Start Date	0001-01- 01T00:00:00
Warranty End Date	0001-01- 01T00:00:00	Warranty Type	
Service Entries active			

Identification Parameters

DRAW N.:	215137	HW N.:	1307329127
HW VER.:	01	SW N.:	1037373659
SW VER.:	0000	ISO CODE	C107020423
PRODUCTION DATE:	03/11/2009		

Faults

1 MALFUNZIONAMENTO MOTORE PASSO-PASSO DELL AVAC
B1040
NO SYMPTOM AVAILABLE

DTC: 0x9040 FMI: 0x0 Status: PRES.

Environmental Conditions

INFO 1 DIAGNOSIS COMPLETED
INFO 2 ERROR PRESENT
INFO 3 WARNING LAMP ON
INFO 4 NO INFORMATION AVAILABLE

01/11/2017 3:34:27 PM - Parameters NFA HEADLIGHT MASTER



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17021179/R1rbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-09-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9865L	Veh. Inspected	SLK 184C
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17010311MFSH	Excess (\$)	0.00
Assign From	AUNG YIN MIN	Assign Date	06/11/2017
2. Vehicle Particulars & Condition			
Make & Model	MASERATI QUATTROPORTE	c.c	4691
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	ZAMJK39C000056012	Colour	BLACK
Odometer	35740	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	285/35Z R19	MICHELIN	6 mm
L/H Front Tyre	285/35Z R19	MICHELIN	6 mm
R/H Rear Tyre	285/35Z R19	MICHELIN	6 mm
L/H Rear Tyre	285/35Z R19	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/10/2017	Inspection Date	15/11/2017
Survey held at	HONG SEH MOTORS PTE LTD 10 FOURTH LOK YANG ROAD JURONG TOWN SINGAPORE 628631		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 184C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COMPLETE FRT BUMPER MQP	DEFORMED	8,456.80	8,456.80
1	AIR CONVEYOR GASKET	NECESSARY	75.00	75.00
5	SCREW	NECESSARY	19.50	19.50
5	WASHER	NECESSARY	17.50	17.50
1	TOW HOOK PLUG (MY2009)	NECESSARY	10.00	10.00
4	BRACKET	NECESSARY	48.00	48.00
1	COMPLETE CALENDAR CHROME	CRACKED	1,656.60	1,656.60
4	SCREW FOR FRT GRILLE	NECESSARY	33.00	33.00
1	FRONT BUMPER CPL NET KIT	CUT	1,570.14	1,570.14
1	RH FOG HEADLIGHT PLATE	NECESSARY	527.35	527.35
1	LH FOG HEADLIGHT PLATE	NECESSARY	527.35	527.35
1	FRONT BUMPER CABLE	NECESSARY	2,818.00	2,818.00
1	GRILL PARK SENSOR SUPPORT LH	NECESSARY	18.00	18.00
1	GRILL PARK SENSOR SUPPORT RH	NECESSARY	18.00	18.00
2	P SENSOR GASKET DARK PAINT	NECESSARY	7.60	7.60
2	INNER PARKING SENSOR	SERVICEABLE	790.00	-
2	FRONT PARKING SENSOR SLEEVE	NECESSARY	99.00	99.00
2	RING VALID FOR CARS WITH LIGHT PAINT	SERVICEABLE	70.00	-
2	OUTER PARKING SENSOR	SERVICEABLE	1,530.00	-
1	OVAL EMBLEM, MGS	NECESSARY	65.00	65.00
1	FRT HOOD BONNET - MQP	TO REPAIR SEE LABOUR	6,845.00	-
24	BUTTON	SERVICEABLE	108.00	-
1	GASKET	SERVICEABLE	352.00	-
1	RH FRONT LED HEADLIGHT	CRACKED	6,250.00	6,250.00
1	LH FRONT LED HEADLIGHT	CRACKED	6,250.00	6,250.00
1	RH HEADLIGHT WASHER PLATE	NECESSARY	93.95	93.95
1	LH HEADLIGHT WASHER PLATE	NECESSARY	93.95	93.95
1	UNDER BODY FLOR SHIELD	SERVICEABLE	380.00	-
3	BRACKET	NOT NECESSARY	7.50	-
7	CAP-MQP	NECESSARY	315.00	315.00

Report Ref No. CS/FCI17021179/R1rbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SCREW	NECESSARY	2.20	2.20
3	SCREW	NECESSARY	12.00	12.00
11	SCREW - MGS	NECESSARY	31.35	31.35
11	BRACKET	NECESSARY	71.50	71.50
6	SCREW	NECESSARY	12.00	12.00
1	RH TELESCOPIC HEADLIGHT WASHER	SERVICEABLE	792.00	-
1	REG PLATE NO.	NECESSARY	80.00	78.00
			40,053.29	29,176.79
	LABOUR			
	REMOVE, INSTALL & RENEW : - FRONT BUMPER, FRONT GRILL, BOTH HEADLAMP WASHER SYSTEM PIPING, FRONT BUMPER AIR CONVEYOR, BOTH HEADLAMP, INDICATOR LAMP AND ENGINE UNDER TRAY. INCLUSIVE OF THE REPAIR OF FRONT HOOD BONNET - MQP.		5,800.00	4,600.00
	RESHAPE LEFT & RIGHT HEADLAMP SUPPORT BRACKET.		1,050.00	850.00
	REMOVE & RENEW FRONT BONNET INCLUDE ALIGNMENT.	NOT NECESSARY	1,200.00	-
	RESET ALL SYSTEM WITH COMPUTER TESTER AND RESET HEADLIGHT AIMING.		1,500.00	1,200.00
	RESET ALL WHEEL ALIGNMENT.	NOT NECESSARY	650.00	-
	RESPRAY PRIMER & PAINT : - FRONT BUMPER, FRONT BONNET, PARKING SENSOR AND BULL BAR.		5,400.00	2,800.00
			15,600.00	9,450.00
	GRAND TOTAL		55,653.29	38,626.79
	RECOMMENDED COST OF REPAIRS			38,626.79

Report Ref No. CS/FCI17021179/R1rbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.