

S. REC. BY:

REF:

CS/MS(17021210/R1b)

Special Instruction:

SUBJECT  
me m/s

R/SU1

## ASSIGNMENT (Office)

From (Person):

Kwok Woon Choo

of

MSU1

Date/Time:

06/11/2017 4:43pm

Estimated Cost:

Bill to:

Op/TP+WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKJ 5154Z

Insured:

at Workshop m/s:

Performance

Tel:

9116 5779

of

303 Alexandra Rd

Policy No:

627 500774SMP

Claim No:

535538

Sum Insured:

Excess:

\$ 750.00

Make of Veh:

(Client's Record)

D.O.A.

27/10/2017

CA / REV /

REP. / REV 24 HRS

07/11/2017 @ 10am owner writing

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Gary

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKJ 5154Z - X
	Sent preli through merimen, seek mandate
9/11/17	Authorise repair & inform Gary Poh by email
	Confirm \$10,318.10, 7 days
	Ref: \$920360, 47%





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17021210/R1rb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 07-11-2017		
		Code : MSG		
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.	Veh. Inspected		SKJ 5154Z	
Policy No.	B27500274SMP	Coverage (\$)	0.00	
Claim No.	535538	Excess (\$)	750.00	
Assign From	MERIMEN (KWOK WOON CHOO)	Assign Date	06/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	27/10/2017	Inspection Date	07/11/2017	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
<b>5a. Remarks</b>				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sun@lkkauto.com](mailto:sun@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 08 Nov 2017

**Preliminary Advice**

Vehicle No	: SKJ5154Z	Accident Date	: 27/10/2017
Make	: BMW 520I	Policy No.	: B27500274SMP
Assignment Date	: 06/11/2017	Excess	: S\$750.00
Date of Inspection	: 07/11/2017	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,513.60	19,521.70
Revised Amount	:S\$	9,443.15	
Check Items (Estimated)	:S\$	4,036.20	
Total	:S\$	13,479.35	

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	70,700.00
Salvage Value	:S\$	
Margin for Repair	:S\$	41,300.00

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

## Print Received Message

This mail is associated with :

**\*SKJ5154Z (535538)**

OD

Oct 27 2017 8:00PM

[SING VARSHA]

Performance Motors Limited

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 08/11/2017 14:40 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$9443.15) - SKJ5154Z - Claim Handler: Kwok Woon Choo

Approved:9443.15:a if c; check items to be confirmed

**Janice Lee (LKKAuto)**

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Thursday, November 09, 2017 2:54 PM  
**To:** 'gary.poh.chaihoon@simedarby.com.sg'  
**Cc:** SUR  
**Subject:** SKJ 5154Z

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKJ 5154Z (excess \$750.00/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 02 May 2018

## **Preliminary Advice**

Vehicle No	: SKJ5154Z	Accident Date	: 27/10/2017
Make	: BMW 520I	Policy No.	: B27500274SMP
Assignment Date	: 06/11/2017	Excess	: S\$750.00
Date of Inspection	: 07/11/2017	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

## **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,521.70	(Include Supplementary \$8,10)
Revised Amount	:S\$	10,318.10	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	10,318.10	
Lump Sum Repair	:S\$		

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	70,700.00
Salvage Value	:S\$	
Margin for Repair	:S\$	41,300.00

## **Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/11/2017 14:53
Date Of Accident	27/10/2017 20:00
Exact Location Of Accident	CAR PARKING AT RESIDENCE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ5154Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SING VARSHA
Passport No/FIN	G5328135X
Email Address	VIKAS.V.SINGH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96690186
Alternative Phone No	OFFICE-87223175

### Vehicle Particulars

Manufacturer	BMW
Model	520
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27500274SMP
Cover Note Number	

### Driver

Name of Driver	VIKAS SINGH
Passport No/FIN	G5328056R
Date Of Birth	15/06/1973
Occupation	INDOOR
Date Of Driving Pass	01/07/2013
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96690186
Fax Number	
Contact Number	OFFICE-97223175
Email Address	VIKAS.V.SINGH@GMAIL.COM



Address	#02-02 SANCTUARY GREEN 185 TANJONG RHU RD
Postcode	436924
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Identification Number **G5328056R**  
 Name **VIKAS SINGH**  
 Date of Birth **15 Jun 1973**  
 Issue Date **01 Jul 2013**  
 Valid Till **30 Jun 2018**

002197616J

Identification Number **G5328135X**  
 Name **SINGH VARSHA**  
 Date of Birth **22 May 1978**  
 Issue Date **10 Jul 2013**  
 Valid Till **09 Jul 2018**

002200750B

REPUBLIC OF SINGAPORE

FIN **G5328056R**



Name  
**SINGH VIKAS**

Date of Birth  
**15-06-1973**

Sex  
**M**

Nationality  
**INDIAN**



**EMPLOYMENT PASS**

Employment of Foreign Manpower Act (Chapter 91A)  
 Republic of Singapore

Employer  
**STANDARD CHARTERED BANK**



Name  
**SINGH VARSHA**  
 Occupation  
**SENIOR ANALYST**

FIN  
**G5328135X**

Date of Application

**09-09-2016**

Date of Issue

**15-09-2016**

Date of Expiry

**01-12-2019**



**L7216350**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles <= 200 cc 01 Jul 2013  
 Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 01 Jul 2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles <= 200 cc 10 Jul 2013  
 Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg 10 Jul 2013

NP 428A



NP 428A



FA1770764

**DEPENDANT'S PASS**  
 Immigration Regulations

FIN **G5328056R**

MULTIPLE JOURNEY VISA ISSUED

Date of Issue **26-09-2016** Date of Expiry **01-12-2019**



YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

**VISIT PASS**  
 Immigration Regulations

Name  
**SINGH VARSHA**



Date of Birth

**22-05-1978**

Sex

**F**

Nationality

**CHINESE**

FIN

**G5328135X**

Date of Issue

**15-09-2016**

Date of Expiry

**01-12-2019**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



Your alternative contact:

MSiG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
Co Reg No. 200412212G GST Reg No. 20-0412212G

Sime Darby Insurance  
Brokers (Singapore) Pte Ltd  
Tel: 6222 2244  
Mon to Fri (excluding PH)  
(8.30 am - 5.45 pm)

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
Individual Ownership

SIME MOTOR PRIVATE  
Comprehensive

Certificate No. B 27500274 SMP

Excess: SGD750

1. Index Mark and Registration Number of Vehicle  
SKJ5154Z

2. Name of Policyholder  
Varsha Singh

3. Effective Date of the Commencement of Insurance for the purposes of the Act  
12/04/2017

4. Date of Expiry of Insurance  
11/04/2018

5. Persons or Classes of Persons entitled to drive\*

Varsha Singh

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT PERFORMANCE MOTORS LTD OR AT ANY WORKSHOP OF YOUR CHOICE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSiG Insurance (Singapore) Pte. Ltd.  
Approved Insurers

  
for Chief Executive Officer

## Enquire PARF/COE Rebate for Registered Vehicle

## Vehicle Owner Particulars

Owner ID Type	Foreign Identification Number
Owner ID	8135X

## Vehicle Details

Vehicle No.	SKJ5154Z
Vehicle to be Exported	No
Intended De-registration Date	08 Nov 2017
Vehicle Make	B.M.W.
Vehicle Model	520I 2.0L AT D/AB 2WD 4DR GAS/D NAV
Primary Colour	Grey
Manufacturing Year	2013
Engine No.	B7420442N20B20B
Chassis No.	WBAXG12040DX53467
Maximum Power Output	135.0 kW (181 bhp)
Open Market Value	\$42,008.00
Original Registration Date	12 Apr 2013
First Registration Date	12 Apr 2013
Transfer Count	0
Actual ARF Paid	\$45,812.00

## Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	11 Apr 2023
PARF Rebate Amount	\$34,359.00

## Intended COE Rebate Details

COE Expiry Date	11 Apr 2023
COE Category	E - Open Category
COE Period(Years)	10
QP Paid	\$66,989.00
COE Rebate Amount	\$36,341.00
<b>Total Rebate Amount</b>	<b>\$70,700.00</b>

The information contained herein is correct as at 08 Nov 2017

OK

112,000  
70,700  
41,300



Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 13 Oct 2017 at 07:07 PM

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401889M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 119941

Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

380, Kampong Arang Road  
East Coast Centre  
Singapore 438180

Tel: 63180888 (AfterSales)  
Fax: 63449773

313, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944

Tel: 63190529 (AfterSales)  
63190533 (Motorrad)  
Fax: 64796621 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 44704  
Date Estimated : 03/11/2017  
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

## - ESTIMATE REPAIR FOR -

Varsha Singh  
185 Tanjong Rhu Road  
#02-02

Singapore 436924

## - ACCOUNT -

66

MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ5154Z	DX53467	12/04/2013	520iA	0

## DESCRIPTION

## VALUE

To replace rear bumper, bootlid, tail panel and attachment  
include knocking cause by the accident

2550 5,525.00

Painting rear bumper, bootlid, tail panel, trunk floor, left  
rear fender, right rear fender.

2537 5,380.00

To check electrical wiring systems and lightings at the  
rear section for proper function.

150 177.00

To remove old PDC assembly, replace damaged parts and  
reconnect to new bumper including conduct checks for  
proper function.

150 177.00

To remove and install boot compartment carpet and garnish  
to facilitate repairs.

230 271.00

To transfer lock mechanism from old to new bootlid  
including conduct checks on new bootlid central locking  
system for proper function.

451 531.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To carry out body cavity preservation.  
(For cut panel).

451? 531.00

Sundries. *NP*

150.00

Total Labour 1: 12,860.00

## DESCRIPTION

## QTY PRIC

## VALUE

TAIL END PANEL

1 817.30

X500? 817.30

BOOTLID

1 1,563.30

151 1,563.30

RR BUMPER GUIDE BOTTOM CENTRE

1 57.50

100 57.50

RR BUMPER CTR GUIDE

1 65.75

100 65.75

## Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 287402259W GST Reg. No. M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64787772

285, Kampong Arang Road  
East Coast Centre  
Singapore 418180  
Tel: 63190888 (AfterSales)  
Fax: 63443772

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190628 (AfterSales)  
63190533/E30 (Motorrad)  
Fax: 64796201 (AfterSales)  
64796234 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 44704  
Date Estimated : 03/11/2017  
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKJ5154Z	DX53467	12/04/2013	520iA	0

## DESCRIPTION

RR BUMPER CTR GUIDE  
RR BUMPER LH MOUNT  
RR BUMPER RH MOUNT  
RR BUMPER CARRIER  
RR BUMPER PANEL PRIMED (PDC)  
RR BUMPER TOW HOOK COVER PRIMED  
RR BUMPER ADAPTER  
EMBLEM GROMMET  
BMW EMBLEM  
MODEL LETTERING 520i  
DECOUPLING RING PDC TORQUE CONVERTE  
BUMPER PDC SENSOR (A90 SOPHISTOGRU

QTY PRIC

1 65.75  
1 141.65  
1 141.65  
1 696.80  
1 1,431.40  
1 23.25  
1 46.80  
2 0.80  
1 67.80  
1 61.05  
4 4.95  
4 363.05

VALUE

65.75  
141.65  
141.65  
696.80  
1,431.40  
23.25  
46.80  
1.60  
67.80  
61.05  
19.80  
1,452.20

Total Parts : 6,653.60

Claims CO / 3rd Party / Uninsured losses / Direct

Regn No.

Date No.

Estimate

07/11/17 @ 1010

Excess

750

Surveyor's Name

Rene

Sig.

Surveyor's Tel

900 10068

Address

C Renter

Authorized Date

Time

RESURVEY PARTS PHOTO BY SURVEYOR

Surveyor's E-mail

No. of Working Days Recommended

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rene 50 part

22/11/17

Labour 1	: 19,513.60	12,860.00
Parts	:	6,653.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,365.95
Grand Total	:	20,879.55

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co.Reg. No. 197401559M, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 44704  
Date Estimated : 03/11/2017  
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
Varsha Singh  
185 Tanjong Rhu Road  
#02-02

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 436924

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKJ5154Z	DX53467	12/04/2013	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# PLUG BLACK D=5MM *	0.90	9.00		8.10 <i>mw</i>
----------------------	------	------	--	----------------

Total Labour :	
Total Parts :	8.10
Total Labour & Parts :	8.10





## FINAL REPORT

Estimate No. : b1 44704  
 Date Estimated : 03/11/2017  
 Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -  
 Vaseha Singh  
 185 Tanjong Rhu Road  
 #02-02

- ACCOUNT - 66  
 MSIG Insurance (S) Pte Ltd  
 4 Shenton Way  
 #21-01 SGX Centre 2  
 Singapore 068807

Singapore 436924

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKJ5154Z	DXS3467	12/04/2013	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments; boot lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint rear bumper, boot lid and tail end panel	2537.00		2,537.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00		451.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,563.30	1.00		1,563.30
RR BUMPER GUIDE BOTTOM CENTRE	57.50	1.00		57.50
RR BUMPER CTR GUIDE	65.75	1.00		65.75
RR BUMPER CARRIER	696.80	1.00		696.80
RR BUMPER PANEL PRIMED (PDC)	1,431.40	1.00		1,431.40
RR BUMPER ADAPTER	46.80	1.00		46.80
EMBLEM GROMMET	0.80	2.00		1.60
MODEL LETTERING 520i	61.05	1.00		61.05
BMW EMBLEM	67.80	1.00		67.80
# PLUG BLACK D=5MM *	0.90	9.00		8.10

### # SUPPLEMENTARY ITEMS

Total Labour :	6,318.00
Total Parts :	4,000.10
Total Labour & Parts :	10,318.10
Deduction for Excess :	750.00
Total Repair Costs less Excess:	9,568.10
GST @7%:	669.77
Grand Total :	10,237.87

**Janice Lee (LKKAUTO)**

---

**From:** PBSP <pml-pbsp@sime-darby.com.sg>  
**Sent:** Saturday, February 24, 2018 11:39 AM  
**To:** Rasul (LKKAUTO); SUR  
**Subject:** URGENT REMINDER: FINAL REPORT / SKJ5154Z  
**Attachments:** Final Report SKJ5154Z.pdf; Final Report SKJ5154Z\_2.pdf

Urgent reminder

---

**From:** PBSP  
**Sent:** Tuesday, 16 January 2018 4:25 PM  
**To:** Rasul; SUR  
**Subject:** FINAL REPORT / SKJ5154Z

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,318.00  
Total Parts : 4,000.10  
Total Labour & Parts : 10,318.10

Repair days: 7

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Nov 2017		06 Nov 2017 16:43 <a href="#">Edit Adj Rpt</a>	<b>S\$10,318.10</b> <a href="#">Edit Estimates</a>	<b>S\$10,318.10</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>SING VARSHA</b> , ID: G5328135X, Tel: +6596690186								
Vehicle Reg. No.:	<b>SKJ5154Z</b>	Date of Loss:	27/10/2017 20:00 - :59 [54 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / 535538</b>	Policy/Cover Note No.:	B27500274SMP (Comprehensive) Coverage: 12/04/2017 - 11/04/2018						
		Excess:	S\$750.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Kwok Woon Choo</b> - 6643 1330]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 06/12/2017]								
Driver/Custodian:	<b>VIKAS SINGH</b> (44 / Male), NRIC: G5328056R, Tel: +6596690186								
Adj Asg. Remarks:	to revert								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (04/05/2018): Alert - Adj Mandate Approved (S\$10318.10) - SKJ5154Z - Claim Handler: Kwok Woon ...</li> <li>MSIG_SG (08/11/2017): Alert - Adj Mandate Approved (S\$9443.15) - SKJ5154Z - Claim Handler: Kwok Woon C...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

\*SKJ5154Z (535538)  
OD  
Oct 27 2017 8:00PM  
[SING VARSHA]  
Performance Motors Limited

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a> <span>▼</span>	
<b>Assessment Reports</b>			1 per page <span>▼</span>	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail Print
1	03/11/17 15:03	Accident Statement	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	08/11/17 12:49	Adjuster Immediate Advice	1 Load HTM	
2	02/05/18 15:19	Adjuster Immediate Advice	1 Load HTM	
<b>Photos/Images</b>			3 per page <span>▼</span>	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail Print
1	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
2	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
3	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
4	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
5	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
6	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
7	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
8	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
9	03/11/17 15:02	Accident Photo [Linked Accident Report Documents]	1 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
2	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
3	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
4	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
5	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
6	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
7	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
8	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
9	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
10	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
11	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
12	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
13	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
14	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
15	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
16	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
17	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
18	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
19	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
20	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
21	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
22	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
23	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
24	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
25	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>
26	04/05/18 10:35	General View	1 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
27	04/05/18 10:35	General View		Load JPG <input checked="" type="checkbox"/>
28	04/05/18 10:35	General View		Load JPG <input checked="" type="checkbox"/>
29	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
30	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
31	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
32	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
33	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
34	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
35	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
36	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	04/05/18 10:36	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/11/17 15:02	PML FAX + OD ESTIMATE		Load PDF <input checked="" type="checkbox"/>
2	06/11/17 15:04	INSD AND DRIVER NRIC + DL + EMPLOYNEBT PASS		Load PDF <input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	03/11/17 15:01	Sketch Plan <small>(Linked Accident Report Documents)</small>		Load TIF <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/17 12:56	WORKSHOP ESTIMATE		Load PDF <input checked="" type="checkbox"/>
2	02/05/18 15:31	SKJ 5154Z FINALISE ESTIMATE		Load PDF <input checked="" type="checkbox"/>
3	14/05/18 16:39	SUPPLEMENTARY PART		Load PDF <input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	03/11/17 15:03	Accident Statement		Load HTM <input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	03/11/17 15:02	Accident Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	03/11/17 15:01	Sketch Plan		Load TIF <input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



# LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG17021210/R1RBQ2

Date: 14/05/2018

### REFERENCE

Insured/Claimant:	SING VARSHA	Policy No:	B27500274SMP	
Date of Loss:	27/10/2017	Nature of Claim:	OD	Claim No: 535538

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ5154Z		
Make & Model:	BMW 520i, 2.0 (A)	Engine No:	B7420442N20B20B
Reg. Date:	12/04/2013 (Man. Year: 2013)	Chassis No:	WBAXG12040DX53467
Colour:	Black	Odometer:	51390 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$112,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,811.70	4,150.10	2,661.60	39.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,710.00	6,168.00	6,542.00	51.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,521.70</b>	<b>10,318.10</b>	<b>9,203.60</b>	<b>47.15</b>
<b>- Excess (S\$)</b>	<b>750.00</b>	<b>750.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>18,771.70</b>	<b>9,568.10</b>	<b>9,203.60</b>	<b>49.03</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,314.02</b>	<b>669.77</b>	<b>644.25</b>	<b>49.03</b>
<b>Nett Amount (S\$)</b>	<b>20,085.72</b>	<b>10,237.87</b>	<b>9,847.85</b>	<b>49.03</b>

### INSPECTION

Date of Assignment: 06/11/2017

Date Inspected: 07/11/2017 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2018)
<b>Parts:</b>	143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKJ5154Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*TAIL END PANEL	Serviceable	817.30 FS	*- FS
3	1		*BOOTLID	Bent	1,563.30 FS	*1,563.30 FS
4	1		*RR BUMPER GUIDE BOTTOM CENTRE	Cracked	57.50 FS	*57.50 FS
5	1		*RR BUMPER CTR GUIDE	Cracked	65.75 FS	*65.75 FS
6	1		*RR BUMPER CTR GUIDE	Repair	65.75 FS	*- FS
7	1		*RR BUMPER LH MOUNT	Serviceable	141.65 FS	*- FS
8	1		*RR BUMPER RH MOUNT	Serviceable	141.65 FS	*- FS
9	1		*RR BUMPER CARRIER	Bent	696.80 FS	*696.80 FS
10	1		*RR BUMPER PANEL PRIMED (PDC)	Deformed	1,431.40 FS	*1,431.40 FS
11	1		*RR BUMPER TOW HOOK COVER PRIMED	Not Necessary	23.25 FS	*- FS
12	1		*RR BUMPER ADAPTER	Cracked	46.80 FS	*46.80 FS
13	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
14	1		*BMW EMBLEM	Necessary	67.80 FS	*67.80 FS
15	1		*MODEL LETTERING 520i	Necessary	61.05 FS	*61.05 FS
16	4		*DECOUPLING RING PDC TORQUE CONVERTE	Serviceable	19.80 FS	*- FS
17	4		*BUMPER PDC SENSOR (A90 SOPHISTOGRAU)	Serviceable	1,452.20 FS	*- FS
18	1		*PLUG BLACK D=5MM	Necessary	8.10 FS	*8.10 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>6,811.70</b>	<b>4,150.10</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER ,BOOTLID ,TAIL PANEL AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	5,525.00	2,550.00
2	PAINTING REAR BUMPER ,BOOTLID ,TAIL PANEL,TRUNK FLOOR ,LEFT REAR FENDER ,RIGHT REAR FENDER	New	5,380.00	2,537.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIR	New	271.00	230.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
7	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>12,710.00</b>	<b>6,168.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >