

22/03/2003

ASS. REC. BY:

REF: CS3/SMD17013746 / Ggb-17

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Gmoh Pau Loong of SMD Date/Time: 08/11/2017

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 2813T Insured: PC 364J

at Workshop m/s Ryder Auto Tel: 9752 6673

of Blk 1 Kaki Bukit Ave 6 # 01-56

Policy No: \_\_\_\_\_ Claim No: CMTD170246 / GPL

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A 17072017  
(Client's Record)

CA / REV / REP. / REV 24 HRS w/p H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 17072017 117 pm Person Contacted: Mr. Lhun Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	<u>SJW 2813T - NR / 11/11/2017 / 15</u>
	<u>PC 364J - X</u>
	<u>Disassemble Part : 18/07/2017</u>
	<u>After repair : 24/07/2017</u>
<u>29/11/17</u>	<u>Submit 4S \$ 6600 , 7 day . (Red: 6400 , 49%).</u>
<u>26/03/17 12:22pm</u>	<u>Email to bene.</u>

RECEIVED 29 NOV 2017.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO17013746/gb-1	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 08-11-2017	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 564J	Veh. Inspected	SJW 2813T
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1702416/GPL	Excess (\$)	0.00
Assign From	GNOH PAU LOONG	Assign Date	08/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/07/2017	Inspection Date	08/11/2017
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

## Catherine Chong (LKK Auto)

---

**From:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>  
**Sent:** Wednesday, 8 November, 2017 9:51 AM  
**To:** Alywin  
**Cc:** 'assignments'; Ashley Chong (LKK Auto)  
**Subject:** Your ref: AS.172056.AY (IN) ; Sompo Ref : CMTD1702416 ; RE: PRI FOR SJW2813T

### Without Prejudice

Dear Sir,

With reference to the captioned, we acknowledge receipt of your letter dated 25.10.2017 and we have clarified with our surveyor, M/s LKK AUTO, that post repair inspection was done for your client's vehicle, SJW2813T.

In view of the above, we will be conducting the paper – resurvey for SJW2813T and we will revert to you as soon as possible and kindly hold hands.

By copy to M/s LKK AUTO,

As just spoken to Ms Catherine, kindly assist in the above, thank you.

Best Regards

**Gnoh Pau Loong**

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](http://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Henry, Irene James

**Sent:** Monday, 17 July, 2017 12:28 PM

**To:** Alywin <alywin@chiaarul.com>

**Cc:** Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; 'assignments' <assignments@lkkauto.com>; Ashley Chong (LKK Auto) <admin-d@lkkauto.com>

**Subject:** Reference: CMTD1702416 ; RE: PRI FOR SJW 2813T

Our Reference: CMTD1702416/GPL

Your Reference: SJW 2813T

Date: 17<sup>TH</sup> July 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S CHIA S ARUL LLC

Accident involving SJW 2813T and PC 564J on 17/07/2017

Dear Sirs,

We refer to your email reply dated 17/07/2017.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO CONSULTANTS PTE LTD** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Best Regards

**Irene Henry**

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: [www.sompo.com.sg](http://www.sompo.com.sg) | Facebook: [www.facebook.com/SompoSG](http://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

---

**From:** Alywin [<mailto:alywin@chiaarul.com>]

**Sent:** Monday, 17 July, 2017 11:31 AM

**To:** Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>

Cc: Gnoh, Pau Loong <[PauLoong.Gnoh@sompo.com.sg](mailto:PauLoong.Gnoh@sompo.com.sg)>

Subject: RE: PRI FOR SJW 2813T

Dear All,

We refer to the above matter.

Kindly be inform that our client is not agreeable to your list of surveyor.

We have our client's instructions to propose our client's list for your nomination:

- 1) Sincere Appraisal - Mr Dave
- 2) WG Appraisal - Mr Winson

Please let us have your reply soon.

Please do not hesitate to contact me should you have any queries thereof.

*Best regards,*

*Mr Alywin Yeo*

*M/s Chia S Arul LLC*

*151 Chin Swee Road*

*#03-09 Manhattan House*

*Singapore 169876*

*Tel: (65) 6733 4647 Fax: (65) 6733 8183*

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

---

**From:** Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]

**Sent:** 17 July, 2017 11:28 AM

**To:** Alywin

**Cc:** Gnoh, Pau Loong

**Subject:** RE: PRI FOR SJW 2813T

Our Reference: CMTD1702416/GPL

Your Reference: SJW 2813T

Date: 17<sup>th</sup> July 2017

Without Prejudice

**BY EMAIL ONLY**

**Attention:**

**M/S CHIA S ARUL LLC**

**Accident involving SJW 2813T and PC 564J on 17/07/2017**

Dear Sir

We refer to your Notice of Accident via email dated 17/07/2017.

Please be informed that Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	<b>Motor Surveyor</b>	<b>Surveyor</b>	<b>Selection (Indicate as tick)</b>
1	In House surveyor	Teo See Ling	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	

		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	Raleigh Services	Andrew Ow Yong	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623  
**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

**From:** Alywin [<mailto:alywin@chiaarul.com>]  
**Sent:** Monday, 17 July, 2017 10:42 AM  
**To:** Henry, Irene James <[irene.henry@sompo.com.sg](mailto:irene.henry@sompo.com.sg)>  
**Subject:** PRI FOR SJW 2813T

Dear All,

We enclosed herewith a copy of PRI for your necessary action.

Please do not hesitate to contact me should you have any queries thereof.

*Best regards,*

*Mr Alywin Yeo*

*M/s Chia S Arul LLC*

*151 Chin Swee Road*

*#03-09 Manhattan House*

*Singapore 169876*

*Tel: (65) 6733 4647 Fax: (65) 6733 8183*

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at [info@chiaarul.com](mailto:info@chiaarul.com). Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/07/2017 09:35
Date Of Accident	17/07/2017 08:05
Exact Location Of Accident	PIE TWDS TUAS B4 JALAN BAHAR EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW2813T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM HANN YAW
NRIC No	S7377683Z
Email Address	RAYLIMHY@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96699862
Alternative Phone No	OTHERS-96699862

### Vehicle Particulars

Manufacturer	HONDA
Model	FREED
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100449644-01000
Cover Note Number	

### Driver

Name of Driver	LIM HANN YAW
NRIC No	S7377683Z
Date Of Birth	29/11/1973
Occupation	INDOOR
Date Of Driving Pass	19/02/1997
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96699862
Fax Number	
Contact Number	OTHERS-96699862
Email Address	RAYLIMHY@HOTMAIL.COM

Address	BLK 673B JURONG WEST ST 65 #10-02
Postcode	642673
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG PIE TWDS TUAS B4 JLN BAHAR EXIT ON THE EXTREME LEFT LANE, IT WAS HEAVY TRAFFIC AND CONGESTED. INFRT OF MY VEH STOP AND I FOLLOWED SUIT SUDDENLY VEH(B) BEARING REG NO PC564J CAME FROM BEHIND AND HIT ONTO MY REAR PORTION OF MY VEH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC564J
Vehicle Make/Model/Colour	TOYOTA HIACE
Details Of Properties	
Name of Driver	JUNIADI BIN HARON
NRIC/Passport Number	S7205527F
Contact Number	83675422
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]*  
 17/7/2017  
 Policyholder's Signature / Date & Time

*[Signature]*  
 17/07/2017  
 Driver's Signature (if driver is not the policyholder) / Date & Time

*[Signature]*  
 17/07/2017  
 Witnessed by Reporting Centre Personnel

Sketch Plan




Sketch Plan #2

Describe Circumstances of the Accident


Pls refer to the statement

Declaration

We declare the foregoing particulars are true in every respect.

 12/2/2017  
Policyholder's Signature / Date & Time

 12/2/2017  
Driver's Signature (if driver is not the policyholder) / Date & Time

 17/07/17  
Witnessed by Reporting Centre Personnel

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	7683Z
Vehicle Details	
Vehicle No.	SJW2813T
Vehicle to be Exported	No
Intended De-registration Date	29 Nov 2017
Vehicle Make	HONDA
Vehicle Model	FREED 1.5G A
Primary Colour	Grey
Manufacturing Year	2008
Engine No.	L15A2334652
Chassis No.	GB31034242
Maximum Power Output	87.0 kW (116 bhp)
Open Market Value	\$20,215.00
Original Registration Date	25 Jan 2010
First Registration Date	25 Jan 2010
Transfer Count	0
Actual ARF Paid	\$20,215.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	24 Jan 2020
PARF Rebate Amount	\$12,129.00
Intended COE Rebate Details	
COE Expiry Date	24 Jan 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$20,501.00
COE Rebate Amount	\$4,414.00
<b>Total Rebate Amount</b>	<b>\$16,543.00</b>

The information contained herein is correct as at 29 Nov 2017

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/07/2017 15:48
Date Of Accident	17/07/2017 08:10
Exact Location Of Accident	PIE - BEFORE JLN BAHAR EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC564J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SUPERBIZ TRANSPORT SERVICE
Co Reg No	-
Email Address	SUPERBIZTS@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-94524599

### Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTSCBU000433
Cover Note Number	

### Driver

Name of Driver	JUNIADI BIN HARON
NRIC No	S7205527F
Date Of Birth	10/02/1972
Occupation	OUTDOOR
Date Of Driving Pass	06/07/2014
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83675422
Fax Number	
Contact Number	
Email Address	SUPERBIZTS@GMAIL.COM

Address BLK 632 BEDOK RESERVIOR RD #02-852 S470632

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHED REPORT

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJW2813T

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver UNKNOWN

NRIC/Passport Number

Contact Number 96699862

Address NA

NA

Postcode NA

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name NA

Phone Number NA

Email Address NA

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Under the Personal Data Protection Act (PDPA) I understand, acknowledge, agree and consent that
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
    - (ii) investigating the accident and/or my claims,
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


 16 10 hrs  
17 7.17

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

PIE BEFORE JLN BAHAR EXIT





VEHICLE INSPECTION REPORT

TO: **Lim Hann Yaw**  
Blk.673B, Jurong West Street 65  
#10-02  
Singapore 642673

REFERENCE

Requested by: **Lim Hann Yaw**  
Date of Request: **17 July, 2017**  
Date of Inspection: **17 July, 2017**

Our Ref: **M/T/23236/2017**  
Policy No.:  
Claim No.:

DETAILS OF VEHICLE

Reg No: <b>SJW 2813 P</b>	Engine No: <b>L15A2334652</b>	Air-Conditioners: <b>Yes</b>
Year: <b>2010</b>	Chassis No: <b>GB31034242</b>	Radio/Cassette: <b>Yes</b>
Make & Model: <b>Honda Freed 1.5</b>	Speedo Reading: <b>173216</b>	Seat Belt: <b>Yes</b>
Colour: <b>Metallic Grey</b>	Carry Capacity: <b>4</b>	Others: <b>Nil</b>


PRE-ACCIDENT CONDITION (STATIC TESTS)

General: **Good**  
Handbrake: **Servicable**  
Footbrake: **Servicable**  
Steering: **Servicable**

TYRES

60% ————— 60%  
↑  
**Firestone**  
60% ————— 60%  
Rim: **Sports**  
Size: **195/60 R 15**

IMPACT: ARROW INDICATES DIRECTION OF IMPACT.



GENERAL DESCRIPTION OF DAMAGE

The impact was confined to the rear portion of the vehicle.

The above vehicle sustained damaged were rear boot floor panel - buckled, rear spare wheel housing panel - distorted, rear o/s & n/s chassis frame - buckled.

APPRAISEMENT

Original Quotation: **\$ 18,546.00** Revised Quotation: **\$ 15,399.60** Less Excess: **Nil**

SPECIAL REMARKS

The estimated period of repairs will take 14 days to complete. Pursuant to your instructions, we have not authorised M/s. Ryder Auto Pte Ltd to repair on your behalf. A trade discount of 20% was noted and the survey was conducted strictly without prejudice basis.

# MIC SURVEY & ASSESSMENT SERVICE

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

NAME OF REPAIRERS: Ryder Auto Pte Ltd

ADDRESS: 1 Kaki Bukit Ave. 6  
#01-56 Autobay  
Singapore 417883

Replaces of Parts		Conditions	Repairs Est.	Our Recommendation
<u>To Supply :-</u>				
1	pc	Rear Bumper	Badly Buckled/ Cracked	950 \$ 1,590.00 ✓ \$ 1,590.00 ✓
1	pcs	Rear Bumper Tow Cover	Missing	85.00 ✓ 85.00 ✓
1	pc	Rear Bumper Beam (Upper)	Bent	166.00 ✓ 166.00 ✓
10	pcs	Rear Bumper Clips	Necessary	125.00 ✓ 125.00 ✓
2	pcs	Rear Bumper o/s & n/s Corner Clips	Cracked	202.00 ✓ 202.00 ✓
1	pc	Rear Tail-gate	Badly Dented/Bent	1,769.00 ✓ 1,769.00 ✓
1	pc	Rear Tail-gate Weatherstrip	Torn	363.00 ✓ 363.00 ✓
1	pc	Rear Tail-gate Emblem	Necessary	48.00 ✓ 48.00 ✓
1	pc	Rear Tail-gate 'FREED' Emblem	Cracked	45.00 ✓ 45.00 ✓
1	pc	Rear Tail-gate Moulding (Outer)	Cracked	366.00 ✓ 366.00 ✓
4	pcs	Rear Tail-gate Moulding Clips(Outer)	Necessary	50.00 ✓ 50.00 ✓
1	pc	Rear Tail-gate Inner Trim	Cracked	496.00 ✓ 496.00 ✓
8	pcs	Rear Tail-gate Inner Trim Clips	Necessary	100.00 ✓ 100.00 ✓
2	pcs	Rear Tail-gate o/s & n/s Stopper	Torn	36.00 ✓ 36.00 ✓
2	pcs	Rear Tail-gate o/s & n/s Hinges	Bent	302.00 ✓ 302.00 X
2	pcs	Rear Tail-gate o/s & n/s Shock Absorber	Bent/Jam	456.00 ✓ 456.00 X
1	pc	Rear Tail-gate Lock (Upper)	Bent	388.00 ✓ 388.00 190
1	pc	Rear Tail-gate Lock (Lower)	Bent	106.00 ✓ 106.00 38
1	pc	Rear Tail-gate Lock Handle Garnish (Inner)	Cracked	211.00 ✓ 211.00 X
1	pc	Rear Tail-gate Lower Panel	Badly Dented	565.00 ✓ 565.00 380
1	pc	Rear Tail-gate Lower Panel Inner Trim	Cracked	268.00 ✓ 268.00 186
4	pcs	Rear Tail-gate Lower Panel Inner Trim Clips	Necessary	50.00 ✓ 50.00 30
2	pcs	Rear Regn. No. Plate Lamp	Cracked	114.00 ✓ 114.00
1	pc	Rear Boot Floor Mat	Torn	463.00 ✓ 463.00 X
3	pcs	Rear Boot Floor Insulator	Necessary	202.00 ✓ 202.00
2	pcs	Rear o/s & n/s Tail-lamp	Cracked	922.00 ✓ 922.00
2	pcs	Rear o/s & n/s Tail-lamp Sealant	Necessary	100.00 ✓ 100.00
4	pcs	Rear o/s & n/s Tail-lamp Clips	Cracked	50.00 ✓ 50.00
2	pcs	Rear o/s & n/s Fender Inner Trim	Cracked/Torn	1,232.00 ✓ 1,232.00
16	pcs	Rear o/s & n/s Fender Inner Trim Clips	Necessary	180.00 ✓ 180.00
1	pc	Rear Windscreen Moulding	Necessary	288.00 ✓ 288.00
14	pcs	Rear Windscreen Moulding Clips	Necessary	175.00 ✓ 175.00
1	pc	Rear Exhaust Muffler	Bent	1,180.00 ✓ 1,180.00
1	pc	Rear Exhaust Muffler Tail Pipe	Bent	182.00 ✓ 182.00
2	pcs	Rear Exhaust Muffler Mounting	Torn	107.00 ✓ 107.00
			<b>\$12,982.00</b>	<b>\$12,982.00</b>
Less 20% discount :-			-	<b>(\$ 2,596.40)</b>
				<b>\$10,385.60</b>
<u>Nett Items :-</u>				
1	pc	Rear Reverse Sensor	Cracked	280.00 ✓ 280.00
1	pc	Rear Camera	Cracked	680.00 ✓ 680.00
1	pc	Rear Regn. No. Plate	Bent	45.00 ✓ 45.00
1	pc	Rear Regn. No. Plate Bracket	Cracked	29.00 ✓ 29.00
1	pc	Rear Windscreen Sealant	Necessary	60.00 ✓ 60.00
1	pc	Rear Windscreen Inner Seal	Necessary	50.00 ✓ 50.00
			<b>\$ 1,144.00</b>	<b>\$ 1,144.00</b>

# MIC SURVEY & ASSESSMENT SERVICE

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

NAME OF REPAIRERS: Ryder Auto Pte Ltd

ADDRESS: 1 Kaki Bukit Ave. 6  
#01-56 Autobay  
Singapore 417883

Replaces of Parts	Conditions	Repairs Est.	Our Recommendation
(2)			
<b>BALANCE B/F :-----</b>		<b>\$14,126.00</b>	<b>\$11,529.60</b>
<u>Labour Charges &amp; Miscellaneous :-</u>			
To dismantle rear portion damaged parts, straighten rear boot floor panel, rear spare wheel housing panel, rear o/s & n/s chassis frame and reweld rear tail-gate lower panel.		\$ 1,800.00	\$ 1,600.00 <sup>1200</sup>
To putty and spray painting (Metallic Paint).		\$ 1,600.00	\$ 1,400.00 <sup>1000</sup>
To replace rear exhaust muffler.		\$ 200.00	\$ 180.00 X
To remove and refit rear windscreen.		\$ 180.00	\$ 150.00 <sup>120</sup>
To remove and replace rear reverse sensor and camera.		\$ 200.00	\$ 180.00 <sup>60</sup>
To remove and replace rear tail-gate.		\$ 180.00	\$ 140.00 X
To check wiring.		\$ 80.00	\$ 60.00 <sup>30</sup>
To re-seal anti rust.		\$ 180.00	\$ 160.00 <sup>90</sup>
		<u>\$18,546.00</u>	<u>\$15,399.60</u>

**SPECIAL REMARKS**

The repairers verbally agreed to repair the vehicle at a global sum of \$13,000.00 corresponding to labour charges, spray painting and replacement of parts. Your liability is \$13,000.00.

  
7  
 LS  
 20/6



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO17013746/Ggbs2-1

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 01-12-2017



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	PC 564J	<b>Veh. Inspected</b>	SJW 2813T
<b>Policy No.</b>	D17MTSCBU00043	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD1702416/GPL	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GNOH PAU LOONG	<b>Assign Date</b>	08/11/2017

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA FREED	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2010
<b>Chassis No.</b>	GB31034242	<b>Colour</b>	GREY
<b>Odometer</b>	173216	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/60R15	FALKEN	5 mm
<b>L/H Front Tyre</b>	195/60R15	FALKEN	5 mm
<b>R/H Rear Tyre</b>	195/60R15	FALKEN	5 mm
<b>L/H Rear Tyre</b>	195/60R15	FALKEN	5 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	17/07/2017	<b>Inspection Date</b>	17/07/2017
<b>Survey held at</b>	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 2813T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	BADLY BUCKLED / CRACKED	1,590.00	980.00
1	REAR BUMPER TOW COVER	MISSING	85.00	30.00
1	REAR BUMPER BEAM (UPPER)	BENT	166.00	90.00
10	REAR BUMPER CLIPS	NECESSARY	125.00	50.00
2	REAR BUMPER O/S & N/S CORNER CLIPS	CRACKED	202.00	80.00
1	REAR TAIL-GATE	BADLY DENTED / BENT	1,769.00	1,290.00
1	REAR TAIL-GATE WEATHERSTRIP	TORN	363.00	150.00
1	REAR TAIL-GATE EMBLEM	NECESSARY	48.00	48.00
1	REAR TAIL-GATE 'FREED' EMBLEM	CRACKED	45.00	45.00
1	REAR TAIL-GATE MOULDING (OUTER)	CRACKED	366.00	287.00
4	REAR TAIL-GATE MOULDING CLIPS (OUTER)	NECESSARY	50.00	30.00
1	REAR TAIL-GATE INNER TRIM	CRACKED	496.00	350.00
8	REAR TAIL-GATE INNER TRIM CLIPS	NECESSARY	100.00	50.00
2	REAR TAIL-GATE O/S & N/S STOPPER	TORN	36.00	36.00
2	REAR TAIL-GATE O/S & N/S HINGES	NOT NECESSARY	302.00	-
2	REAR TAIL-GATE O/S & N/S SHOCK ABSORBER	NOT NECESSARY	456.00	-
1	REAR TAIL-GATE LOCK (UPPER)	BENT	388.00	190.00
1	REAR TAIL-GATE LOCK (LOWER)	TO REPAIR SEE LABOUR	106.00	-
1	REAR TAIL-GATE LOCK HANDLE GARNISH (INNER)	NOT NECESSARY	211.00	-
1	REAR TAIL-GATE LOWER PANEL	BADLY DENTED	565.00	380.00
1	REAR TAIL-GATE LOWER PANEL INNER TRIM	CRACKED	268.00	186.00
4	REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS	NECESSARY	50.00	30.00
2	REAR REGN. NO. PLATE LAMP	CRACKED	114.00	114.00
1	REAR BOOT FLOOR MAT	NOT NECESSARY	463.00	-
3	REAR BOOT FLOOR INSULATOR	NECESSARY	202.00	150.00
2	REAR O/S & N/S TAIL-LAMP	CRACKED	922.00	746.00
2	REAR O/S & N/S TAIL-LAMP SEALANT	NECESSARY	100.00	60.00
4	REAR O/S & N/S TAIL-LAMP CLIPS	CRACKED	50.00	30.00
2	REAR O/S & N/S FENDER INNER TRIM	CRACKED / TORN	1,232.00	1,232.00
16	REAR O/S & N/S FENDER INNER TRIM CLIPS	NECESSARY	180.00	90.00
1	REAR WINDSCREEN MOULDING	NECESSARY	288.00	120.00
14	REAR WINDSCREEN MOULDING CLIPS	NECESSARY	175.00	60.00

Report Ref No. CS3/SMO17013746/Ggbs2-1



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	1,180.00	-
1	REAR EXHAUST MUFFLER TAIL PIPE	BENT	182.00	130.00
2	REAR EXHAUST MUFFLER MOUNTING	TORN	107.00	107.00
	LESS 20% DISCOUNT		-	-1,428.20
			12,982.00	5,712.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR REVERSE SENSOR (SN)	CRACKED	280.00	200.00
1	REAR CAMERA (SN)	SERVICEABLE	680.00	-
1	REAR REGN. NO. PLATE (SN) }	BENT	45.00	45.00
1	REAR REGN. NO. PLATE EMBLEM (SN) }	CRACKED	29.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	50.00
			1,144.00	355.00
	<b><u>LABOUR</u></b>			
	TO DISMANTLE REAR PORTION DAMAGED PARTS, STRAIGHTEN REAR BOOT FLOOR PANEL, REAR SPARE WHEEL HOUSING PANEL, REAR O/S & N/S CHASSIS FRAME AND REWELD REAR TAIL-GATE LOWER PANEL. INCLUSIVE OF THE REPAIR OF REAR TAIL-GATE LOCK (LOWER) AND REAR EXHAUST MUFFLER.		1,800.00	900.00
	TO PUTTY AND SPRAY PAINTING (METALLIC PAINT).		1,600.00	1,000.00
	TO REPLACE REAR EXHAUST MUFFLER.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN.		180.00	120.00
	TO REMOVE AND REPLACE REAR REVERSE SENSOR AND CAMERA		200.00	60.00
	TO REMOVE AND REPLACE REAR TAIL-GATE.	NOT NECESSARY	180.00	-
	TO CHECK WIRING.		80.00	30.00
	TO RE-SEAL ANTI RUST.		180.00	90.00
			4,420.00	2,200.00
<b>GRAND TOTAL</b>			<b>18,546.00</b>	<b>8,267.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>6,600.00</b>

Report Ref No. CS3/SMO17013746/Ggbs2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.