

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

NOT ADVISED

HQ - Transport Command
Kranji Camp 13
151, Chua Chu Kang Way
(688248)

Attention : Motor Claim Department

Estimate : ES005256

Date : 06/11/2017
Vehicle Num. : SLM 4476Z (LCR)
Make/Model : TOYOTA PRIUS HYBRID
Chassis/Eng# :
Accident Date : 04/11/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

REAR BUMPER (PIRUS) ✓ Cut 423.90
REAR BUMPER CENTER GUARD (PIRUS) ? J Deform. 552.30
REAR BUMPER REINFORCEMENT(PIRUS) ? ✓ DT 318.80

List TotalS\$:

25.00% Discount S\$:

1,295.00

323.75

971.25

LABOUR :

To labour charge for removing rear bumper assy
reinforcement out to facilitate repairs and
replacement of damaged parts
To respray rear bumper

Labour Total S\$:

200 600.00

200 400.00

1,000.00

1) Parts : \$ 971.25

2) Labour : \$ 400.00

\$ 1371.25 @ 3 days.

E. & O.E.

Total S\$: 1,971.25

for WORLD AUTO PTE LTD

Parts 1295.00
Less 323.75
971.25
Labour 400.00
Net 1,371.25

Sebastian.
14/11/2017.

- Part by part repair.

- Question Mark Item
Photo.

- Photo Before Paint
9003614

sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Before Paint Survey
15/11/2017 1615